

6. Adjust measuring pins to zero.




Fig. 162

8. The measuring pins on the damaged side will now show how great the deformation is and whether new sections are necessary or whether adjustments will suffice.




Fig. 163

7. The undamaged side of the chassis and thereby the centerline of the car can be centered laterally by setting the pins to zero.

Tolerances

32 B0

The drawing on page B 61 gives all necessary dimensions and tolerances in millimeters. Chassis

measurements which are not within the tolerances but not greater than 4 mm may be corrected.

Beyond 4 mm new sections should be installed.