

4> Drive a Stepper motor interface to rotate the motor in clockwise by N steps. Introduce suitable delay between successive steps.

A. WAVE DRIVE :-

```
#include <reg.h>
#include <reg 52.h>
#include <stdio.h>
void delay (int);
void main () {
do {
P2 = 0x01;
delay(1000);
P2 = 0x02;
delay(1000);
P2 = 0x04;
delay(1000);
P2 = 0x08;
delay(1000);
}
while(1);
}

void delay (int k) {
int i, j;
for(i = 0; i < k; i++) {
for(j = 0; j < 100; j++) {
}
}
```


FULL DRIVE :-

```
#include <reg52.h>
```

```
#include <stdio.h>
```

```
void delay(int);
```

```
void main() {
```

```
do {
```

```
P2 = 0x03;
```

```
delay(1000);
```

```
P2 = 0x06;
```

```
delay(1000);
```

```
P2 = 0x09; P2 = 0x0c;
```

```
delay(1000);
```

```
P2 = 0x09;
```

```
delay(1000);
```

```
}
```

```
while(1);
```

```
}
```

```
void delay(int k) {
```

```
int i, j;
```

```
for(i = 0; i < k; i++) {
```

```
for(j = 0; j < 100; j++) {
```

```
}}}
```


HALF DRIVE :-

#include <reg52.h>

#include <stdio.h>

void delay(int);

void main() {

{

P2 = 0x01;

delay(1000);

P2 = 0x03;

delay(1000);

P2 = 0x02;

delay(1000);

P2 = 0x06;

delay(1000);

P2 = 0x04;

delay(1000);

P2 = 0x0C;

delay(1000);

P2 = 0x08;

delay(1000);

P2 = 0x09;

delay(1000);

}

while(1);

}

void delay(int k) {

int j, i;

for (i = 0; i < k; i++) {

for (j = 0; j < 100; j++) {

{

}