

Strengthening & Corrosion in Metals

Instructor : Prof. Bishakh Bhattacharya
Dept. of Mechanical Engineering
IIT Kanpur
India

E-mail : *bishakh@iitk.ac.in*



Smart Materials Structures and Systems
Laboratory
IIT Kanpur

Content

- ✓ Strengthening Mechanisms in Metals
- ✓ Corrosion in metals
- ✓ Corrosion types & prevention



Strengthening Mechanism in Metals

- The ability of a metal to **plastically deform** depends on the ability of **dislocations** to **move**.
- Thus restricting or **hindering dislocation** motion makes a material **harder and stronger**.
- Some mechanism to strengthen metals are as follows:
 - ✓ Grain size reduction
 - ✓ Solid-solution strengthening
 - ✓ Strain hardening



Grain size reduction


- Grain boundary acts as a barrier for dislocations for two reasons:-
 - ✓ **Mis-orientation** : Difficult for a dislocation to pass into another grain, especially if it is more misaligned.
 - ✓ **Atomic disorder** Near/within a grain boundary region leads to discontinuity of slip planes from one grain into the other.
- A **fine-grained** material (one that has small grains) is **harder** and **stronger** than **coarse grained**, due to **greater** total **grain boundary area** to restrict dislocation motion.

Hall-Petch relation showing dependence of Yield strength (σ_y) on average grain diameter (d) as

$$\sigma_y = \sigma_o + k_y d^{-1/2}$$


where, σ_o & k_y are constant for particular material

Heat treatment after plastic deformation and changing the rate of solidification are the ways to alter grain size.







(a)



(b)




(c)



(d)

Figure 1: 50x Photomicrographs of A356 Samples with Solidification Rates (a) $6.2^{\circ}\text{C}/\text{sec}$, (b) $3.8^{\circ}\text{C}/\text{sec}$, (c) $2.0^{\circ}\text{C}/\text{sec}$ and (d) $0.2^{\circ}\text{C}/\text{sec}$

Hall–Petch constants		
Material	σ_o [MPa]	k [MPa m ^{1/2}]
Copper	25	0.11
Titanium	80	0.40
Mild steel	70	0.74
Ni ₃ Al	300	1.70





Change of
Strength with
Grain Diameter
in Mild Steel




Solid Solution Strengthening


- Pure metals are almost always softer than their alloys.
- Adding another element that goes into interstitial or substitutional positions in a solution increases strength.
- The impurity atoms cause lattice strain which can "anchor" dislocations.
- Thus, Alloys are stronger than pure metals.



Effect: Nickel added as an alloy in Copper



Compressive Strain imposed on host atoms by larger impurity atom



Tensile strain imposed on host atoms by smaller impurity atom.




Strain hardening

- Strain hardening is the phenomenon whereby a ductile metal becomes harder and stronger as it is plastically deformed.
- It is also called as **Work hardening / Cold working** because temperature at which deformation takes place is lower than melting temperature.



$$\% \text{ Cold working} = \left(\frac{A_o - A_d}{A_o} \right) \times 100$$

A_o = Original area
 A_d = Deformed area



Strain imposed on nearby atoms

The effects of strain hardening may be removed by annealing heat treatment (slow heating & slow cooling).



Summary of Strengthening mechanisms

- **Refining grain boundaries** - Serve as barriers to dislocation motion; thus refining the grain size of a polycrystalline material renders it harder and stronger.
- **Solid - solution strengthening** - Results from lattice strain interactions between impurity atoms and dislocations.
- **Strain hardening** - Enhancement of strength with increased plastic deformation.

Precipitation/Age hardening

- Technique used to increase the **yield strength** of **malleable materials** like Al-Cu alloys, stainless steels, etc.
- Based on changes in **solid solubility** with **temperature** to produce fine particles of an **impurity phase**, which blocks the movement of **dislocations** in a crystal's lattice.
- Alloys must be kept at elevated temperature for **hours** to allow precipitation to take place. This time delay is called **aging**.





Corrosion of Metals



Smart Materials Structures and Systems
Laboratory
IIT Kanpur

Corrosion

- **Corrosion** is defined as the **destructive** and **deteriorative loss** of a metal which is **electrochemical** in nature and ordinarily **begins** at the **surface**.
- The material loss takes place either by
 - ✓ Dissolution
 - ✓ Formation of scale or a film (*oxidation*)
- It is estimated that approximately 5% of an industrialized nation's income is spent on:-
 - ✓ Corrosion prevention
 - ✓ Maintenance or replacement of products lost or contaminated





Electrochemical Reaction

- **Oxidation (anodic) reaction:** Metals have free electrons which they give-up.
- **Reduction (cathodic) reaction:** Electrons transferred to another chemical species.

Oxidation reaction



Reduction reaction



Corrosion of Zinc in an acid solution



When does the oxidation of the material provide a protective layer?

$$\text{Pilling - Bedworth ratio, PB} = \frac{\text{Volume of the oxide formed}}{\text{Volume of metal consumed in the oxidation}}$$


For good oxidation resistance the oxide should be adherent to the surface.

PB < 1 : Tensile stresses in oxide film → brittle oxide cracks & thus **un-protective**.

1 < PB ≤ 2 : Compressive stresses in oxide film → uniformly over metal surface, thus **protective**.


PB > 2 : High compressive stresses in oxide film → oxide cracks & flakes off, **un-protective**.

Oxide	PB Ratio
K ₂ O	0.41
Na ₂ O	0.58
MgO	0.79
Al ₂ O ₃	1.38
NiO	1.60
Cu ₂ O	1.71
Cr ₂ O ₃	2.00
Fe ₂ O ₃	2.16



Galvanic Series

Ranks the **reactivity** of metals in **sea water**



Forms of Corrosion

1. Uniform Attack

- Most common form of corrosion.
- Oxidation and reduction reactions occur randomly over the surface.
- Maximum metal loss by this form.



Uniform Attack

2. Galvanic Corrosion

- Occurs when two metals or alloys of different compositions are electrically coupled in presence of an electrolyte.
- Less noble/more reactive metal will get corroded.
- **Example:** Steel corrosion in domestic water heater having Cu - steel junction.
- Avoid either coupling of dissimilar metals or choose relatively close metals from galvanic series.
- Use large anode area.
- Electrically insulate dissimilar metals.




Galvanic corrosion of steel in Water heater



3. Intergranular Corrosion

- Occur along grain boundaries in some stainless steel operating at temperature 500 - 800°C for long time.
- Heat causes formation of chromium carbide (Cr_{23}C_6) particles along grain boundary while depleted region gets corroded.
- Hence, reduce carbon content below 0.03% & add Titanium or Niobium which form carbide to protect Chromium.



Corrosion in stainless steel

Reference: W.D Callister, 7 Ed.

4. Stress Corrosion

- Stress & corrosion phenomenon occur simultaneously



**Crack in Brass pipe
under ammonia pressure**

5. Erosion–Corrosion

- Combined effect of chemical attack & mechanical wear due to fluid motion.
- Example : Propellers, turbine blades, valves, and pumps ,i.e., where there is an abrupt change in fluid speed or direction.




**Wear & corrosion
of propeller blades**



Smart Materials Structures and Systems
Laboratory
IIT Kanpur

6. Crevice corrosion

- Localized corrosion.
- Occur due to concentration difference of fluid/ions between two region of same metal piece.



Crevice corrosion

7. Pitting corrosion

- Localized corrosion attack - Small pits & holes forms.
- Initiated usually by scratch on surface and then grow downwards (due to gravity).



Pitting corrosion – wash basin



Corrosion Resistance

Aerated Water:

High resistance – **Lead Alloy**, Steel Alloy, **Titanium Alloy**, Nickel Alloy, **Copper Alloy**

Medium resistance – Aluminium Alloy

Low resistance - Carbon steels

Strong Acids:

High resistance – **Lead Alloy**, **Titanium alloy**, Stainless Steel

Medium – Aluminium Alloy

Strong Alkali:

High resistance – Nickel Alloys, Steels, **Titanium Alloy**


Medium – **Copper Alloys**, Zinc Alloys

UV - all alloys




Corrosion Prevention

1. Using metals which form a protective oxide layer.
2. Adding inhibitors, for example - Amines & hydrazines removes oxygen.
3. Reducing Temperature – decreases corrosion rate.
4. Painting
5. Cathodic Protection
 - ✓ The metal to be protected is connected to another more reactive metal, which gives up its electrons and gets oxidized (sacrificial anode).
 - ✓ Mg & Zn(galvanizing) are commonly used.



Magnesium sacrificial anode




Galvanic protection of steel



In the **next lecture**, we will learn:

- ✓ Ceramic Materials
- ✓ Classification & their properties

best of luck



Smart Materials Structures and Systems
Laboratory
IIT Kanpur