

MATERIAL REMOVAL PROCESSES

Theory of Metal Machining

1. Overview
2. Theory of Chip Formation
3. Force Relationships
4. Power and Energy Relationship
5. Cutting Temperature


1

Introduction

- Everyday Experience: Scraping the ice from your windshield
 - Edge angle of the ice scraper
 - Force required depending on the characteristics of ice
- Incentives: Making a ceramic vase out of clay
 - Shaping
 - Removal of excess materials - 'machining'
- Powder Metal or Cast
 - Exact dimension
 - Tolerance & Surface Finish

2

Classification



3


Material Removal Processes

A family of shaping operations through which undesired excess material is removed from a starting workpart so the remaining part become closer to the desired shape

- Categories:
 - *Machining* – material removal by a sharp cutting tool, e.g., turning, milling, drilling
 - *Abrasive processes* – material removal by hard, abrasive particles, e.g., grinding
 - *Nontraditional processes* - various energy forms other than sharp cutting tool to remove material

4

Machining




- A *shearing* process in which excess materials is removed by cutting tools.
 - A variety of work materials
 - 'Repeatable' regular geometries
 - Close tolerance ($<0.025\text{mm}$)
 - Smooth surface finish (0.4mm)
 - Waste, Expensive: Cost and Time
 - Other processes such as casting, forging, and bar drawing create the general shape
 - Machining provides the final shape, dimensions, finish, and special geometric details

5

1. Overview

- Types
 - Turning - Lathe
 - Drilling – Drill press
 - Milling – Milling Machine
 - Peripheral
 - Face
- Cutting Tool



6


Cutting condition

- Relative motion between tool and work
- Cutting conditions
 - Cutting speed, v (m/s) – Surface speed
 - Feed f (m): the lateral distance traveled by the tool during one revolution.
 - Depth of cut d (m)
- Material Removal Rate: $MRR = v f d$
 - Roughing - removes large amounts of material, at high feeds and depths, low speeds
 - Finishing - Achieves final dimensions, tolerances, and finish, Low feeds and depths, high cutting speeds

7

Machine Tools


- A power-driven machine that performs a machining operation
 - Holds workpart
 - Positions tool relative to work
 - Provides power and controls speed, feed, and depth.
 - Pumps a Cutting fluid



8

2. Theory of Chip Formation

- Orthogonal Cutting Model

Rake angle: α Shear angle: ϕ

Chip thickness ratio:

$$r = \frac{t_o}{t_c} = \frac{l_s \sin \phi}{l_s \cos(\phi - \alpha)}$$


By rearranging

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

 r is always less than 1.0.

9

Shear Strain in chip



$$\text{Using } \sin(\alpha \pm \beta) = \sin \alpha \cos \beta \pm \cos \alpha \sin \beta$$

$$\cos(\alpha \pm \beta) = \cos \alpha \cos \beta \mp \sin \alpha \sin \beta$$

$$\gamma = \frac{AC}{BD} = \frac{DC + AD}{BD} = \tan(\phi - \alpha) + \cot \phi$$

$$= \frac{\sin(\phi - \alpha)}{\cos(\phi - \alpha)} + \frac{\cos \phi}{\sin \phi} = \frac{\cos \alpha}{\sin \phi \cos(\phi - \alpha)}$$


As ϕ (from 10° to 35°) increase, γ (from 5 to 2) decreases.

10

Velocity

$$\frac{V}{\sin\left(\frac{\pi}{2} - \phi + \alpha\right)} = \frac{V_s}{\sin\left(\frac{\pi}{2} - \alpha\right)} = \frac{V_c}{\sin \phi}$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$




$$\dot{\gamma} = \frac{V_s}{\Delta y} = \frac{\cos \alpha}{\cos(\phi - \alpha)} \frac{V}{\Delta y}$$

where Δy is the finite thickness of the shear plane, typically 0.03mm.Shear Strain rate is around 10^3 - 10^6sec^{-1}

11

Actual Chip Formation

- Discontinuous chip
 - Brittle materials at low cutting speed
 - High tool-chip friction and large feed and depth
- Continuous chip
 - Ductile materials with high speeds and small feed and depth of cut
- Continuous chip with built-up edge
 - Ductile material at low to medium speeds
- Serrated chip
 - Difficult-to-machine metals at high cutting speeds



The 'Real' Cutting Force

Cutting Forces are measured with Dynamometer.

- Area: $A = bh$
where b = chip width
 h = chip thickness
- Temperature (500-1000°C)
- Pressure (1000-3000 MPa)

13

3. Force Relationships

F : Friction Force F_s : Shear Force F_c : Cutting Force
 N : Normal Force F_n : Normal Force F_r : Thrust Force

14

Force Diagram

$$F = F_c \sin \alpha + F_t \cos \alpha$$

$$N = F_c \cos \alpha - F_t \sin \alpha$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_n = F_c \sin \phi + F_t \cos \phi$$

$$R = \frac{F_s}{\sin \phi \cos(\phi + \beta - \alpha)}$$

$$= \frac{\tau_s t_o w}{\sin \phi \cos(\phi + \beta - \alpha)}$$

$$F_c = \frac{F_s \cos(\beta - \alpha)}{\sin \phi \cos(\phi + \beta - \alpha)}$$

$$F_t = \frac{F_s \sin(\beta - \alpha)}{\sin \phi \cos(\phi + \beta - \alpha)}$$

15

Cutting Force

- Cutting Force: $F_c = bh \tau_s \left[\frac{\cos(\beta - \alpha)}{\sin \phi \cos(\phi + \beta - \alpha)} \right] = K_c b h$ $K_c [N/mm^2]$
- Thrust Force: $F_t = bh \tau_s \left[\frac{\sin(\beta - \alpha)}{\sin \phi \cos(\phi + \beta - \alpha)} \right] = K_t b h$

$$F_s = R \cos(\phi + \beta - \alpha) = F_c \cos \phi - F_t \sin \phi = \frac{\tau_s b h}{\sin \phi}$$

$$F_n = R \sin(\phi + \beta - \alpha) = F_c \sin \phi + F_t \cos \phi$$

K_c and K_t must be calibrated through machining experiments.

Top View

16

The Merchant Equation

- Shear stress: $\tau = \frac{F_s}{A_s}$
- Shear Plane Area: $A_s = \frac{t_o w}{\sin \phi}$
- Shear stress: $\tau = \frac{F_c \cos \phi - F_t \sin \phi}{t_o w / \sin \phi}$
- Merchant's Assumption: Shear plane angle will form to minimize energy
- After differentiating τ w.r.t ϕ , Merchant's Equation:

$$\phi = 45 + \frac{\alpha}{2} - \frac{\beta}{2}$$

17

Implication of Merchant's Eq.

$$\phi = 45 + \frac{\alpha}{2} - \frac{\beta}{2}$$

- An increase in rake angle causes the shear plane angle to increase.
- A decrease in friction angle cause the shear plane angle to increase.
- The analysis from orthogonal cutting can be used in a typical turning if the feed is small relative to depth of cut.

Effect of shear plane angle ϕ :


(a) higher ϕ with a resulting lower shear plane area;

(a) smaller ϕ with a resulting larger shear plane area.

18

Turning vs. Orthogonal

Feed f	Uncut Chip thickness t_o
Depth d	Width of cut w
Cutting speed v	Cutting speed v
Cutting force F_c	Cutting force F_c
Feed force F_f	Thrust force F_t




19

4. Power & Energy Relation

- Power (energy per unit time) $P_c = F_c V$
 $HP_c = \frac{F_c V}{33,000}$
 $hp_c = \frac{P}{33,000}$ P in ft-lb/min
- Horse power $P_g = \frac{P_c}{E}$ or $hp_g = \frac{hp_c}{E}$ with mechanical efficiency $E=90\%$
- Unit Power $P_u = \frac{P_c}{MRR}$
- Specific energy $U = P_u = \frac{P_c}{MRR} = \frac{F_c v}{v t_o w} = \frac{F_c}{t_o w}$

20

Size Effect & Energy Distribution



21

Specific Energy for various work materials ($t_o=0.25\text{mm}$)

Materials	Brinell Hardness	Specific Energy (U)	
		N-m/mm ³	Hp/in ³ /min
Carbon Steel	150-200	1.6	240,000
	200-250	2.2	320,000
	251-300	2.8	400,000
Alloy Steels	200-250	2.2	320,000
	251-300	2.8	400,000
	301-350	3.6	520,000
	351-400	4.2	640,000
Cast iron	125-175	1.1	160,000
	175-250	1.6	240,000
Stainless steel	150-200	2.8	400,000
Aluminum	50-100	0.7	100,000
Aluminum Alloys	100-150	0.8	120,000
Magnesium Alloys	50-100	0.4	60,000

22

Problem 21.30

A lathe performs a turning operation on a work piece of 6in diameter. The shear strength of the work=40,000lb/in². The rake angle of the tool =10°. The machine settings are: rotational speed=500rev/min, feed=0.0075in/rev. and depth=0.075in. The chip thickness after the cut is 0.015in. Determine: (a) the horsepower required (b) the unit horsepower for this material, (c) the unit horsepower with the correction factor (1 for $t_o=0.01\text{in.}$) Use the orthogonal model.

(a) To get HP, F_c and v are needed

$$r = \frac{t_o}{f} = \frac{0.0075}{0.015} = 0.5$$

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha}; \quad \phi = \arctan \left(\frac{0.5 \cos 10}{1 - 0.5 \sin 10} \right) = 28.3^\circ$$

$$\phi = 45 + \frac{\alpha}{2}; \quad \beta = 2 \left(45 + \frac{10}{2} - 28.3 \right) = 43.4^\circ \quad (b) \text{ } HP_u$$

$$A_s = \frac{t_o w}{\sin \phi} = \frac{0.0075 \cdot 0.075}{\sin 28.3} = 0.00119 \text{ in}^2$$

$$F_s = S A_s = 40,000(0.00119) = 47.5 \text{ lb}$$

$$F_c = \frac{F_s \cos(\beta - \alpha)}{\cos(\phi + \beta - \alpha)} = \frac{47.5 \cos(43.3 - 10)}{\cos(28.3 + 43.4 - 10)} = 83.6 \text{ lb}$$

$$v = \omega r = 500 \text{ rev/min} (\pi 6 / 12) \text{ ft/rev} = 785 \text{ ft/min}$$

$$HP = \frac{F_c v}{33,000} = \frac{83.6(785)}{33,000} = 2 \text{ hp}$$

23

5. Cutting Temperature

- Cook's dimensional analysis

$$T = 0.4 \frac{U}{\rho C} \left(\frac{v t_o}{K} \right)^{0.333}$$

- Experimental Measurement
 - Tool-chip thermocouple
 - Trigger's results $T = K v^m$
 - RC-130B Ti ($T=479v^{0.162}$)
 - 18-8 Stainless steel ($T=135v^{0.361}$)
 - B113 Free machining steel ($T=86.2v^{0.348}$)

24

Chatter Analysis

- Mechanical vibration

Free Vibration: $m\ddot{x} + c\dot{x} + kx = 0$

Forced Vibration: $m\ddot{x} + c\dot{x} + kx = F_o \sin \omega t$

Assume $x(t) = X \sin(\omega t + \phi)$

Or using complex harmonic functions

$$m\ddot{x} + c\dot{x} + kx = F_o e^{j\omega t}$$

$$\text{Assume } x(t) = X e^{j(\omega t + \phi)}$$

$$(k - \omega^2 m + j\omega c) X e^{j\phi} e^{j\omega t} = F_o e^{j\omega t} = F_o e^{j\phi} e^{j\omega t}$$

$$\text{Magnitude ratio: } |H(\omega)| = \left| \frac{X}{F_o} \right| = \frac{1}{k} \frac{1}{\sqrt{(1 - r^2)^2 + (2\zeta r)^2}}$$

$$\text{Phase: } \phi = \tan^{-1} \frac{-2\zeta r}{1 - r^2} + \alpha$$

$$\text{where } r = \omega / \omega_n \quad \zeta = c / 2\sqrt{km}$$

$$\text{and } \omega_n = \sqrt{\frac{k}{m}}$$

