


SCREW GAUGE & ITS USE

Presented by
Department of BSHU (Physics)
Subject: Physics Lab-1
Subject Code: BSPH-191/ BSPH-291

Micrometer Screw Gauge

A screw gauge is an instrument that is used to measure small lengths with accuracy than a vernier scale. It is called as micrometre screw gauge.

Construction: A simple screw gauge consists of a U-shaped metal frame with a metal stud at its one end. A hollow cylinder (or sleeve) has a millimeter scale - over it along a line called index line parallel to its axis. The hollow cylinder acts as a nut. It is fixed at the end of U-shaped frame opposite to the stud. A Thimble has a threaded spindle inside it.



SCREW GAUGE AND ITS USE

EXPERIMENTAL PROCEDURE


Before you use any micrometer you should know about least count.

Least Count (L.C.)



= pitch / no. of divisions on micrometer thimble

= $1/100 = 0.01$

Pitch = distance travelled by thimble on linear scale in one rotation.




SCREW GAUGE AND ITS USE

Positive Zero Error	Negative Zero Error
<p>This occurs when the zero mark on the circular scale is shifted down from the horizontal line on the main scale.</p>	<p>This occurs when the zero mark on the circular scale is shifted up from the horizontal line on the main scale.</p>
<p>Horizontal line on main Scale is in the line the 2 division mark, above the zero mark On the thimble scale.</p> <p>2 divisions = 0.02 mm Zero error = + 0.02 mm</p> 	<p>Horizontal line on main scale is in the line with the 3 division mark, below the zero mark on the thimble scale.</p> <p>3 divisions = 0.03 mm Zero error = - 0.03 mm</p> 

CORRECTION OF POSITIVE ZERO ERROR


- In this figure Horizontal line on main scale is in the line with the 2 division mark, above the zero mark On the thimble scale.
- 2 divisions = 0.02mm, Zero error = + 0.02 mm
- If the observed reading = 4 mm, then,
actual measurement = Observed reading – Zero error
= 4 mm – (+0.02) mm
= 3.08mm

Positive Zero Error



CORRECTION OF POSITIVE ZERO ERROR

- In this figure, Horizontal line on main scale is in the line with the 3 division mark, above the zero mark On the thimble scale.
- 3 divisions = 0.03mm, Zero error = - 0.03 mm
- If the observed reading = 4 mm, then
actual measurement = Observed reading – Zero error
= 4 mm – (-0.03) mm
= 4.03 mm



SCREW GAUGE AND ITS USE

HOW TO MEASURE THE DIAMETER OF SPHERE

