

HNC-8 Numerical Control System Software

Manual of PLC Programming



V1.24

2016-02

Wuhan Huazhong Numerical Control Co., Ltd.

Content

CONTENT	错误！未定义书签。
PREFACE	1
OVERVIEW	3
SPECIFICATIONS OF PLC	4
SEQUENTIAL PROGRAM NOTION	5
ALLOCATION INTERFACE	6
SEQUENTIAL PROGRAM	7
SEQUENTIAL PROGRAM COMPOSITION	12
ADDRESS	14
BASIC INSTRUCTION	15
LD	19
LDI	21
OUT	23
OOUT	25
SET	27
RST	28
AND	29

ANI	30
OR.....	31
ORI.....	32
LDP	33
LDF	35
ANDP	36
ANDF	37
ORP	38
ORF	39
ORB	40
ANB.....	42
MPS、MRD、MPP	44
BASIC ELEMENT	46
NORMAL-OPEN CONTACT	47
NORMAL-CLOSE CONTACT	48
TRUE CONTACT	49
RIISING EDGE OF CONTACT	50
FALLING EDGE OF CONTACT	51

LOGIC OUTPUT	52
INVERTED LOGIC OUTPUT	53
SETTING OUTPUT	54
RESET OUTPUT	55
BASIC FUNCTION MODULE	56
CONTROL INSTRUCTION	57
<i>Instruction M Get MGET</i>	<i>57</i>
<i>M Instruction Response MACK</i>	<i>58</i>
<i>T Instruction Get TGET</i>	<i>59</i>
<i>T Instruction Response TACK</i>	<i>60</i>
<i>Handwheel Control RTOMPG</i>	<i>61</i>
<i>Thermal Error Compensation Module TEMPSEN</i>	<i>62</i>
MATHEMATICAL OPERATION	64
<i>Addition ADD</i>	<i>64</i>
<i>Subtraction SUB</i>	<i>66</i>
<i>Multiplication MUL</i>	<i>68</i>
<i>Division DIV</i>	<i>70</i>
<i>Increase One INC</i>	<i>72</i>

<i>Decrease One DEC</i>	73
<i>Logic AND WAND</i>	74
<i>Logic OR WOR</i>	75
<i>Logic XOR WXOR</i>	77
<i>Complement NEG</i>	79
COUNTER	80
<i>Plus-minus Counter CTR</i>	80
<i>Counter CTRC</i>	82
<i>Custom Plus-minus Counter CTUD</i>	84
TIMER	86
<i>Delay-on Timer TMRB</i>	86
<i>Delay-off Timer STMR</i>	88
PROCESS CONTROL	90
<i>Initialization Module End IEND</i>	90
<i>PLC1 Module End 1END</i>	91
<i>PLC2 Module End 2END</i>	92
<i>Jump JMP</i>	93
<i>Label LBL</i>	94

<i>Call Subprogram CALL</i>	95
<i>Subprogram Start SP</i>	96
<i>Subprogram End SPE</i>	97
<i>Subprogram Return RETN</i>	98
<i>Loop LOOP</i>	99
<i>Next Loop NEXT</i>	100
COMPARISON	101
<i>Comparison CMP</i>	101
<i>Lower Than LT</i>	103
<i>Area Comparison ACMP</i>	104
<i>Consistency Comparison COIN</i>	105
DATA MANIPULATION	106
<i>Moving Data MOV</i>	106
<i>Relative Moving Data XMOV</i>	107
<i>Batch Moving BMOV</i>	109
<i>Multiple Moving Data FMOV</i>	111
<i>Data Exchange XCH</i>	113
<i>Data Reset ZRST</i>	115

<i>Encoding ENCO</i>	116
<i>Decoding DECO</i>	118
<i>Transformation COD</i>	120
<i>Data Search SER</i>	122
<i>Register Merging ASSEM</i>	124
<i>Register Decomposition DISAS</i>	126
<i>Area Conversion ACVT</i>	128
<i>Alternate Output ALT</i>	130
<i>Fetch Rising Edge PLS</i>	131
<i>Fetch Falling edge PLF</i>	132
<i>Points Transformation PTN</i>	133
<i>Number Conversion NTP</i>	135
<i>Part Count PARTCNT</i>	137
<i>Part-counting Clear PARTCLR</i>	138
<i>Temperature Collection Module HEADSEN</i>	140
STATUS WORD AND CONTROL WORD PROGRAMMING	142
INTRODUCTION ON STATUS WORD AND CONTROL WORD	143
<i>Axis Status Word</i>	145

<i>Axis Control Word</i>	150
<i>Channel Status Word</i>	154
<i>Channel Control Word</i>	158
EXAMPLE OF STATUS WORD AND CONTROL WORD PROGRAMMING	164
<i>Work Pattern Setting</i>	164
<i>Work Pattern Getting</i>	165
<i>Control of Feed Axis and Spindle</i>	166
<i>Home</i>	167
<i>Incremental Rate Override</i>	168
<i>Cycle Start and Feed Hold</i>	169
EXTENSION FUNCTION MODULE	170
NC FUNCTION	171
<i>Channel Mode Setting MDST</i>	171
<i>Channel Mode Getting MDGT</i>	173
<i>Mode MDI</i>	175
<i>Locking Channel MST</i>	176
<i>Cycle Start CYCLE</i>	177
<i>Emergency Stop STOP</i>	178

<i>Reset RESET</i>	179
<i>Channel Exchange CHANSW</i>	180
<i>Feed Hold Start HOLD</i>	181
<i>Cycle Start LED CYCLED</i>	182
<i>Feed Hold LED HOLDLED</i>	183
<i>Block Skip (G31) ESCBLK</i>	184
<i>Rapid Override RPOVRD</i>	186
<i>Feedrate Override FEEDOVRD</i>	187
<i>Spindle Override SPDLOVRD</i>	188
<i>Incremental (Stepping) Rate STEPMUL</i>	190
<i>Dryrun DRYRUN</i>	191
<i>Block Skip SKIP</i>	192
<i>User Input USERIN</i>	193
<i>User Output USEROUT</i>	194
<i>Selection Stop SELSTOP</i>	196
<i>Vector Tool Direction Setting TOOLSET</i>	197
<i>Vector Tool Direction Clear TOOLCLR</i>	198
<i>8-bit Nixie Tube NIXIE</i>	199

<i>Tool Display TOOLUSE</i>	201
FUNCTIONAL UNIT OF AXIS	202
<i>Spindle JOG SPDLJOG</i>	202
<i>Spindle Control 【Servo Spindle】 SPDLBUS</i>	203
<i>Spindle Control with Gear 【Servo Spindle】 SPDLBUS1</i>	204
<i>Spindle Orientation Enable SPDLORI</i>	207
<i>Completing Spindle Orientation SPDLOROK</i>	208
<i>Spindle Control 【DA】 SPDA</i>	209
<i>Zero Speed Detection for Spindle SPDLZERO</i>	211
<i>Spindle Speed Arrival SPDLRCH</i>	212
<i>Driven Axis Home SUBAXEN</i>	213
<i>Release Driven Axis DESYN</i>	214
<i>Axis Jog JOGSW</i>	215
<i>Axis Stepping STEPAXIS</i>	216
<i>Jog Velocity JOGVEL</i>	217
<i>Home Run HOMRUN</i>	218
<i>Home Run 1 HOMERUN1</i>	219
<i>Home Approaching Switch HOMESW</i>	220

<i>Home Completing HOMLED</i>	221
<i>Axis Enable AXEN</i>	222
<i>Axis Ready (Bust) AXRDY</i>	223
<i>Axis Lock AXISLOCK</i>	224
<i>Relative PMC Axis Movement AXISMOVE</i>	225
<i>Absolute PMC Axis Movement AXISMVTO</i>	226
<i>The Second Soft Limit of Axis AXLMF2</i>	227
<i>Block Switch in Positive Limit Direction AXISPLMT</i>	228
<i>Block Switch in Negative Limit Direction AXISNLMT</i>	229
<i>Handwheel MPGSET</i>	230
<i>Servo Enable (Bus) SVSW</i>	231
<i>Axis Mode AXISMODE</i>	232
<i>Axis Reference REFPT</i>	233
<i>During Axis Home AXISHOM2</i>	234
<i>During Axis Moving AXMOVING</i>	235
SYSTEM FUNCTION	236
<i>Rotation ROT</i>	236
<i>Alarm ALARM</i>	238

Event EVENT 239

Save Data SAVEDATA 240

Reset Setting Output RSTCHK 241

Reset Clear RSTCLR 242

OPERATIONAL MONITORING AND ONLINE MODIFICATION FOR LADDER DIAGRAM 243

ONLINE DIAGNOSIS FOR LADDER DIAGRAM 245

SEARCH 249

CHANGE 251

Insert Straight Line 252

Insert Vertical Line 252

Delete Vertical Line 253

Delete Component 253

Normal Open 254

Normal Closed 255

Logical Output 255

Inverted Output 256

Functional Module 256

Return 257

COMMAND	258
<i>Select</i>	259
<i>Delete</i>	259
<i>Move</i>	260
<i>Copy</i>	263
<i>Paste</i>	264
<i>Insert Line</i>	264
<i>Add Line</i>	265
<i>Return</i>	266
LOAD	267
DISCARD	268
SAVE	269
RETURN	270
INSTRUCTION ON PLC DEVELOPMENT ENVIRONMENT	271
OVERVIEW	272
INSTALLATION OF DEVELOPMENT ENVIRONMENT	273
DEVELOPMENT ENVIRONMENT INTERFACE	276
<i>Menu</i>	276

<i>Ladder Diagram Interface</i>	<i>279</i>
<i>Statement List Interface</i>	<i>281</i>
<i>Symbol List Interface</i>	<i>282</i>
DEVELOPMENT ENVIRONMENT OPERATION.....	283
<i>Symbol List Operation.....</i>	<i>283</i>
<i>Ladder Diagram Operation</i>	<i>287</i>
<i>Statement List Operation</i>	<i>293</i>
APPENDIX A	296

Preface

Reader manual is for machine user, which covers PLC introductions on HNC-8 CNC and their use, programming methods, examples and the like.

The

Scope The programming applies to HNC-8 numerical control system with V1.24.

Notes of this manual is authorized, organized and implemented by Wuhan Huazhong Numerical Control Co., Ltd. (HNC).

Without authorization or written permission, no entity or individual may change the manual content. HNC will not be responsible for any losses caused by that.

The matters which are not especially described in this manual are regarded as “Impossible” or “Not Allowed”.

Updates

and The copyright of this manual is subject to Wuhan Huazhong Numerical Control Co., Ltd (HNC). Any publishing and copy by other units or upgrades individuals are illegal, who may be investigated for legal responsibility.

Technical support

Marketing Department: 027-87180095 , 027-87180303

Fax : 027-87180303

E-mail : Zip Code : 430223

market@h Address : HUST Park, Miaoshan Region, East-lake Development Zone,

uazhongcn Wuhan, Hubei Province, China

c.com

Overview

This chapter includes:

- 1.1 Specifications of PLC
- 1.2 Sequential Program Notion
- 1.3 Allocation Interface
- 1.4 Sequential Program
- 1.5 Sequential Program Composition
- 1.6 Address

Specifications of PLC

Specifications Different PLC types have different program capacities, function instruction counts, and usage range of register.

Specification	HNC8
Programming language	Ladder, STL
Execution cycle of the first level program	1ms
Program capacity	
Ladder program	5000 lines
Statement list	10000 rows
Symbol name	1000
Instruction Basic instruction, Function instruction	
Internal relay of single byte (R)	400 bytes (R0~~R399)
Internal relay of double-byte (W)	400 bytes (W0~~W199)
Internal relay of four-byte (D)	400 bytes (D0~~D99)
Timer (T)	128 (T0~~T127)
Counter (C)	128 (C0~~C127)
Subprogram (S)	---
Label (L)	---
User-defined parameter (P)	200 (P0~~P199)
Holding storage area	
Timer (T)	128 (T300~~T427)
Counter (C)	128 (C300~~C427)
Four-byte register (B)	200 bytes (B0~~B49)
I/O module (X)	X0~~X512
(Y)	Y0~~Y512

Sequential Program Notion

Notion A brief description on sequential program is provided before on programming. Sequential program indicates that, the program which logically controls the machine and its relevant devices. For the personnel of electrical automation control engineering, the widely-used control flow is based on sequential control, from which, sequential program, a programming method for PLC control, is generated.

Numerical control system firstly converts the program to a format, then CPU decodes and operates it. CPU rapidly reads each instruction in the storage, and operates program via arithmetic operation. Sequential program starts from the ladder diagram and other standard PLC languages. The ladder diagram can be understood as the execution order of CPU arithmetic operation.

The above is performed by PLC programming software, the role of which is to document sequential program.

Allocation Interface

Interface

PLC interacts with external devices by external I/O. After control object is identified and relevant input/output signals are calculated, corresponding interfaces can be allocated to devices.

For easier debugging to PLC of numerical control system, input/output points of panel interfaces for series 818 have been fixed, and for that of other devices, refer to the electrical principle drawing.

Allocation

Panel points have been allocated in the standard PLC programs of Series 8 system, user doesn't need to change their definitions. At programming time, user uses other intermediate registers instead of input/output registers, to program. Several system interfaces has been described in Appendix 7, to make a better understand of panel point distribution of series 8. Y487 and Y488 are output addresses of digital tubes on panel, X480 and X491 are panel input signals, and Y480 and Y486 are panel output signals.

Sequential Program

PLC sequential control is achieved by software, and the principle of it is different from that of common relay circuit. Thus, the principle of sequential control should be fully understood at the time of designing PLC sequential program.。

Execution of sequential program

In general relay control circuit, each relay may operate at the same time. In the figure below, when relay A acts, relay D and E can act at the same time (in the event of contact B and C being closed). In PLC sequential control, relays act in sequence. When relay A operates, relay D operates first, and then relay E operates (see figure 2.1(a)), that is, each relay operates in the order described in the ladder diagram.




Figure 2.1 (a)

Figure A and B show the movement difference between relay circuit and PLC program.




Figure2.1 (b)

Relay circuit

The actions in figure 2.1b(A) and figure 2.1b(B) are the same. After A (button switch) is turned on, B and C are on, with current flowing through coil B and C. B is cut off after C is switched on.

PLC program Similar with relay circuit, in figure 2.1b(A), after A (button switch) is turned on, B and C are on, and B is switched off after a PLC program cycle. However, in figure 2.1b(B), after A (button switch) is turned on, C is switched on, but B is not.

Loop execution Sequential program executes from the beginning of the ladder diagram until the end, after that, it goes back to execute the beginning of the ladder diagram again, which is called loop execution.

That execution time from the beginning to the end is called loop period. The loop period of PLC2 depends on the controlled steps. The shorter the loop period, the rapider the response of signal.


Prior execution

Sequential program consists of three parts: initialization program, the first level program, the second level program.

The initialization program is performed once when system starts.


The first level program executes every 1ms.

If the first level is longer, the total execution time will be longer. Therefore, you should document as short program of the first level as possible. The second level program can be automatically separated into n parts, and executes every n ms.



Segmentation of the second level program


Segmentation of the second level program is to execute the first level program. When the number of segmentations is n, the implementation process is as below diagram:



When the last part of the second level program has executed, the program starts from the beginning again. In the event of n segmentations, the time for one loop execution is n ms ($1\text{ms} \times n$). The first level program executes every 1ms, and the second level program executes every $n \times 1\text{ms}$. If the steps of the first level program increases, the steps of the second level program will correspondingly decrease within 1ms, then more segmentations will be gotten, and program processing time will be longer. For this reason, the first level program should be documented as briefly as possible.

The first level program only handles short pulse signal, which includes emergency stop, axis over-travel, and the like.

When subprogram is used, sequential program consists of:




Sequential Program Composition

Composition For traditional PLC, ladder diagram can be only established sequentially. The ladder diagram language, which allows structured program, has the following advantages:

- ◆ The program is easily to be understood and documented.
- ◆ It is more convenient to find out programming errors.
- ◆ It is easy to find out reasons of causing errors.

There are three main structured programming means


Subprogram



Subprogram regards the ladder diagram block as the processing unit.


Nesting

The combination of documented subprograms forms structured program.



Conditional branch

Main program executes recurrently and detects whether condition is satisfied or not. If condition is satisfied, corresponding subprogram is executed; if condition is not satisfied, corresponding subprogram is not executed.



Address

Address Definition Address is used to differentiate signals. Various of addresses correspond to input and output signals of machine and CNC, internal relay, counter and the like. The address is composed of address No. and bit No.

Address format



A word must be specified to the left of address No., to express the signal types as below table:

Register	Signal	Range
X	Input signal from machine	X0~~X512
Y	Signal output from PLC to machine	Y0~~Y512
F	Input signal from NC	F0~~F3119
G	Signal output from PLC to NC	G0~~G3119
R	Internal relay of single byte	R0~~R399
W	Internal relay of double-byte	W0~~W199
D	Internal relay of four-byte	D0~~D99
B	Outage hold relay	B0~~B49
P	User-defined parameter	P0~~P199
C	Counter (Those after C300 can be held after usage.)	C0~~C127 C300~~C427
T	Timer (Those after T300 can be held after usage.)	T0~~T127 T300~~T427
L	Label number	---
S	Subprogram number	---

Basic Instruction

Sequential program is mainly composed of coil, contact, symbol and function block. The segments, by which elements of ladder diagram are jointed, form the logical relationship of sequential program. Sequential program can be described by ladder diagram language, as well as statement list language which is written by mnemonics (LD, AND, OR, etc.) and register address. Ladder diagram is written by coil contact of relay and function block.

As the international standard of IEC61131-3 lays out, ladder diagram language and statement list language can convert each other logically, and ambiguity caused by this can be avoided through some programming methods. In HNC_LADDER_WIN(V1.0) editing software, you can see that the two languages can mutually transform.

To better understand documenting and inner-making of sequential program, and to avoid errors in logic or understanding, see the explanation of basic concepts as following:

Type:

PLC instruction of series 8 is divided into basic instruction and function instruction.


Basic instruction

Basic instruction is the most basic and most common part of sequential program, with a total of 19. It executes one-bit manipulation.

Function instruction

Function instruction can perform the functions that is hard to be done by basic elements, and it can simplify programming.

Storage of logical outcome (ST)



Stack register (to store the intermediate result calculated)

Result being executed

Storage of logical outcome is a stack-like structure. Result of the current instruction is saved in ST0. When reading instruction such as LD and LDI appears, result of current instruction is needed to be saved in stack. When ANB or ORB instruction is encountered, the storage makes ST1 result out stack and

logically calculate with result in ST0, which then is saved in ST0. Therefore, when sequential program is documented with statement list instruction, ANB and ORB must correspond to the input instructions after the first instruction, one to one; otherwise, errors may occur.

Storage of multi-output logical outcome

The role of this storage is similar with that of logical outcome storage. It is to save result of current node, and is usually used for multi-output instruction with conditional judgements (see detailed command instruction for the usage of MPS, MRD, MPP). What differs from storage of logical outcome is that, it permits reading result of node without stack out of the result. Only when the embedded use of multi-output function is needed is storage push performed. Similarly, MPS and MPP instructions must be used correspondingly; otherwise, logical errors may occur.

Pre and Post

Pre indicates that other elements can be connected to the front of the element, and post indicates that other elements can be connected to the back of the element.

Here are constraint rules about the graphics in this manual:


Graphics	Meaning
○	Can be used or not
√	Must be used
×	Cannot be used
○ —	Can use pre component or not
—	Must use pre component
· · —	Cannot use pre component
— ○	Can use post component or not
—	Must use post component
— · ·	Cannot use post component

Detailed basic instructions are listed below:

No.	Instruction	Function
1	LD	Read in specified element signal status
2	LDI	Read in inverted status of specified element signal
3	LDT	Read in true element signal status
4	OUT	Output result of logical operation to specified address
5	OOUT	Output inverse result of logical operation to specified address
6	SET	After Logic OR the calculation result to signal in specified address, return the result to this address.
7	RST	After Logic AND the inverted calculation result to signal in specified address, return the result to this address.
8	AND	Logic AND
9	ANI	Logic AND the inverted specified signal
10	OR	Logic OR
11	ORI	Logic OR the inverted specified signal
12	LDP	Read in rising edge of signal
13	LDF	Read in falling edge of signal
14	ANDP	Logic AND rising edge of specified signal
15	ANDF	Logic AND falling edge of specified signal
16	ORP	Logic OR rising edge of specified signal
17	ORF	Logic OR falling edge of specified signal
18	ORB	Block logic OR
19	ANB	Block logic AND
20	MPS	Node result push
21	MRD	Reading node result
22	MPP	Node result pull

LD

Format




Function

Read out status signal (1 or 0) of specified address, and save that signal in ST0. It is used for the situation in which programming starts from the normal-open node.

Parameter

Register point parameter

Example



	5	LD	X5 . 0	D			D
	6	ORI	X5 . 1	E			$D + \overline{E}$
	7	OR	X5 . 3	F			$D + \overline{E} + F$
	8	AND	X5 . 4	G			$(D + \overline{E} + F)G$
	9	OUT	R10 . 0	Output W2			$(D + \overline{E} + F)G$
Desc ription							

LDI

Format

LDI □□□□.□
 └─Parameter 1


Function

Read out status signal (1 or 0) of specified address, and save that inverted signal in ST0. It is used for the situation in which programming starts from normal-closed node.

Parameter

Register point parameter


Example



	5	LDI	X5 . 0	D			\overline{D}
	6	ORI	X5 . 1	E			$\overline{D} + \overline{E}$
	7	OR	X5 . 3	F			$\overline{D} + \overline{E} + F$
	8	AND	R5 . 4	G			$(\overline{D} + \overline{E} + F)G$
	9	OUT	R10 . 1	W2			$(\overline{D} + \overline{E} + F)G$
Desc ription							

OUT

Format



Function

Output result of logic operation (status of ST0) to the specified address. It is used to output the result to one or more than one addresses.

Parameter


Register point parameter

Example

Ladder Diagram								
	No.	Instr uction	Addr ess	Bit No.	Refer ence	ST2	ST1	ST0
	1	LDI	R1 . 0	A				\overline{A}
	2	ORI	X5 . 0	C				$\overline{A} + \overline{C}$
	3	ANI	G1 . 1	B				$(\overline{A} + \overline{C})\overline{B}$
	4	OUT	R10 . 0	W1				$(\overline{A} + \overline{C})\overline{B}$
Operation Process	5	OUT	R10 . 1	W2				$(\overline{A} + \overline{C})\overline{B}$

Desc ription	Cases about series circuit and parallel circuit
-----------------	---

OOOUT

Format**Function**

Output result of inverted logic operation (status of ST0) to the specified address.

It is used to output the result to one or more than one addresses.

Parameter


Register point parameter

Example

Ladder Diagram								
Operation Process	No.	Instr uction	Addr ess	Bit No.	Refer ence	ST2	ST1	ST0
	1	LD	R1 . 0	A				A
	2	OR	X5 . 0	C				A + C
	3	AND	G1 . 1	B				(A + C).B
	4	OUT	R10 . 0	W1				(A + C).B
	5	OOU T	R10 . 1	W2				(A + C).B
Description								

SET

Format



Function

Logic OR the result of logic operation (ST0) to the specified address, which then is output to the same address.

Parameter


Register point parameter

Example

Ladder Diagram	<p>The ladder diagram shows a network with three components. On the left, there are two parallel branches. The top branch contains a normally open contact labeled 'R1.0' with 'A' below it. The bottom branch contains a normally open contact labeled 'X5.0' with 'B' below it. These two branches are connected in parallel to a coil on the right labeled 'R10.0' with '1' inside a circle and 'C' below it.</p>							
	No.	Instruction	Address	Bit No.	Reference	ST2	ST1	ST0
	1	LD	R1 . 0	A				A
	2	OR	X5 . 0	B				A + B
Operation Process	3	SET	R10 . 0	C				A + B
	Descriptio							

RST

Format



Function

Logic AND the inverted result of logic operation (ST0) to the specified address, which then is output to the same address.


Parameter

Register point parameter

Example

Ladder Diagram	<p>The ladder diagram shows three rungs. The first rung has a normally open contact labeled 'R1.0' with 'A' below it. The second rung has a normally open contact labeled 'X5.0' with 'B' below it. The outputs of these two rungs are connected in parallel to a coil labeled 'R10.0' with 'C' below it. The coil is represented by a circle with '0' inside.</p>							
	No.	Instr uctio n	Addr ess	Bit No.	Refer ence	ST2	ST1	ST0
	1	LD	R1 . 0	A				A
	2	OR	X5 . 0	B				$A + B$
Operation Process	3	RST	R10 . 0	C				$A + B$
	Description							

AND

Format**Function**

Logic AND


Parameter

Register point parameter

Example

See the example for LD instruction

ANI

Format**Function**

Logic AND NOT

Parameter


Register point parameter

Example

See the example for LD instruction

OR

Format



Function

Logic OR

Parameter

Register point parameter

Example

See the example for LDI instruction

ORI

Format

ORI □□□□.□

└──────────┘ └──┘

Address Bit No

No

Function

Logic OR NOT

Parameter


Register point parameter

Example

See the example for LDI instruction

LDP

Format



Function

Get rising edge of trigger element signal, and save the signal in ST0.

Set input signal to 1 in the next scanning period of the rising edge of input signal.

It is used for the situation in which programming starts from elements of rising edge.

Parameter


Register point parameter

Control condition

Input signal: Set output signal to 1 at the rising edge of signal (0→1) .

Output signal: During operation, input signal keeps 1 within one PLC scanning period.

Operation




Example

Ladder Diagram					
	No.	Instruction	Address	Bit No.	Reference
	1	LDP	R1 . 0		Rising edge of A
	2	ORF	X5 . 0		Falling edge of B
	3	ANDP	R2 . 0		Rising edge of C
	4	ANDF	R4 . 0		Falling edge of D
Operation Process	5	OUT	R10 . 1		Output W1

LDF

Format



Function

Get falling edge of trigger element signal, and save the signal in ST0.

Set input signal to 1 in the scanning period of the falling edge of input signal.

It is used for the situation in which programming starts from elements of falling edge.

Parameter


Register point parameter

Control condition

Input signal: Set output signal to 1 at the falling edge of signal (1->0) .

Output signal: During operation, input signal keeps 1 within one PLC scanning period.


Operation



Example

See the example for LDP instruction

ANDP

Format**Function**

Logic AND rising edge


Parameter

Register point parameter

Example

See the example for instruction LDP

ANDF

Format**Function**

Logic AND falling edge


Parameter

Register point parameter

Example

See the example for instruction LDP

ORP

Format**Function**

Logic OR rising edge

Parameter

Register point parameter


Example

See the example for instruction LDP

ORF

Format

Function



Parameter

Register point parameter

Example

See the example for instruction LDP

ORB

Format

ORB

Function

- 1) ORB is independent, and doesn't need to connect with other elements or function blocks.
- 2) ORB is to connect two or more series circuits that contain more than one series blocks or contain the series ANB blocks.
- 3) Start the programming with LD or LDI, and have all series block being in parallel via ORB.

Parameter

No parameter

Example

Ladder Diagram	<div><div><div><div><div>X1.0</div><div>X2.0</div></div><div><div>A</div><div>B</div></div><div><div>X1.1</div><div>X2.1</div></div><div><div>D</div><div>E</div></div><div><div>X1.2</div><div>X2.2</div></div><div><div>F</div><div>G</div></div></div><div><div>ORB</div><div>ORB</div></div><div><div>R10.0</div><div>H</div></div></div></div>							
Operation Process	No.	Instr uction	Add ress	Bit No.	Refer ance	ST2	ST1	ST0
	1	LD	X1 .	0	A			A
	2	AND	X2 .	0	B			A.B
	3	LD	X1 .	1	D		A.B	D
	4	AND	X2 .	1	E		A.B	D.E
	5	ORB						AB+DE
	6	LD	X1.	2	F		AB+DE	F
	7	AND	X2.	2	G		AB+DE	F.G
	8	ORB						AB+DE+FG
9	OUT	R10.	1	H			AB+DE+FG	
Descriptio								

ANB

Format

ANB


Function

- 1) ANB is independent, and doesn't need to connect with other elements or function blocks.
- 2) ANB is to connect two or more parallel circuits that contain more than one parallel-connected blocks or contain the parallel ORB blocks.
- 3) Starts programming with LD or LDI, and have all series block being in parallel via ORB.

Parameter

No parameter

Example

Ladder Diagram								
Operation Process	No.	Instr uction	Addr ess	Bit No.	Refer ence	ST2	ST1	ST0
	1	LD	X1 .	0	A			A .
	2	OR	X1 .	1	B			$A + B$
	3	LD	X2 .	0	C		$A+B$	C
	4	AND	X4.	4	D		$A+B$	$C.D$
	5	LD	X1 .	2	E	$A +$	$C.D$	E
	6	AND	X2 .	1	F	$A +$	$C.D$	$E.F$
	7	ORB					$A+B$	$C.D + E.F$
	8	OR	X1.	3	G		$A+B$	$CD+EF+G$
	9	ANB						$(A+B)(CD+EF+G)$
	10	OR	X2.	2	H			$(A+B)(CD+EF+G)+H$
11	OUT	R10.	0	I			$(A+B)(CD+EF+G)+H$	
Descriptio								

43

MPS、MRD、MPP

Format

MPS
MRD
MPP

Function

- 1) MPS Stores signal states of this point, waiting to be used when other lines are output.
- 2) MRD reads signal from last storage point, connects to the next node, of which signal status is always the same.
- 3) MPP brings up signal status from this storage point, connects to the next node, and removes the status of this node.
- 4) Every MPS must ends with MPP.
- 5) The last connection line must be ended with MPP.

Parameter

No parameter

Example

Ladder Diagram	Statement List	
	LD X1.0 MPS LD X1.1 OR X1.2 ANB OUT Y1.0 MRD LD X1.3 AND X1.4 LD X1.5 (followed by the right)	AND X1.6 ORB ANB MPP AND X1.7 OUT Y0.3 LD X2.3 OR X2.4 ANB OUT Y0.4
	LD X1.0 MPS AND X1.1 MPS AND X1.2 OUT Y1.0 MPP AND X1.3 (followed by the right)	OUT Y1.1 MPP AND X1.4 MPS AND X1.5 OUT Y0.2 MPP AND X1.6 OUT Y2.0
	LD X1.0 MPS AND X1.1 MPS AND X1.2 MPS AND X1.3 MPS AND X1.4 (followed by the right)	OUT Y1.0 MPP OUT Y1.1 MPP OUT Y0.2 MPP OUT Y2.0 MPP OUT Y2.1

Basic Element

This chapter includes the sections as following:

3.1 Normal-open Contact

3.2 Normal-close Contact

3.3 True contact

3.4 Rising edge of Contact

3.5 Falling edge of Contact

3.6 Logic Output

3.7 Inverted Logic Output

3.8 Setting Output

3.9 Reset Output

Normal-open Contact

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Address >	□□□□. □	BOOL	X、Y、F、 G、R、W、 D、P、T、 C、B	Register bit to be checked	Pre ○
					Post ✓

Function When the bit saved in the specified address is “1”, the normal-open contact is closed; If the contact is closed, the signal will flow through this contact.


Parameter Parameter 1: register point parameter, in the form of X0.1.

Example

Ladder Diagram	
Description	When signal of X0.1 or X0.4 is “1”, and X0.2 signal is “1”, the current is conducted, with R10.1 being output.

Normal-close Contact

Symbol



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses>	□□□□.□	BOOL	X、Y、F、G、R、W、D、P、T、C、B	Register bit to be checked	Pro ○
					Post ✓

Function When the bit saved in the specified address is “0”, the normal-open contact is open; If the contact is open, the signal will flow through this contact.

Parameter Parameter 1: register point parameter, in the form of X0.1.

Example

Ladder Diagram	
Description	When signal of X0.1 or X0.4 is “0”, and X0.2 signal is “1”, the current is conducted, with R10.1 being output.

True Contact

Symbol



Parame ter	Paramet er form	Data type	Storage area	Explanat ion	Properties
None	None	None	None	None	Pre ○
					Post ✓

Function When PLC is turned on, the signal on the left of an element can always reach the right through it. This function is usually used as the switch setting of function module input, and used for those which need constantly valid input.

Parameter No parameter.

Example

Ladder Diagram

R14.4 CTR B0 R39.0


T T 32

Description

When the second input of counter uses true contact, the counting starts with 1 after counter is reset; when the third input uses true contact, the counter counts in continuous subtraction.

Rising edge of Contact

Symbol



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses>	□□□□.□	BOOL	X、Y、F、G、R、W、D、P、T、C、B	Contact of rising edge detection	Pre ○
					Post ✓

Function When signal is changed from “0” to “1”, this contact is conducted.

Parameter Parameter 1: register bit.

Example

Ladder Diagram	See the example for LDP instruction.
Description	

Falling Edge of Contact

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Addres s>	□□□□. □	BOOL	X、Y、F、 G、R、W、 D、P、T、 C、B	Contact of falling edge detectio n	Pre ○
					Post ✓

Function When signal is changed from “1” to “0”, this contact is conducted.

Parameter Parameter 1: register bit.

Example

Ladder	See the example for LDF instruction.
Descriptio	

Logic Output

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Addres s>	□□□□. □	BOOL	Y、G、R、 W、D、B	Output coil	Pre ○
					Post ×

Function Output result of logical operation to output register.

Parameter Parameter 1: register bit.

Example

Ladder	See the example for OUT instruction.
Descriptio	

Inverted Logic Output

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Addres s>	□□□□. □	BOOL	Y、G、R、 W、D、B	Inverted output coil	Pre ○
					Post ×

Function Output inverted result of logical operation to output register.

Parameter Parameter 1: register bit.

Example

Ladder	See the example for OOUT instruction.
Descriptio	

Setting Output

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Addres s>	□□□□. □	BOOL	Y、G、R、 W、D、B	Setting output coil	Pre ○
					Post ×

Function When result of logical operation is “1”, set output coil to output status, until this coil is reset by other functions.

Parameter Parameter 1: register bit.

Example

Ladder	See the example for SET instruction.
Descriptio	

Reset Output

Symbol



Paramet er	Paramet er form	Data type	Storage area	Explanat ion	Properties
<Addres s>	□□□□. □	BOOL	Y、G、R、 W、D、B	Reset output coil	Pre ○
					Post ×

Function When result of logical operation is “1”, reset output coil, until this coil is set by other functions.

Parameter Parameter 1: register bit.

Example

Lad	See the example for RST instruction.
Des	

Basic Function Module

This chapter includes:

4.1 Control Instruction

4.2 Mathematical Operation

4.3 Counter

4.4 Timer

4.5 Process Control


4.6 Comparison

4.7 Data Manipulation

Control Instruction

Instructin M Get MGET

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s 1>	□□□□	INT	Constant	Channel No.	Pre ○
<Addres s 2>	□□□□	INT	Constant	M code No.	Post ✓

Function


Through the channel selected by parameter 1, parameter 2 selects M code number which needs to be determined. When this channel gets this M code, the output is “1”; otherwise, the output is “0”.

Example

Ladder Diagram	<p>The ladder diagram shows a normally open contact labeled 'X2.0' connected to an MGET instruction box. The MGET box has two sub-addresses: '0' and '3'. The output of the MGET instruction is connected to a coil labeled 'R4.0'.</p>
Statement List	<pre>LD X2.0 MGET 0 3 WRT R4.0</pre>
cript	When channel 0 executes M3, R4.0 is set.

M Instruction Response MACK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○ Post ×
<Address 2>	□□□□	INT	Constant	M code No.	

Function


When M Code has been implemented in this channel, it is necessary to reply to M code. After the reply, this M instruction can continue the next instructions.

Example

Ladder Diagram	
Statement List	LD X3.6 MACK 0 3
Script	When X3.6 is effective, M3 in channel 0 is responded.

T Instruction Get TGET


Format

					
Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○ Post ✓
<Address 2>	□□□□	INT	Constant, Y, G, R, W, D, B	T code No.	

Function


Through the channel selected by parameter 1, parameter 2 is where the gotten T code is stored in. When this channel gets T code, the output is 1; otherwise, the output is 0.

Example

Ladder Diagram	
Statement List	LDT TGET 0 R5 OUT R6.1
Description	When channel 0 executes T instruction, T instruction parameter is sent to R5 register, and R6.1 is reset.

T Instruction Response TACK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	<div><div></div><div></div><div></div><div></div></div>	INT	Constant	Channel No.	Pre <div></div> Post <div></div>


Function Through the channel selected by parameter 1, set to T code response in this channel.

Example

Ladder Diagram	
Statement List	<div>LD X3.4</div> <div>TACK 0</div>
Script	When X3.4 is turned on, T instruction in this channel is replied.

Handwheel Control RTOMPG

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ○ Post ×
<Address 2>	□□□□	INT	Constant		

Function Handwheel control (only for series 8)

Parameter Parameter 1: the register which the handwheel pulse increment inputs. (The default register for handwheel of series 8 is X490)


Parameter 2: MPG number, this parameter is for handwheel numbering. When there are more than one handwheels, they are distinguished by this parameter.

Example

Ladder Diagram	<p>The ladder diagram shows a normally open contact labeled X3.4 in series with an RTO MPG coil. The coil has two parameters: X40 and 0.</p>
Statement List	LD X3.4 RTOMPG X40 0
Description	When X3.4 is turned on, enable handwheel control. Handwheel pulse control register X40 is set into handwheel 0.

Thermal Error Compensation Module TEMPSEN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○ Post ×
< Address 2>	□□□□. □	BOOL	X		
< Address 3>	□□□□	INT	Constant		
< Address 4>	□□□□. □	BOOL	P		

Function

Analog signal of temperature sensor is converted to digital signal by AD of IO module, and is input to a position (group number) of X register which is determined by device parameter of IO module.

Parameter

Parameter 1: number of temperature sensor (number of temperature register). HNC-8 NC system is limited to input of 20 temperature acquisition signals. Therefore, the range of values for temperature sensor number is zero to nineteen.


Parameter 2: group number of X register corresponding to the digital signal of temperature acquisition.

Parameter 3: thermocouple grid type (its default value is 0. 1: the corresponding model is built to calculate temperature, by the user parameter specified by “parameter 4” which includes the lowest and highest (the temperature corresponding to the voltage of 6.7 V) temperatures; 2: temperature

sensor of PT100 is supported, and thermocouple grid of HIO-1075 is connected; 3: temperature sensor of KTY84-300 is supported, and thermocouple grid of HIO-1076 is connected; 4: the relationship between the measured temperature and the resistance calculated by the entered value of DA is linear. The corresponding model is built to calculate temperature, by the user parameter (P parameter) specified by “parameter 4” which includes the lowest and highest temperatures, as well as minimum and maximum resistances (unit: 0.01Ω).

Note: The thermocouple grid type of 2 and 3 are standard configurations, where the corresponding bus thermocouple grid can be connected, there are models of corresponding temperature in system, and the value of P parameter doesn't need to be set.

Parameter 4: set the range of acquisition temperature for temperature sensor by user parameter (P parameter). As shown in the figure below, P30 specifies the acquisition for the lowest temperatures, and P31 specifies the acquisition for the highest temperatures (the temperature corresponding to the voltage of 6.7 V, unit: degree). If the thermocouple grid type is 2 or 3, set value of P parameter will not be read.


Ladder Diagram	
Statement List	TEMPSEN 0 X15 0 P30
Description	The temperatures which have been gathered by No. 0 temperature sensor, is put into X15 register. P30 specifies the lowest acquisition temperatures.

Example

Mathematical Operation

Addition ADD

Format




Paramete r	Parameter form	Data type	Storage area	Expl ana tion	Properti es
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓ Post ○
< Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
< Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform addition operation.


Parameter Parameter 1: augend
 Parameter 2: addend
 Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<pre>LD X3.4 ADD D0 100 D1 OUT R4.0</pre>
Description	When X3.4 is turned on, $D1 = D0 + 100$ is implemented.

Subtraction SUB

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
< Address 1>	□□□□	INT	Constant, X、Y, F, G, R, W, D, P, B		Pre ✓ Post ○
< Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
< Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform subtraction operation.


Parameter Parameter 1: minuend
Parameter 2: subtrahend
Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<div>LD X3.4</div> <div>SUB D0 100 D1</div> <div>OUT R4.0</div>
Description	When X3.4 is turned on, D1=D0-100 is implemented.

Multiplication MUL

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓ Post ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform multiplication operation.


Parameter Parameter 1: multiplicand
Parameter 2: multiplier
Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<div>LD X3.4</div> <div>MUL D0 100 D1</div> <div>OUT R4.0</div>
Description	D1=D0*100 When X3.4 is turned on, D1=D0*100 is implemented.

Division DIV

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓ Post ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform division operation.


Parameter Parameter 1: dividend
Parameter 2: divisor
Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<pre>LD X3.4 DIV D0 100 D1 OUT R4.0</pre>
Description	When X3.4 is turned on, $D1 = D0/100$ is implemented.

Increase One INC

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Y, G, R, W, D, B		Pre ✓ Post ○

Function Perform plus-one operation.


Parameter Parameter 1: operand.

Example

Ladder Diagram	
Statement List	LD X3.4 INC D0 OUT R4.0
Description	When X3.4 is turned on, D0=D0+1 is implemented.

Decrease One DEC

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s 1>	□□□□	INT	Y, G, R, W, D, B		Pre ✓ Post ○

Function Perform minus-one operation.


Parameter Parameter 1: operand.

Example

Ladder Diagram	
Statement List	LD X3.4 DEC D0 OUT R4.0
Description	When X3.4 is turned on, D0=D0-1 is implemented.

Logic AND WAND

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre <input checked="" type="checkbox"/> Post <input type="radio"/>
<Address 2>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Y, G, R, W, D, B		

Function Perform logic AND.

Parameter Parameter 1: the number being operated.

Parameter 2: operand.


Parameter 3: operation result output address.

Example

Ladder Diagram	<p>The diagram shows a single ladder rung. It starts with a normally open contact labeled 'X3.4'. This is connected to a WAND function block. The block has three inputs: 'D0', '100', and 'D1'. The output of the block is connected to a coil labeled 'R4.0'.</p>
Statement List	<pre>LD X3.4 WAND D0 100 D1 OUT R4.0</pre>
Description	When X3.4 is turned on, D0=D0&100 is implemented.

Logic OR WOR

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓ Post ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform logic OR


- Function**
- Parameter 1: the number being operated.
 - Parameter 2: operand.
 - Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<pre>LD X3.4 WOR D0 100 D1 OUT R4.0</pre>
Description	<p>When X3.4 is turned on, D0=D0 100 is implemented.</p>

Logic XOR WXOR

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓ Post ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Y, G, R, W, D, B		

Function Perform logic XOR.


Parameter Parameter 1: the number being operated.
Parameter 2: operand
Parameter 3: operation result output address.

Example

Ladder Diagram	
Statement List	<pre>LD X3.4 WXOR D0 100 D1 OUT R4.0</pre>
cript	<p>When X3.4 is turned on, $D0 = D0 \wedge 100$ is implemented.</p>

Complement NEG

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s 1>	□□□□	INT	Y, G, R, W, D, B		Pre ✓ Post ○

Function Perform complement operation.

Parameter Parameter 1: operand


Example

Ladder Diagram	
Statement List	LD X3.4 NEG D0 OUT R4.0
cript	When X3.4 is turned on, D0=-D0 is implemented.

Counter

Plus-minus Counter CTR

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□. □	BOOL	R, W, D, B		Pre ✓ Post ✓
<Address 2>	□□□□	INT	Constant, R, W, D, B, P		

Function Common plus-minus counter.

Parameter Parameter 1: current value of counter. This function is used to get the current value of the counter.

Parameter 2: preset value of counter.

Input


Input 1: control input

Input 2: start value after counter is reset. When condition is satisfied, the counting starts with 1; when condition is not satisfied, the counting starts with 0.

Input 3: plus-minus input. When condition is satisfied, the counter is incremented; when condition is not satisfied, the counter is decremented.


Input 4: reset input

Example

Ladder Diagram	
Statement List	<pre> LD X2.5 LD X4.0 LD X4.1 LD X4.2 CTR R0 16 OUT Y1.4 </pre>
Description	<p>If X4.0 is turned on, the counting will start with 1. If X4.1 is turned on, the counter will decrease the count. When X2.5 has been turned on sixteen times, the output is Y1.4. X4.2 is the reset signal, to clear the counter output. When X2.5 has been turned on five times, the value of R0 is 6</p>

Counter CTRC

Format




Parameter	Parameter form	Data type	Storage area	Properties
<Address 1>	□□□□	INT	Constant	Pre ✓ Post ✓
<Address 2>	□□□□	INT	Constant, R, W, D, B, P	

Function Fixed counter

Parameter Parameter 1: number of counter
 Parameter 2: preset value of counter


Input Input 1: control input
 Input 2: reset input

Example

Ladder Diagram	
Statement List	<pre>LD X2.5 LD X4.0 CTRC 0 100 OUT Y1.4</pre>
Description	<p>When X2.5 is switched on and then off 100 times, the counter is on. When X4.0 is switched on, the counter is reset, and the signal is output to Y1.4.</p>

Custom Plus-minus Counter CTUD

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓ Post ✓
<Address 2>	□□□□	INT	Constant, R, W, D, B, P		

Function Plus-minus counter of custom start value.

Parameter Parameter 1: number of counter
Parameter 2: preset value of counter

Input Input 1: control input
Input 2: start value after reset. When condition is satisfied, the counting starts with 1; when condition is not satisfied, the counting starts with 0.
Input 3: plus-minus input. When condition is satisfied, the counter is incremented; when condition is not satisfied, the counter is decremented.
Input 4: Reset input


Example

Ladder Diagram	
Statement List	<pre>LD X2.5 LD X2.6 LD X2.7 LD X2.8 CTUD 0 100 OUT Y1.4</pre>
Description	<p>When X2.5 is switched on and off 100 times, counter 0 is on, and the signal is output to Y1.4. When X2.6 is switched on, the counter 0 counts with 1 after being reset; otherwise, the counter 0 counts with 0. When X2.7 is switched off, the count is incremented; otherwise, the count is decremented. When X2.8 is switched on, the counter 0 is reset.</p>

Timer


Delay-on Timer TMRB

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓ Post ○
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□	INT	Constant, R、W、D、P		

Sequence diagram



Function

Delay-on timer

Parameter Parameter 1: number of timer

Parameter 2: time unit, the details are as following:

Time unit is hour, in the event of the value being 3;


Time unit is minute, in the event of the value being 2;

Time unit is second, in the event of the value being 1;

Time unit is millisecond, in the event of the value being 0.


Parameter 3: Length of timing.

Example

Ladder Diagram	
Statement List	<pre>LD X35.5 TMRB 1 0 100 OUT Y4.2</pre>
Description	<p>After X35.5 has been on for 100ms, timer 1 is switched on, and the signal is output to Y4.2.</p>


Delay-off Timer STMR

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address1>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		Pre <input checked="" type="checkbox"/> / Post <input type="checkbox"/>
<Address2>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		
<Address3>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant, R, W, D, P		

Sequence diagram



Function

Delay-off timer

Parameter

Parameter 1: number of timer

Parameter 2: time unit, the details are as following:

Time unit is hour, in the event of the value being 3;


Time unit is minute, in the event of the value being 2;

Time unit is second, in the event of the value being 1;

Time unit is millisecond, in the event of the value being 0.

Parameter 3: Length of timing.


Example

Ladder Diagram	
Statement List	<pre>LD X35.5 STMR 1 0 100 OUT Y4.2</pre>
Description	<p>After X35.5 has been off for 100ms, timer 1 is off, and the output of Y4.2 is cut off.</p>

Process Control

Initialization Module End IEND

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
None	None	None	None		Pre × Post ×

Function

Defining initialization module is ended. Program generally is preceded by initialization module which is performed only once after the system is turned on.

Example

Ladder Diagram	
Comment	IEND
Script	Initializer is ended.

PLC1 Module End 1END

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
None	None	None	None		Pre × Post ×

Function PLC1 module is finished.

Example

Ladder Diagram	
Statement List	1END
Description	PLC1 program is ended.

PLC2 Module End 2END

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
None	None	None	None		Pre × Post ×


Function PLC2 module is finished.

Example

Ladder Diagram	
Statement List	2END
Description	PLC2 program is ended.

Jump JMP

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Address s1>	□□□□	INT	L		Pre ✓ Post ×


Function Jump by tag.

Example

Ladder Diagram	
Statement List	LD X35.5 JMP L1111
Script	If x35.5 is on, go to the positon labeled L1111 to continue the execution.

Label LBL

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	L		Pre ○ Post ×


Function Label, jump by label. It is used with JMP.

Example

Ladder Diagram	
Statement List	LBL L1111
Description	Set label L1111.

Call Subprogram CALL

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s1>	□□□□	INT	S		Pre ○ Post ×

Function Call subprogram.


Parameter Subprogram number.

Example

Ladder Diagram	
Statement List	LD X12.2 CALL S123
Description	When X12.2 input is valid, jump to the subprogram of No. S123 to execute.

Subprogram Start SP

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s1>	□□□□	INT	S		Pre × Post ×

Function To start subprogram.

Parameter Number (support up to 512 numbers of subprogram.

Example

Ladder Diagram	
Statement List	SP S111
Description	Set subprogram number of S111.

Subprogram End SPE

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
None	None	None	None		Pre × Post ×

Function To end Subprogram.

Parameter

Example

Ladder Diagram	
Statement List	SPE
Description	Subprogram is ended.

Subprogram Return RETN

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
None	None	None	None		Pre ○ Post ×

Function Subprogram return. If this instruction is encountered in the subprogram, the execution will jump out of the subprogram, and continue the rest.


Parameter

Example

Ladder Diagram	
Statement List	LDI R100.0 RETN
Script	If normal-closed point of R100.0 is valid, the subprogram will return.

Loop LOOP

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
<Addres s1>	□□□□	INT	Constant		Pre × Post ×

Function To start the loop. The statement within the body of each loop will be executed. After all loops are finished, the rest statement will be continued. This instruction must be used with NEXT instruction.

Parameter Number of loops, constant and register can be used.

Example

Ladder Diagram	
Statement List	LOOP 5 NEXT
cript	Five times of loops

Next Loop NEXT

Format



Paramet er	Parameter form	Data type	Storage area	Explanation	Properti es
None	None	None	None		Pre × Post ×

Function Enter the next loop.


Example

Ladder Diagram	
Statement	NEXT
Script	Enter the next loop. It is used with the instruction LOOP.

Comparison

Comparison CMP

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	When the address 1 is larger than address 2, the output is 0, when the address 1 is smaller than or equal to the address 2, the output is 1.	Pre ○ Post ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		

Function To compare. When the address 1 is larger than address 2, the output is 0, when the address 1 is lower than or equal to the address 2, the output is 1.


Parameter Parameter 1: comparing data, can be constant and register.
Parameter 2: data being compared, can be constant and register.

Example

Ladder Diagram	
Description	When $R0 \leq 100$, the condition is satisfied.

Lower Than LT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant , X, Y, F, G, R, W, D, P, B	When the address 1 is larger than or equal to the address 2, the output is 0, when the address 1 is smaller than the address 2, the output is 1.	Pre ○ Post ✓
<Address 2>	□□□□	INT	Constant , X, Y, F, G, R, W, D, P, B		

Function

To compare. When the address 1 is larger than or equal to the address 2, the output is 0, when the address 1 is smaller than the address 2, the output is 1.

Parameter


Parameter 1: comparing data, can be constant and register.
Parameter 2: data being compared, can be constant and register.

Example

Ladder Diagram	
Description	When R0<100, the condition is satisfied.

Area Comparison ACMP

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	When data of address 3 is larger than that of address 1, and smaller than that of address2, the output is 1.	Pre ○ Post ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		

Function Area comparison. When data of address 3 is larger than that of address 1, and smaller than that of address2, the output is 1.


Parameter Parameter 1: the low end of comparison range, can be constant or register.
Parameter 2: the high end of comparison range, can be constant or register.
Parameter 3: Comparing data, can be constant or register.

Example

Ladder Diagram	
Desc	When R0<100 and R0>0, the condition is satisfied.

Consistency Comparison COIN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	When the data of address 1 and address 2 are the same, the output is 1; when they are not the same, the output is 0.	Pre ○ Post ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		

Function

Consistency comparison, When the data of address 1 and address 2 are the same, the output is 1; when they are not the same, the output is 0.

Parameter

Parameter 1: benchmark data, can be constant and register.
Parameter 2: comparing data, can be constant and register.


Example

Ladder Diagram	<p>The ladder diagram shows a single rungs. On the left, there is a normally open contact labeled 'T'. This is connected to the 'COIN' module. The module has two inputs: the top input is labeled 'R0' and the bottom input is labeled '100'. The output of the module is connected to a terminal on the right.</p>
Description	When R0=100, the condition is satisfied.

Data Manipulation

Moving Data MOV

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Moving data	Pre ○
<Address 2>	□□□□	INT	Y, G, R, W, D, B		Post ✓

Function To move data. To transfer source data to destination address.


Parameter Parameter 1: source data, can be constant and register.
Parameter 2: destination data, and be constant and register.

Example

Ladder Diagram	<p>The ladder diagram shows a normally open contact labeled 'T' connected to the MOV instruction box. The MOV box has 'D0' in the top section and 'D1' in the bottom section. The circuit ends at a vertical line on the right.</p>
Description	Data in D0 is assigned to data in D1.

Relative Moving Data XMOV

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□ □ □ □	INT	Constant	Relative moving data	Pre ○ Post ✓
<Address 2>	□ □ □ □	INT	G、R、W、D、B		
<Address 3>	□ □ □ □	INT	Constant		
<Address 4>	□ □ □ □	INT	G、R、W、D、B		

Function To move data. To transfer source data to the destination address.


Parameter Parameter 1: the format of operand 1. 0 represents register, 1 represents register B, 2 represents register P. For example, the parameter 1 is 0 and the parameter 2 is R10, which can represent R10 address; the parameter 1 of 1 and the parameter 2 of R10 represent the register B, and the data stored in R10 group of register B; the parameter 1 of 2 and the parameter 2 of R10 represent the register P, and the data stored in R10 group of register P.

Parameter 2: the address of operand 1.

Parameter 3: the address of operand 2.


Parameter 4: the address of operand 2.

Example

Ladder Diagram	
Description	Assign the data shifted to D1 in register B to the position shifted to D2 in register B.

Batch Moving BMOV

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Moving the data in batch.	Pre ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Constant		Post ✓


Function Move data in batch. Multiple data of source starting address is transferred to starting address of destination.

Parameter Parameter 1: Starting address of source data

Starting address of destination


Parameter 3: Moving number, can only be constant.

Example

Ladder Diagram	 <p>The diagram shows a single rungs of a ladder logic circuit. It begins with a normally closed contact labeled 'T'. This contact is connected to the left side of a rectangular instruction box. The box is divided into three horizontal sections: the top section contains the text 'BMOV', the middle section contains 'D0', and the bottom section contains the number '2'. The right side of the instruction box is connected to a vertical line, representing the power rail.</p>
Description	<p>Two data starting from D0 is assigned to two positions starting from D2, that is, D0 is assigned to D2, and D1 is assigned to D3.</p>

Multiple Moving Data FMOV

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Y, G, R, W, D, B	Multiple moving data.	Pre ○ Post ×
<Address 2>	□□□□	INT	Y, G, R, W, D, B		
<Address 3>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		

Function Multiple moving data. Source data is transferred to a space that from the starting address of destination to ending address of destination.


Parameter Parameter 1: starting address of destination
Parameter 2: ending address of destination
Parameter 3: source data

Example

Ladder Diagram	
Description	D3 data is assigned to the position that from D0 to D2.

Data Exchange XCH

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address1>	□□□□	INT	Constant	It is used to exchange data.	Pre ○
<Address 2>	□□□□	INT	G, R, W, D, B		
<Address 3>	□□□□	INT	Constant		
<Address 4>	□□□□	INT	G, R, W, D, B		Post ✕


Function

Data exchange. Address of operand 2 is exchanged with address of operand 4. The format of operand 2 can be represented by the value of address 1. 0 indicates the default register which is used in address 2, 1 indicates that B register is used in address 2. In the same way, the format of operand 4 can be represented by the value of address 3.

Parameter


Parameter 1: the format of operand 1. 0 indicates register, 1 indicates B register, and 2 indicates P register. For example, parameter 1 is 0 and parameter 2 is R10, which represent the address R10. Parameter 1 of 1, and parameter 2 of R10, represent B register, and the data stored in group R10 of register B. Parameter 1 of 2, and parameter 2 of R10, represent P register, and the data stored in group R10 of register P.

Example

Ladder Diagram	 <p>The diagram shows a single-step ladder logic instruction. It begins with a normally closed contact labeled 'T'. This contact is connected to the left side of a rectangular instruction box. Inside this box, the label 'XCH' is positioned to the left of a vertical stack of four smaller boxes. These boxes contain the values '1', 'D1', '1', and 'D2' from top to bottom. The right side of the instruction box is connected to a final output line, represented by a vertical bar on the right.</p>
Description	Exchange the data shifted to D1 with the data shifted to D2 in register B.

Data Reset ZRST

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□ □ □ . □	BOOL	Y, G, R, W, D, B	Data reset	Pre ○
<Address 2>	□ □ □ . □	BOOL	Y, G, R, W, D, B		Post ✓

Function Data reset. Reset the data which is from starting address of operand to ending address of operand.


Parameter Parameter 1: starting address of operand
Parameter 2: ending address of operand

Example

Ladder Diagram	
Description	0 is assigned to the position that from D0 to D1

Encoding ENCO

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address1>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, B	It is used for override value conversion	Pre ○
<Address2>	□□□□	INT	Constant		
<Address3>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, B	It is used for override value conversion	Post ×
<Address4>	□□□□. □	BOOL	Y, G, R, W, D, P, B		

Function Encode. When there are 5 data bits (3, 5, 7, 8, 9) from the starting position of encoded data, if source data is 3, the output is 00000001B, if source data is 5, the output is 00000010B, if source data is 7, the output is 00000100B.


Parameter Parameter 1: the starting position of encoded data, can use register D.
Parameter 2: number of coded data, can be constant.
Parameter 3: source data, can be register R and D.
Parameter 4: Output address of destination data, can be register R and D.

Example

Ladder Diagram	 <p>The diagram shows a single-rung ladder logic circuit. On the left, there is a normally closed contact labeled 'T'. A horizontal line connects this contact to the input of a function block labeled 'ENCO'. The 'ENCO' block is a rectangle with four stacked output fields on its right side: 'D8', '8', 'D1', and 'D2'. A horizontal line extends from the 'D8' output field to a vertical busbar on the right. The other three output fields ('8', 'D1', and 'D2') are not connected to any other components.</p>
Description	After being encoded, data in D1 is output to D2.

Decoding DECO

Format



错误!

Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address1>	<div><div><div></div><div></div><div></div><div></div></div><div>.</div><div></div></div>	BOOL	X, Y, F, G, R, W, D, P, B	It is used for override value conversion	Pre √
<Address 2>	<div><div><div></div><div></div><div></div><div></div></div></div>	INT	Constant		
<Address 3>	<div><div><div><div></div><div></div><div></div><div></div></div><div>.</div><div></div></div></div>	BOOL	X, Y, F, G, R, W, D, P, B		
<Address 4>	<div><div><div><div></div><div></div><div></div><div></div></div><div>.</div><div></div></div></div>	BOOL	Y, G, R, W, D, P, B		Post ×


Function Decoding, which is reversed to encoding.

Parameter Parameter 1: the starting position of decoded data, can use register D.
Parameter 2: number of decoded data, can be constant.

Parameter 3: source date, can be register R and D


Parameter 4: Output address of destination data, can be register R and D.

Example

Ladder Diagram	
Des	After being decoded, the data in D1 is output to D2

Transformation COD

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address1>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, B	It is used for override value conversion	Pre ✓
<Address 2>	□□□□	INT	Constant		Post ×
<Address 3>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, B		
<Address 4>	□□□□. □	BOOL	Y, G, R, W, D, P, B		

Function

Code transformation. It is mainly used for override value conversion. Take spindle override as an example, there are 8 data bits (50, 60, 70, 80, 90, 100, 110, 120) from D0; when source data is 0, the data transformed is 50; when source data is 1, the data transformed is 60; when source data is 2, the data transformed is 70.

Parameter


Parameter 1: the starting position for transforming data, can be register D.

Parameter 2: the number of data being transformed, which can be constant.

Parameter 3: source data, can be register R and D.


Parameter 4: output address of the target data, can be register R and D.

Example

Ladder Diagram	
Description	After being transcoded, the data in D1 is output to D2.

Data Search SER

format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	X, Y, F, G, R, W, D, P, B	When data has been found, the output is 1; when data hasn't been found, the output is 0.	Pre ✓
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□	INT	X, Y, F, G, R, W, D, P, B		Post ×
<Address 4>	□□□□	INT	Y, G, R, W, D, P, B		

Function

To search data. Search a data in a statement list. When the data is found, the output is 1; when the data is not found, the output is 0.

Parameter


Parameter 1: searching address, can only be register D.

Parameter 2: searching range, can be constant.

Parameter 3: the data to be searched, can be constant and register X, Y, K, L, F, G, R, D.


Parameter 4: the output address of searched result, can only be register D.

Example

Ladder Diagram	
Description	Search the data of D4 in the four data from D0, and output the position of the data being found to D5.

Register Merging ASSEM

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	X, Y, F, G, R, W, D, P, B	To merge the data of several registers into one register.	Pre ✓
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□	INT	G, W, D, B		Post ✕

Function To merge several register data into one register.


parameter

Parameter 1: source data.

Parameter 2: quantity of source registers, can only be constant.


Parameter 3: target address, can be register G, W, D, B.

Example

Ladder Diagram	
Description	Merge the four data which are from X0 into one data (that is, merge four 8-bit data into one 32-bit data)

Register Decomposition DISAS

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	F, G, W, D, P, B	To break up the data of one register into several registers.	Pre ✓
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□	INT	Y, G, R, W,		Post ✕

Function To break up the data of one register into several registers.

Parameter


- Parameter 1: source address.
- Parameter 2: number of source registers, can only be constant.
- Parameter 3: target address, can be register Y, G, R, W.

Example

Ladder Diagram	
Description	Break up the data of D0 into the four data which are from Y0 (that is, one 32-bit data is broken up into 4 8-bit data).

Area Conversion ACVT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	P	Convert source data which follows a certain proportional relationship to target data.	Pre ✓
<Address 2>	□□□□	INT	X, Y, F, G, R, W, D, P, B		
<Address 3>	□□□□	INT	Y, G, R, W, D, B		Post ✕

Function Convert source data which follows a certain proportional relationship to target data.


parameter Parameter 1: Address of proportional relationship.

0	Minimum value of source data
1	Maximum value of source data
2	Minimum value of target data
3	Maximum value of target data

Parameter 2: number of source registers.


Parameter 3: target address, can be register Y, G, R, W, D, B;

Example

Ladder Diagram	
Description	<p>Convert D0 data which follows a certain proportional relationship to D1. $D1 = (D0 - P0) * (P3 - P2) / (P1 - P0) + P0$;</p>

Alternate Output ALT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses 1>	□□□□	INT	Constant	Number	Pre ✓
					Post ✓

Function


Alternate output. The component keeps its output status, until it encounters the rising edge, then the output status changes (change from 0 to 1, or 1 to 0).

Example

Ladder Diagram	
Description	When R100.0 is turned off from turned on, the module 1 changes the output status.

Fetch Rising Edge PLS

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses 1>	□□□□	INT	Constant	Rising edge module number	Pre ○
					Post ✓

Function

Get the status of the current line or current position, and get its trigger signal of the rising edge.


Set the input signal to 1 in the current scan cycle of the rising edge signal. (Note the difference between the trigger component of rising edge for basic component and this function). This function is suitable for the situations where the rising edge status needs to be detected.

Example

Ladder Diagram	
Description	When R100.0 status is changed from 0 to 1, fetch its rising edge status and the output of R10.0 is 1.

Fetch Falling edge PLF

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Falling edge module number	Pre ○
					Post ✓

Function

Get the status of the current line or current position, and get its trigger signal of the falling edge.


Set the input signal to 1 in the current scan cycle of the falling edge signal. (Note the difference between the trigger component of falling edge for basic component and this function). This function is suitable for the situations where the falling edge status needs to be detected.

Example



Points Transformation PTN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BOOL	Y, G, R, W, D, B	When the point is effective, the corresponding number is generated.	Pre ○
<Address 2>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> . <input type="checkbox"/>	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 3>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		
<Address 4>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> . <input type="checkbox"/>	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 5>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		Post ×
<Address 6>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> . <input type="checkbox"/>	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 7>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		
<Address 8>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> . <input type="checkbox"/>	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 9>	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	INT	Constant		

Function To build the corresponding relationship between points and numbers. When the point is effective, the corresponding number is generated.

Parameter

Parameter 1: the destination address.

Parameter 2: point 1

Parameter 3: number 1

Parameter 4: point 2

Parameter 5: number 2


Parameter 6: point 3

Parameter 7: number 3

Parameter 8: point 4


Parameter 9: number 4

Example

Ladder Diagram	 <pre> graph LR subgraph PTN [PTN] direction TB Y30_0[Y30.0] --- R0[R0] Y30_1[Y30.1] --- R0 Y30_2[Y30.2] --- R0 Y30_3[Y30.3] --- R0 end </pre>
Description	<p>When Y30.0 is effective, R0=0.</p> <p>When Y30.1 is effective, R0=1.</p> <p>When Y30.2 is effective, R0=2.</p> <p>When Y30.3 is effective, R0=3.</p>

Number Conversion NTP

Format



Parameter	Parameter form	Data type	Storage area	Explanat ion	Properti es
<Address 1>	□□□□	BOOL	Y, G, R, W, D, B		Pre ○
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 4>	□□□□	INT	Constant		
<Address 5>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, T, C, B		Post ×
<Address 6>	□□□□	INT	Constant		
<Address 7>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, T, C, B		
<Address 8>	□□□□	INT	Constant		
<Address 9>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, T, C, B		

Function

To build the corresponding relationship between numbers and points. The point signal corresponding to the number in Parameter 1 is generated.

Parameter 1: the address of source data

Parameter 2: number 1

Parameter 3: point 1

Parameter Parameter 4: number 2

Parameter 5: point 2


Parameter 6: number 3

Parameter 7: point 3

Parameter 8: number 4


Parameter 9: point 4

Example

Ladder Diagram	
Description	<p>When R0=0, Y30.0 is effective.</p> <p>When R0=1, Y30.1 is effective.</p> <p>When R0=2, Y30.2 is effective.</p> <p>When R0=3, Y30.3 is effective.</p>

Part Count PARTCNT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses 1>	□□□□	INT	Constant	When condition is satisfied, 1 is added to part count of <Address 1> channel.	Pre ○
					Post ✓

Function To count machined parts.


Parameter Parameter 1: channel number

Example

Ladder Diagram	
Description	When 32.1 is turned on, 1 is added to the part count of channel 0.

Part-counting Clear PARTCLR

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	When condition is satisfied, part count of <Address > channel is cleared to zero.	Pre ○
					Post ✓

Function Clear the count of the part.


Parameter Parameter 1: channel number.

Example

Ladder Diagram	
Description	When X32.1 is turned on, the part count in channel 0 is cleared.

Temperature Collection Module HEADSEN

Format




Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□. □	BOOL	X, Y, F, G, R, W, D, P, T, C, B	When Address 2 is 0, the temperature collection module starts to count, and the temperature data in Address 1 is stored in the starting address given by Address 3.	Pre ○
<Address 2>	□□□□	INT	Constant		Post ×
<Address 3>	□□□□	INT	Constant		

Function Temperature collection module.

Parameter Parameter 1: total quantity of temperature collection data, can be constant.
Parameter 2: enable switch of temperature collection module, 0 indicates counting starts, other values indicate the module is not enabled.
Parameter 3: the initial location where the temperature collection data is stored, and it can be register.

Example

Ladder Diagram	
Description	<p>When X32.1 is turned on, the temperature collection module starts to count, and 10 temperature data is stored in the initial location given by D1.</p>

Status Word and Control Word Programming

This chapter includes:

5.1 Introduction on Status Word and Control Word

5.2 Example of Status Word and Control Word Programming




Introduction on Status Word and Control Word

Overview

The status word and control word are the most direct way of the interaction between CNC and PLC. The status data of system can be obtained through the status word, and you can write control word to change the system state. In the system series 8, F represents status word with its property being read-only, G represents control word with its property being read-write.

However, to limit the use of some key functions of system, some control words are restricted, or are invisible to user. Please read following constraints of status word and control word carefully.

Usage
restrictions
of status
word and
control
word

	can be used
	reserved for future extension
	cannot be used by user


Range of
application

Status words and control words can be divided into three types for each of its function in the system. They all have serviceable range, refer to the configuration manual for details.

- ◆ Status words and control words of axis
- ◆ Status words and control words of channel
- ◆ Status words and control words of system

Symbol
form

Take the words of channel as an example:



In this example, the format is channel 3, the second group of status word, and

No.0 status word. 2560 is the offset of the channel status word. The format of other types of words is similar.

Axis Status Word

Overview 80 status words are configured for each axis. Each status word has a 16-bit byte. The first row indicates the bits from 0 to 7, and the second row indicates the bits from 8 to 15. The axis status words need to be used with the logical number offset of axis.

Axis status word	D7	D6	D5	D4	D3	D2	D1	D0
	D15	D14	D13	D12	D11	D10	D9	D8

F0

Subaxis follow	Subaxis zero	Subaxis home	Home completing	Home failure	Return to the second reference	Return to the first reference	Axis moving
Axis reset	Axis lock	Axis parameter ok	Axis overload	The forth reference	The third reference	The second reference	The first reference

F1

SPD arrival	Spindle stop	Orientation completing	Rapid feed	Reserved	Reserved	Spindle mode	PMC enable
Index axis locking	Index position	Index axis unlocking	Reserved	Reserved	Reserved	Reserved	Reserved

F2

Servo parameter	Zero capture	Reserved	Servo home	2 nd stage home	Reserved	Servo ready	Capture the first Z pulse
Spindle stop	SPD arrival	Gain switch	Z pulse capture	Torque control	Speed control	Position control	Sv ready

F3

Reserved	Reserved	Reserved	Reserved	Reserved	Servo prompt	Servo alarm	Normal servo
Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Orientation completing

Details

【F0.0】 During the axis movement, when the axis is moving, the value is 1; when the axis is not moving, the value is 0.

【F0.1】 The first step of returning home: when the axis is returning home without meeting home block, the value is 1; otherwise, the value is 0.

【F0.2】 The second step of returning home: when Z pulse is being looked for, the value is 1; otherwise, the value is 0.

【F0.3】 Unsuccessful homing: when the axis hasn't returned to zero, the value is 1; otherwise, the value is 0.

【F0.4】 Successful homing: When the axis has been to zero, the value is 1; otherwise, the value is 0.

【F0.5】 Subaxis is returning home.

【F0.6】 Zero point of subaxis has been checked.

【F0.7】 Following status of subaxis has been released.

【F0.8】 Confirm the first reference: when the axis is at the first reference point, the value is 1; otherwise, the value is 0.

【F0.9】 Confirm the second reference: when the axis is at the second reference point, the value is 1; otherwise, the value is 0.

【F0.10】 Confirm the third reference: when the axis is at the third reference point, the value is 1; otherwise, the value is 0.

【F0.11】 Confirm the forth reference: when the axis is at the forth reference point, the value is 1; otherwise, the value is 0.

【F0.13】 Axis parameter is effective.

【F0.14】 Axis has been locked.

【F0.15】 Axis has been repositioned.

【F1.0】 PMC control enabled. When PMC control has been enabled, the value is 1; otherwise, the value is 0.

【F1.1】 Feed spindle mode. 1 is position mode, and 0 is speed mode.

【F1.5】 Orientation of feed spindle has been finished.

【F1.6】 Feed spindle is at zero speed.

【F1.7】 Feed spindle speed arrival.

【F1.13】 Index axis is unlocked. 1 indicates that system notifies PLC to unlock index axis. The index axis is enabled.

【F1.14】 Index axis is at index position.

【F1.15】 Index axis is locked. 1 indicates that system notifies PLC to lock index axis. The index axis is disabled.

【F2.0】 When Z pulse is captured once during homing of axis, the value is 1; otherwise, the value is 0.

【F2.1】 When servo ready flag is 0, servo can receive incremental data.

【F2.3】 Capture Z pulse of the second encoder, which is mainly used for homing of distance code grating scale.

【F2.4】 When servo has been back to zero, the output is 1.

【F2.6】 Zero capture, which is mainly used for spindle. When spindle meets the first Z pulse at rotating time, set the value to 1. In the event of CS switching, the value needs to be set to 1.

【F2.7】 Servo parameter switch. 0: default parameter. 1: switch to the second set of parameter.

【F2.8】 When bus servo is ready, the value is 1; otherwise, the value is 0.

【F2.9】 When servo is in position control mode, the value is 1; otherwise, the value is 0.

【F2.10】 When servo is in speed control mode, the value is 1; otherwise, the value is 0.

【F2.11】 When servo is in torque control mode, the value is 1; otherwise, the value is 0.

【F2.12】 When Z pulse is encountered, the value is 1; otherwise, the value is 0.

【F2.13】

【F2.14】 When the spindle speed reaches, the value is 1, otherwise, the value is 0.

【F2.15】 Spindle stop: when spindle stops, the value is 1; otherwise, the value is 0.

【F3.0】 When servo is normal, the value is 1.

【F3.1】 When servo alarms, the value is 1.

【F3.2】 When servo prompts, the value is 1.

【F3.8】 Spindle orientation is completed After spindle orientation is set, spindle starts directing. After the directing is completed, servo returns the signal of completing spindle orientation, and the value is 1; otherwise, the value is 0.

【F4】 Number of channel which the axis belongs to. (Channel number is in decimal.)

【F5】 Number of driven axes which are guided. (Number of driven axes is in decimal.)

【F[6/7]】 Real-time output command increment, motor coordinate.

- 【F[8/9/10/11]】 Real-time output command position, motor coordinate. (metric system)
- 【F[12/13/14/15]】 Output command pulse position, unit: pulse.
- 【F[16/17]】 Command pulse per cycle. Number of command pulses which is sent to servo each cycle.
- 【F[18/19]】 Output command torque.
- 【F[20/21/22/23]】 Actual feedback position of encoder 1. (metric system)
- 【F[24/25/26/27]】 Actual feedback position of encoder 2. (metric system)
- 【F[28/29/30/31]】 Command position of machine. (metric system)
- 【F[32/33/34/35]】 Actual position of machine. (metric system)
- 【F[36/37]】 Axis alarm
- 【F36.2】 Plus software limit switch reached.
- 【F36.3】 Minus software limit switch reached
- 【F36.4】 Actual speed is overspeed.
- 【F36.6】 Overspeed
- 【F36.7】 Super acceleration.
- 【F36.8】 Z pulse cannot be found.
- 【F36.9】 Connection has been aborted.
- 【F36.10】 Not referenced.
- 【F36.11】 Sync position out-of-tolerance
- 【F36.12】 Slave axis zero check is aborted
- 【F36.13】 Sync speed out-of-tolerance
- 【F37.0】 Plus software limit exceeded.
- 【F37.2】 Minus software limit exceeded.
- 【F37.2】 Acceleration does not match maximum speed.
- 【F[38/39]】 Axis prompt
- 【F38.0】 Max compensation ratio exceeded.
- 【F38.1】 Max compensation exceeded.
- 【F38.2】 Zero offset parameter is too small.
- 【F38.4】 Software limit is too large.
- 【F38.5】 The second software limit is too large.
- 【F38.6】 Absolute encoder cycle digits are illegal.
- 【F38.7】 Position overflow.
- 【F38.8】 Target is outside plus software limit.
- 【F38.9】 Target is outside minus software limit.
- 【F38.10】 Mask angle of Z pulse needs to be adjusted.
- 【F38.11】 Reference position needs to be adjusted.
- 【F38.12】 Tracking error is too large.
- 【F[70]】 Current axis mode.

Axis Control Word

Overview

80 control words are configured for each axis. Each control word has a 16-bit byte. The first row indicates the bits from 0 to 7, and the second row indicates the bits from 8 to 15. The axis control words need to be used with the logical number offset of axis.

Axis control word

G0	D7	D6	D5	D4	D3	D2	D1	D0
	D15	D14	D13	D12	D11	D10	D9	D8

Axis enable	Axis lock	Home block	Home start	No axis motion in negative direction	No axis motion in positive direction	Negative limit	Positive limit
Axis reset	Compensation expansion	Reserved	Reserved	Subaxis follow	Reserved	Reserved	Reserved

*SP rotation CCW	*SP rotation CW	*SP orientation	*SP Jog	Expand software limit	The second software limit	Relative pmc motion	Absolute pmc motion
Response locking	Response unlocking	Reserved	CS response	Reserved	Reserved	Reserved	Reserved

Servo Parameter	Reserved	Reserved	Reserved	Capture Z pulse of encoder 2	Reserved	Reserved	Capture Z pulse
Spindle current-limiting	Directional gear-shift	Reserved	Spindle orientation	Torque control	Speed control	Position control	Servo gain

Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Servo enable
Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved

Details

- 【G0.0】 Positive limit switch of axis.
- 【G0.1】 Negative limit switch of axis.
- 【G0.2】 No axis movement in positive direction.
- 【G0.3】 No axis movement in negative direction.
- 【G0.4】 Set to start homing.
- 【G0.5】 Set home block.
- 【G0.6】 Set to lock the axis.
- 【G0.7】 Set axis enable
- 【G0.11】 Set to disable function of subaxis following
- 【G0.14】 Compensation expansion
- 【G0.15】 Single-axis reset
- 【G1.0】 Absolute PMC axis motion is enabled.
- 【G1.1】 Relative PMC axis motion is enabled.
- 【G1.2】 The second software limit is enabled.
- 【G1.3】 Extension software limit is enabled.
- 【G1.4】 Feed-spindle Jog.
- 【G1.5】 Feed-spindle orientation.
- 【G1.6】 Feed -spindle rotates in clockwise direction.
- 【G1.7】 Feed -spindle rotates in counter clockwise direction.
- 【G1.12】 Response flag of PLC to spindle C/S switch.
- 【G1.14】 Response flag of PLC to signal of unlocking index axis.
- 【G1.15】 Response flag of PLC to signal of locking index axis.
- 【G2.0】 Z pulse flag. (when motor is at the position of Z pulse, this flag is 1.)
- 【G2.1】 Wait for zero pulse
- 【G2.2】 Turn off function of searching zero pulse.
- 【G2.3】 Capture zero pulse of the second encoder.
- 【G2.7】 Servo parameter switch. 0: Default parameter, 1: switch to the second set of parameter.
- 【G2.8】 Servo gain switch.
- 【G2.9】 Switch to position control mode.

【G2.10】 Switch to speed control mode.

【G2.11】 Switch to torque control mode.

【G2.12】 Spindle orientation start.

【G2.14】 Directional gear-shift of spindle.

【G2.15】 Spindle current-limiting

【G3.0】 Servo enable switch.

【G4】Axis jog flag. When the axis is manual, or returning to zero, or the spindle is rotating, this flag is effective.

【G5】 Increment flag of axis. When axis is moving incrementally, this flag is effective.

【G[6/7]】Jog speed. 0: stop; 1: Jog speed in parameter; 2: Rapid traverse speed in parameter; >2: Self-defined speed.

【G8】 Incremental rate.

【G9】 Handwheel rate.

【G[10/11]】 handwheel pulse.

【G[12/13/14/15]】 Axis feedback position, unit: pulse

【G[16/17/18/19]】 Axis feedback position 2, unit: pulse

【G[20/21]】 Actual speed of axis, unit: pulse. Actual axis-speed is the incremental value per cycle of the actual feedback position of axis (G12-G15).

【G[22/23]】 Actual speed 2 of axis

【G[24/25]】 Actual torque of axis

【G[26/27]】 Tracking error. (Tracking error of axis is the difference between the actual axis feedback position (G12-G15) and the axis command position (F12-F15).)

【G[28/29/30/31]】 Counter value of encoder 1

【G[32/33/34/35]】 Counter value of encoder 2

【G[36/37]】 Real-time compensation value.

【G[38/39]】 Sample timestamp

【G[40/41/42/43]】 Latch position 1 (when the first encoder has z pulse, the current position is latched, which is used for G31 or distance code homing.

【G[44/45/46/47]】 Latch position 1 (when the second encoder has z pulse, the current position is latched, which is used for G31 or distance code homing.

- 【G[48/49/50/51]】 Target position of absolute movement for PMC axis.
- 【G[52/53/54/55]】 Incremental movement of PMC axis
- 【G[56/57]】 Servo alarm code.
- 【G[58/59]】 Servo prompt code.
- 【G60】 (2 is handwheel interruption, and 103 is PMC mode)
- 【G61】 Override value of PMC axis.
- 【G62.0】 PMC axis stop.
- 【G62.1】 Zero handwheel interruption.
- 【G62.2】 Turn on function of tangent following.
- 【G62.4】 Index axis switch.
- 【G62.5】 When coupling of driven axis is restored, synchronize the position of synchronization axis.
- 【G62.8】 Spindle control, write actual rotation speed to instruction.
- 【G62.9】 Start spindle rotation speed of gear shift.
- 【G64】 Current axis gear.
- 【G66/67】 Gear shift of spindle.
- 【G68/69】 Z pulse position.
- 【G70/71】 Z pulse interval 1.
- 【G72/73】 Z pulse interval 2.
- 【G74】 Gear shift of spindle.
- 【G78/79】 Sample data of servo

Channel Status Word

Overview 80 control words are configured for each channel. Each control word has a 16-bit byte. The first row indicates the bits from 0 to 7, and the second row indicates the bits from 8 to 15. The axis control words need to be used with the logical number offset of channel.

Axis status word	D7	D6	D5	D4	D3	D2	D1	D0
	D15	D14	D13	D12	D11	D10	D9	D8

F2560

User intervention	非自动时运动	Cycle start	Feedhold	Mode #3	Mode #2	Mode #1	Mode #0
Search Z pulse	Resetting	Suspend request	Rest flag	Verify state	reserved	Cut thread	Cutting

F2561

reserved	reserved	Wait for completion	Interrupt on skip	Interrupt on complete	Procedure complete	Program start	Program select
reserved	reserved	reserved	reserved	reserved	reserved	Non-null completion	Non-null instruction

F2562

reserved	reserved	reserved	reserved	reserved	reserved	reserved	reserved
4S instruction	3S instruction	2S instruction	1S instruction	Spindle is at constant linear speed	Index instruction	Tool offset flag	reserved

Details

【F2560.0 ~F2560.3】 To get mode

0: Reset mode 1: Auto mode 2: Manual mode

3: Increment mode 4: Handwheel mode 5: Home mode

6: PMC mode 7: Single block mode 8: MDI mode

【F2560.4】 Feedhold: channel is in state of feedhold.

【F2560.5】 Cycle start: channel is in state of cycle start.

【F2560.6】 Axis moves in non-auto mode.

【F2560.7】 User movement is interfering.

【F2560.8】 Cutting.

【F2560.9】 Thread-cutting: channel is in state of cutting thread, and feedhold is not allowed.

【F2560.11】 Verify state.

【F2560.12】 Channel reset: in the event of channel reset or reset button on panel being pressed, channel reset is effective, until channel reset response is set.

【F2560.13】 Suspend request.

【F2560.14】 Channel is resetting.

【F2560.15】 When axis is returning home to look for Z pulse, switching mode is not allowed.

【F2561.0】 Program is selected, which is set by interpreter.

【F2561.1】 Program start, which is set by channel control.

【F2561.2】 Program is completed, which is set by channel control.

【F2561.3】 Interrupt instruction G28/G31 is completed.

【F2561.4】 Skip interrupt instruction.

【F2561.5】 Wait for completing instruction.

【F2561.8】 There are non-empty instruction flags in channel.

【F2561.9】 Non-empty instruction flag is completed in channel.

【F2562.9】 Tool offset mark [tool offset number is in T instruction]

【F2562.10】 PLC index instruction flag.

【F2562.11】 Spindle is at constant linear speed.

【F2562.12】 The first S instruction.

【F2562.13】 The second S instruction.

【F2562.14】 The third S instruction.

【F2562.15】 The forth S instruction.

【F2569】 Tool offset number, which is in T instruction.

- 【F[2570/2571]】 The first S instruction. Unit: 0.001 revolution/minute.
- 【F[2572/2573]】 The second S instruction. Unit: 0.001 revolution/minute.
- 【F[2574/2575]】 The third S instruction. Unit: 0.001 revolution/minute.
- 【F[2576/2577]】 The forth S instruction. Unit: 0.001 revolution/minute.
- 【F2578/79】 G31 number which is currently waiting signal.
- 【F2580】 Currently running coordinate system.
- 【F[2581/2589]】 Axis numbers of nine axes in channel
- 【F[2590/2593]】 Axis number of the forth spindle in channel.
- 【F[2594/2595]】 Alarm code of syntax error.
- 【F[2596/2599]】 Channel alarm code.
- 【F[2600/2603]】 Channel prompt number.
- 【F[2604/2607]】 User output.
- 【F[2608/2615]】 M codes which run in channel, with a maximum of 8.
- 【F2616】 T instruction in channel. When T code is executing in channel, the value of T code is in register; otherwise, the output is 1.
- 【F2617】 B instruction in channel. B axis in boring machine is executed by PLC, and indexing is executed by B instruction.
- 【F2632】 Number of tool which is alarmed for the maximum life span being reached.
- 【F2636.0】 Channel is resetting.
- 【F2632.1】 Program has been stopped exactly.
- 【F2632.2】 Flag of inclined axis
- 【F2632.3】 Interpolation instruction runs in channel.
- 【F2632.4】 Flag of spindle synchronization.
- 【F2632.5】 Handwheel feed direction.
- 【F2637.0】 Subprogram process start.
- 【F2637.1】 Subprogram waits for feedhold, and saves breakpoint.
- 【F2637.2】 Break point flag.
- 【F2637.3】 Start to load subprogram.
- 【F2637.4】 Complete loading.
- 【F2637.5】 Start running.

【F2637.6】 Complete running.

【F2637.7】 Breakpoint has been restored.

【F2637.8】 Process ends.

【F2637.9】 Process error

【F2637.10】 Process reset.

【F2637.11】 Process waits for interpreter reset to complete.

【F2638.0】 Tool life-span manage – cumulative times of tool changing

Channel Control Word

Overview 80 control words are configured for each channel. Each control word has a 16-bit byte. The first row indicates the bits from 0 to 7, and the second row indicates the bits from 8 to 15. The axis control words need to be used with the logical number offset of channel

Axis control word	D7	D6	D5	D4	D3	D2	D1	D0
	D15	D14	D13	D12	D11	D10	D9	D8
G2560	Measurement interruption	Dry run	Cycle start	Feedhold	Work mode	Work mode	Work mode	Work mode
	Data save	Data recovery	Reset	Clear cache	Emergency stop	Panel reset	Reset response	Verify
G2561	Data recovery	Arbitrary row	Rerun	Explanation reset	Selection stop	Skip block flag	Rerun 2	Interpreter startup
	Reserved	Program modification	Reserved	Handwheel interruption	External interruption	User motion	Reserved	Explanation save
G2562	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved
	Reserved	Reserved	Rotation speed arrival	No spindle	MST lock	Speed check	Reserved	Reserved
G2620	Panel enable	PMC	Handwheel	Home reference	Increment	Manual	Single block	Auto
	Reserved	Reserved	Reserved	Reserved	Reserved	Rapid traverse	Incremental rate	
G2621	Handwheel 1				Handwheel 0			
	Reserved	Reserved	Reserved	Handwheel 1 enable	Hanwheel 1 rate		Hanwheel 0 rate	

G2622

Axis 7+	Axis 6+	Axis 5+	Axis 4+	Axis 3+	Axis 2+	Axis 1+	Axis 0+
Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Axis 8+

G2623

Axis 7-	Axis 6-	Axis 5-	Axis 4-	Axis 3-	Axis 2-	Axis 1-	Axis 0-
Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Reserved	Axis 8-

Details

【G2560.0/1/2/3】 Work mode. 0: reset mode, 1: auto mode, 2: manual mode, 3: increment mode, 4: handwheel mode.

【G2560.4】 Feedhold: Set feedhold in channel.

【G2560.5】 Cycle start: set cycle start in channel.

【G2560.6】 Dry run: set to dry run in channel.

【G2560.7】 Measure interruption flag. When this flag is set to 1, system interrupts ongoing G31 instruction. It is used with G2582.

【G2560.8】 Verify

【G2560.9】 PLC reset response: when PLC has been reset, set this flag to 1.

【G2560.10】 Panel reset flag. Through detecting this flag, PLC discover whether the system is resetting.

【G2560.11】 Emergency stop flag. This flag is set for emergency stop of machine.

【G2560.12】 Flag of channel buffering clear.

【G2560.13】 This flag is set for resetting machine.

【G2560.14】 Flag of channel data recovery.

【G2560.15】 Channel data save.

【G2561.0】 Flag of interpreter startup.

【G2561.1】 Flag of the second step of program rerun.

【G2561.2】 Flag of skipping block. When this flag is set to 1, system skips block.

【G2561.3】 Selection stop flag. When this flag is set to 1, system performs

selection stop.

【G2561.4】 Flag of interpreter reset.

【G2561.5】 Flag of program rerun.

【G2561.6】 Flag of MDI resetting to program header

【G2561.7】 Flag of interpreter data recovery.

【G2561.8】 Flag of interpreter data save.

【G2561.9】 Exact-stop check.

【G2561.10】 Flag of user motion control.

【G2561.11】 Flag of external interruption.

【G2561.12】 Turn on handwheel interruption.

【G2561.14】 Flag of program modification.

【G2561.15】 Coordinate of workpiece or tool changes, require to re-explain.

【G2562.0】 S instruction response word of No.1 spindle.

【G2562.1】 S instruction response word of No.2 spindle.

【G2562.2】 S instruction response word of No.3 spindle.

【G2562.3】 S instruction response word of No.4 spindle.

【G2562.8】 Feed direction of trial cut by handwheel. 0 is moving forward, 1 is retracting.

【G2562.10】 Spindle speed check.

【G2560.10】 Flag of panel reset. PLC discovers whether system is resetting by detecting this flag.

【G2560.11】 Emergency stop, to set channel of emergency stop.

【G2562.11】 MST lock.

【G2562.12】 Spindle is not started.

【G2562.13】 Spindle speed doesn't reach.

【G2562.14】 Following start.

【G2562.15】 Trial cut by handwheel. Use handwheel rate.

【G2563】 T instruction.

【G2564】 Feedrate override.

【G2565】 Rapid traverse override.

【G2566/67/68/69】 Spindle override. Override of four spindles in channel.

【G2570/71/72/73/74/75/76/77】 Spindle output instruction, output instructions of four spindles in channel. After obtaining spindle rotation speed (F2570-F2577), PLC calculates spindle override, and outputs spindle instruction. In servo spindle, the output is spindle rotation, and in converter spindle, the output is DA value.

【G2578】 F2578.1 imaginary axis control.

【G2579】 Machined-part counts

【G2580/81】Mask in protected area.

【G2582】G31 number. When G31 execution is interrupted, the number of interrupted G31.

【G2584/85/86/87】User bit input

【G2588~2607】User value input.

【G2608~2615】M code response of channel. When PLC is not executing M code, set to -1; when PLC is executing M code, set to -2; when PLC has executed M code, set to the currently executed M code.

【G2616】T code response of channel. When PLC has executed T code, set to the currently executed T code; otherwise, set to -1.

【G2617】Tangent following of tool.

【G2636.0】Channel reset (PLC sets register, and notifies HMI to reset channel.)

【G2636.3】IRQ control

【G2636.4】 No channel reset **【Reset button is invalid】**

【G2636.5】 Life timing/counting pause.

【G2560.15】 Channel data save

【G2561.0】 Interpreter start.

【G2637】 Subprogram calling start.

【G2638】 Counting of tool changing.

【G2970】 Flag of system activity channel.

【G2978】 System activity control channel

【G2980~2989】 Control word of handwheel **【previous axis selection】**

【G2990~2999】 Display output of handwheel.

【G3010~3025】 External alarm of PLC (External alarm of PLC, and $8 \times 32 = 256$ external alarms exist concurrently).

【G3040~3055】 External event of PLC (external event of PLC, and $8 \times 32 = 256$ external events exist concurrently).

【G3056~3070】 External reminder of PLC (external reminder of PLC, and $8 \times 32 = 256$ external events exist concurrently).


【G3080~3099】 Temperature sensor value.

Example of Status Word and Control Word Programming

Work Pattern Setting

Example

Ladder diagram



Function

Set the status in the working pattern of channel. When the axis is in the position control mode, set the working pattern of the current channel to auto, single block, manual, increment, handwheel or home.

Work Pattern Getting

Example

Ladder diagram





Function

Get the status in the working pattern of channel, which can be auto, single block, manual, increment, handwheel or home.

Control of Feed Axis and Spindle

Example

Ladder diagram




Function

It is used to control the movement of feed axis, and the spindle rotation. Set the current channel mode to manual mode, if you press Axis selection, and positive or negative movement button, the moving status of the current axis will be set, thus the axis will move; if you press spindle rotation (CW or CCW) button, the rotation direction of the spindle will be set.

Home

Example

Ladder diagram




Function

Obtain whether the current channel is returning home, through the status register. During the process of meeting the home block, which is the first home process, switching to other statuses is allowed; During the process of researching Z pulse, which is the second home process, switching to other statuses is not allowed.

Incremental Rate Override

Example

Ladder diagram




Function

Incremental rate consumes two bits. 00 represents x1, 01 represents x10, 10 represents x100, and 11 represents x1000. The axis movement is controlled by the setting of above axis register.

Cycle Start and Feed Hold

Example

Ladder diagram



Function

When the working pattern of channel is auto or single block, and is not at cycle start, set to cycle start. Set to feed hold under the status of cycle start. If the setting is successful, the system will be at the state of feed hold.

Extension Function Module

This chapter includes:

6.1 NC Function


6.2 Functional Unit of Axis

6.3 System Function

NC Function

Channel Mode Setting MDST

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○ Post ×
<Address 2>	□□□□	INT	Constant, F, G, R, W, D, P, B	Work mode value	

Function

Set the work mode of the current channel (Auto, Single-block, Manual, Increment, Reference home, Handwheel, PMC)


Parameter

Work mode Parameter	Auto	Single-block	Manual	Increment	Reference home	Hand wheel	PMC
D2□□□	1	2	4	8	16	32	64

Supplementary note


If one of channel state is axis homing, switching mode will not be allowed.

Example

Ladder Diagram	
Statement List	MDST 0 R0
Description	Set the work mode of channel 0 based on the value of R0.

Channel Mode Getting MDGT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○
<Address 2>	□□□□	INT	Constant, F, G, R, W, D, P, B	Work mode value	Post ×

Function

To get the work mode value of the current channel.


Parameter

Work mode Parameter	Auto	Single-block	Manual	Increment	Reference home	Hand wheel	PMC
D2□□□	1	2	4	8	16	32	64

Supplementary note


If one of channel state is axis homing, switching mode will not be allowed.

Example

Ladder Diagram	 <p>The diagram shows a single ladder rung. It starts with a normally open contact labeled 'T'. This contact is connected to a coil (output) labeled 'MDGT'. The coil has two parameters: '0' in the top right corner and 'R1' in the bottom right corner. The rung ends at a vertical line on the right.</p>
Statement List	MDGT 0 R1
Description	Take the work mode of Channel 0 into R1 register.

Mode MDI

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○ Post ×

Function To get MDI mode of the channel.


Parameter Parameter 1: channel No.

Example

Ladder Diagram	<p>The ladder diagram shows a normally open contact labeled 'X36.4' connected to a coil labeled 'MDI 0'. The coil is represented by a rectangle divided into two sections, with 'MDI' in the left section and '0' in the right section. The coil is connected to a terminal labeled 'R10.1'.</p>
Statement List	MDI 0
Description	When X36.4 is turned on, channel 0 is in MDI mode.

Locking Channel MST

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ✓ Post ×

Function


Lock the channel MST. When this function is turned on, all MST instructions of this channel are not available, and are skipped.

Example

Ladder Diagram	
Statement List	MST 0
Description	When X36.4 is turned on, channel 0 is locked.

Cycle Start CYCLE

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ✓ Post ×

Function


Set the channel which needs cycle start by parameter, and perform cycle start via ACT signal.

Example

Ladder Diagram	<pre> graph LR X36.4 --- COIL[Cycle 0] style X36.4 fill:none,stroke:none style COIL fill:#fff,stroke:#000 </pre>
Statement List	CYCLE 0
Description	When X36.4 is turned on, set the channel 0 to cycle start.

Emergency Stop STOP

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ✓ Post ×

Function


Set the channel which needs emergency stop by parameter, and start emergency stop via ACT signal.

Example

Ladder Diagram					
Statement List	<pre>LD X1.2 STOP 0</pre>				
Description	When X1.2 is turned on, set the channel 0 to emergency stop.				

Reset RESET

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ✓ Post ×

Function


Set the channel which needs reset by parameter, and activate reset via ACT signal.

Example

Ladder Diagram	
Statement List	<pre>LD X2.4 RESET 0</pre>
Description	When X2.4 is turned on, the channel 0 is set to reset.

Channel Exchange CHANSW

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Set the channel of feedhold	Pre ✓ Post ×

Function


Parameter Set the channel which needs to be exchanged by parameter, and enable the channel exchange via ACT signal.

Example

Ladder Diagram		
Statement List	<pre>LD X36.4 CHANSW 0</pre>	
Description	When X36.4 is turned on, set the channel 0 to the active channel.	

Feed Hold Start HOLD

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Set the channel of feedhold	Pre ✓ Post ×

Function


Parameter Set the channel which needs feed hold by parameter, and enable feed hold through ACT signal.

Example

Ladder Diagram	
Statement List	<pre>LD X36.4 HOLD 0</pre>
Description	When X36.4 is turned on, set the channel 0 to feed hold.

Cycle Start LED CYCLED

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	To get the channel which needs cycle start.	Pre ○
					Post ×

Function


Set the channel that needs cycle start by parameter, if the cycle start is successfully set, the output will light the cycle start LED.

Example

Ladder Diagram	
Statement List	<pre> LDT CYCLED 0 OUT Y36.4 </pre>
Description	Get the cycle start state of channel 0, and the cycle start LED is lit.

Feed Hold LED HOLDLED

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	To get the channel of feedhold state.	Pre ○
					Post ✓

Function


Set the channel where the feed hold LED needs to be lit by parameter, and light feed hold LED through ACT signal.

Example

Ladder Diagram	
Statement List	<pre> LDT HOLDLED 0 OUT Y36.5 </pre>
Description	Control the feed hold LED based on the feed hold status of the channel 0.

Block Skip (G31) ESCBLK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	The channel where the block skip function needs to be activated.	Pre ○ Post ×
<Address 2>	□□□□	INT	Constant	The number of G31	

Function


Set the channel where the block skip function needs to be activated by parameter, and enable this function through ACT signal.

Example

Ladder Diagram	
Statement List	<pre>LDP X31.4 ESCBLK 0 1</pre>
Description	When the rising edge of X31.4 is turned on, the first G31 statement in the channel 0 is activated.

Rapid Override RPOVRD

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Override value	Post ×

Function

The channel is selected by parameter 1. The override value is passed by parameter 2 with the register. The rapid override function is enabled by ACT.

Supplementary note


The override value cannot be changed at the thread-cutting time.

Example

Ladder Diagram	
Statement List	<pre>LDT RPOVRD 0 R7</pre>
Description	Set the rapid override of the channel 0 by the value of R7

Feedrate Override FEEDOVRD

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Override value	Post ×

Function

The channel is selected by parameter 1. The override value is passed by parameter 2 with the register. The feedrate override function is enabled by ACT.

Supplementary note


The override value cannot be changed at the thread-cutting time.

Example

Ladder Diagram	
Statement List	<pre>LDT FEEDOVRD 0 R7</pre>
Description	Set the feedrate override of the channel 0 with the value of R7.

Spindle Override SPDLOVRD

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○ Post ×
<Address 2>	□□□□	INT	Constant	Spindle No.	
<Address 3>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Override value	


Function

The channel is selected by the parameter 1, the override value is passed by the parameter 3 with register, and ACT enables rapid override function.

Supplementary note

The override value cannot be changed at the thread-cutting time.


Example



Statement List	LDT SPDLOVRD 0 0 R7
Description	Set the No. 0 spindle override value of the channel 0, by the value of R7.

Incremental (Stepping) Rate STEPMUL

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Axis No.	Pre ○ Post ×
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	Rate	

Function

Parameter The axis number is set by the parameter 1, the rate is passed by the parameter 2 with register, and ACT enables feedrate override function.

Supplementary note


This function can only be used in the incremental (stepping) status.

Example

Ladder Diagram	
Statement List	<pre>LDT STEPMUL 0 R7</pre>
Description	Set the incremental rate of the channel 0 by the R7 value.

Dryrun DRYRUN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓ Post ×

Function

Press Dryrun button in the auto mode on the control panel, its indicator lamp is lit, and CNC is in dryrun status, where the feed rate specified by the program is ignored, and the coordinate axis moves at the rapidest speed.

The machine doesn't perform actual cutting in dryrun status. The purpose of dryrun is to confirm the cutting path and the program.

During the process of actual cutting, this function must be turned off; otherwise, it may cause danger.

This function cannot work on thread cutting.

Parameter


Parameter 1: channel No.

Example

Ladder Diagram	
Statement List	DRYRUN 2
Description	When Y32.2 is turned on, the channel 2 is in dry run.

Block Skip SKIP

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function

The system can skip some specified blocks in the auto mode. If “/” is put at the start of a program block, press Block skip, then this block will be skipped in the auto mode; if Block skip is released, “/” will not work, and this block will be implemented.

Parameter


Parameter 1: channel No.

Example

Ladder Diagram	
Statement List	SKIP 2
Description	When Y32.2 is turned on, block-skip of channel 2 is valid.

User Input USERIN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
<Address 2>	□□□□	INT	Constant		Post ✕
<Address 3>	□□□□	INT	Constant		

Function

Set the user input. When ACT is effective, set user-defined group and bit to 1, the macro-variable changes accordingly.

Parameter

Parameter 1: channel No.

Parameter 2: not available at present


Parameter 3: power of 2. For example, 17 means that the value of #1190 is $2^{17}=131072$.

Example

Ladder Diagram	
Statement List	USERIN 0 1 1
Description	When X31.4 is turned on, the macro-variable #1190 of user input group which corresponds to the channel 0 is 2.

User Output USEROUT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	None	None	None		Pre ×
<Address 3>	□□□□	INT	Y, R		

Function

Set the user output. Set the value of macro-variable #1191 in the program, which will determine the group number and position number of user-defined output. 32-bit output is defined, and four groups of 8-bit outputs are obtained. The start address of output is defined by parameter 3.

Parameter

Parameter 1: channel No.

Parameter 2: not available at present.

Parameter 3: Parameter 3: the start address of output register. The output value is 32-bit. Therefore, for y register of 8-bit, four y registers are used.


Example

e

Ladder Diagram	
Statement List	USEROUT 0 1 Y1
Description	Y1.2 and Y1.3 will be output, and other bits of Y1 to Y4 are 0.

Selection Stop SELSTOP

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function

When “Selection stop” is enabled (the indicator light is on), the program stops at M01 in the auto mode.

Parameter


Parameter 1: channel No.

Example

Ladder Diagram	
Statement List	SELSTOP 0
Description	When Y32.2 is turned on, the selection stop of channel 0 is effective.

Vector Tool Direction Setting TOOLSET

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ×
					Post ✓

Function


This function is generally used for 5-axis machining. Set the vector direction of the current tool in this channel to Z direction, enable this function, manually feed and retract the tool along the vector direction.

Example

Ladder Diagram	
Statement List	TOOLSET 0
Description	When Y32.2 is turned on, the tool orientation of channel 0 is effective.

Vector Tool Direction Clear TOOLCLR

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Addresses 1>	□□□□	INT	Constant	Channel No.	Pre ×
					Post ✓

Function


This function is generally used for 5-axis machining. Z direction is cancelled in this channel as the vector direction of the current tool. This function is used in conjunction with TOOLSET function.

Example

Ladder Diagram	<pre> graph LR T[] --- TOOLCLR[TOOL CLR] TOOLCLR --- 0[0] </pre>
Statement List	TOOLCLR 0
Description	The tool direction of channel 0 is set to be invalid.

8-bit Nixie Tube NIXIE

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B	The number to be shown by the digital tube	Pre ✓
<Address 2>	□□□□	INT	Constant	"0" indicates single byte, and "1" indicates double-byte.	Post ✓
<Address 3>	□□□□	BOOL	Y, R, W, D, B	Set the 8-bit digital tube on the panel	

Function

The 8-bit digital tube on the panel displays the number of the current tool.


Example

Ladder Diagram	
Statement List	NIXIE R23 0 Y37

Descripti on	The tool number in R23 is displayed to the digital tube.
-----------------	--

Tool Display TOOLUSE

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ○
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Post ×

Function Display the tool number in the currently executed T code to the interface of CNC.

Parameter Parameter 1: channel number

Parameter: tool number


Example

Ladder Diagram	
Statement List	TOOLUSE 0 R23
Description	The tool number of channel 0 is displayed on the interface.

Functional Unit of Axis

Spindle JOG SPDLJOG

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	BOOL	X, Y, F, G, R, W, D, P, B		Post ×

Function Control spindle manually.


Parameter Parameter 1: spindle number
Parameter 2: signal of rotation direction;

Example

Ladder Diagram	
Statement List	SPDLJOG 0 X32.4
Description	When X31.4 is effective, if X32.4 is valid, the 0 axis will rotate at the default speed in the clockwise direction.

Spindle Control 【Servo Spindle】 SPDLBUS

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	Constant		Post ×

Function

A spindle in a channel is set to be valid. Set the device which is set to be associated with the spindle number by the channel parameter, to the spindle. For example, the logical axis number of the 0 axis for the current channel 0 is 5, (suppose No.5 axis is enabled), then the logical axis 5 is regarded as the first spindle of the current channel. The spindle is enabled to be effective by this functional module.

Parameter

Parameter 1: channel number


Parameter 2: spindle number

Example

Ladder Diagram	<p>The diagram shows a single-rung ladder logic circuit. It starts with a normally open contact labeled 'X31.4'. This contact is connected to a coil (output) labeled 'SPDL BUS'. The coil has two parameters: '0' in the top position and '1' in the bottom position. The circuit ends with a vertical line representing the power rail.</p>
Statement List	SPDLBUS 0 1
Description	When X31.4 is effective, the No.1 spindle of channel 0 is controlled.

Spindle Control with Gear 【Servo Spindle】 SPDLBUS1

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	Constant		
<Address 3>	□□□□	INT	Constant, Y, G, R, W, D, B		
<Address 4>	□□□□	INT	P		

Function Bus spindle control with gear.

Parameter

Parameter 1: channel number.


Parameter 2: spindle number.

Parameter 3: gear register, with gear starting with 1.

Parameter 4: control parameter. The specified parameter holds the data such as maximum rotational speed of spindle motor, initial rotational speed and the like. Reference value of spindle control value for parameter 4 includes:


0	Maximum rotational speed of motor
1	Minimum rotational speed of actual measurement
2	Maximum rotational speed of actual measurement
3	Numerator of current transmission ratio
4	Denominator of current transmission ratio

Example

Ladder Diagram	
Statement List	
Description	<p>When X31.4 is effective, the current gear for No. 1 spindle override of channel 0 is in R1 register. Control parameter is in user parameters from P2. Refer to the Parameter manual for filling in parameters, according to the actual condition of machine.</p>

Spindle Orientation Enable SPDORI

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Axis number	Pre ○
					Post ×

Function


Spindle orientation enable. The spindle needs to be directed to a specified angle at the beginning of tool changing and rigid tapping. Perform spindle orientation via this function. The orientation angle is set by the parameter in the servo amplifier.

Example

Ladder Diagram	
Statement List	SPDLORI 0
Description	The spindle orientation for No.0 spindle.

Completing Spindle Orientation SPDLOROK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
					Post ✓

Function orientation is complete, which indicates that the spindle has been at the specified orientation angle.

The spindle


Parameter Parameter 1: 轴号。Parameter 1: axis number

Example

Ladder Diagram	
Statement List	SPDLOROK 0
Description	When No.0 spindle orientation has been enabled, set R10.1 to be effective.

Spindle Control 【DA】 SPDA

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	Constant		Post ×
<Address 3>	□□□□	INT	Constant, Y, G, R, W, D, B		
<Address 4>	□□□□	BOOL	Y, G, R, W, D, B		
<Address 5>	□□□□	BOOL	P		

Function DA control of spindle. It is used to control the analog spindle.

Parameter Parameter 1: channel number

Parameter 2: spindle number


Parameter 3: gear register (gear starts from 1)

Parameter 4: invalid

Parameter 5: reference of spindle control value includes:


0	Maximum rotational speed of motor
1	Minimum rotational speed of actual measurement
2	Maximum rotational speed of actual measurement
3	Numerator of current transmission ratio
4	Denominator of current transmission ratio

Example

Ladder Diagram	
Statement List	SPDA 1 0 R1 R2 P5
Description	Channel 1. The current gear for spindle 0 of channel 1 is in R1 register. The reference value of spindle control is in R2. Control parameter is in P5.

Zero Speed Detection for Spindle SPDLZERO

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
					Post ×

Function Zero speed detection for spindle.


Parameter Parameter 1: axis number

Example

Ladder Diagram	
Statement List	SPDLZERO 1
Description	Zero speed detection for the No.1 spindle.

Spindle Speed Arrival SPDLRCH

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ○
					Post ×

Function


To detect whether the spindle speed reaches the instruction speed.

Example

Ladder Diagram	
Statement List	SPDLRCH 1
Description	Speed arrival for the No.1 spindle.

Driven Axis Home SUBAXEN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel number	Pre ✓
					Post ✕

Function

Enable the sub-axis to return to zero. When this function is turned on, the driven axis returns home to search Z pulse. Z pulse has been found, which means homing of driven axis is completed. Then the driving axis continues to return to zero.

Parameter


Parameter 1: Driven-axis number

Example

Ladder Diagram	
Statement List	SUBAXEN 0
Description	When X32.6 is valid, the driven axis is enabled to return to zero.

Release Driven Axis DESYN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function

Release driven axis. An axis is set to the driven axis of another one by parameter. If some instructions are sent to driving axis, driven axis will also get those. When the function of driven axis release is turned on, the driven axis is disassociated with the driving axis, without receiving instruction pulse of the driving axis.

Parameter


Parameter 1: Driven axis number

Example

Ladder Diagram	
Statement List	DESYN 0
Description	When X32.6 is valid, the No.0 driven axis is released.

Axis Jog JOGSW

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ○
<Address 2>	□□□□	BOOL	X, Y, F, G, R, W, D, P, B		Post ×

Function Enable axis jog by manual.

Parameter Parameter 1: axis number


Parameter 2: the positive direction of axis jog. The value of 1 indicates the positive direction, and the value of 0 indicates the negative direction.

Example

Ladder Diagram	
Statement List	JOGSW 0 X32.3
Description	When X32.3 is turned on, axis 0 is enabled to move manually in positive direction; when X32.3 is not turned on, axis 0 is enabled to move manually in negative direction.

Axis Stepping STEPAXIS

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ○
<Address 2>	□□□□	BOOL	X, Y, F, G, R, W, D, P, B		Post ×

Function Enable axis by stepping.

Parameter Parameter 1: axis number.


Parameter 2: the direction of axis stepping. “0” represents jog in the positive direction, and “1” represents jog in the negative direction.

Example

Ladder Diagram	<p>The ladder diagram shows a single rungs. It starts with a normally open contact labeled 'T'. This is followed by the STEPAXIS function block. The block has two inputs: the top input is labeled '0' and the bottom input is labeled 'X32.3'. The output of the block is connected to the right rail.</p>
Statement List	STEPAXIS 0 X32.3
Description	When X32.3 is turned on, axis 0 is enabled to jog in negative direction; when X32.3 is not turned on, axis 0 is enabled to jog in positive direction.

Jog Velocity JOGVEL

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Post ✕

Function Manually control the jog speed.

Parameter Parameter 1: axis number

Parameter 2: axis speed, and its value can be as below:


- 1: jog speed of parameter
- 2: rapid traverse speed of parameter
- >2: speed (pulse/circle)

Example

Ladder Diagram	
Statement List	JOGVEL 0 R0
Description	When X33.2 is turned on, the 0 axis runs at the speed specified in R0.

Home Run HOMRUN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function To start to return home.


Parameter Parameter 1: axis number

Example

Ladder Diagram	
Statement List	HOMRUN 1
Description	When X1.1 is turned on, the axis 1 starts to return home.

Home Run 1 HOMERUN1

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
<Address 2>	□□□□	BOOL	X, Y, F, G, R, W, D, P, B		Post ✕

Function To start to return home.

Parameter Parameter 1: axis number


Parameter 2: the direction where the axis returns home.

Example

Ladder Diagram	
Statement List	HOMERUN1
Description	When X1.1 is turned on, the axis 1 starts to return home; when X23.3 is turned on, the Jog of axis 0 in positive direction is enabled.

Home Approaching Switch HOMESW

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function The axis meets the home block.


Parameter Parameter 1: axis number

Example

Ladder Diagram	
Statement List	HOMESW 1
Description	X1.4 is turned on, which means the axis 1 meets the home block.

Home Completing HOMLED

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✓

Function Returning home is complete.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	HOMLED 1
Description	Axis 1 has completed homing, and the lamp of axis 1 is lit.

Axis Enable AXEN

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function Axis enable.


Parameter Parameter 1: axis number, can be constant and register.

Example

Ladder Diagram	
Statement List	AXEN 1
Description	When X0.1 is turned on, axis 1 is enabled.

Axis Ready (Bust) AXRDY

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ×
					Post ✓

Function The axis is ready.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	AXRDY 1
Description	When the axis 1 has been ready, R10.1 is set to 1.

Axis Lock AXISLOCK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function The axis is locked.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	AXISLOCK 2
Description	When X2.0 is turned on, the axis 2 is locked.

Relative PMC Axis Movement AXISMOVE

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Post ✕

Function

PMC axis is a special motion axis, which cannot be moved by the instruction, and cannot be used for the interpolation. The PMC axis can only be moved by the PLC program. This instruction is used to move the PMC axis, and specify the relative moving distance.

Parameter

Parameter 1: axis number


Parameter 2: axis movement (unit: 1/1000mm, or 1/1000 degree).

Example

Ladder Diagram	
Statement List	AXISMOVE 2 2
Description	When X2.0 is turned on, axis 2 relatively moves the distance of 2 units.

Absolute PMC Axis Movement AXISMVTO

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Post ✕

Function

This instruction is used to move the PMC axis to an absolute position.

Parameter

Parameter 1: axis number


Parameter 2: the position that the axis moves (unit: 1/1000mm, or 1/1000 degree).

Example

Ladder Diagram	
Statement List	AXISMVTO 2 2
Description	When X2.0 is turned on, the axis 2 moves to the position 2.

The Second Soft Limit of Axis AXLMF2

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Pre ✓
					Post ✕

Function The second soft limit of the axis.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	AXLMF2 2
Description	When X2.0 is turned on, the second soft limit of the axis 2 is effective.

Block Switch in Positive Limit Direction AXISPLMT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function The positive limit direction of the axis.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	AXISPLMT 1
Description	X1.1 being effective represents the positive limit direction of the axis 1.

Block Switch in Negative Limit Direction AXISNLMT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function The negative limit direction of the axis.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	AXISNLMT 1
Description	X1.2 being effective indicates the axis 1 meets the negative limit point.

Handwheel MPGSET

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
<Address 2>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		Post ✕
<Address 3>	□□□□	INT	Constant, X, Y, F, G, R, W, D, P, B		

Function

To set handwheel.

Parameter

Parameter 1: handwheel number.

Parameter 2: axis number.


Parameter 3: override value.

Example

Ladder Diagram	
Statement List	MPGSET 1 R6 R7
Description	Handwheel 1 gets its incremental value. The axis number selected by the handwheel 1 is stored in R6. Override value of the handwheel 1 is stored in R7.

Servo Enable (Bus) SVSW

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
					Post ×

Function Servo enable.


Parameter Parameter 1: axis number.

Example

Ladder Diagram	
Statement List	SVSW 1
Description	Servo enable of the axis 1.

Axis Mode AXISMODE

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	Constant		Post ×

Function To select the working mode of the axis.

Parameter Parameter 1: axis number.


Parameter 2: “0” is position, “1” is speed, and “2” is torque.

Example

Ladder Diagram	
Statement List	AXISMODE 1 1
Description	The working mode of axis 1 is set to the speed mode.

Axis Reference REFPT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	Constant		Post ✓

Function To confirm the axis reference.

Parameter Parameter 1: axis number.


Parameter 2: Parameter 2: “2” indicates that the second reference is valid, “3” indicates that the third reference is valid, “4” indicates that the fifth reference is valid.

Example

Ladder Diagram	
Statement List	REFPT 1 2
Description	The second reference of the axis 1 is valid, and R10.1 is output.

During Axis Home AXISHOM2

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Axis number	Pre ○
					Post ○

Function


To get the home status while the axis is returning home. In the process of axis home, some operations cannot be performed, in which case the home status must be judged. The corresponding F status word is F0.2.

Example

Ladder Diagram	<p>The diagram shows a single ladder rung. It begins with a vertical line on the left, followed by a horizontal line that connects to a rectangular box. This box is divided into two sections: the left section contains the text 'AXIS HOM2' and the right section contains the number '0'. After this box, the horizontal line continues to the right and connects to a circular coil labeled 'R1.1'. The rung ends at a vertical line on the right.</p>
Statement List	AXISHOM2 0
Description	The home sign of axis 0 is valid. While the axis is returning home, R1.1 is output, where other manual operations are not allowed.

During Axis Moving AXMOVING

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Axis number	Pre <input type="radio"/> Post <input type="radio"/>

Function

To get the axis status during its movement. In the process of axis moving, some operations cannot be performed, in which case the status must be judged. The corresponding F status word is F0.0.


Example

Ladder Diagram	
Statement List	AXMOVING 0
Description	The moving sign of axis 0 is valid. While the axis is moving, R1.1 is output.

System Function

Rotation ROT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
<Address 2>	□□□□	INT	X, Y, F, G, R, W, D, P, B		Post ✓
<Address 3>	□□□□	INT	X, Y, F, G, R, W, D, P, B		
<Address 4>	□□□□	INT	X, Y, F, G, R, W, D, P, B		

Function

Rotation control, which is used for tool rest and the like. The output is 0 for the rotation in the clockwise direction, and the output is 1 for the rotation in the counter clockwise direction.

Parameter

Input 1: enable on/off

Input 2: starting number. If the number is 0, the position number of rotational equipment starts from 0; if the number is 1, the position number of rotational equipment starts from 1.

Input 3: Whether to select a cutter nearby. If it is 0, the cutter will be selected in the clockwise direction; if it is 1, the cutter will be selected nearby.

Input 4: target location type. When the value is 0, the current target location is counted; when the value is 1, the previous location of target is counted.

Count result. The value of 0 represents the number of count locations, and the value of 1 represents the count steps.

Parameter 1: maximum quantity of cutter rests.


Parameter 2: address of current position.

Parameter 2: address of target position

Parameter 4: address of count result. The meaning of count result is determined by input 4 and input 5.


Input 5:

Example

Ladder Diagram	
Statement List	ROT 16 B0 R27 R59
Description	<p>R66.0 is a true contact, where the setting status of ROT module is: start counting for the starting numbers from 1, use the function of short-path selecting tool, count the current target location, output the counting steps, and output the counting value to R59. The current tool location is saved in B0, and the target tool location is saved in R27.</p>

Alarm ALARM

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ○
					Post ×

Function To generate alarm.


Parameter Parameter 1: alarm code. The PLC alarm code is from 1 to 256, and the prompt number of PLC is from 501 to 884.

Example

Ladder Diagram	
Statement List	ALARM 3
Description	When X3.4 is turned on, the alarm 3 is generated.

Event EVENT

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant		Pre ✓
					Post ✕

Function To create the event object.


Parameter Parameter 1: event number.

Example

Ladder Diagram	
Statement List	EVENT 122
Description	When 30.4 is turned on, the event 122 is generated.

Save Data SAVEDATA

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
None					Pre ✓
					Post ✕

Function To save all data.


Parameter None.

Example

Ladder Diagram	
Statement List	SAVEDATA
Description	When X30.4 is turned on, the data, which hasn't been saved before outage, can be saved.

Reset Setting Output RSTCHK

Format



Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Channel No.	Pre ✓
					Post ✓

Function

To get panel reset signal (must be used with RSTCLR simultaneously). If some reset actions in PLC need to be performed after the reset button on the panel is pressed, use this function module. “Resetting...” will be shown on the CNC interface.


Example

Ladder Diagram	
Statement List	RSTCHK 0
Description	The output of setting reset is 1

Reset Clear RSTCLR

Format

Parameter	Parameter form	Data type	Storage area	Explanation	Properties
<Address 1>	□□□□	INT	Constant	Use it together with RSTCHK.	Pre ✓
					Post ✕



Function

After the reset actions in PLC are complete, the reset must be cleared (must be used with RSTCHK simultaneously), and the signal of completing reset is transmitted to CNC. “Reset done” will be shown on the CNC interface.

Parameter


Channel number.

Example

Ladder Diagram	<pre> graph LR X305[X30.5] --- RSTCLR[RST CLR] RSTCLR --- Param["0"] Param --- Output(()) </pre>
Statement List	RSTCLR 0
Description	When 30.5 is turned on, the reset is cleared, and the output is 0.









Operational Monitoring and Online Modification for Ladder Diagram

The function of operational monitoring and online modification for the ladder diagram, which is provided by PLC edit function, will monitor changes in the status of each component in the ladder diagram, and force a modification of a component status to achieve the goals of debugging.




Press “Ladder diagram monitoring” on the diagnosis interface, to access the ladder diagram interface, as seen above. The buttons on this interface include Ladder diagram diagnosis, Search, Change, Command, Load, Discard, Save and Return.


The next sections offer more details.

	Ladder diagram diagnosis: view the value of each variable, and perform intervention operations of component.
	Search: type the component name to search the component.
	Change: perform component modification operations.
	Command: can edit the ladder diagram.
	Load: load the current information on the ladder diagram.
	Discard: undo the edits of ladder diagram.
	Save: save the edits of ladder diagram.
	Return: return to the previous action.

Online Diagnosis for Ladder Diagram




Press Ladder diagram diagnosis button to access the corresponding interface, as seen in below figure. There are 6 buttons on this interface: Inhibit, Enable, Redo, Decimal, Hexadecimal, and Return.




Press “Diagnosis→Ladder diagram monitoring→Ladder diagram diagnosis”, to view the value of each variable. User can move the cursor up and down to view variables. As seen above, the component turning green indicates that this component is turned on or is valid, then user can use operations on the component, such as inhibit, enable, redo and the like.



Inhibit function button. Move the cursor on the component, and press Inhibit button, to shield the component. As shown in the below diagram, press Inhibit, the component turns red, which indicated that the component is shielded. Press Restore button to restore the function of the component, which will be covered later.




Enable function button. Move the cursor on the component, press Enable button, and the component is enabled. As demonstrated below, the cursor has been moved on the component, press Enable button, the component turns green, which indicates that the component is enabled. In the below figure, X0.0 is normally open. Move the cursor on X0.1, press Enable button, the component turns green, and is switched off.






Restore function button. Move the cursor on the component, and press Restore, to undo the shielding or enabling operations described above. Press this button after Inhibit function is enabled, the red color on the component disappears, which indicates that the function of component is restored, as shown in the figure below.





The value in this system is by default in decimal, user can press the button corresponding to “hexadecimal”, then the value is in hexadecimal, which is shown as below:

➤ In decimal



➤ In hexadecimal






Return function button. Press this button to return to the interface of ladder diagram monitoring, for performing other operations.


Search



Press Search, then the operation interface as shown in the figure below appears, where the component can be looked up.




For example, type X0.0, press “Enter”, the first X0.0 of the program under the cursor line can be found. See illustration as below:






The found component is covered by blue cursor. If you want to continue to search, press “Continue”, then the next one can be found.












The functional button of Return. Press this button to return to the interface of the ladder diagram monitoring.

Change

User can press the corresponding functional button of “Change” menu, to perform operations on the new component.




	Straight line: insert a straight line
	Vertical line: insert a vertical line
	Delete vertical line: Delete a vertical line
	Delete component: delete a component
	Normal open: insert a normal-open contact
	Normal closed: insert a normal-closed contact
	Logical output: insert an output
	Inverted output: insert an inverted output
	Functional module: insert a function (user can press the initial word of the component, to select it)


Insert Straight Line




Press the functional button of “Straight Line” to insert a straight line in the ladder diagram, see as below:



Insert Vertical Line




Press the functional button of “Vertical line” to insert a vertical line after the cursor, as shown in the figure below:



Delete Vertical Line



Press the functional button of “Delete Vertical Line” to delete the vertical line after the cursor, as demonstrated below:




Delete Component




Move the cursor on the component to be deleted, press the functional button of “Delete Component” to delete the component in the ladder diagram.

➤ Before the deletion




➤ After the deletion



Normal Open




Move the cursor to the position where the normal-open contact is to be inserted, press the functional button of “Normal open” to insert the normal-open contact at the specified position.



Normal Closed




Move the cursor to the position where the normal-closed contact is to be inserted, press the functional button of “Normal close” to insert the “normal-closed” contact at the specified position. as shown in the figure below:



Logical Output




Move the cursor to the position where the logical output needs to be inserted, press the functional button of “Logical output” to insert the logical output at the specified position in the ladder diagram, as shown in the figure below. It is important to note that pre can be added to the logical output, but post cannot. Refer to the section of programming for details.



Inverted Output




Move the cursor to the position where the inverted output needs to be inserted, press the functional button “Inverted output” to insert the inverted output at the specified position in the ladder diagram, which is illustrated by the following figure.




Functional Module



Press the functional module button to access the operation interface shown as below figure, and select the functional module needed.

 JOG	 DGN	 CHO		2017-02-16 13:39:11 	
(2/2) ZAXIST00 MUCH TRACKING ERROR					
DESYN	DISAS	DIV	DRYRUN	ENCO	ESCBLE
EVENT	FEEDOVRD	FILT	FMOV	HEADSEN	HOLD
HOLDLED	HONELED	HOMERUN	HOMERUM1	HOMESW	INC
JOGSW	JOGVEL	LT	NACK	MDGT	MDI
MDST	MGET	MOV	MFGSET	MSTLOCK	MUL
NEG	NTP	NIXIE	PARTCLR	PARTCNT	PLF
PLS	PTN	REFPT	RESET	RFID	ROT
RPOVRD	RSTCHK	RSTCLR	RTOMPG	SAVEDATA	SELSTOP
DGN 回零挡块					

Then hit Enter to enter the selected functional module into the ladder diagram. User can press the initial word of the component to select the relevant component.




Press functional module button again to return to the interface of operation modification.








Return

Press “Return” to return to the previous operation interface.

Command

User can press the buttons listed in the below table to edit the ladder diagram.




	Select: select the cursor line
	Delete: delete the cursor line
	Move: move the selected component
	Copy: copy the selected component
	Paste: paste the selected component
	Insert row: insert a line before the cursor line
	Add row: insert a line after the cursor line

Select



Move the cursor to the line that you want to select, press the functional button of “Select”, the selected line turns blue, and then press “Select” button again to select the next line of the current line. It is illustrated by the following figure. You can perform the operations such as delete, after selecting the line you want.




Delete




Move the cursor to the line to be deleted, press “Select” button, the line turns blue, then press “Delete” to delete this line.

➤ Before the deletion




➤ After the deletion




Move




First move the cursor to the line to be moved, then press “Select” button, this line turns blue.



Press the functional button “Move” to access the interface which is shown in the below figure, and the selected line disappears.




Move the cursor to the target line, and press “Paste” to move the selected line to the target line.




Copy



Move the cursor to the position of the line that needs to be copied, then press the functional buttons of “Select” and “Copy”. See as below:




Move the cursor to the target line, and press the functional button of “Paste” to paste the copied line.



Paste



The functional button of “Paste” has been applied in section 7.4.3 and 7.4.4. Refer to the two sections for the detailed operations.




Insert Line




As shown in the figure below, move the cursor to the next line of the line to be inserted, press the functional button of “Insert line”, then the line is inserted. Note that the line is generally inserted above the cursor line.

➤ Before inserting,



➤ After inserting,




Add Line




The functional button of “Insert line” is in contrast to “add line” where the line is added below the cursor line, as shown in the figure below, press the functional button of Add line, then a new line is added below the cursor line.

➤ Before adding



➤ After adding



Return

Press the functional button of Return to back to the previous interface.

Load



Edit and check the ladder diagram, press the functional button of Load, then the system loads the current ladder diagram.

Discard



If you want to re-edit the edited ladder diagram, press the functional button of “Discard” to cancel the operations that you have edited to the diagram.

Save



After the ladder diagram is saved, press this button, to save the ladder diagram edit operations.

Return

Press the functional button of Return, to return to the diagnosis interface.

Instruction on PLC Development Environment

This chapter includes:

7.1 Overview

7.2 Installation of Development Environment

7.3 Development Environment Interface

7.4 Development Environment Operation


Overview

HNC-LADDER-WIN Numerical Ladder Diagram Programming Software is a latest software of PLC program development environment for Series 8 NC system. This software runs on Windows XP operating system, and can easily set up ladder diagrams by visual graph programming. It is compatible with various of PLS languages that are compliant to IEC61131-3 international standard, and is a simple, efficient, and reliable PLC development tool.


Installation of Development Environment

Using the example of installing from CD on Chinese Windows XP, this section explains how to install the ladder diagram development environment.


- (1) Boot into Chinese WindowsXP.
- (2) Place the disk of ladder diagram development environment in the CD-ROM drive.
- (3) Double click Setup.exe file under the directory of Huazhong NC ladder diagram, the installation program may run automatically, and then the installation wizard appears.
- (4) The greeting window appears after the installation wizard interface.




- (5) Click "Next (N)", and the selection dialog displays on the screen.



- (6) After doing some necessary modifications to your installation path on the selection dialog, click “Next(N)”.



- (7) Then the formal installation starts, with the above displaying on the screen.



- (8) After the installation is complete, the installation complete interface appears.

Development Environment Interface

Development Environment of ladder diagram is divided into four parts: menu, ladder diagram, statement list, and symbol table.

Menu

The bar at the top of the development environment is called menu, where every pulldown menus of ladder diagram interface are listed. Clicking a menu item shows the command options in the pulldown menu. Click a command to handle relevant operation.

There are six items in the development environment menu: file, view, tool, window, and help, which are discussed in the following:

File

The “File” menu contains the command items working on files, which mainly provide operations on files of ladder diagram with user.

New	This item is for creating a new project.
Open	This item is to open an existing dft file.
Save	This item is for saving files of current window as dft files.
Save as	The function of this item likes “save ladder diagram” item, which is to save open files, and the difference is that this item is to save the open files with new names.
Close	This item is for closing current ladder diagram interface.
Load dit file	This item is for opening existing dit files.
Print	This item is for printing current window contents.
Print preview	This item is for previewing print effect.
Print setup	Parameter This item is to set printing parameters.
Exit	When you select this item, the program exits.

Edit

The “Edit” menu contains rapid operations of copy, paste and the like, of which the purpose is to improve the efficiency of writing the ladder diagram.

Cut	Cut string and element.
Copy	Copy string and element
Paste	Paste string and element
Insert row	Insert a row at the current cursor location
Delete row	Delete the row which the current cursor locates.

View

“View” menu is to control the subwindow displaying in the main window.

Ladder diagram	To open (close) ladder diagram view.
Statement list	To open (close) statement list view.
Symbol list	To open (close) symbol list view.
Primitive tree	To open (close) primitive tree view on the left.
Message box	To open (close) message box at the bottom.
Toolbar	To open (close) toolbar.
Status bar	To open (close) status bar.

Tool

The function of “Tool” menu is to find/replace.

Search	To search the specified string.
Search next	To continue to search the specified string.
Replace	To replace the specified string.

Window

“Window” menu is used to open each window.

Overlap	To arrange subwindows in overlap.
Tile	To arrange subwindows in tiling.
REG	To display symbol list window.
STL	To display statement list window.
LADDER	To display ladder diagram window.


Help

About NEWPLC: to display the software version.

Ladder Diagram Interface

Four parts including toolbar, primitive tree, edit window, and message box are in the ladder diagram window.

Toolbar and primitive tree can dock freely, that means, they can be put on any of the four side walls of the main window. Toolbar can be located anywhere on the desktop.




Toolbar

There are two toolbars including action bar and component bar, in the ladder diagram interface.

- (1) Action bar is used to manipulate new files quickly, such as zooming, undo, redo, and so on.




- (2) Component bar is used to fast add the basic input/output cell and the selection function module.



Primitive Tree

Primitive tree is used for selection function module. Double-clicking the icon can expand and collapse the instruction tree. Select the instruction icon needed from the instruction tree.



Edit Window

Edit window is for displaying and editing the ladder diagram. The area between the left busbar and the right busbar is the editing domain of the ladder diagram, the row number you are currently editing displays on the left of the left busbar, and the comments to the meaning of output status for the current line displays on the right of the right busbar.




Message Box

While the ladder diagram is being compiling, the statement error and syntax error which can be recognized, may appear in the message box.

Line7 Column1 : No connection in elements
 Line7 Column1 : Parameters error
 Line7 Column3 : No connection in elements
 Line7 Column10 : Parameters error

Statement List Interface

Toolbar and edit window are in the statement list interface.



Toolbar

An action tool is in the statement list interface.




Edit Window

Edit window is for displaying and editing statement list, and can judge the current row when the statement list is being editing.

× LDT x3

Symbol List Interface

Symbol names and comments of relevant addresses can be defined in symbol list interface.



Selection box for register is on the left of edit window of the symbol list, and edit box for register is on the right.

The edit box for register includes number, address, symbol name and comments.

- Number: automatically generate the number of the current symbol name in all the symbol names.
- Address: the specified address.
- Symbol name: the symbol name corresponding to the specified address.
- Comments: the comments corresponding to the specified address.

Development Environment Operation

Before editing PLC, first define the symbol name for the address to be used, and annotate the address, then edit PLC in the way of ladder diagram or statement list.


Symbol List Operation

Symbol list is used to define the symbol name for the specified address, and annotate the address.

Add Symbol List

Here in X10.0 (the positive limit direction of X axis) as an example to introduce.

X10.0 is in X register. Select X register in the selection box of register. X10.0 is in X000-X0049.



All the register bits and points from X0000 and X0049 may appear in the edit box of register.

No.	Address	Symbol Name	Note	
	X0			
0	X0.0			
1	X0.1			
2	X0.2			
3	X0.3			
4	X0.4			
5	X0.5			
6	X0.6			
7	X0.7			
	X1			
8	X1.0			
9	X1.1			
10	X1.2			
11	X1.3			
12	X1.4			
	X1.5			
	X1.6			
	X1.7			
	X2			
13	X2.0			
14	X2.1			
15	X2.2			
16	X2.3			
17	X2.4			
18	X2.5			
19	X2.6			
20	X2.7			
	X3			

Click “Symbol name” item at the X10.0 row three times, then the edit box pops up.

No.	Address	Symbol Name	Note	
	X9.2			
	X9.3			
	X9.4			
	X9.5			
	X9.6			
	X9.7			
	X10			
	X10.0			
	X10.1			
	X10.2			
	X10.3			
	X10.4			
	X10.5			
	X10.6			
	X10.7			
	X11			
	X11.0			
	X11.1			
	X11.2			
	X11.3			
	X11.4			
	X11.5			
	X11.6			
	X11.7			
	X12			
	X12.0			
	X12.1			
	X12.2			

Type “positive X limit”, and hit Enter button.

After typing the symbol name, annotate the address. The edit box will pop up, with the three-click on the “comments” item at the X10.0 row.

No.	Address	Symbol Name	Note	
	X9.2			
	X9.3			
	X9.4			
	X9.5			
	X9.6			
	X9.7			
	X10			
27	X10.0	X Positive limi		
	X10.1			
	X10.2			
	X10.3			
	X10.4			
	X10.5			
	X10.6			
	X10.7			
	X11			
	X11.0			
	X11.1			
	X11.2			
	X11.3			
	X11.4			
	X11.5			
	X11.6			
	X11.7			
	X12			
	X12.0			
	X12.1			
	X12.2			

Type “positive X limit, active high” in the edit box, and hit Enter button.

No.	Address	Symbol Name	Note	
	X9.2			
	X9.3			
	X9.4			
	X9.5			
	X9.6			
	X9.7			
	X10			
27	X10.0	X Positive limi	X Positive limi Active high	
	X10.1			
	X10.2			
	X10.3			
	X10.4			
	X10.5			
	X10.6			
	X10.7			
	X11			
	X11.0			
	X11.1			
	X11.2			
	X11.3			
	X11.4			
	X11.5			
	X11.6			
	X11.7			
	X12			
	X12.0			
	X12.1			
	X12.2			

Then defining the symbol name of X10, and annotating X10.0 are complete.

Delete Symbol List

When the symbol name and comments of X10.0 are not needed, delete them.

Select “X10.0” in the column of address, and hit Delete button, to delete X10.0 from the list.

No.	Address	Symbol Name	Note	
	X9.2			
	X9.3			
	X9.4			
	X9.5			
	X9.6			
	X9.7			
	X10			
27	X10.0	X Positive limi	X Positive limi	Active high
	X10.1			
	X10.2			
	X10.3			
	X10.4			
	X10.5			
	X10.6			
	X10.7			
	X11			
	X11.0			
	X11.1			
	X11.2			
	X11.3			
	X11.4			
	X11.5			
	X11.6			
	X11.7			
	X12			
	X12.0			
	X12.1			
	X12.2			

Ladder Diagram Operation

The ladder diagram is composed of rows which themselves have up to 10 cells.

插入元件 Inserting Component


Inserting components can be separated into two types: inserting basic components and inserting functional components.

➤ Inserting basic components

- (1) When you want to insert basic component, first select a position on the ladder diagram.



- (2) Click the basic component to be inserted on the toolbar.




- (3) Then the component is inserted in the ladder diagram.




➤ Inserting functional components


- (1) Select the functional components needed from the primitive tree.



Or select it from the selection box of component on the toolbar.




- (2) Double-left click the ladder diagram, then the functional component is inserted.




Deleting Component

Select the component to be deleted in the ladder diagram, and hit Delete button to delete it.



Deleting Multi-row

Select the rows needed to be deleted. (Drag the mouse to select the area to be deleted)



Hit Delete button to delete the selected area.


Cutting, Copying and Pasting Component

First select a component in the ladder diagram.




Then choose “Cut” or “Copy” in the “Edit” menu. Or right-click the component to be cut or copied, and select “Cut” or “Copy”.

➤ The first way




➤ The second way

At last, paste the component on other locations.




Cutting, Copying and Pasting Multi-row


The first step: drag the mouse to select the rows to be cutted or copied.




The second step: click “Cut” or “Paste” in the menu. Or right-click the component to be cut or copied, and click “Cut” or “Paste”.




The third step: select somewhere on the ladder diagram.






The forth step: Click “Paste”




Insert Row

A row can be inserted before the position selected in the ladder diagram.



Delete Row

Can delete a row selected in the diagram.



Undo



Using this button in the toolbar to undo the previous operations

Redo



Select this button on the toolbar to recover the undone operations.

Conversion



Using this button to convert the current ladder diagram to the corresponding statement list. If there are errors in the ladder diagram, the message box showing error information will pop up.

Output




Using this button to convert the current ladder diagram to the corresponding statement list, and output the plc.dit file (execution file of ladder diagram). If there are errors in the ladder diagram, the message box showing error information will pop up.


Statement List Operation

Edit


In the statement list, type characters directly to edit the statement list.



After a line of statement has been typed and the cursor is moved away, the system will check and arrange the line.




If there are errors in this line, the statement list will annotate the errors.



Cut, Copy and Paste

Use the mouse to drag on the statement list, to select some statements.



Then use Cut, Copy and Paste in the menu, to work accordingly.

Conversion



Select this button on the toolbar, to convert the current statement list to the corresponding ladder diagram.

Output



Hit this button on the toolbar to convert the current ladder diagram to the corresponding statement list, and output the plc.dit file (execution file of ladder diagram).

Appendix A

➤ Panel of 818A lathe

	0	1	2	3	4	5	6	7
X480	Auto	Single block	Manual	Increment	Reference home	Chuck release/clamping	Internal/External clamping	Dry run
X481	Block skip	Option stop	MST Lock	Machine Lock	Tailstock loosening/tightening	Hydraulic start	Feed hold II	Manual tool changing
X482		—X		x1	x10	x100	x1000	Lamp
X483	Protective door	—Z	Fast forward	+Z	Spindle Jog	Cooling	Lubrication	Spindle upshift
X484	Chip removal CW	Chip removal CCW		+X		Spindle CW	Spindle stop	Spindle CCW
X485	Spindle downshift		Overtravel release					
X486	Rapid override				Cycle start	Feed hold		
X487	Spindle override							
X488	Handwheel emergency stop, Handwheel axis selection, and Handwheel rate							
X489	Feedrate override							
X490	Incremental pulse per cycle for handwheel							
X491								

➤ Panel of 818A milling machine

	0	1	2	3	4	5	6	7
X480	Auto	Single block	Manual	Increment	Reference home	Tool changing permission	Tool clamping	Dry run
X481	Block skip	Option stop	Z-axis lock	Machine Lock	Protective door	Lamp	Feed hold II	Manual tool changing
X482	+4	+Z	—Y	x1	x10	x100	x1000	F1
X483	F2	+X	Fast forward	—X	Spindle orientation	Spindle Jog	Spindle brake	Cooling
X484	F3	F4	+Y	—Z	—4	Spindle CW	Spindle stop	Spindle CCW
X485	Lubrication		Overtravel release					
X486	Rapid override				Cycle start	Feed hold		
X487	Spindle override							
X488	Handwheel emergency stop, Handwheel axis selection and Handwheel rate							
X489	Feedrate override							
X490	Incremental pulse per cycle for handwheel							
X491								

➤ Panel of 818B lathe

	0	1	2	3	4	5	6	7
X480	Auto	Single block	Manual	Increment	Reference home	Chuck clamping	Tailstock loosening /tightening	Dry run
X481	Block skip	Option stop	MST Lock	Machine Lock	Center rest	Tailstock joint	Feed hold II	Manual tool changing
X482				0%	25%	Spindle CW	Spindle stop	Spindle CCW
X483	Lamp	+C	—Y		50%	100%	Spindle Jog	Spindle upshift
X484	Spindle downshift	Protective door	—X	Fast forward	+X	F1	F2	Cooling
X485	Lubrication	Hydraulic start	Auto power off		+Y	—C	F3	F4
X486	Chip removal CW	Chip removal stop	Chip removal CCW	Overtravel release	Cycle start	Feed hold		
X487	Spindle override							
X488	Handwheel emergency stop, Handwheel axis selection, and Handwheel rate							
X489	Feedrate override							
X490	Incremental pulse per cycle for handwheel							
X491								

➤ Panel of 818B milling machine

	0	1	2	3	4	5	6	7
X480	Auto	Single block	Manual	Increment	Reference home	Tool changing permission	Tool clamping	Dry run
X481	Block skip	Option stop	Z-axis lock	Machine Lock			Tool magazine CW	Tool magazine CCW
X482	X	Y	Z	0%	25%	Spindle CW	Spindle stop	Spindle CCW
X483	Lamp	A	B	C	50%	100%	Spindle orientation	Spindle Jog
X484	Spindle brake	Protective door	7	8	9	F1	F2	Cooling
X485	Lubrication	Chip blowing	Auto power off	—	Fast forward	+	F3	F4
X486	Chip removal CW	Chip removal stop	Chip removal CCW	Overtravel release	Cycle start	Feed hold		
X487	Spindle override							
X488	Handwheel emergency stop, Handwheel axis selection, and Handwheel rate							
X489	Feedrate override							
X490	Incremental pulse per cycle for handwheel							
X491								

