

Common Clinical and Laboratory Errors

Problem	Cause	Management
<p>Poor marginal fit of the crown/fixed bridge retainer</p> <p>Consequences include an increased risk of:</p> <ul style="list-style-type: none"> • Plaque retention • Secondary caries • Localised periodontitis • Cement dissolution • Poor aesthetics 	<p>Clinical related:</p> <ul style="list-style-type: none"> • Inaccurate impression • Poor gingival retraction • Inadequate marginal preparation <p>Laboratory related:</p> <ul style="list-style-type: none"> • Dye was damaged during pouring up of casts • Poor dye trimming • Inaccurate identification of the finish line • Casting bleb on the fit surface • Damage to adjacent teeth proximal surfaces during cast sectioning. The crown will not seat due to tight contacts • No dye spacer • Inaccurate wax up 	<p>Clinical:</p> <ul style="list-style-type: none"> • Retake the impression • Re-define the margins, ensuring sufficient proximal and axial reduction <p>Laboratory</p> <ul style="list-style-type: none"> • Communicate the problem with the laboratory
<p>Crown/fixed bridge retainer not seating</p> <p>Consequences include an increased risk of:</p> <ul style="list-style-type: none"> • Patient discomfort • Plaque retention • Secondary caries • Localised periodontitis • If not identified, this may lead to unnecessary occlusal adjustments 	<p>Clinical related:</p> <ul style="list-style-type: none"> • Inaccurate impression • Undercuts in the final preparation • Insufficient taper of the axial walls • Drifting/tilting of adjacent teeth due to loss of the temporary crown and the patient not seeking re-temperisation (e.g. if the tooth is previously root canal treated and asymptomatic, the patient is less likely to seek re-temperisation) • A poor/open contact point on a long term temporary crown can result in minimal drifting of the adjacent teeth, reducing the interproximal space available <p>Laboratory related:</p> <ul style="list-style-type: none"> • Damage to adjacent tooth dental stone • Dye abrasion caused by repeated crown insertion and removal • No dye spacer • Casting bleb on the fit surface • Poor dye trimming • Inaccurate wax up 	<p>Clinical:</p> <ul style="list-style-type: none"> • Retake the impression • Check for undercuts in the final preparation • Ensure 4-6 degree tapered axial walls • Ensure good contact points on the temporary crown • Minimal interproximal reduction with a high speed handpiece • If the dye is worn, consider using 'occlude' spray to identify the undercut area on the tooth preparation • Laboratory • If it is unmanageable chairside, communicate the problem with the laboratory
<p>Occlusal interferences of the crown/onlay/bridge retainer/bridge pontic</p> <p>Consequences include an increased risk of:</p> <ul style="list-style-type: none"> • Post-operative pain on biting • Occlusal trauma • Crown/onlay/bridge retainer/bridge pontic fracture • Opposing tooth cuspal fracture • Decementation • Bruxism 	<p>Clinical related:</p> <ul style="list-style-type: none"> • Inaccurate impression • Insufficient occlusal reduction • Inaccurate bite registration • Poor planning and clinical assessment <p>Laboratory related:</p> <ul style="list-style-type: none"> • Damage to the opposing tooth dental stone • No dye spacer • Casting bleb on the fit surface • Poor dye trimming • Inaccurate wax up leading to greater thickness of the restoration 	<p>Clinical:</p> <ul style="list-style-type: none"> • Retake the impression • Ensure the appropriate occlusal reduction has been carried out. This depends on the material of the indirect restoration • If the casts cannot be hand articulated, take a facebow. Also, ensure translucency of the cusp tip areas in the set bite registration paste • Take a comprehensive occlusal assessment • Minor interferences can be adjusted chairside prior to cementation <p>Laboratory:</p> <ul style="list-style-type: none"> • If it is unmanageable chairside, communicate the problem with the laboratory