



ENGINE PERFORMANCE REPORT

APL ANTWERP

Engine : Main Engine

Performance Date : Jul 3rd 2023

Evaluation Report

Evaluation Report - Main Report

Parameter	Alerts	Comments / Recommendation
Pscav	Low	1. Check the turbocharger casings assembly. 2. Clean the turbocharger filter. 3. Chemical cleaning required for Air coolers. 4. Check the compressor axial clearance because during overhauling the bearing assembly are not correct.
Tscav	Normal	
Pmax	Very High	1. Exhaust valve opening too late.i.e incorrect exhaust valve timing/Check the Exhaust valve opening timing. 2. Overload of the engine/Check the load of the engine.
Pcomp	Very Low	1. Piston rings (leaking)/Replace the Piston Rings. 2. Piston crown (Burnt)/Check the piston crown by means of the template. 3. Cylinder liner (Worn)/Check the liner by means of the measuring tool. 4. Leaking Exhaust Valve/ Replace or overhaul the valve. 5. Exhaust valve (Timing) may be wrong/Check the valve Timing. 6. Piston rod and stuffing box (leaking)/ Overhaul the stuffing box.
Exhaust Temperature	Very Low	1. Falling scavenge air temperature./Check the sea water system thermostat valve is functioning correctly. 2. Air/gas/steam in fuel system./Check the suction side of the supply pump for air leakage, Check the fuel oil supply pump and circulating pump pressures, Check the function of the de-aerating valve,Check the fuel oil preheater for steam leakage.
Exhaust Gas Temperature T/C Inlet	Normal	
Exhaust Gas Temperature T/C Outlet	Normal	
SFOC	Normal	
TC Inlet-TC Outlet	Very Low	
Torque Rich Index	Within Range	

Evaluation Report - Unit wise Report

Parameter	Alerts	Comments / Recommendation
No records found		

Performance Chart


Group

All Group Selected

Chart

All Chart Selected

Pmax Vs Cylinders



Cylinder	Pmax (Bar)		
	Measured	Average	Deviation
Performance Date - 03-Jul-2023			
1	400	400	0
2	400	400	0
3	400	400	0
4	400	400	0
5	400	400	0
6	400	400	0
7	400	400	0
8	400	400	0
9	400	400	0
10	400	400	0
11	400	400	0

