

Transformer Project: Task 1

EEE2044S – Power Engineering



Prepared By:

Group B: Number 63

Ronak Mehta - MHTRON001

Vikyle Naidoo - NDXVIK005

Kyle Segal - SGLKYL001

Faculty of Engineering and the Built Environment

13th August 2018

AIM:

The aim of this task is to design a transformer by means of analytical design equations.

CALCULATIONS:

1) Use the VA rating and voltage ratio to determine the rated primary and secondary currents

Power rating: 3VA

Primary Voltage: 30V

Secondary Voltage: 12V

- **Primary Current:**

$$P = IV$$

$$I = \frac{P}{V} = \frac{3VA}{30V}$$

$$\underline{I_{\text{primary}} = 0.1A}$$

- **Secondary Current:**

$$P = IV$$

$$I = \frac{P}{V} = \frac{3VA}{12V}$$

$$\underline{I_{\text{secondary}} = 0.25A}$$

2) Use the magnetization curves provided in the appendix to choose a suitable magnetic operation point for the transformer core. Justify your choice

We have chosen the point (100, 0.65); $H=100\text{At/m}$ and $B=0.65\text{T}$

This point was chosen because it is in the linear region of the B-H curve and therefore hasn't saturated at this point.

3) Choose a suitable value for N_1 and solve for A. N_1 should not exceed 500 turns and number of laminations also should not exceed 80 laminations. (Hint: Use $V_1 = 4.44fN_1B_{\text{max}}A$)

Chose $N_1 = 209$ turns

$$V_1 = 4.44fN_1B_{\text{max}}A$$

$$A = V_1 / 4.44f N_1 B_{\text{max}}$$

$$A = 30 / (4.44)(50)(209)(0.65)$$

$$\Rightarrow \underline{A = (0.9947 \cdot 10^{-3}) \text{ m}^2}$$

4) Assume a stacking factor $K_s=0.98$, calculate the physical cross-sectional area. K_s is the ratio of magnetic steel area available for flux and the physical cross sectional area of the laminations with their insulation coating.

$$A_{\text{physical}} = (1.02)(0.9947 \times 10^{-3})$$

$$\underline{A_{\text{physical}} = (1.014 \times 10^{-3}) \text{ m}^2}$$

5) Using the physical cross sectional area, calculate the core depth and the number of laminations required for your transformer, given that the thickness of one lamination is 0.5mm

$$\text{Depth, } d = A / 25.4 \times 10^{-3}$$

$$d = 1.014 \times 10^{-3} / 25.4 \times 10^{-3} = (39.95 \times 10^{-3}) \text{ m}$$

$$\underline{d = 40 \text{ mm}}$$

1 layer = 0.5mm thick

? layer = 40 mm

⇒ 80 laminations needed

6) Use the above information along with the number of turns and size of the transformer window to choose an appropriate size for each winding. Note that the allowable current density for a winding is approximately 3 A/mm^2 . (Hint: you can use the attached American Wire Gauge conversion table to determine the appropriate wire diameter)

Winding 1:

$$I_1 = 0.1 \text{ A and } I_{1\text{max}} = 0.141 \text{ A}$$

$$\text{Current Density} = I / A_w = 3 \text{ A/mm}^2$$

$$A_w = 0.141 / 3 = \underline{0.047 \text{ mm}^2}$$

Thus, reading off the chart:

⇒ Choose AWG N° = 30

Winding 2:

$$I_2 = 0.25 \text{ A and } I_{2\text{max}} = 0.354 \text{ A}$$

$$\text{Current Density} = I / A_w = 3 \text{ A/mm}^2$$

$$A_w = 0.354 / 3 = \underline{0.118 \text{ mm}^2}$$

Thus, reading off the chart:

⇒ Choose AWG N° = 26