

1. Project organization

After configuring “[Servo_Firmware.ioc](#)” file and generating code with STM32CubeMx, some code is inserted in sections “[USER CODE BEGIN/USER CODE END](#)” in some files. And all non STM32CubeMx generated source files are added in “[Servo_Firmware/Core/Src/App/](#)” directory.

This section is about:

1. File “[Servo_Firmware.ioc](#)”
2. Inserted code in sections “[USER CODE BEGIN/USER CODE END](#)”
3. Non STM32CubeMx generated source files (in “[Servo_Firmware/Core/Src/App/](#)”)

1.1 Notes to “[Servo_Firmware.ioc](#)” file

NVIC Controller configuration:

NVIC		Code generation		
NVIC Interrupt Table		Enabled	Preemption Priority	Sub Priority
Non maskable interrupt		<input checked="" type="checkbox"/>	0	0
Hard fault interrupt		<input checked="" type="checkbox"/>	0	0
Memory management fault		<input checked="" type="checkbox"/>	0	0
Prefetch fault, memory access fault		<input checked="" type="checkbox"/>	0	0
Undefined instruction or illegal state		<input checked="" type="checkbox"/>	0	0
System service call via SWI instruction		<input checked="" type="checkbox"/>	0	0
Debug monitor		<input checked="" type="checkbox"/>	0	0
Pendable request for system service		<input checked="" type="checkbox"/>	0	0
PVD interrupt through EXTI line 16		<input type="checkbox"/>	0	0
Flash global interrupt		<input type="checkbox"/>	0	0
RCC global interrupt		<input type="checkbox"/>	0	0
EXTI line1 interrupt		<input checked="" type="checkbox"/>	0	0
USB high priority or CAN TX interrupts		<input type="checkbox"/>	0	0
TIM2 global interrupt		<input type="checkbox"/>	0	0
TIM4 global interrupt		<input checked="" type="checkbox"/>	0	0
TIM3 global interrupt		<input checked="" type="checkbox"/>	1	0
ADC1 and ADC2 global interrupts		<input checked="" type="checkbox"/>	2	0
USB low priority or CAN RX0 interrupts		<input checked="" type="checkbox"/>	3	0
Time base: System tick timer		<input checked="" type="checkbox"/>	4	0

Interrupts “[EXTI line 1](#)” and “[TIM4 global](#)” are responsible to PWM input signal (position signal input to board) length measurement and timeout. They have equal highest interrupt priority, interrupting them with anything what takes significant amount of MCU cycles will lead to incorrect input signal length calculation, thus incorrect position or vibration.

Interrupt “[TIM3 global](#)” calls PID calculation on every overflow. PID calculation interruption with EXTI1/TIM4 interrupts could not cause any problem. Because TIM3 is

running in continuous mode and its countdown is going even while its interrupt handler is executing or when this handler is interrupted by another interrupt. Assuming that signal interrupts take very small amount of MCU cycles, handlers of these interrupts as well as PID calculation interrupt handler will exit timely before next "TIM3 global" interrupt occurs.

Next lower priority is USB, not sure how its interruption with all above interrupts can affect normal operation, but even anything such occurs, we will notice it by lost or incorrect data at MCU or PC side. I have not yet observed anything such.

Next and lowest priority has "Time base: System tick timer". We use this interrupt for functions delay of which for some time will not affect system operation:

- Calling device input signal timeout function (indicates "signal lost")
- LED timeout function in position change mode
- motor timeout function when it is being testing from PC app (forward/backward rotation via PC app buttons)

ADC1 configuration:

ADC1 is used for detecting potentiometer position, by measuring voltage on it. As you can notice here, "Vrefint" channel is not used for voltage calculation accuracy and we don't actually calculate ADC input voltage at all. If there was any need in measuring of actual voltage to calculate position, it would have terrible drift without Vrefint taking in account. But because of input voltage to potentiometer is equal to microcontroller VDD voltage (not taking in account voltage drop on wires and any electrical noise on them), ADC results will always represent potentiometer position besides of actual VDD value.

1.1 Inserted code in sections "USER CODE BEGIN/USER CODE END"

.