

ND NORSK DATA	ENGINEERING CHANGE ORDER		PAGE 1 OF 6
	ECO NO.: 100-766		
VALID FOR	PART NOs. : 324574 VERSIONS : BB NAME : TELEFIX DRIVER PRINT NOs.: 1844 ND NOs. : --		
NEW VERSION	PART NOs. : 324574 VERSIONS : CB NAME : TELEFIX DRIVER		
SYMPTOMS	<u>LAYOUT ERROR:</u> Telefix and console are not working.		
COMPO- NENTS	REMOVE:	INSERT:	Part No.
VALIDITY	X EQUIPMENT IN PRODUCTION X FUTURE PRODUCTION * FIELD ACTION		
RESPONS- IBILITY	APPROVED BY: ERIK DATE: 890823	REVISION: _____ DATE: _____	ISSUED BY: _____ _____

ND NORSK DATA	ENGINEERING CHANGE ORDER	PAGE 2 OF 6.
PART NO.: 324574	BB > CB	ECO NO.: 100-766
ISSUED	DATE: 871006	BY (INITIALS): AMA

Remove connection	13x.101y - 14x.101y	(Ac 3 - U12/9)	S
Remove connection	5x.100y - 14x.100y	(Ac 2 - U12/10)	S

Connect	13x.100y - 14x.100y	(- Ac 2)
Connect	5x.100y - 14x.101y	(- Ac 3)

Connect	8x. 92y - 10x. 93y	(U25/1 - U25/15)
Connect	8x.104y - 10x.105y	(U26/1 - U26/15)

