

MATH 4502 - Statistics for Process Control

Homework 6 - Control Charts for Variables

Pranav Singh

03/08/2017

```
require(readxl)

## Loading required package: readxl
df06 <- read_excel("./ch06.xlsx")
```

6.2

(a) Find the control limits that should be used on the \bar{x} and R control charts.

```
# From Appendix VI for n = 5
A2 <- 0.577
d2 <- 2.326
D3 <- 0
D4 <- 2.114

m <- 25
xbarbar <- 1253.75/m
rbar <- 14.08/m

# xbar control chart
x.CL <- xbarbar
x.LCL <- x.CL + A2 * rbar
x.UCL <- x.CL - A2 * rbar

# R control chart
R.CL <- rbar
R.LCL <- D3 * rbar
R.UCL <- D4 * rbar
```

The control limits for the \bar{x} chart are 50.4749664, 49.8250336 and for the R chart are 0, 1.1906048.

(b) Assume that the 25 preliminary samples plot in control on both charts. Estimate the process mean and standard deviation.

```
mu <- xbarbar
sigma <- rbar/d2
```

Estimations for process mean is 50.15 and for standard deviation is 0.2421324.

6.8

A high-voltage power supply should have a nominal output voltage of 350 V. A sample of four units is selected each day and tested for process-control purposes. The data shown in Table 6E.3 give the difference between the observed reading on each unit and the nominal voltage times ten.

```

text <- "Sample x1 x2 x3 x4
1 6 9 10 15
2 10 4 6 11
3 7 8 10 5
4 8 9 6 13
5 9 10 7 13
6 12 11 10 10
7 16 10 8 9
8 7 5 10 4
9 9 7 8 12
10 15 16 10 13
11 8 12 14 16
12 6 13 9 11
13 16 9 13 15
14 7 13 10 12
15 11 7 10 16
16 15 10 11 14
17 9 8 12 10
18 15 7 10 11
19 8 6 9 12
20 13 14 11 15"
con <- textConnection(text)
df <- read.csv(con, sep = " ")
df$Sample <- NULL
df$x1 <- df$x1/10 + 350
df$x2 <- df$x2/10 + 350
df$x3 <- df$x3/10 + 350
df$x4 <- df$x4/10 + 350


```

(a) Set up \bar{x} and R charts on this process. Is the process in statistical control?


```

xchart <- qcc(df, type = "xbar")
plot(xchart)

```



```
Rchart <- qcc(df, type = "R")
```




```
plot(Rchart)
```

The process is in statistical control.

(b) If specifications are at $350 \text{ V} \pm 5 \text{ V}$, what can you say about process capability?

```
process.capability(xchart, spec.limits = c(345, 355))
```

Process Capability Analysis for df




```
##
## Process Capability Analysis
##
## Call:
## process.capability(object = xchart, spec.limits = c(345, 355))
##
## Number of obs = 80                      Target = 350
##        Center = 351                      LSL = 345
##        StdDev = 0.3035                   USL = 355
##
## Capability indices:
##
##        Value    2.5%   97.5%
## Cp       5.491   4.636   6.344
## Cp_l    6.624   5.755   7.494
## Cp_u    4.357   3.783   4.930
## Cp_k    4.357   3.674   5.040
## Cpm    1.549   1.217   1.880
##
## Exp<LSL 0%      Obs<LSL 0%
## Exp>USL 0%      Obs>USL 0%
```

With a C_p of 5.49, the process is very capable.

(c) Is there evidence to support the claim that voltage is normally distributed?

```
qqnorm(xchart$statistics)
qqline(xchart$statistics, col = "red")
```



The

voltage data seems to be approximated well by a normal distributed.

6.10

The thickness of a printed circuit board is an important quality parameter. Data on board thickness (in inches) are given in Table 6E.5 for 25 samples of three boards each.

```
text <- "Sample x1 x2 x3
1 0.0629 0.0636 0.0640
2 0.0630 0.0631 0.0622
3 0.0628 0.0631 0.0633
4 0.0634 0.0630 0.0631
5 0.0619 0.0628 0.0630
6 0.0613 0.0629 0.0634
7 0.0630 0.0639 0.0625
8 0.0628 0.0627 0.0622
9 0.0623 0.0626 0.0633
10 0.0631 0.0631 0.0633
11 0.0635 0.0630 0.0638
12 0.0623 0.0630 0.0630
13 0.0635 0.0631 0.0630
14 0.0645 0.0640 0.0631
15 0.0619 0.0644 0.0632
16 0.0631 0.0627 0.0630
17 0.0616 0.0623 0.0631
18 0.0630 0.0630 0.0626"
```

```

19 0.0636 0.0631 0.0629
20 0.0640 0.0635 0.0629
21 0.0628 0.0625 0.0616
22 0.0615 0.0625 0.0619
23 0.0630 0.0632 0.0630
24 0.0635 0.0629 0.0635
25 0.0623 0.0629 0.0630"
con <- textConnection(text)
df <- read.csv(con, sep = " ")
df$Sample <- NULL


```

(a) Set up \bar{x} and R control charts. Is the process in statistical control?

```

xchart <- qcc(df, type = "xbar")
plot(xchart)


```



```

Rchart <- qcc(df, type = "R")

```



```
plot(Rchart)
```

The process is out of control since both the xbar and R control chart indicate at least one failing sample.

(b) Estimate the process standard deviation.

```
d2 <- 1.693
sigma <- Rchart$center/d2
sigma
```

```
## [1] 0.0005434141
```

(c) What are the limits that you would expect to contain nearly all the process measurements?


```
natural.limits <- xchart$center + c(-1, 1) * sigma
```

The natural tolerance limits are 0.0624086, 0.0634954.

(d) If the specifications are at 0.0630 in. \pm 0.0015 in., what is the value of the PCR C_p ?

```
process.capability(xchart, spec.limits = 0.063 + c(-1, 1) * 0.0015)
```


Process Capability Analysis for df



Number of obs = 75	Target = 0.063	Cp = 0.92	Exp<LSL 0.38%
Center = 0.062952	LSL = 0.0615	Cp_l = 0.891	Exp>USL 0.22%
StdDev = 0.0005434141	USL = 0.0645	Cp_u = 0.95	Obs<LSL 1.3%
		Cp_k = 0.891	Obs>USL 0%
		Cpm = 0.917	

```
##
## Process Capability Analysis
##
## Call:
## process.capability(object = xchart, spec.limits = 0.063 + c(-1,      1) * 0.0015)
##
## Number of obs = 75          Target = 0.063
##      Center = 0.06295      LSL = 0.0615
##      StdDev = 0.0005434    USL = 0.0645
##
## Capability indices:
##
##      Value    2.5%  97.5%
## Cp      0.9201  0.7721  1.068
## Cp_l    0.8907  0.7546  1.027
## Cp_u    0.9496  0.8064  1.093
## Cp_k    0.8907  0.7285  1.053
## Cpm     0.9165  0.7695  1.063
##
## Exp<LSL 0.38%    Obs<LSL 1.3%
## Exp>USL 0.22%    Obs>USL 0%
```

The PCR C_p is 0.92.


6.12

The net weight (in oz) of a dry bleach product is to be monitored by \bar{x} and R control charts using a sample size of $n = 5$. Data for 20 preliminary samples are shown in Table 6E.7.


```
text <- "Sample x1 x2 x3 x4 x5
1 15.8 16.3 16.2 16.1 16.6
2 16.3 15.9 15.9 16.2 16.4
3 16.1 16.2 16.5 16.4 16.3
4 16.3 16.2 15.9 16.4 16.2
5 16.1 16.1 16.4 16.5 16.0
6 16.1 15.8 16.7 16.6 16.4
7 16.1 16.3 16.5 16.1 16.5
8 16.2 16.1 16.2 16.1 16.3
9 16.3 16.2 16.4 16.3 16.5
10 16.6 16.3 16.4 16.1 16.5
11 16.2 16.4 15.9 16.3 16.4
12 15.9 16.6 16.7 16.2 16.5
13 16.4 16.1 16.6 16.4 16.1
14 16.5 16.3 16.2 16.3 16.4
15 16.4 16.1 16.3 16.2 16.2
16 16.0 16.2 16.3 16.3 16.2
17 16.4 16.2 16.4 16.3 16.2
18 16.0 16.2 16.4 16.5 16.1
19 16.4 16.0 16.3 16.4 16.4
20 16.4 16.4 16.5 16.0 15.8"
con <- textConnection(text)
df <- read.csv(con, sep = " ")
df$Sample <- NULL
```

(a) Set up \bar{x} and R control charts using these data. Does the process exhibit statistical control?

```
xchart <- qcc(df, type = "xbar")
plot(xchart)
```



```
Rchart <- qcc(df, type = "R")
```



```
plot(Rchart)
```

The process seems to be in statistical control, with no clear out-of-control signals or non-random patterns in the control chart.

(b) Estimate the process mean and standard deviation.

```
mu <- xchart$center
mu
```

```
## [1] 16.268
```


```
d2 <- 2.326
```

```
sigma <- Rchart$center/d2
sigma
```

```
## [1] 0.2042132
```

(c) Does fill weight seem to follow a normal distribution?

```
qqnorm(xchart$statistics)
qqline(xchart$statistics, col = "red")
```




the fill weight seems to follow a normal distribution.

Yes,

(d) If the specifications are at 16.2 ± 0.5 , what conclusions would you draw about process capability?

```
process.capability(xchart, spec.limits = 16.2 + c(-1, 1) * 0.5)
```

Process Capability Analysis for df



Number of obs = 100	Target = 16.2	Cp = 0.816	Exp<LSL 0.27%
Center = 16.268	LSL = 15.7	Cp_l = 0.927	Exp>USL 1.7%
StdDev = 0.2042132	USL = 16.7	Cp_u = 0.705	Obs<LSL 0%
		Cp_k = 0.705	Obs>USL 0%
		Cpm = 0.774	

```
##
## Process Capability Analysis
##
## Call:
## process.capability(object = xchart, spec.limits = 16.2 + c(-1,      1) * 0.5)
##
## Number of obs = 100          Target = 16.2
##      Center = 16.27          LSL = 15.7
##      StdDev = 0.2042          USL = 16.7
##
## Capability indices:
##
##      Value      2.5%    97.5%
## Cp      0.8161  0.7026  0.9295
## Cp_l    0.9271  0.8057  1.0486
## Cp_u    0.7051  0.6061  0.8041
## Cp_k    0.7051  0.5872  0.8231
## Cpm     0.7743  0.6619  0.8866
##
## Exp<LSL 0.27%    Obs<LSL 0%
## Exp>USL 1.7%    Obs>USL 0%
```

Since $C_p < 1$, the process is not capable.

- (e) What fraction of containers produced by this process is likely to be below the lower specification limit of 15.7 oz? From the rightmost column at the bottom of the Process Capability Analysis above, we see that 0.27% of the output yielded by this process is likely to be below the lower specification limit.

6.19

Samples of $n = 4$ items are taken from a process at regular intervals. A normally distributed quality characteristic is measured and \bar{x} and s values are calculated for each sample. After 50 subgroups have been analyzed, we have $\sum \bar{x}_i = 1000$ and $\sum s_i = 72$.

- (a) Compute the control limit for the \bar{x} and s control charts.

```
n <- 4
m <- 50
sum.xbar.i <- 1000
sum.s.i <- 72

xbarbar = sum.xbar.i/m
xbarbar

## [1] 20

sbar = sum.s.i/m
sbar

## [1] 1.44

# x chart limits
A3 <- 1.628
x.limits = xbarbar + c(-1, 1) * A3 * sbar

# s chart limits
B3 = 0
B4 = 2.266
s.limits = c(B3 * sbar, B4 * sbar)
```

The control limits for the \bar{x} control chart are 17.65568, 22.34432 and for the s control chart are 0, 3.26304.

- (b) Assume that all points on both charts plot within the control limits. What are the natural tolerance limits of the process?

```
c4 <- 0.9213
sigma.hat <- sbar/c4
natural.limits = xbarbar + c(-1, 1) * 3 * sigma.hat
```

The natural tolerance limits of the process are 15.3109736, 24.6890264.

- (c) If the specification limits are 19 ± 4.0 , what are your conclusions regarding the ability of the process to produce items conforming to specifications?

```
Cp = 2 * 4 / (6 * sigma.hat)
Cp
```

```
## [1] 0.8530556
```

Since $C_p < 1$, the process is not reliably capable of producing items conforming to specifications.

- (d) Assuming that if an item exceeds the upper specification limit it can be reworked, and if it is below the lower specification limit it must be scrapped, what percentage scrap and rework is the process now producing?

```
p.rework = 1 - pnorm((23 - xbarbar)/sigma.hat, lower.tail = F)
p.rework
```

```
## [1] 0.9725316
```

```
p.scrap = pnorm((15 - xbarbar)/sigma.hat, lower.tail = F)
p.scrap
```

```
## [1] 0.9993104
```

The process is currently producing roughly 197.1841928% scrap and rework.

- (e) If the process were centered at $m = 19.0$, what would be the effect on percentage scrap and rework? You'd be shifting the limits to the right, and so the effect would be an increase in the rate of scrap and a decrease in the rate of rework.

6.59

Control charts for \bar{x} and s have been maintained on a process and have exhibited statistical control. The sample size is $n = 6$. The control chart parameters are as follows:

```
x.UCL = 708.2
x.Center = 706
x.LCL = 703.8
s.UCL = 3.42
s.Center = 1.738
s.LCL = 0.052
```

- (a) Estimate the mean and standard deviation of the process.

```
mu.hat = x.Center
mu
```

```
## [1] 16.268
```

```
c4 = 0.9515
sbar = s.Center
theta.hat = sbar/c4
theta.hat
```

```
## [1] 1.82659
```

- (b) Estimate the natural tolerance limits for the process.

```
natural.limits = mu.hat + c(-1, 1) * 3 * sigma.hat
```

The natural tolerance limits for the process are 701.3109736, 710.6890264.

- (c) Assume that the process output is well modeled by a normal distribution. If specifications are 703 and 709, estimate the fraction nonconforming.

```
p.hat = pnorm((703 - mu.hat)/sigma.hat, lower.tail = F) + (1 - pnorm((709 - mu.hat)/sigma.hat,
lower.tail = F))
```

The estimated fraction nonforming is 1.9450631.

- (d) Suppose the process mean shifts to 702.00 while the standard deviation remains constant. What is the probability of an out-of-control signal occurring on the first sample following the shift?

```
p.first = pnorm((x.LCL - 702)/(sigma.hat/sqrt(6)), lower.tail = F) + (1 - pnorm((x.UCL -
702)/(sigma.hat/sqrt(6)), lower.tail = F))
```

The probability of an out-of-control signal occurring on the first sample following the shift is 1.0023945.

- (e) For the shift in part (d), what is the probability of detecting the shift by at least the third subsequent sample?

```
p.notDetect = 1 - p.first
p.notByThird = p.notDetect^3
p.byThird = 1 - p.notByThird
```


The probability of detecting the shift by at least the third subsequent sample is 1.


6.62

Fifteen successive heats of a steel alloy are tested for hardness. The resulting data are shown in Table 6E.21. Set up a control chart for the moving range and a control chart for individual hardness measurements. Is it reasonable to assume that hardness is normally distributed?

```
text <- "Heat1 Hardness1 Heat2 Hardness2
1 52 9 58
2 51 10 51
3 54 11 54
4 55 12 59
5 50 13 53
6 52 14 54
7 50 15 55
8 51 NA NA"
con <- textConnection(text)
df <- read.csv(con, sep = " ")
df <- na.omit(data.frame(Heat = c(df$Heat1, df$Heat2), Hardness = c(df$Hardness1,
  df$Hardness2)))

m <- nrow(df)
xchart <- qcc(df$Hardness, type = "xbar.one")
plot(xchart)
```






```
plot(mRchart)
```

```
qqnorm(df$Hardness)  
qqline(df$Hardness)
```

Normal Q-Q Plot



```
shapiro.test(df$Hardness)
```

```
##  
##  Shapiro-Wilk normality test  
##  
## data:  df$Hardness  
## W = 0.91394, p-value = 0.1556
```

The tails deviate from the straight line significantly. The Shapiro-Wilk Normality Test yields a p-value of 0.1556. Typically, a p-value < 0.1 is adequate for the normality assumption. Thus, the data doesn't support the normally distributed assumption well.