



Cyprus
University of
Technology

EEN452 - Control and Operation of Electric Power Systems

Part 2B: Synchronous machine model (detailed)

<https://sps.cut.ac.cy/courses/een452/>

Dr Petros Aristidou

Department of Electrical Engineering, Computer Engineering & Informatics

Last updated: February 22, 2025

Extend the model of the synchronous machine considered in the previous lesson to ...


- ① ... add more details appropriate for dynamic studies;
- ② ... include the effect of damper windings;
- ③ ... be applicable to machines with salient-pole rotors (hydro power plants);

Much of the material was adapted from the courses delivered by Prof. Thierry Van Cutsem at the University of Liege.

In this lesson, we consider:

- a machine with a single pair of poles, for simplicity. This does not affect the electrical behaviour of the generator (it affects the moment of inertia and the kinetic energy of rotating masses)
- the general case of a **salient-pole** machine. For a round-rotor machine: set some parameters to the same value in the d and q axes (to account for the equal air gap width)
- the configuration with **four** rotor windings (f , d_1 , q_1 , q_2). For a salient-pole generator: remove the q_2 winding.

- 1 Modelling of machine with magnetically coupled circuits**
- 2 Park transformation and equations
- 3 Energy, power and torque
- 4 The synchronous machine in steady state
- 5 Nominal values, per unit system and orders of magnitudes



Stator windings (generator convention):

$$v_a(t) = -R_a i_a(t) - \frac{d\psi_a}{dt} \quad v_b(t) = -R_b i_b(t) - \frac{d\psi_b}{dt} \quad v_c(t) = -R_c i_c(t) - \frac{d\psi_c}{dt}$$

R_T : Resistance of (a,b,c) phase ψ_T : flux linkage in (a,b,c) phase

In matrix form:

$$\mathbf{v}_T = -\mathbf{R}_T \mathbf{i}_T - \frac{d\psi_T}{dt}$$

$$\mathbf{R}_T = \text{diag}(R_a \ R_a \ R_a)$$

Field windings (motor convention):

$$v_f(t) = R_f i_f(t) + \frac{d\psi_f}{dt}$$

$$0 = R_{d1} i_{d1}(t) + \frac{d\psi_{d1}}{dt}$$

$$0 = R_{q1} i_{q1}(t) + \frac{d\psi_{q1}}{dt}$$

$$0 = R_{q2} i_{q2}(t) + \frac{d\psi_{q2}}{dt}$$

R_r : Resistance of (f, d1, q1, q2) winding ψ_r : flux linkages in (f, d1, q1, q2) winding

In matrix form:


$$\mathbf{v}_r = -\mathbf{R}_r \mathbf{i}_r - \frac{d\psi_r}{dt}$$

$$\mathbf{R}_r = \text{diag}(R_f \ R_{d1} \ R_{q1} \ R_{q2})$$

Saturation being neglected, the fluxes vary linearly with the currents according to:

$$\begin{bmatrix} \psi_T \\ \psi_r \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{TT}(\theta_r) & \mathbf{L}_{Tr}(\theta_r) \\ \mathbf{L}_{Tr}^T(\theta_r) & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_T \\ \mathbf{i}_r \end{bmatrix}$$


- \mathbf{L}_{TT} and \mathbf{L}_{Tr} vary with the position θ_r of the rotor but \mathbf{L}_{rr} does not
- the components of \mathbf{L}_{TT} and \mathbf{L}_{Tr} are periodic functions of θ_r
- the space harmonics in θ_r are assumed negligible = sinusoidal machine assumption.



$$L_{TT}(\theta_r) =$$

$$\begin{bmatrix} L_0 + L_1 \cos(2\theta_r) & -L_m - L_1 \cos(2(\theta_r + \frac{\pi}{6})) & -L_m - L_1 \cos(2(\theta_r - \frac{\pi}{6})) \\ -L_m - L_1 \cos(2(\theta_r + \frac{\pi}{6})) & L_0 + L_1 \cos(2(\theta_r - \frac{2\pi}{3})) & -L_m - L_1 \cos(2(\theta_r + \frac{\pi}{2})) \\ -L_m - L_1 \cos(2(\theta_r - \frac{\pi}{6})) & -L_m - L_1 \cos(2(\theta_r + \frac{\pi}{2})) & L_0 + L_1 \cos(2(\theta_r + \frac{2\pi}{3})) \end{bmatrix}$$


$$L_0, L_1, L_m > 0$$



$$\mathbf{L}_T(\theta_r) =$$

$$\begin{bmatrix} L_{af} \cos(\theta_r) & L_{ad1} \cos(\theta_r) & L_{aq1} \sin(\theta_r) & L_{aq2} \sin(\theta_r) \\ L_{af} \cos(\theta_r - \frac{2\pi}{3}) & L_{ad1} \cos(\theta_r - \frac{2\pi}{3}) & L_{aq1} \sin(\theta_r - \frac{2\pi}{3}) & L_{aq2} \sin(\theta_r - \frac{2\pi}{3}) \\ L_{af} \cos(\theta_r + \frac{2\pi}{3}) & L_{ad1} \cos(\theta_r + \frac{2\pi}{3}) & L_{aq1} \sin(\theta_r + \frac{2\pi}{3}) & L_{aq2} \sin(\theta_r + \frac{2\pi}{3}) \end{bmatrix}$$

$$L_{af}, L_{ad1}, L_{aq1}, L_{aq2} > 0$$





- 1 Modelling of machine with magnetically coupled circuits
- 2 Park transformation and equations**
- 3 Energy, power and torque
- 4 The synchronous machine in steady state
- 5 Nominal values, per unit system and orders of magnitudes

- Flux linkages, induced voltages, and currents change continuously as the electric circuit is in relative motion – **very difficult to model and solve!**
- Mathematical transformations are often used to decouple variables and to solve equations involving time varying quantities by referring all variables to a common frame of reference
- Among the various transformation methods, the most well-known are:
 - Clarke Transformation
 - Park Transformation



2 Park and Clarke transformations

- **Clarke Transformation:** This transformation converts balanced three-phase quantities into balanced two-phase quadrature quantities.
- **Park Transformation:** This transformation converts vectors in balanced two-phase orthogonal stationary system into orthogonal rotating reference frame.



Three-phase reference frame



Two-phase reference frame




Rotating reference frame



The three reference frames considered in this implementation are:

- Three-phase reference frame, in which I_a , I_b , and I_c are co-planar three-phase quantities at an angle of 120 degrees to each other.
- Orthogonal stationary reference frame, in which I_α (along α axis) and I_β (along β axis) are perpendicular to each other, but in the same plane as the three-phase reference frame.
- Orthogonal rotating reference frame, in which I_d is at an angle θ (rotation angle) to the α axis and I_q is perpendicular to I_d along the q axis.




2 Clarke transformation

The three-phase quantities are translated from the three-phase reference frame to the two-axis orthogonal stationary reference frame using Clarke transformation¹:

$$\begin{bmatrix} \alpha \\ \beta \\ 0 \end{bmatrix} = \sqrt{\frac{2}{3}} \begin{bmatrix} 1 & -\frac{1}{2} & -\frac{1}{2} \\ 0 & \frac{\sqrt{3}}{2} & -\frac{\sqrt{3}}{2} \\ \sqrt{\frac{1}{2}} & \sqrt{\frac{1}{2}} & \sqrt{\frac{1}{2}} \end{bmatrix} \begin{bmatrix} a \\ b \\ c \end{bmatrix}$$

where:

- a , b , and c are three-phase quantities
- α and β are stationary orthogonal reference frame quantities
- 0 is the zero component of the two-axis system in the stationary reference frame



¹We use a power invariant version that preserves active and reactive power

The two-axis orthogonal stationary reference frame quantities are transformed into rotating reference frame quantities using Park transformation²:

$$\begin{bmatrix} d \\ q \\ 0 \end{bmatrix} = \underbrace{\sqrt{\frac{2}{3}} \begin{bmatrix} \cos(\theta_r) & \cos(\theta_r - \frac{2\pi}{3}) & \cos(\theta_r + \frac{2\pi}{3}) \\ \sin(\theta_r) & \sin(\theta_r - \frac{2\pi}{3}) & \sin(\theta_r + \frac{2\pi}{3}) \\ \sqrt{\frac{1}{2}} & \sqrt{\frac{1}{2}} & \sqrt{\frac{1}{2}} \end{bmatrix}}_{\mathcal{P}} \begin{bmatrix} a \\ b \\ c \end{bmatrix}$$

where:

- I_a , I_b , and I_c are three-phase quantities
- I_d and I_q are the components of the two-axis system in the rotating reference frame
- 0 is the zero component of the two-axis system in the stationary reference frame


²We use a power invariant version that preserves active and reactive power

Transforming the stator quantities gives:

$$\mathbf{v}_{dq0} = \mathcal{P} \mathbf{v}_{abc} \quad \mathbf{i}_{dq0} = \mathcal{P} \mathbf{i}_{abc} \quad \boldsymbol{\psi}_{dq0} = \mathcal{P} \boldsymbol{\psi}_{abc}$$

We can also see that:

$$\mathcal{P} \mathcal{P}^T = \mathbf{I} \Leftrightarrow \mathcal{P}^{-1} = \mathcal{P}^T$$



2 Park transformation


Total magnetic field created by the currents i_a , i_b , and i_c :

$$\text{projected on d axis: } k \left(\cos(\theta_r) i_a + \cos\left(\theta_r - \frac{2\pi}{3}\right) i_b + \cos\left(\theta_r - \frac{4\pi}{3}\right) i_c \right) = k \sqrt{\frac{3}{2}} i_d$$

$$\text{projected on q axis: } k \left(\sin(\theta_r) i_a + \sin\left(\theta_r - \frac{2\pi}{3}\right) i_b + \sin\left(\theta_r - \frac{4\pi}{3}\right) i_c \right) = k \sqrt{\frac{3}{2}} i_q$$

The Park transformation consists of replacing the (a , b , c) stator windings by three equivalent windings (d , q , 0):

- the d winding is attached to the d axis
- the q winding is attached to the q axis
- the currents i_d and i_q produce together the same magnetic field, to the multiplicative constant $\sqrt{\frac{3}{2}}$



Applying the Park transformation to the equations of slide 5, we get:

$$v_d = -R_a i_d - \dot{\theta}_r \psi_q - \frac{d\psi_d}{dt}$$

$$v_q = -R_a i_q + \dot{\theta}_r \psi_d - \frac{d\psi_q}{dt}$$

$$v_0 = -R_a i_0 - \frac{d\psi_0}{dt}$$

where:

$\dot{\theta}_r \psi_q$, $\dot{\theta}_r \psi_d$: speed voltages

$\frac{d\psi_d}{dt}$, $\frac{d\psi_q}{dt}$: transformer voltages

2 Park equations of the synchronous machine

Applying the Park transformation to the equations of slide 7, we get:

$$\begin{bmatrix} \psi_T \\ \psi_r \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{TT} & \mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^T & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_T \\ \mathbf{i}_r \end{bmatrix} \Leftrightarrow \begin{bmatrix} \mathcal{P}^{-1} \psi_P \\ \psi_r \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{TT} & \mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^T & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathcal{P}^{-1} \mathbf{i}_P \\ \mathbf{i}_r \end{bmatrix}$$

$$\begin{bmatrix} \psi_P \\ \psi_r \end{bmatrix} = \begin{bmatrix} \mathcal{P} \mathbf{L}_{TT} \mathcal{P}^{-1} & \mathcal{P} \mathbf{L}_{Tr} \\ \mathbf{L}_{Tr}^T \mathcal{P}^{-1} & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_P \\ \mathbf{i}_r \end{bmatrix} = \begin{bmatrix} \mathbf{L}_{PP} & \mathbf{L}_{Pr} \\ \mathbf{L}_{rP}^T & \mathbf{L}_{rr} \end{bmatrix} \begin{bmatrix} \mathbf{i}_P \\ \mathbf{i}_r \end{bmatrix}$$

$$\begin{bmatrix} \mathbf{L}_{PP} & \mathbf{L}_{Pr} \\ \mathbf{L}_{rP}^T & \mathbf{L}_{rr} \end{bmatrix} = \begin{bmatrix} L_{dd} & & L_{df} & L_{dd1} & & \\ & L_{qq} & & & L_{qq1} & L_{qq2} \\ & & L_{00} & & & \\ L_{df} & & & L_{ff} & L_{fd1} & \\ L_{dd1} & & & L_{fd1} & L_{d1d1} & \\ & L_{qq1} & & & & L_{q1q1} & L_{q1q2} \\ & L_{qq2} & & & & L_{q1q2} & L_{q2q2} \end{bmatrix}$$

*zero entries have been left empty for legibility

where:

$$\begin{aligned}L_{dd} &= L_0 L_m + \frac{3}{2} L_1 \\L_{qq} &= L_0 L_m - \frac{3}{2} L_1 \\L_{df} &= \sqrt{\frac{3}{2}} L_{af} \\L_{dd1} &= \sqrt{\frac{3}{2}} L_{ad1} \\L_{qq1} &= \sqrt{\frac{3}{2}} L_{aq1} \\L_{qq2} &= \sqrt{\frac{3}{2}} L_{aq2} \\L_{00} &= L_0 - 2L_m\end{aligned}$$

- As expected, all components are independent of the rotor position θ_r !
- There is no magnetic coupling between d and q axes (this was already assumed in \mathbf{L}_{Tr} and \mathbf{L}_{rr} : zero mutual inductances between coils with orthogonal axes).

2 Park equations of the synchronous machine

If we ignore the 0 component (is this a valid simplification?) and we group (d, f, d1) and (q, q1, q2), we get:

$$\begin{bmatrix} v_d \\ -v_f \\ 0 \end{bmatrix} = - \begin{bmatrix} R_a & & \\ & R_f & \\ & & R_{d1} \end{bmatrix} \begin{bmatrix} i_d \\ i_f \\ i_{d1} \end{bmatrix} - \begin{bmatrix} \dot{\theta}_r \psi_q \\ 0 \\ 0 \end{bmatrix} - \frac{d}{dt} \begin{bmatrix} \psi_d \\ \psi_f \\ \psi_{d1} \end{bmatrix}$$

$$\begin{bmatrix} v_q \\ 0 \\ 0 \end{bmatrix} = - \begin{bmatrix} R_a & & \\ & R_{q1} & \\ & & R_{q2} \end{bmatrix} \begin{bmatrix} i_q \\ i_{q1} \\ i_{q2} \end{bmatrix} + \begin{bmatrix} \dot{\theta}_r \psi_d \\ 0 \\ 0 \end{bmatrix} - \frac{d}{dt} \begin{bmatrix} \psi_q \\ \psi_{q1} \\ \psi_{q2} \end{bmatrix}$$

with the following flux-current relations:

$$\begin{bmatrix} \psi_d \\ \psi_f \\ \psi_{d1} \end{bmatrix} = \begin{bmatrix} L_{dd} & L_{df} & L_{dd1} \\ L_{df} & L_{ff} & L_{fd1} \\ L_{dd1} & L_{fd1} & L_{d1d1} \end{bmatrix} \begin{bmatrix} i_d \\ i_f \\ i_{d1} \end{bmatrix}$$

$$\begin{bmatrix} \psi_q \\ \psi_{q1} \\ \psi_{q2} \end{bmatrix} = \begin{bmatrix} L_{qq} & L_{qq1} & L_{qq2} \\ L_{qq1} & L_{q1q1} & L_{q1q2} \\ L_{qq2} & L_{q1q2} & L_{q2q2} \end{bmatrix} \begin{bmatrix} i_q \\ i_{q1} \\ i_{q2} \end{bmatrix}$$

- 1 Modelling of machine with magnetically coupled circuits
- 2 Park transformation and equations
- 3 Energy, power and torque**
- 4 The synchronous machine in steady state
- 5 Nominal values, per unit system and orders of magnitudes

$$p_T + p_{Js} + \frac{dW_{ms}}{dt} = p_{r \rightarrow s}$$

where

p_T : three-phase instantaneous power leaving the stator

p_{Js} : Joule losses in stator windings

W_{ms} : magnetic energy stored in the stator windings

$p_{r \rightarrow s}$: power transfer from rotor to stator (mechanical? electrical?)

Three-phase instantaneous power leaving the stator:

$$\begin{aligned} p_T(t) &= v_a i_a + v_b i_b + v_c i_c = v_d i_d + v_q i_q + v_0 i_0 \\ &= - \underbrace{\left(R_a i_d^2 + R_a i_q^2 + R_a i_0^2 \right)}_{p_{Js}} - \underbrace{\left(i_d \frac{d\psi_d}{dt} + i_q \frac{d\psi_q}{dt} + i_0 \frac{d\psi_0}{dt} \right)}_{dW_{ms}/dt} + \dot{\theta}_r (\psi_d i_q - \psi_q i_d) \\ &\Rightarrow p_{r \rightarrow s} = \dot{\theta}_r (\psi_d i_q - \psi_q i_d) \end{aligned}$$

$$P_m + p_f = p_{Jr} + \frac{dW_{mr}}{dt} + p_{r \rightarrow s} + \frac{dW_c}{dt}$$

where

P_m : mechanical power provided by the turbine

p_f : electrical power provided to the field winding (by the excitation system)

p_{Jr} : Joule losses in the rotor windings

W_{mr} : magnetic energy stored in the rotor windings

W_c : kinetic energy of all rotating masses

Instantaneous power provided to field winding:

$$p_f = v_f i_f = v_f i_f + v_{d1} i_{d1} + v_{q1} i_{q1} + v_{q2} i_{q2}$$

$$= \underbrace{\left(R_f i_f^2 + R_{d1} i_{d1}^2 + R_{q1} i_{q1}^2 + R_{q2} i_{q2}^2 \right)}_{p_{Jr}} + \underbrace{\left(i_f \frac{d\psi_f}{dt} + i_{d1} \frac{d\psi_{d1}}{dt} + i_{q1} \frac{d\psi_{q1}}{dt} + i_{q2} \frac{d\psi_{q2}}{dt} \right)}_{dW_{mr}/dt}$$

$$\Rightarrow P_m - \frac{dW_c}{dt} = \dot{\theta}_r (\psi_d i_q - \psi_q i_d)$$

$$J \frac{d^2 \theta_r}{dt^2} = T_m - T_e$$

where

J : moment of inertia of all the rotating masses

T_m : mechanical torque applied to the rotor by the turbine

T_e : electromagnetic torque applied to the rotor by the generator

Multiplying by $\dot{\theta}_r$:

$$J \dot{\theta}_r \ddot{\theta}_r = \dot{\theta}_r (T_m - T_e)$$

$$\frac{dW_c}{dt} = P_m - \dot{\theta}_r T_e$$

where

P_m : mechanical power applied to the rotor by the turbine

Hence, the (compact and elegant!) expression of the electromagnetic torque is:

$$T_e = \psi_d i_q - \psi_q i_d$$

$$T_e = L_{dd}i_d i_q + L_{df}i_f i_q + L_{dd1}i_{d1} i_q - L_{qq}i_q i_d - L_{qq1}i_{q1} i_d - L_{qq2}i_{q2} i_d$$

$(L_{dd} - L_{qq})i_d i_q$: synchronous torque due to rotor saliency

- exists in salient-pole machines only
- even without excitation ($i_f = 0$), the rotor tends to align its direct axis with the axis of the rotating magnetic field created by the stator currents, offering to the latter a longer path in iron
- a significant fraction of the total torque in a salient-pole generator

$L_{dd1}i_{d1} i_q - L_{qq1}i_{q1} i_d - L_{qq2}i_{q2} i_d$: damping torque

- due to currents induced in the damper windings
- zero in steady-state operation

$L_{df}i_f i_q$: only component involving the field current i_f

- the main part of the total torque in steady-state operation
- in steady state, it is the synchronous torque due to excitation
- during transients, the field winding also contributes to the damping torque

- 1 Modelling of machine with magnetically coupled circuits
- 2 Park transformation and equations
- 3 Energy, power and torque
- 4 The synchronous machine in steady state**
- 5 Nominal values, per unit system and orders of magnitudes

In steady-state we have:

- Balanced three-phase currents of angular frequency ω_N flow in the stator windings
- a direct current flows in the field winding subjected to a constant excitation voltage:

$$i_f = \frac{V_f}{R_f}$$

- the rotor rotates at the synchronous speed:

$$\theta_r = \theta_r^0 + \omega_N t$$

- no current is induced in the other rotor circuits:

$$i_{d1} = i_{q1} = i_{q2} = 0$$

$$\begin{aligned}i_a &= i_b = i_c = 0 \\ \Rightarrow i_d &= i_q = i_0 = 0 \\ \Rightarrow \psi_d &= L_{df} i_f \quad \text{and} \quad \psi_q = 0\end{aligned}$$

Park equations:

$$v_d = 0, \quad v_q = \omega_N \psi_d = \omega_N L_{df} i_f$$

Getting back to the stator voltages, e.g. in phase a :

$$v_a(t) = \sqrt{\frac{2}{3}} \omega_N L_{df} i_f \sin(\theta_r^0 + \omega_N t) = \sqrt{2} E_q \sin(\theta_r^0 + \omega_N t)$$

where:

$E_q = \frac{\omega_N L_{df} i_f}{\sqrt{3}}$: e.m.f. proportional to excitation current = RMS voltage at the terminal of the opened machine.

$$v_a(t) = \sqrt{2}V \cos(\omega_N t + \theta) \quad i_a(t) = \sqrt{2}I \cos(\omega_N t + \psi)$$

$$v_b(t) = \sqrt{2}V \cos(\omega_N t + \theta - \frac{2\pi}{3}) \quad i_b(t) = \sqrt{2}I \cos(\omega_N t + \psi - \frac{2\pi}{3})$$

$$v_c(t) = \sqrt{2}V \cos(\omega_N t + \theta + \frac{2\pi}{3}) \quad i_c(t) = \sqrt{2}I \cos(\omega_N t + \psi + \frac{2\pi}{3})$$

$$\begin{aligned} i_d &= \sqrt{\frac{2}{3}} \sqrt{2}I \left[\cos(\theta_r^0 + \omega_N t) \cos(\omega_N t + \psi) + \cos(\theta_r^0 + \omega_N t - \frac{2\pi}{3}) \cos(\omega_N t + \psi - \frac{2\pi}{3}) \right. \\ &\quad \left. + \cos(\theta_r^0 + \omega_N t + \frac{2\pi}{3}) \cos(\omega_N t + \psi + \frac{2\pi}{3}) \right] \\ &= \frac{I}{\sqrt{3}} \left[\cos(\theta_r^0 + 2\omega_N t + \psi) + \cos(\theta_r^0 + 2\omega_N t + \psi - \frac{4\pi}{3}) + \cos(\theta_r^0 + 2\omega_N t + \psi - \frac{4\pi}{3}) \right. \\ &\quad \left. + 3 \cos(\theta_r^0 - \psi) \right] = \sqrt{3}I \cos(\theta_r^0 - \psi) \end{aligned}$$

Similarly:

$$i_q = \sqrt{3}I \sin(\theta_r^0 - \psi) \quad i_0 = 0$$

$$v_d = \sqrt{3}V \cos(\theta_r^0 - \theta) \quad v_q = \sqrt{3}V \sin(\theta_r^0 - \theta) \quad v_0 = 0$$

In steady-state, i_d and i_q are constant. This was expected!

$$\psi_d = L_{dd}i_d + L_{df}i_f$$

$$\psi_q = L_{qq}i_q$$

The electromagnetic torque:

$$T_e = \psi_d i_q - \psi_q i_d$$

is constant. This is important from mechanical viewpoint (no vibrations!).

Park equations:

$$v_d = -R_a i_d - \omega_N L_{qq} i_q = -R_a i_d - X_q i_q$$

$$v_q = -R_a i_q - \omega_N L_{dd} i_d = -R_a i_q + X_d i_d + \sqrt{3}E_q$$

$$v_0 = 0$$

where

$X_d = \omega_N L_{dd}$: direct-axis synchronous reactance

$X_q = \omega_N L_{qq}$: quadrature-axis synchronous reactance

4 Phasor diagram


The Park equations become:

$$V \cos(\theta_r^0 - \theta) = -R_a I \cos(\theta_r^0 - \psi) - X_q I \sin(\theta_r^0 - \psi)$$

$$V \sin(\theta_r^0 - \theta) = -R_a I \sin(\theta_r^0 - \psi) + X_d I \cos(\theta_r^0 - \psi) + E_q$$


which are the projections on the d and q axes of the complex equation:

$$\underline{E}_q = \underline{V} + R_a \underline{I} + jX_d \underline{I}_d + jX_q \underline{I}_q$$



Round-rotor machine ($X_d = X_q = X$):

$$\underline{E}_q = \underline{V} + R_a \underline{I} + jX(\underline{I}_d + \underline{I}_q) = \underline{V} + R_a \underline{I} + jX \underline{I}$$



Not valid for a salient-pole generator!

$$\underline{E}_q = E_q e^{j(\theta_r^0 - \frac{\pi}{2})}$$

$$\underline{I}_d = I \cos(\theta_r^0 - \psi) e^{j\theta_r^0} = \frac{I_d}{\sqrt{3}} e^{j\theta_r^0}$$


$$\underline{I}_q = I \sin(\theta_r^0 - \psi) e^{j(\theta_r^0 - \frac{\pi}{2})} = -j \frac{I_q}{\sqrt{3}} e^{j\theta_r^0}$$

$$\underline{I} = \underline{I}_d + \underline{I}_q = \left(\frac{I_d}{\sqrt{3}} - j \frac{I_q}{\sqrt{3}} \right) e^{j\theta_r^0}$$

$$\underline{V}_d = V \cos(\theta_r^0 - \theta) e^{j\theta_r^0} = \frac{V_d}{\sqrt{3}} e^{j\theta_r^0}$$

$$\underline{V}_q = V \sin(\theta_r^0 - \theta) e^{j(\theta_r^0 - \frac{\pi}{2})} = -j \frac{V_q}{\sqrt{3}} e^{j\theta_r^0}$$

$$\underline{V} = \underline{V}_d + \underline{V}_q = \left(\frac{V_d}{\sqrt{3}} - j \frac{V_q}{\sqrt{3}} \right) e^{j\theta_r^0}$$



Three-phase complex power produced by the machine:

$$\underline{S} = 3\underline{V}\underline{I}^* = 3 \left(\frac{v_d}{\sqrt{3}} - j \frac{v_q}{\sqrt{3}} \right) \left(\frac{i_d}{\sqrt{3}} + j \frac{i_q}{\sqrt{3}} \right) = (v_d - jv_q)(i_d + ji_q)$$

$$\Rightarrow \quad P = v_d i_d + v_q i_q \quad Q = v_d i_q - v_q i_d$$

P and Q as functions of V , E_q and the internal angle δ . Assuming $R_a \cong 0$:

$$v_d = -X_q i_q \quad \Rightarrow \quad i_q = -\frac{v_d}{X_q}$$

$$v_q = -X_d i_d + \sqrt{3} E_q \quad \Rightarrow \quad i_d = -\frac{v_q - \sqrt{3} E_q}{X_d}$$

$$v_d = \sqrt{3} V \cos(\theta_r^0 - \theta) = -\sqrt{3} V \sin(\delta), \quad v_q = \sqrt{3} V \sin(\theta_r^0 - \theta) = \sqrt{3} V \cos(\delta)$$

$$P = 3 \frac{E_q V}{X_d} \sin(\delta) + \frac{3V^2}{2} \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \sin(2\delta) \xrightarrow{\text{round-rotor}} P = 3 \frac{E_q V}{X} \sin(\delta)$$

$$Q = 3 \frac{E_q V}{X_d} \cos(\delta) - \frac{3V^2}{2} \left(\frac{\sin^2(\delta)}{X_q} + \frac{\cos^2(\delta)}{X_d} \right) \xrightarrow{\text{round-rotor}} Q = 3 \frac{E_q V}{X} \cos(\delta) - 3 \frac{V^2}{X}$$

- 1 Modelling of machine with magnetically coupled circuits
- 2 Park transformation and equations
- 3 Energy, power and torque
- 4 The synchronous machine in steady state
- 5 Nominal values, per unit system and orders of magnitudes**

- nominal line voltage V_N : voltage for which the machine has been designed (in particular its insulation). The real voltage may deviate from this value by a few %
- nominal current I_N : current for which machine has been designed (in particular the cross-section of its conductors). Maximum current that can be accepted without limit in time
- nominal apparent power: $S_N = \sqrt{3}V_N I_N$

Conversion of parameters in per unit values:

- base power: $S_B = S_N$
- base voltage: $V_B = \frac{V_N}{\sqrt{3}}$
- base current: $I_B = \frac{S_N}{3V_B}$
- base impedance: $Z_B = \frac{3V_B^2}{S_B}$

(more typical of machines with a nominal power above 100 MVA)
(pu values on the machine base)

	round-rotor	salient-pole
resistance R_a	0.005 pu	
direct-axis reactance X_d	1.5 - 2.5 pu	0.9 - 1.5 pu
quadrature-axis reactance X_q	1.5 - 2.5 pu	0.5 - 1.1 pu

5 Park (equivalent) windings

- base power: S_N
- base voltage: $\sqrt{3}V_B$
- base current: $\sqrt{3}I_B = \frac{S_N}{\sqrt{3}V_B}$ (single-phase formula!)

Thus:

$$i_{dpu} = \frac{i_d}{\sqrt{3}I_B} = \frac{\sqrt{3}}{\sqrt{3}} \frac{I}{I_B} \cos(\theta_r^0 - \psi) = I_{pu} \cos(\theta_r^0 - \psi)$$

$$i_{qpu} = I_{pu} \sin(\theta_r^0 - \psi), \quad v_{dpu} = V_{pu} \cos(\theta_r^0 - \theta), \quad v_{qpu} = V_{pu} \sin(\theta_r^0 - \theta)$$

$$\underline{I} = \underline{I}_d + \underline{I}_q = (i_d - ji_q)e^{j\theta_r^0} \quad \underline{V} = \underline{V}_d + \underline{V}_q = (v_d - jv_q)e^{j\theta_r^0}$$

- All coefficients $\sqrt{3}$ have disappeared
- hence, the Park currents (resp. voltages) are exactly the projections on the machine d and q axes of the phasor \underline{I} (resp. \underline{V})