



# **Sheet metal / plate cutting**

# Gas cutting



- Oxy-fuel cutting is a **thermal cutting process** that uses **oxygen and fuel** gas (such as **acetylene, propane, MAPP, propylene and natural gas**) to cut through materials.
- The oxyfuel process is the most widely applied industrial thermal cutting process because it can cut **thicknesses from 0.5mm to 250mm**, the equipment is low cost and can be used manually or mechanized.
- There are **several fuel gas and nozzle design** options that can significantly **enhance performance** in terms of **cut quality and cutting speed**.










# Oxy-fuel cutting

- Oxyfuel gas cutting (OFC) is a group of oxygen cutting processes that use **heat from an oxyfuel gas flame** to raise the temperature of the metal to its **kindling temperature** before a high-pressure stream of oxygen is directed onto the metal, causing it to be cut.
- Oxyfuel gas cutting is most commonly performed with oxyacetylene cutting (OFC-A).

Fuel Gas	Flame (Fahrenheit)	Temperature* (Celsius)
Acetylene	5589°	3087°
MAPP®	5301°	2927°
Natural gas	4600°	2538°
Propane	4579°	2526°
Propylene	5193°	2867°
Hydrogen	4820°	2660°

# The Chemistry of a Cut

- The oxyfuel gas cutting torch works by **first preheating** the metal to its **kindling temperature** before a high-pressure stream of pure oxygen is turned on to rapidly oxidize or burn the metal away.
- **Kindling point** and **kindling temperature** are two terms that have the same meaning; they refer to the **lowest temperature at which a material will combust or start burning**.
- **Combustion** is a chemical reaction with heated iron (**Fe**) and high-pressure oxygen (**O**). The oxygen forms an **iron oxide**, primarily **Fe<sub>3</sub>O<sub>4</sub>**, that is **light gray** in color.
- As with any combustion process, **heat** is produced as the metal is **burned**. This heat helps carry the cut along.



# Physics of a Cut

- Preheat:




- The **size and number of preheat holes** in a tip have an effect on both the top and bottom edges of the metal.
- An **excessive amount** of preheat flame results in the **top edge of the plate being melted or rounded off**.

- Speed:


- The **cutting speed should be fast enough** so that the drag lines have a slight slant backward.
- If the **cutting speed is too fast**, the oxygen stream **may not** have time to **go completely through the metal**, resulting in an **incomplete cut**.
- **Too slow** a cutting speed results in the cutting stream **wandering**, thus causing **gouges** in the side of the cut.

- Pressure:


- A **correct pressure** setting results in the sides of the **cut being flat and smooth**.
- A **pressure** setting that is **too high** causes the cutting stream to expand as it leaves the tip, resulting in the sides of the **kerf being slightly dished**.
- When the **pressure** setting is **too low**, the **cut may not go completely through** the metal.




### **CORRECT CUT**




### **PREHEAT FLAMES TOO HIGH ABOVE THE SURFACE**




### **TRAVEL SPEED TOO SLOW**




### **PREHEAT FLAMES TOO CLOSE TO THE SURFACE**



### **TRAVEL SPEED TOO FAST**




### **CUTTING OXYGEN PRESSURE TOO HIGH**






# Plasma arc cutting

- Plasma is an **electrically conductive gas**.
- The **ionisation of gases** causes the creation of **free electrons and positive ions** among the gas atoms.
- Plasma cutters have the unique ability to cut metals **without making them very hot**.
- This means that there is **less distortion** and heat damage than would be caused with an oxyacetylene cutting torch.
- Very **intricate shapes** can be cut out without warping.
- The cuts are made by a **high temperature, high velocity gas** jet generated by constricting an arc between a tungsten electrode and the component.
- **Stainless steel** and non-ferrous metals such as **aluminium**.






- The plasma created by an **arc** is an **ionized gas** that has both electrons and positive ions whose charges are nearly equal to each other.
- The term arc plasma is defined as gas that has been heated to at least a **partially ionized condition**, enabling it to **conduct an electric current**.
- Plasma **welding** torches produce a **low-velocity plasma** and **cutting** torches produce a **high-velocity plasma** stream.
- Plasmas produce both **high temperature** and **intense light**.
- The amount of **heat and light depends** on the amount of **energy** in watts (volts and amps).



# Plasma (Cutting) Gas Selection

- Selecting the **proper gas** for the material you are cutting is critical to get a **quality cut**.
- Plasma gas is also called the **cutting gas**.
- This is the gas that is ionised in the plasma process and exits through the nozzle orifice.
- Examples of plasma gas are:
  - **Air**
  - **Oxygen**
  - **Nitrogen**
  - **Argon-Hydrogen**



There are a **number of variations** of the conventional plasma cutting process such as:

- Dual gas plasma cutting
  - This process uses **two different gasses**, one for the **plasma** and one as an **external shielding gas**.
  - Shielding gas to **protect the cut surface**, it will be much **cleaner and free from oxides and nitrides**.
- Water injected plasma cutting
  - This process uses a concentrated column of **water surrounding the plasma column**.
  - The water column concentrates the plasma stream by **increasing its swirl**, resulting in a **higher density** and **increased temperature** for **faster mechanized cutting**.
- Water shielding plasma cutting
  - The large quantity of water in this process is used to **cool the torch** and **reduce the sound and reflected light**.
  - This mechanized cutting process uses a **much higher water** flow than does the water injection process.
- Precision plasma cutting
  - This mechanized process is used on **thinner materials at slower cutting speeds** so that **very accurate cuts** can be made.

# Cutting speed

- Manufacturers have developed charts that list various types of **materials**, **thicknesses of materials**, and the recommended **cutting speed**.
- The charts may also include information regarding the **maximum cutting speed for each material and thickness**.
- The **higher speeds** do not produce the **same high-quality cuts** as the recommended cutting speeds.
- For a given **electric power and gas mixture**, there is an **optimum speed range** for each type and thickness of material.
- **Excess speed** causes a **decreased kerf width** with an **increased bevel** but current intensity is the main factor determining kerf width.

Mild Steel


Arc Current	Arc Voltage	Pierce Delay	Material Thickness		Recommended Cut Speed		Maximum Cut Speed	
			in	mm	ipm	mm/min	ipm	mm/min
100	153	0.5	1/4	6.4	135	3429	208	5283
	155	0.5	3/8	9.5	77	1955	119	3022
	159	1.0	1/2	12.7	57	1447	88	2235
	160	1.0	5/8	15.9	40	1016	61	1549
	161	1.5	3/4	19.0	26	660	47	1193
	163	NA	1	25.4	18	457	28	711
	167	NA	1 1/4	31.8	12	305	19	482

# Metals

- Any material that is electrically conductive can be cut using the PAC process.
- In a few applications nonconductive materials can be coated with conductive material so that they can be cut also.
- However, it is possible to make cuts in metal as thick as 7 in. (180 mm) or more.
- The most popular materials cut are carbon steel up to 1 in. (25 mm), stainless steel up to 7 in. (180 mm), and aluminum up to 6 in. (150 mm).
- Other metals commonly cut using PAC are copper, nickel alloys, high-strength, low-alloy steels, and clad materials.

# Torch Standoff Distance


- The torch standoff distance is the distance from the nozzle tip to the work.
- This distance is very critical to producing quality plasma arc cuts.
- As the torch is raised, increasing the standoff distance, the arc force is diminished.
- The plasma stream loses some of its stiffness and is constricted by the metal's resistance to being cut. This causes the kerf angle or angular deflection to increase.





# SoD and Kerf

- The terms *kerf angle* and *angular deflection* refer to the squareness of the cut.
- At the *correct standoff distance* the work side of the cut is *nearly square*.
- As the *distance increases* and the plasma stream begins to be *deformed*, the *kerf angle increases* and *dross begins* to form on the *bottom edge* as the *top edge* starts to be *rounded*.
- As the *torch is raised* further above the metal surface, the *kerf angle* begins to *rapidly increase*.




# Kerf

- The **kerf** is the **space left in the workpiece as the metal is removed during a cut.**
- The width of a PAC kerf is often **wider than that of an oxyfuel cut.**
- Several **factors will affect** the width of the kerf.
  - *Standoff distance*
    - The **closer** the torch nozzle tip is to the work, the **narrower the kerf** will be.
  - *Orifice diameter*
    - Keeping the **diameter** of the nozzle orifice as **small** as possible will keep the **kerf smaller.**
  - *Power setting*
    - **Too high or too low** of a power setting will cause an **increase in the kerf width.**
  - *Travel speed*
    - As the **travel speed is increased**, the **kerf width will decrease**; however, the bevel on the sides and the **dross formation** will increase if the **speeds are excessive.**

# Laser cutting

- Laser cutting
  - Pyrolytic
  - Photolytic
- Pyrolytic
  - Material removal is due to heating of the substrate material.
  - Melting and evaporation.
  - Pulsed laser producing light in the infrared or visible part of the spectrum (Nd:YAG and CO<sub>2</sub>) are used.



- The **power density** in the laser spot should be the order of **106 W/cm<sup>2</sup> or higher**.
- Material **melts and some of it evaporates** at the bottom of the hole created.
- **Rapid expansion** of the vapour > a **steep pressure gradient** arises with the surrounding atmosphere > causes the **molten material and vapour to be rapidly ejected** from the hole (**‘molten ejection’**).
- **Generate recast layer** on the inside wall of the hole.
- Sometimes builds up the **dross at the entrance or exit** of the hole.
- At **higher power densities** (over 108 W/cm<sup>2</sup>) material removal by evaporation is controlled > less cast build up and better hole quality.

- The laser **penetrates** to the substrate depending on the **wavelength** of the laser and **refractive index**.
- The high electric field generated due to **laser light removes the electrons** from the substrate.
- The generated **free electrons collides** with the atoms of the substrate > **transfer energy > heating the surface > vaporization**.
- The **pressure between the seed plasma and the atmosphere** lead to a rapid **expansion and cooling** of the plasma.
- The process takes place in **vaccum or gaseous** environment.


- **Photolytic process**

- Material removal from the breaking of chemical bonds.
- To break molecular bonds, the energy level of each single photon must be higher than the bond energy, of the order of few electron volts.
- Excimer lasers emit light of very short wavelength (i.e. in the UV spectrum)
- The photon energy is then in the range of 4 to 8 eV, powerful enough to break many of the molecular bonds of natural and synthesized materials.



# Arrangements of laser cutting

- Laser cutting-
  - Thermal process
  - Focused laser beam is used to **melt material in localized area**.
  - A co-axial gas jet is used to eject the molten metal and create a kerf.
- A **continuous cut** is generated by stirring the laser beam on workpiece under CNC control.
- There are **three major categories** of laser cutting
  - Fusion cutting
  - Flame cutting
  - Remote cutting



- *Fusion cutting*

- An **inert gas** (typically **nitrogen**) is used to **expel the molten material out** of kerf.
- Nitrogen gas **does not exothermically react** with the molten material > **does not** contribute to the **energy input**.

- *Flame cutting*



- **Oxygen** is used as the **assistant gas**.
- Exerts **mechanical forces** on the molten material + creates **an exothermic reaction** > **increases the energy input** to the process.

- *Remote cutting*

- The material is **partially evaporated (ablated)** by a **high intensity laser beam** allowing **thin sheets to be cut with no assist gas**.

# Kerf in laser cutting

- The **laser burns away a portion** of material when it cuts through.
- Kerf is **width of material** that is removed by a cutting process.
- Kerf shape
  - **V-shaped**
  - A **taper wall where the upper part is wider**, the kerf gradually narrows down until the width of the lower part becomes zero.



- **Striations** are formed at the top of the surface during laser cutting according to **cutting speed**.
- Striation, i.e. **periodic lines** appearing on the cut surface, is one of the most **important quality factors** in laser cutting.
- It affects the **surface roughness, appearance and geometry precision** of laser cut products.

