


# Step by step design procedure of Flyback transformer

| Step by step design of Flyback transformer for QR mode |  |       |
|--|--|-------|
| Sr. No   | Content                                      | Page  |
| 1  | Flow Diagram                                 | 2     |
| 2  | Basic definition and terminology             | 3-6   |
| 3  | Design Specification                         | 6     |
| 4  | Core Selection                               | 7     |
| 5  | Calculate Inductance and Turns Based on $AI$ | 8     |
| 6  | Calculate Copper Loss                        | 8-10  |
| 7  | Calculate Flux Density and Core Loss         | 10-11 |
| 8  | Bobbin Fit Factor                            | 11-12 |
| 9  | Reference                                    | 13    |

**Author - Shiv Mishra**  
**Hardware Developer (Secure Meters Ltd.)**  
**B.E.(Electronics & Communication)**  
**Udaipur (Rajasthan)**  
**Mob - +91-8871232248**

# Step by step design procedure of Flyback transformer

## 1. Flow Diagram



|                 |        | SI                    | CGS             | CGS to SI             |
|-----------------|--------|-----------------------|-----------------|-----------------------|
| Flux Density    | B      | Tesla                 | Gauss           | $10^{-4}$             |
| Field Intensity | H      | A-T/m                 | Oersteds        | $1,000/4\pi$          |
| Permeability    | $\mu$  | $4\pi \times 10^{-7}$ | 1               | $4\pi \times 10^{-7}$ |
| Area            | Ae     | m <sup>2</sup>        | cm <sup>2</sup> | $10^{-4}$             |
| Length          | le, lg | m                     | cm              | $10^{-2}$             |

Table 1 – Magnetic parameters and conversion factors.

# Step by step design procedure of Flyback transformer

## 2. Basic definition and terminology

### Inductance

$$L_{\text{inductance}} = \frac{.4 \times \pi \times N^2 \times (A_e) \times 10^{-9}}{l_g + \frac{l_e}{\mu}}$$

$$L_{\text{ind}} = A l \times N^2$$

**Where:**

Linductance = Henry's

$\mu$  = core permeability

N = number of turns

$A_e$  = core cross-section ( $\text{mm}^2$ )

$l_e$  = core magnetic path length (mm)

$l_g$  = gap (mm)

Since manufacture specified all data data in mm

### Core Geometry

$$l_e = \frac{\pi(OD - ID)}{\ln\left(\frac{OD}{ID}\right)} \quad (3)$$

**Where:**

OD = outside diameter of core (mm)

ID = inside diameter of core (mm)

N = number of turns

$A_e$  = core cross-section (effective area)  $\text{mm}^2$

$l_e$  = Mean magnetic path length (mm)




Figure 2 –  $l_e$  is a simple calculation with a toroid.

Since manufacture specified in mm, Convert mm to m for SI unit

# Step by step design procedure of Flyback transformer

## Ampere's Law

Ampere's law states that the total magnetic force along a closed path is proportional to the ampere-turns in a winding that the path passes through. SI unit.

$$H \approx \frac{N \times I}{l_e} \text{ amper-turns/meter (A-T/m)}$$

Where:

- H = magnetizing force (ampere-turns/meter)
- N = number of turns
- l<sub>e</sub> = core magnetic path length (m)
- I = peak magnetizing current (amperes)

## Faraday's Law


The total magnetic flux, Φ, passing through a surface of area, A<sub>e</sub>, is related to the flux density, β. The flux rate of change is proportional to the volts per turn applied to a winding. If a secondary winding is coupled to all of the flux in a primary winding, then all of the volts per turn in the primary will be induced in the secondary winding. Lines of flux follow a closed path and have no beginning or end. In the SI system, flux density is expressed in tesla

$$\text{SI: } \Delta\Phi = \frac{1}{N} \int E \times dt$$
$$E = N \times \frac{d\Phi}{dt} \approx N \times A_e \times \frac{d\beta}{dt} \Rightarrow \beta = \frac{\int E \times dt}{N \times A_e}$$

Where:

- β = flux density (tesla)
- N = number of turns
- A<sub>e</sub> = effective core area (m<sup>2</sup>)
- E = voltage across coil (volts)

## BH Curves



# Step by step design procedure of Flyback transformer

*H is proportional to I (current); therefore, as the peak-to-peak current in a magnetic increases, the excursion of the flux also increases. At the top part of the BH curve, B flattens out; at this point the magnetic is in saturation. Once the current in a magnetic drives the flux to saturation, the core no longer exhibits magnetic properties and the magnetic becomes a wire. Thus it is important to calculate the flux density for a given design to make sure that you don't saturate the core.  $\beta_{ac}$  is peak-to-peak flux density;  $\beta_{max}$  is the peak flux density.  $\beta_{max}$  assumes square wave excitation.*

$$\beta_{ac} = \frac{V_{in} \times T_{on}}{A_e \times N_p}$$


$$\beta_{max} = \frac{L_p \times I_p}{A_e \times N_p}$$

- $\beta$  = flux density in tesla
- $N_p$  = number of primary turns
- $T_{on}$  = on time (sec)
- $A_e$  = effective core area (m2)
- $V_{in}$  = voltage (volts)
- $L_p$  = primary inductance (Henry's)
- $I_p$  = peak primary current (A)

### Core Loss

*The power loss in a core is related to half the AC flux density of the core and the frequency applied to the core. To determine core loss, manufacturers normally provide a graph of power loss as a function of peak flux density and core material.*

$$\beta_{acpeak} = \frac{\beta_{ac}}{2}$$



$$P_{core\ loss} = P_v \left( \frac{KW}{m^3} \right) \times V_e \left( m^3 \right)$$

# Step by step design procedure of Flyback transformer

Permeability and Inductance Rolloff




Figure 5 – Permeability as a function of magnetizing force (H) (courtesy of Ferroxcube).

As current is increased in a magnetic and the flux density gets closer to core saturation, the permeability starts to roll off. Permeability is an important parameter, because as permeability rolls off, the inductance decreases (as shown in Equation 1). If the inductance decreases, the peak to-peak current goes up in the magnetic; this causes the flux density to increase and push the core closer to saturation. Therefore, permeability can cause a snowball effect as the core gets closer to saturation.

### 3. Design Specification

| General                                  |                        |     |             |     |
|--|------------------------|-----|-------------|-----|
| Topology                                 | Quasi-Resonant Flyback |     |             |     |
| Main Output Power                        | 10                     | W   |             |     |
| Maximum Switching Frequency at Full Load | 140                    | kHz | 140000      | Hz  |
|  |                        |     |             |     |
| Input                                    |                        |     |             |     |
| Minimum Input Voltage                    | 85                     | VAC | 76          | VDC |
| Maximum Input Voltage                    | 265                    | VAC | 375         | VDC |
| Primary Peak Current                     | 1.155                  | A   |             |     |
| Primary RMS Current                      | 0.425                  | A   |             |     |
|  |                        |     |             |     |
| Outputs                                  |                        |     |             |     |
| Secondary Output Voltage                 | 5                      | V   |             |     |
| Secondary Peak Current                   | 13.861                 | A   |             |     |
| Secondary RMS Current                    | 5.382                  | A   |             |     |
| Bias Voltage                             | 16                     | V   |             |     |
| Bias Current                             | 50                     | mA  | 0.05        | A   |
|  |                        |     |             |     |
| Inductance and Turns Ratio               |                        |     |             |     |
| Primary Inductance                       | 190.918                | μH  | 0.000190918 | H   |
| Leakage Inductance                       | 3.818                  | μH  | 0.000003818 | H   |
| Primary to Secondary Turns Ratio         | 12                     |     |             |     |

# Step by step design procedure of Flyback transformer

| 4. Core Selection  |  |          |
|--|--|----------|
| Core selection is based on size, material and gap. These factors work together to determine the core loss and inductance per turn of the core. |  |          |
| Output Power Level   | Recommended Core Types   |          |
| 0-10W  | EFD15<br>SEE16<br>EF16<br>EPC17<br>EE19<br>EF(D)20<br>EPC25<br>EF(D)25 |          |
| 10-20W   | EE19<br>EPC19<br>EF(D)20<br>EE or EI22<br>EF(D)25 EPC25                |          |
| 20-30W   | EI25<br>EF(D)25<br>EPC25<br>EPC30<br>EF(D)30                           |          |
| 30-50W   | EI28<br>EER28(L)<br>ETD29<br>EF(D)30<br>EER35                          |          |
| 50-70W   | EER28L<br>ETD34<br>EER35<br>ETD39                                      |          |
| 70-100W  | ETD34<br>EER35<br>ETD39<br>EER40<br>E21                                |          |
| For 10 W application I have choosen below core   |  |          |
| Part No  | EFD20/10/7-3F3-A-100   |          |
| Manufacturer   | Ferroxcube   |          |
| Core Name  | EFD20  |          |
| Material   | 3F3  |          |
| Al   | 0.000000082  | 82*10^-9 |
| Note: the Al required is not standard the core gap had to be custom-cut to obtain the necessary Al   |  |          |

# Step by step design procedure of Flyback transformer

| 5. Calculate Inductance and Turns Based on Al   |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
|---|-----------------------|--|---------------------|---------------|-----|-----------------------|---------------------|---------------------|---------------|----|------|------|----------|----------|----|-------|-------|---------|----------|----|-------|--------|----------|----------|----|------|------|---------|----------|
| Np  | 48                    | Turns  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Ns  | 4                     | Turns  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| $N_P = \left( \frac{L_P}{Al} \right)^{1/2}$   |                       | $N_S = \frac{N_P}{\text{Turns ratio}}$         |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
|   |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| 6. Calculate Copper Loss  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Current density, J, is a rule of thumb that says a wire should not handle any more than 400 A/cm^2  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| J   | 400                   | A/cm^2   | Assume              |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Primary Wire Area   | 0.0010625             | cm^2   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Skin depth at 100°C   | 0.0203                | cm   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Primary wire area = $\frac{I_{\text{primary\_rms}}}{J}$   |                       | Skin depth at 100°C = $\frac{7.6}{\sqrt{f}}$ : |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
|   |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Determine annular inner ring area at 100°C  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Since we have not yet determined the correct wire gauge so calculate from 26AWG to 32AWG  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Area ring 26AWG 100°C = area 26AWG  | 0.001287              | cm^2   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Area ring 28AWG 100°C = area 28AWG  | 0.00081               | cm^2   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Area ring 30AWG 100°C = area 30AWG  | 0.000509              | cm^2   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Area ring 30AWG 100°C = area 30AWG  | 0.00032               | cm^2   |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Note : when the skin depth is greater than the radius of the wire, we must set the ring area equal to the area of the wire.   |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| <table><tr><th>AWG</th><th>Copper Diameter in cm</th><th>Copper Radius in cm</th><th>Copper Area in cm^2</th><th>Ω/cm at 100°C</th></tr><tr><td>26</td><td>0.04</td><td>0.02</td><td>0.001287</td><td>0.001789</td></tr><tr><td>28</td><td>0.032</td><td>0.016</td><td>0.00081</td><td>0.002845</td></tr><tr><td>30</td><td>0.025</td><td>0.0125</td><td>0.000509</td><td>0.004523</td></tr><tr><td>32</td><td>0.02</td><td>0.01</td><td>0.00032</td><td>0.007192</td></tr></table> |                       |  |                     |               | AWG | Copper Diameter in cm | Copper Radius in cm | Copper Area in cm^2 | Ω/cm at 100°C | 26 | 0.04 | 0.02 | 0.001287 | 0.001789 | 28 | 0.032 | 0.016 | 0.00081 | 0.002845 | 30 | 0.025 | 0.0125 | 0.000509 | 0.004523 | 32 | 0.02 | 0.01 | 0.00032 | 0.007192 |
| AWG   | Copper Diameter in cm | Copper Radius in cm                            | Copper Area in cm^2 | Ω/cm at 100°C |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| 26  | 0.04                  | 0.02   | 0.001287            | 0.001789      |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| 28  | 0.032                 | 0.016  | 0.00081             | 0.002845      |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| 30  | 0.025                 | 0.0125   | 0.000509            | 0.004523      |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| 32  | 0.02                  | 0.01   | 0.00032             | 0.007192      |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| $R_{\text{skin 26AWG 100°C}} = \frac{\text{Area 26AWG cm}^2}{\text{Area ring 26AWG 100°C cm}^2}$  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rskin 26AWG 100°C   | 1                     |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rskin 28AWG 100°C   | 1                     |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rskin 30AWG 100°C   | 1                     |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rskin 32AWG 100°C   | 1                     |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Determine wire resistance due to skin effects   |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rcopper 26AWG 100°C   | 0.001287              | ohms/cm  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rcopper 28AWG 100°C   | 0.00081               | ohms/cm  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rcopper 30AWG 100°C   | 0.000509              | ohms/cm  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rcopper 32AWG 100°C   | 0.00032               | ohms/cm  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |
| Rcopper 26AWG 100°C = wire 26AWG ohms/cm 100°C x Rskin 26AWG 100°C  |                       |  |                     |               |     |                       |                     |                     |               |    |      |      |          |          |    |       |       |         |          |    |       |        |          |          |    |      |      |         |          |



# Step by step design procedure of Flyback transformer

|   |                 |       |
|---|-----------------|-------|
| <b>Determine the number of primary wires in parallel required:</b>  |                 |       |
|   |                 |       |
| Numbers of wires primary 26AWG  | 0.826           |       |
| Numbers of wires primary 28AWG  | 1.312           |       |
| Numbers of wires primary 30WG   | 2.087           |       |
| Numbers of wires primary 32AWG  | 3.320           |       |
| $\text{Numbers of wires primary 26AWG} = \frac{\text{Area required primary cm}^2}{\frac{\text{Area 26AWG cm}}{\text{Rskin 26AWG 100}^\circ\text{C}}}$   |                 |       |
|   |                 |       |
| <b>Determine primary copper loss</b>  |                 |       |
| Number of primary wires   | 1               |       |
| length per turn   | 0.0341          | m     |
| Rcopper primary resistance 26AWG  | 0.0021176268642 | ohm   |
| Pcopper primary loss 26AWG  | 0.0003824963524 | W     |
| $\text{Rcopper primary resistance 26AWG} = \text{Rcopper 26AWG } 100^\circ\text{C} \times N_p \times \frac{\text{Length per turn cm}}{\text{Number of primary wires}}$<br>$\text{Pcopper primary loss 26AWG} = I_{\text{primary rms}}^2 \times \text{Rcopper primary 26AWG}$  |                 |       |
|   |                 |       |
| <b>Determine secondary wire AWG and losses</b>  |                 |       |
| Secondary wire area   | 0.0135          | m^2   |
| Number of wires secondary 28AWG   | 17              | 5.000 |
| Rcopper secondary 28AWG   | 0.01910         | ohms  |
| Pcopper secondary loss 28AWG  | 0.103           | W     |
| $\text{Secondary wire area} = \frac{I_{\text{secondary rms}}}{J}$<br>$\text{Number of wires secondary 28AWG} = \frac{\text{Secondary wire area cm}^2}{\frac{\text{Area 28AWG cm}}{\text{Rskin 28AWG } 100^\circ\text{C}}}$<br>$\text{Rcopper secondary 28AWG} = \text{Rcopper 28AWG } 100^\circ\text{C} \times N_s \times \frac{\text{Length per turn cm}}{\text{Number of wires secondary}}$<br>$\text{Pcopper secondary loss 28AWG} = I_{\text{secondary rms}}^2 \times \text{Rcopper secondary 28AWG}$ |                 |       |
|   |                 |       |
| <b>Determine bias wire AWG and losses:</b>  |                 |       |
| number of bias wires  | 1.000           |       |
| Number of turns bias winding (Nsb)  | 12.867          |       |
| Rcopper bias 32AWG  | 0.000140        | ohm   |
| Pcopper bias loss 32AWG   | 3.5E-07         | W     |

# Step by step design procedure of Flyback transformer

Number of turns bias winding (Nsb) =  $N_s \times \frac{V_{bias}}{V_{out}}$

Rcopper bias 32AWG=Rcopper 32AWG 100°C × Nsb ×  $\frac{\text{Length per turn cm}}{\text{Number of bias wires}}$

Pcopper bias loss 32AWG = Ibias rms<sup>2</sup> × Rcopper bias 32AWG

## 7. Calculate Flux Density and Core Loss


### Effective core parameters from manufacture datasheet

|                             |       |                  |            |                |
|-----------------------------|-------|------------------|------------|----------------|
| core factor( $\Sigma l/A$ ) | 1.52  | mm <sup>-1</sup> |            |                |
| Effective volume (Ve)       | 1460  | mm <sup>3</sup>  | 0.00000146 | m <sup>3</sup> |
| Effective length            | 47    | mm               |            |                |
| Effective Area(Ae)          | 31    | mm <sup>2</sup>  | 0.000031   | m <sup>2</sup> |
| Minimum Area(Amin)          | 29    | mm <sup>2</sup>  |            |                |
| Mass of core half (m)       | 3.5   | g                |            |                |
|                             |       |                  |            |                |
| βac                         | 0.147 | Tesla            |            |                |
| βmax                        | 0.147 | Tesla            |            |                |

For a flyback converter running in discontinuous current mode, the AC flux density, βac, is equal to the maximum flux density, βmax .

βac =  $\frac{V_{in\ min} \times T_{on\ max}}{A_e \times N_p}$

βmax =  $\frac{L_p \times I_{pri\_p}}{A_e \times N_p}$



the saturation point for the given core is about 250 mT. So this design is about 60 percent of maximum flux.

# Step by step design procedure of Flyback transformer

| B-H Curve                        |           |       |  |
|----------------------------------|-----------|-------|--|
| Determine core loss:             |           |       |  |
| Bunipolar                        | 0.000     | Tesla | <div>Bunipolar = <math>\frac{\beta_{ac}}{2}</math></div> |
| Pcore                            | 60        | kW/m3 |  |
| Pcore loss                       | 0.0000876 | W     |  |
| Total magnetic power dissipation | 1.0E-01   | W     |  |

$P_{core\ loss} = P_{core} \times V_e\ per\ m^3$




Figure 15 – Specific power loss as a function of peak flux density with frequency as a parameter (courtesy of Ferroxcube).

## 8. Bobbin Fit Factor

Winding data and area product for EFD20/10/7 coil former (SMD) with 10-solder pads

| Number of Sections | Winding Area (mm <sup>2</sup> ) | Minimum Winding Width (mm) | Average Length of Turn (mm) | Area Product Ae x Aw (mm <sup>2</sup> ) | Type Number       |
|--------------------|---------------------------------|----------------------------|-----------------------------|---|-------------------|
| 1                  | 27.7                            | 13.5                       | 34.1                        | 859                                     | CPHS-EFD20-1S-10P |

Figure 16 – Winding data (courtesy of Ferroxcube).

| AWG | Copper Diameter in cm with Insulation | Copper Area in cm <sup>2</sup> with Insulation |
|-----|---------------------------------------|--|
| 26  | 0.046                                 | 0.001671                                       |
| 28  | 0.037                                 | 0.001083                                       |
| 30  | 0.03                                  | 0.000704                                       |
| 32  | 0.024                                 | 0.000459                                       |

# Step by step design procedure of Flyback transformer

Turns per layer 26AWG =  $\frac{\text{Bobbin width cm}}{\text{Diameter 26AWG with isolation}} - 2$

Buildup in cm =  $\frac{\text{Winding area cm}^2}{\text{Bobbin width cm}}$

Layers =  $\frac{\text{Buildup in cm}}{\text{Diameter 26AWG with isolation}}$

|                          |             |      |
|--------------------------|-------------|------|
| Bobbin width             | 1.35        | cm   |
| Turns per layer 26AWG    | 27.34782609 |      |
| Turns per layer 28AWG    | 34.48648649 |      |
| Turns per layer 30 AWG   | 43          |      |
| Winding area             | 0.277       | cm^2 |
| Buildup                  | 0.205       | cm   |
| Layers                   | 4.460547504 |      |
| Total bobbin turns 26AWG | 121.9862774 |      |
| Total turns needed       | 81.22442307 |      |
| Winding factor           | 0.665848855 |      |

Total bobbin turns 26AWG = turns per layer × layers

Total turns needed

= Np × number of primary wires + Ns × number of secondary wires  
+ Nsb × number of bias wires = 81

Winding factor =  $\frac{\text{Total turns needed}}{\text{Total bobbin turns 26AWG}}$

# Step by step design procedure of Flyback transformer

*Reference : "Power Transformer Design" by Lloyd H. Dixon.  
Ferroxcube. Soft Ferrites and Accessories.*