

## Step 1 — Create Equipment Master

**Execute T-Code:** IE01

### **Important fields:**

- Equipment Category: **M** (Machine) or **Q** (Quality Instrument)
- Description: “Digital Vernier Caliper”
- Location & Work Center
- Maintenance Plant
- Assign Class Type **002 (Equipment)** for characteristics

## Step 2 — Create Calibration Task List (Inspection Plan)

**Execute T-Code:** IP01

**Purpose:** Define calibration steps and measurements.

### **Key Fields:**

- Usage: **4 (Plant Maintenance + Calibration)**
- Status: **Released**
- Assign Operations (e.g., “Check Accuracy at 10mm”)
- Assign Master Inspection Characteristics (MICs)

## Step 3 — Assign Task List to Equipment

**Execute T-Code:** IE02 → “Usage” Tab → **Assign Task List**

Link the equipment with the calibration plan.

## Step 4 — Schedule Calibration

**Execute T-Code:** IP30

**Purpose:** System checks due dates and generates calibration lots.

### **Input:**

- Scheduling Period: 30 days
- Maintenance Plan: Enter plan number

**Output:**

- Inspection Lot generated (e.g., **1400001234**)

## **Step 5 — View Inspection Lot**

**Execute T-Code:** QA03

**Important tabs:**

- General data
- Inspection plan assignment
- MICs assigned
- Sample size
- Due date

## **Step 6 — Record Calibration Results**

**Execute T-Code:** QE51N

**Steps:**

1. Enter inspection lot
2. Select MIC
3. Enter measured values
4. Save results

System calculates Pass/Fail based on values provided.

## **Step 7 — Usage Decision**

**Execute T-Code:** QA11

**Select:**

- **Accept** (UD code: ACPT)
- **Reject** (UD code: REJT)

If rejected → Create maintenance order automatically/ manually.

## **Step 8 — Print Calibration Certificate**

**Execute T-Code:** QA03 → “Print Certificate”