



BM83 MSPK2v1.3.4 Release Note

VERSION 1.3.4

The following are the attributes of this firmware version for specific system requirements and device settings. This release includes one firmware variants and is located at the following directory structure.

SPP: IS2083 Turnkey v1.2.4\Software\IS2083 Image\MSPK2v1.3.4\SPP

Included a BM83 Getting Started Guide to walk through BM83 collateral, software package usage and general application setup & configuration.

Firmware updates:

Items	Version
8051 Images	MSPKv2_1.03.0406_SPP
DSP Image	MSPK2.0_DSP_FW_V1.04.0410
Host MCU	1.6.6

Utility Tool Updates:

Items	Version
Config GUI Tool	1.3.22
isUpdate Tool	3.14
SpkCommandSetTool	206.009
iOS Apps	1.6.4
Android Apps	4.40

Error Resolution and feature enhancement

- Added ANSSI Bluetooth Core Vulnerabilities fix
- Added I2S volume control option to select "**Hardware**", "**DSP**" and "**Hybrid**"
- Added a UART command to read latency value during run time
- Added 8/16KHZ support for I2S as Aux-in
- Extended line in latency from 80ms to 160ms in Line In Concert mode
- Provided a settings in Config GUI tool to allow master speaker linkback mobile phone when aux-in is inserted during powerup has been resolved.
- Improved Audio Uart Command Document
- Improved BM83 Config GUI Tool Help Menu & Display
- Modified Config GUI tools so output is saved as a text file for config settings comparison.
- Improved isUpdate tools and Config GUI tools so that config setting dumped from BM83 can be loaded into ConfigTool.
- iPhone 6 Plus, Samsung S10e : BT link abnormal disconnect in idle mode has been resolved
- Modified MCU code to request BLE connection parameter update when transparent service established.
- Added a settings in Config GUI tools to disable line-in audio fade in/out when the volume suddenly transit from low to high
- Resolved the cracking sound issue in HFP with mSBC codec
- iPhone 12 Mini : sound breaking periodically(every 3~4 minute) in concert mode has been resolved
- Added feature to allow I2S input with analog audio output
- Slow BLE response during A2DP playback has been resolved

- Added an embedded file explorer in Android MBA app to display OTA file of default folder. This may avoid any compatibility issues with some 3rd party file manager
- DSP GUI Tools Issue : Enabling Audio effect leads to uncheck MCLK abnormally has been resolved

Behaviour and Limitation

Limitation:

Please refer to “**BM83 MSPK2 Design Limitation.pdf**” for the MSPK2 behavior and limitation. The document is located under “Document” folder

Behavior:

The number of linkback device is related to the profiles settings but not the device pattern settings in the config GUI tools:

Connection Setting		
--- Power On Link Back Setting	Enable	
--- Search Paired Device Pattern Setting	Last Device Only	
--- Power On Link Back Profile(s) Setting	Last Device	
Search paired device pattern setting	Power on link back profiles setting	Number of linkback devices
All devices	A2DP	2
Last device	A2DP	2
All devices	Last device	1
Last device	Last device	1

VERSION1.3.2

The following are the attributes of this firmware version for specific system requirements and device settings. This release includes three firmware variants and is located at the following directory structure.

SPP: IS2083 Turnkey v1.2.2\Software\IS2083 Image\MSPK2v1.3.2\SPP

GFP: IS2083 Turnkey v1.2.2\Software\IS2083 Image\MSPK2v1.3.2\GFP

PBAP: IS2083 Turnkey v1.2.2\Software\IS2083 Image\MSPK2v1.3.2\PBAP

Details of these variants are discussed in IS2083/BM83 Bluetooth Audio Applications Design Guide.

Firmware updates:

Items	Version
8051 Images	MSPKv2_1.03.0206_GFP MSPKv2_1.03.0206_PBAP MSPKv2_1.03.0206_SPP
DSP Image	MSPK2.0_DSP_FW_V1.04.000A
Host MCU	1.6.5

Utility Tool Updates:

Items	Version
Config GUI Tool	1.3.12
isUpdate Tool	3.02
SpkCommandSetTool	206.003
iOS Apps	1.6.4

Android Apps

4.10

Error Resolution

- BM83 Concert primary resets sometime within 30 min when music is paused has been resolved.
- BM83 Concert mode, audio discontinuity is observed in the presence of microwave oven frequency has been resolved.
- DSP Tool EQ settings doesn't show saved parameters has been resolved
- Unexpected changes in I2S voice output volume and bad voice quality with iPhone has been resolved
- sometimes continuous sound break is observed in Secondary speaker if Concert Primary is connected with Win 10 PC has been resolved
- Audio break issue in concert primary and secondaries has been improved by
 - o decreasing MSPK broadcast times if the media buffer is low
 - o adding some delay for silence padding when media buffer is empty in Concert Satellite
 - o Extending media buffer to 400ms from 340 ms for MSPK SBC

Errata

- Latest update in Android 10 and Android 11 Devices has added more fragments and irregular transmission of AAC Bluetooth payload in the presence of WIFI. This results in continuous audio break in Primary and Secondary speakers
 - ➔ It is recommended to disable AAC codec in MSPK to overcome this issue with Android Devices.

VERSION1.3.1

The following are the attributes of this firmware version for specific system requirements and device settings. This release includes three firmware variants and is located at the following directory structure.

SPP: IS2083 Turnkey v1.2.1\Software\IS2083 Image\MSPK2v1.3.1\SPP

GFP: IS2083 Turnkey v1.2.1\Software\IS2083 Image\MSPK2v1.3.1\GFP

PBAP: IS2083 Turnkey v1.2.1\Software\IS2083 Image\MSPK2v1.3.1\PBAP

Details of these variants are discussed in IS2083/BM83 Bluetooth Audio Applications Design Guide.

Firmware updates:

Items	Version
8051 Images	MSPKv2_1.03.0106_GFP MSPKv2_1.03.0106_PBAP MSPKv2_1.03.0106_SPP
DSP Image	MSPK2.0_DSP_FW_V1.04.0009
Host MCU	1.6.3

Utility Tool Updates:

Items	Version
Config GUI Tool	1.3.12
isUpdate Tool	3.02
SpkCommandSetTool	206.003
iOS Apps	1.6.4
Android Apps	4.9

New Features and Feature Enhancement

- Added Enabled/Disable link back feature when remote doesn't have link key.

Bug Fixed

- BM83 resets with frequent connect/disconnect in concert mode has been resolved.
- Audio click heard in both primary and secondary in concert mode has been resolved.
- BM83 resets in Concert mode when Primary is in scanning mode and volume is changed on the secondary has been resolved.
- BM83 connection issue with old phone (Bluetooth 2.0) has been resolved.
 - o A bug was introduced while fixing this issue has also been resolved.
- BM83 OTA DFU issue fixed in Android MBA_v4.09_Android-release.apk.
- Link back failure with some Android phone when the device is deleted/forgotten from the phone has been resolved.
- Unexpected changes in I2S voice output volume results in bad sound quality using mSBC with iPhone has been resolved.
- Sometimes deleting the paired device record from the phone resets BM83 running with GFP firmware has been resolved.
- Sometime pairing fails with Google Pixel4 when device name is changed through MBA app has been resolved.
- Updated Config Tools to fix/add the following issues:
 - o Customized BLE Advertising name was not saved properly in the file. When the file was reopened, it was only showing only first four letters of the name has been fixed.
 - o Added an option to enable/disable link back when remote has no link key.
- Work around has been added to resolve P3_2 GPIO not returning to high state some times when power off/on happens quickly.
- Volume synchronization issue in concert mode when a secondary device is added in the group has been resolved.

VERSION1.3**Firmware updates:**

Items	Version
8051 Images	MSPKv2_1.03.0008_GFP MSPKv2_1.03.0008_PBAP MSPKv2_1.03.0008_SPP
DSP Image	MSPK2.0_DSP_FW_V1.04.0006
Host MCU	1.6.3

Utility Tool Updates:

Items	Version
Config GUI Tool	1.3.08
isUpdate Tool	3.02
SpkCommandSetTool	206.003
iOS Apps	1.6.4
Android Apps	4.8

New Features and Feature Enhancement

- A2DP audio mixed with one of the following input : Aux-in/I2S/Microphone.
New MMI action (0x80/0x81) commands control the mixer. Config Tool provide option for this feature.
- Microphone input as Line-in input to Concert master.
- New mechanism in Concert mode endless grouping to interleave between general access code (for new slave) and dedicated access code (for paired slave). New UART command (0x4B) control the endless grouping. Config Tool provide option for this feature.
- Fully support AVC vendor dependent 0x0B(0x4A) command and 0x1A(0x5D) event for AVC vendor dependent command / response.
- Enhance UART command 0x08 to provide project target version.
- Improved OTA/UART DFU flash validation performance
- Enhanced LDAC audio quality by reducing quantization noise floor and harmonic distortion
- Provided BT CoD setting in configuration tools
- MCLK can be enabled under I2S slave.
- 32 bytes vendor data can be stored in flash by Config GUI tools. Uart command (0x31 / 0x13) can retrieve/update the stored data.

Bug Fixed

- Ringtone volume with external codec in embedded mode
- Sometimes not able to increase/decrease volume from 2nd Concert Slave device.
- Firmware do not respond 0x4A uart command after many tries.
- Concert Slave standalone did not trigger auto power off after concert master auto power off.
- No audio output under embedded mode with "power on directly" enabled.
- Paired device list is not updated correctly after 9th device is paired.
- Embedded battery mode cannot auto power off with initial voltage below 3V
- Missing battery UART event and cannot auto power off mode under low power mode.
- Concert mode AAC cannot be used if A2DP do not support AAC.
- Sometime DSP reconfiguration of BCLK for different sampling rate, results in I2S left channel audio silence
- Isupdate v2.97 tool doesn't upgrade firmware through USB.

Errata

- Concert master seldomly cannot link back to iPhone SE (iOS 13.5) once it form concert group.
→ It can be recovered when trigger BT reconnection again.

VERSION1.2

The following are the attributes of this firmware version for specific system requirements and device settings. This release include 3 firmware variants and located at the following directory structure.

SPP: IS2083 Turnkey v1.1.0\Software\IS2083 Image\MSPK2v1.2\SPP

GFP: IS2083 Turnkey v1.1.0\Software\IS2083 Image\MSPK2v1.2\GFP

PBAP: IS2083 Turnkey v1.1.0\Software\IS2083 Image\MSPK2v1.2\PBAP

Details of these variants are discussed in BM83 application user guide.

New Features and Feature Enhancement

- Bluetooth Spec security vulnerability resolution
 - o SWEYNTTOOTH BLE vulnerabilities issues
 - o BIAS(Bluetooth Impersonation Attacks) vulnerability issue(CERT/CC VU#647177)
 - o Key Negotiation of Bluetooth(KNOB) BR/EDR Vulnerability(CERT VU#918987)
- Added New UART commands
 - o Host MCU DFU UART Command Sets
 - o AVRCP Vendor Dependent Command Sets
 - o New parameter type to Read BTM Version which include BTM FW version and DSP version details
 - o Battery Level Indication to support feature in Report Read Feature List Reply event
 - o Enable Device Into Test Mode (EDUTM) command.
 - o Re-introduced UART command to control GPIO
- New Configuration Parameters
 - o Enable AVRCP Browsing Feature (default Enable)
 - o Allow Users to Enable Device Under Test (default Disable)
 - o Auto Role Switch to BT Master (default Enable)
 - o Enable Role Switch in Link Policy (default Disable)
 - o Force As Bluetooth Slave Role (default Disable)
 - o Save MSPK Role When Connected (default Disable)
 - o MSPK Power Saving Grouping Interval
 - o Enable Concert Mode Master SPK Endless Grouping (default Disable)
 - o Allow Voice Prompt in MSPK Slave (default Disable)
- Config Tool improvement
 - o Drop down target selection(MSPK/GFP/PBAP/AT). Config tool will allow available configuration parameters to be customized.
 - o User data manipulation feature provided
- DFU process enhancement
- MBA App
 - o DSP OTA tuning scheme
- LDAC Codec Enhancement
 - o Passed with latest Sony LDAC conformance certification spec
 - o Extend media buffer to 32K Byte to meet Sony recommendation of Bluetooth high audio quality design

PBAP

- Created PBAP image and added in the release
- Resolved PABP connection issue

Google Fast Pair

- Created GFP and added in the release
- Compatible with existing MBA mobile App feature
- Include Google Fast Pair option into application layer general pairing procedure.
- New Configuration Parameters
 - o Google Fast Pair (default Enable)
 - o Google Fast Pair Model ID
 - o Google Fast Pair Private Key
 - o Google Fast Pair TX Power
 - o Battery Notification (default Disable)

Error Resolution

- Audio Issue fix
 - o EQ parameter setting timing error results in EQ mode ineffective
 - o Audio break issues under WCT or/and general A2DP mode corner cases resolved
 - o WCT volume sync under MCU mode error.
 - o Disabling MCLK, disable signal at MCLK1 pin
- Tone/ Voice Prompt issues fixed
 - o Tone play abnormal with line-in enable while powering off
 - o Maximum volume causes voice prompt and sine tone disappear
 - o Tone playing abnormal with BLE link exists
- Bluetooth connectivity issue fixed
 - o Revised profiles/ACL disconnection handling to avoid state machine transition incorrect
 - o Bluetooth stack and profile defects result in profiles connection failure
 - o SCO link handling incorrect make voice dial and voice transfer abnormal.
- Application behavior enhancement
 - o Revise power down flow. Delay PMU power down after power off DSP to avoid AMP pop noise.
 - o Revise MFB button detection for power on pairing flow
 - o Revise report battery level flow
 - o Revise audio source switching flow between A2DP and line-in result in incorrect source reported
 - o Revise CV mode charging flow to make charging curve lower down smoothly as expected.
 - o Memory leak in A2DP connection

Errata

- I2S should be configured as I2S Master for both master and slave speakers when BM83 Concert speakers configured as I2S out. I2S slave is not recommended as Audio discontinuity and unsync between master and slave speakers are observed when configured as I2S slave. There is no restriction on I2S (Master/Slave) in single speaker case.
- BM83 will try to be Bluetooth Slave role during LDAC playback:
 - ⇒ Some mobiles (e. g. Samsung S8) do not receive ACK properly BM83 is Bluetooth Master role during LDAC playback. It will cause audio break because of lower throughput. To have better performance in this circumstance, BM83 will try to be Slave role once LDAC codec is selected.
- Only support max to 2 A2DP links while A2DP LDAC decode playback:
 - ⇒ Because of above, while second ACL link was created, it would become a scatternet topology. Under this scenario, only 2 A2DP links can be served.
- Coexistence of BLE and SCO link in OTA DSP tuning:
 - ⇒ While performing "Voice" OTA DSP tuning via BLE, SCO link is created for transmitting/receiving SCO voice and the voice waveform was captured to measure DSP parameter effect. We suggest customers do not perform tuning and transmit/receive SCO voice simultaneously if BLE master and SCO receiver are not in the same device. Otherwise, BLE disconnection might be observed.
- One shot audio break occurred while using Android Phone playing A2DP music and trigger BLE connection.
 - ⇒ We observed Android phone will change Bluetooth Low Energy Connection Interval as 7.5 ms to query GATT Service Table. It will cause audio break because of lower throughput of A2DP streaming.
- A2DP / Aux-in source switch in A2DP suppress Aux-in case
 - ⇒ While configured to A2DP has higher priority than line-in, switching audio source to line-in from A2DP by MBA could not make line-in music play immediately. This is because most phone will transmit silence A2DP music after paused A2DP. Due to configured to A2DP has higher priority than line-in, the silence music is still decoding but unable heard, this make line-in music delay to play until A2DP silence music is really terminated. The delay time is various by different phone brand. Sometimes it could be longest to more than 10 seconds.
- iPhone do not display battery level icon for Bluetooth accessory
 - ⇒ We observed iPhone do not display battery level if CoD (Class of Device) of BM83 is 0x240414 (for minor device class is 0x14 Loudspeaker). But iPhone would display battery level if CoD of BM83 was setting to 0x240404 (for minor device class is 0x04 Wearable Headset Device).

VERSION1.0

The following are the attributes of this firmware version for specific system requirements and device settings

- OTA DFU feature enabled using MBA app(Android & iOS)
- LDAC support enabled
- MCLK can be enabled/disabled in Config Tool
- PBAP 1.2 enabled
- Digital microphone support is enabled
- AAC codec support added for MSPK
- AVRCP browsing feature enabled
- DSP OTA tuning enabled
- Software Development Kit(SDK) enabled
- SPKCommandsetTool crashing issue fixed
- BLE disconnection issue with Samsung S10E resolved
- Connection issue after connection is rejected is resolved
- Fixed BLE and Bluetooth classic disconnect when phone call is disconnected
- SW I2C driver Added

1. Document Revision History

Revision	Date	Section	Description
1	4/19/2019	Document	Initial Revision
1.1	06/30/2019	V1.0	Added v1.0 release details
1.2	05/08/2020	V1.2	Added v1.2 release details
1.3	8/28/2020	V1.3	Added V1.3 release details
1.3.1	12/15/2020	V1.3.1	Added V1.3.1 release details
1.3.2	1/29/2021	V1.3.2	Added V1.3.2 release details
1.3.4	7/15/2021	V1.3.4	Added V1.3.4 release details

The Microchip Website

Microchip provides online support via our website at <http://www.microchip.com/>. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to <http://www.microchip.com/pcn> and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: <http://www.microchip.com/support>.

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION,

INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A. Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN:

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit <http://www.microchip.com/quality>.



Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: http://www.microchip.com/support Web Address: http://www.microchip.com Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455 Austin, TX Tel: 512-257-3370 Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088 Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075 Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924 Detroit Novi, MI Tel: 248-848-4000 Houston, TX Tel: 281-894-5983 Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380 Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078	Australia - Sydney Tel: 61-2-9868-6733 China - Beijing Tel: 86-10-8569-7000 China - Chengdu Tel: 86-28-8665-5511 China - Chongqing Tel: 86-23-8980-9588 China - Dongguan Tel: 86-769-8702-9880 China - Guangzhou Tel: 86-20-8755-8029 China - Hangzhou Tel: 86-571-8792-8115 China - Hong Kong SAR Tel: 852-2943-5100 China - Nanjing Tel: 86-25-8473-2460 China - Qingdao Tel: 86-532-8502-7355 China - Shanghai Tel: 86-21-3326-8000 China - Shenyang Tel: 86-24-2334-2829 China - Shenzhen Tel: 86-755-8864-2200 China - Suzhou Tel: 86-186-6233-1526 China - Wuhan Tel: 86-27-5980-5300 China - Xian Tel: 86-29-8833-7252 China - Xiamen Tel: 86-592-2388138 China - Zhuhai Tel: 86-756-3210040	India - Bangalore Tel: 91-80-3090-4444 India - New Delhi Tel: 91-11-4160-8631 India - Pune Tel: 91-20-4121-0141 Japan - Osaka Tel: 81-6-6152-7160 Japan - Tokyo Tel: 81-3-6880- 3770 Korea - Daegu Tel: 82-53-744-4301 Korea - Seoul Tel: 82-2-554-7200 Malaysia - Kuala Lumpur Tel: 60-3-7651-7906 Malaysia - Penang Tel: 60-4-227-8870 Philippines - Manila Tel: 63-2-634-9065 Singapore Tel: 65-6334-8870 Taiwan - Hsin Chu Tel: 886-3-577-8366 Taiwan - Kaohsiung Tel: 886-7-213-7830 Taiwan - Taipei Tel: 886-2-2508-8600 Thailand - Bangkok Tel: 66-2-694-1351 Vietnam - Ho Chi Minh Tel: 84-28-5448-2100	Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 Denmark - Copenhagen Tel: 45-4450-2828 Fax: 45-4485-2829 Finland - Espoo Tel: 358-9-4520-820 France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 Germany - Garching Tel: 49-8931-9700 Germany - Haan Tel: 49-2129-3766400 Germany - Heilbronn Tel: 49-7131-72400 Germany - Karlsruhe Tel: 49-721-625370 Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 Germany - Rosenheim Tel: 49-8031-354-560 Israel - Ra'anana Tel: 972-9-744-7705 Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781 Italy - Padova Tel: 39-049-7625286 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Norway - Trondheim Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820