

23/09/17

# Fundamentals of electromagnetics

①


Important for mechatronic actuators

→ Biot Savart law

$$\int dB = \frac{\mu}{4\pi} \int \frac{I d\vec{l} \times \vec{e}_r}{r^2}$$

$dl$  = elementary length of  
conductor carrying  
current  $I$

$\vec{e}_r$  = unit vector from  $dl$  to  $P$



Field at point  $P$  can be obtained by

BS law as current carrying conductor placed  
at  $y$  axis is responsible for generating this  
magnetic field.

$$d\vec{l} = dl \vec{j}$$

$$\vec{e}_r = -\cos\theta \vec{i} - \sin\theta \vec{j}$$

$$d\vec{l} \times \vec{e}_r = [-\cos\theta (\vec{i} \times \vec{j}) - \sin\theta \vec{j} \times \vec{j}] dl$$

$$= -\cos\theta \vec{k} dl$$

$$B \text{ at point } P = \frac{\mu I}{4\pi} \int_{-\infty}^{\infty} \frac{-\cos\theta dl}{r^2}$$

$$r = r_0 / \cos\theta \quad r^2 = \frac{r_0^2}{(\cos\theta)^2}$$

$$dl = r_0 \tan\theta$$

$$dl = r_0 \sec^2\theta d\theta$$

$$B = \frac{\mu I}{4\pi} \int_{-\pi/2}^{\pi/2} \frac{-\cos\theta}{r_0^2} \cdot \cos^2\theta (r_0 \sec^2\theta d\theta)$$

$$= \frac{\mu I}{4\pi} \int_{-\pi/2}^{\pi/2} \frac{-\cos\theta}{r_0} d\theta$$

$$B = \frac{\mu I}{4\pi r_0} \left[ \sin\theta \right]_{-\pi/2}^{\pi/2}$$

$$B = \frac{\mu I}{2\pi r_0}$$

length of current  
carrying conductor  
is  $\infty$ . Hence


$$\theta = -\pi/2 \rightarrow \pi/2$$

## Ampere's Law

Integral of a magnetic field over a closed path is equal to the current passing through the area covered by the closed path times the permeability of medium covered by the closed path of integration.

$$\oint_C \vec{B} \cdot d\vec{s} = \mu \cdot i$$

ex Previous case



$B$  along a circle of radius  $r_0$  will be constant (see fig). Hence we consider this circle as closed path.

$$\therefore \vec{B} \cdot d\vec{s} = B \cdot 2\pi r$$

since  $d\vec{s}$  along the direction of  $B$ .

$$2\pi r_0 B = \mu i$$


$$B = \frac{\mu I}{2\pi r_0}$$

same as before.

$\Rightarrow$  Although both Ampere's law & Biot Savart law are always true (for steady currents), the use of one law or against the other should be made as per the convenience. ~~For~~ ex. only for problems with symmetry (as above)  $B$  can be pulled out of the integral.

$\Rightarrow$  Also when path traced ~~goes through~~ passes through multiple media, we use the method of reluctance for analysing magnetic circuits.

ex



coil carrying current  $i$ . consider loop  $\phi_1 \rightarrow$  No current passes through the area of loop  $\rightarrow$  No  $B$  along the loop. Considering many such loops outside the coil  $\Rightarrow$  flux is zero outside the coil.

Also by similar arguments

$\Rightarrow$  flux is uniform inside the coil.

$$\oint_{\phi_2} \vec{B} \cdot d\vec{s} = \mu i$$

$$B \cdot l = \mu N i$$

$$B = \frac{\mu N i}{l}$$

## Lorentz force



Current carrying conductor placed in magnetic field.

$$\vec{F} = q \vec{v} \times \vec{B}$$

$$= \frac{q ds}{dt} \times \vec{B}$$

$$= \int \frac{dq}{dt} \times \vec{B}$$

$$\boxed{\vec{F} = I \cdot \vec{s} \times \vec{B}}$$



$\Rightarrow$  Fundamental principle of motor.

Electromagnetic Circuits

$$\text{Reluctance } R = \frac{l}{\mu A}$$

Similar to concept of resistance  $R = \frac{\rho l}{A}$

$$\text{Flux } \Phi_B = \int \vec{B} \cdot d\vec{A} \quad (\text{Weber or } \text{Tesla} \cdot \text{m}^2)$$

$$H = \frac{\vec{B}}{\mu}$$

Magnetomotive force =  $H \cdot l$

$$\text{MMF} = \frac{\vec{B}}{\mu} l \quad \dots \text{equivalent to Voltage.}$$

Magnetic field strength.

For example for coils we saw that

$$B = \frac{\mu N i}{l} \rightarrow \text{Inside coil.}$$

$$\text{MMF} = \frac{\mu N i}{l} \cdot l = \underline{\underline{N i}}$$



example magnetic circuit

$$R_{\text{core}} = \frac{l_c}{\mu_c A_c}$$

$$R_g = \frac{l_g}{\mu_0 A_g}$$

$$\Phi_B = \frac{N i}{R_{\text{total}}}$$

$$R_{\text{total}} = R_c + R_g$$

$$= \frac{l_c}{\mu_c A_c} + \frac{l_g}{\mu_0 A_g}$$



$$\mu_c \gg \mu_0$$

$$R_{\text{total}} \approx \frac{l_g}{\mu_0 A_g}$$

$$\Phi_B = \frac{N i}{l_g} \cdot \mu_0 A_g$$

$$\boxed{\Phi_B = \frac{N i \mu_0 A_g}{l_g}}$$

- Flux ~~through~~ through the circuit.





## Flux linkage

When a conductor is placed in magnetic field ~~typically~~  
flux links with the conductor flux linkage =  $N\Phi_B$  for  $N$  turns ~~in~~ coils.

More flux linkage more resistance to current change will be created in the coil. according to Faraday's law, for change of flux


$$\frac{d\phi}{dt} = L \cdot \frac{di}{dt} = \text{Emp induced in coil.}$$

$$N \frac{d\Phi_B}{dt} = L \frac{di}{dt}$$

$$N\Phi_B = Li \quad \therefore$$

~~for~~

ex previous magnetic circuit for coil





$$\Phi_B = \frac{Ni\mu_0 A}{l_g}$$

$$Li = \frac{N^2 i \mu_0 A}{l_g}$$

$$L = \frac{N^2 \mu_0 A}{l_g}$$

self inductance

## Application to solenoid case:



equivalent magnetic circuit

$$R_p = \frac{\mu_p l_p}{N^2 A_p} \quad R_g = \frac{\mu_0 l_g}{N^2 A_g}$$

$$\mu_p \gg \mu_0 \Rightarrow R_p \approx 0$$

$$l_g = x$$

$$\Phi_B = \frac{NI}{R_t} = \frac{NI \mu_0 A}{x}$$

flux linkage to coil =  $N \Phi_B$

$$\lambda = \frac{N^2 I \mu_0 A}{x}$$

$$\lambda = L i \quad \boxed{L = \frac{N^2 \mu_0 A}{x}}$$

## Lagrange formulation for solenoid with spring loaded plunger

$$KE = \frac{1}{2} L \dot{i}^2 + \frac{1}{2} m \dot{x}^2$$

$m$  = mass of plunger


$\dot{x}$  = velocity of plunger.

$$T = KE = \frac{1}{2} \frac{C_L}{x} \dot{i}^2 + \frac{1}{2} m \dot{x}^2$$

$$C_L = N^2 \mu_0 A \quad Lx = \frac{C_L}{x}$$

$$V = PE = \frac{1}{2} k x^2$$

$$= \frac{1}{2} k (x_0 - x)^2$$



$$\mathcal{L} = T - V$$

$$= \left( \frac{1}{2} \frac{C_L}{x} \dot{i}^2 + \frac{1}{2} m \dot{x}^2 \right) - \left( \frac{1}{2} k (x_0 - x)^2 \right)$$

$$i = q$$

Generalized coordinates  $q \in x, \quad i = \dot{q}$

$$\frac{d}{dt} \left( \frac{\partial \mathcal{L}}{\partial \dot{q}} \right) = \frac{d}{dt} \left( \frac{1}{2} \frac{C_L}{x} (2\dot{q}) \right) = \frac{C_L}{x} \ddot{q} + \frac{C_L \dot{q}}{x^2} (-\dot{x})$$

(7)

$$\frac{\partial L}{\partial q} = 0.$$

$V_1 =$  external force in direction of  $q$

$$\frac{d}{dt} \left( \frac{\partial L}{\partial \dot{q}} \right) - \frac{\partial L}{\partial q} = V_1$$

$$\therefore \frac{C_L}{x} \ddot{q} + \frac{C_L \dot{q}}{x^2} (-\dot{x}) = V_1$$

$$\therefore \frac{C_L}{x} \frac{d\dot{i}}{dt} - \frac{C_L \dot{i}}{x^2} \dot{x} = V_1$$

$$\boxed{V_1 = Lx \frac{d\dot{i}}{dt} - \frac{Lx}{x} \dot{i} \dot{x}} \Rightarrow \text{Neglecting resistive loss in circuit.}$$

$$\boxed{V_1 = Lx \frac{d\dot{i}}{dt} - \frac{Lx}{x} \dot{i} \dot{x} + R\dot{i}}$$

$$\frac{d}{dt} \left( \frac{\partial L}{\partial \dot{x}} \right) = \frac{d}{dt} \left( \frac{1}{2} m (2\dot{x}) \right) = m\ddot{x}$$

$$\begin{aligned} \frac{\partial L}{\partial x} &= \frac{1}{2} \cdot \frac{C_L}{x^2} (-1) \dot{i}^2 - \frac{1}{2} K x (x_0 - x) \cdot (-1) \\ &= -\frac{1}{2} \frac{C_L \dot{i}^2}{x^2} + \frac{1}{2} K (x_0 - x) \end{aligned}$$

$$\frac{d}{dt} \left( \frac{\partial L}{\partial \dot{x}} \right) - \frac{\partial L}{\partial x} = 0.$$

$$m\ddot{x} + \frac{1}{2} \frac{C_L \dot{i}^2}{x^2} - K(x_0 - x) = 0.$$

$$\boxed{m\ddot{x} + Kx + \frac{C_L \dot{i}^2}{2x^2} - Kx_0 = 0.}$$

# Lagrange formulation for motor (PMDc)

$$KE = \frac{1}{2} L \dot{i}^2 + \frac{1}{2} J \dot{\theta}^2$$

$J$  = inertia of motor

$L$  = inductance =  $L_p + L_s$

Now inductance is result of flux linkages. There are two kinds of flux

linkages = ① from self magnetic field - self inductance -  $L_s$ .

② from permanent magnet of motor -  $L_p$ .



Flux linkage Linkage due to permanent magnet =  $2 \Phi_p N = \lambda_p$ .

(Both sides of coil are in magnetic field)

Inductance due to this  $\lambda_p$  is  $L_p$ .

$$\Phi_p = \theta \propto B$$

$$\lambda_p = 2 \Phi_p N = L_p i$$

$$L_p = \frac{2 \Phi_p N}{i} \quad i = \dot{q} \quad q = \text{charge}$$

$$T = \frac{1}{2} \left( L_s + \frac{2 \Phi_p N}{\dot{q}} \right) \dot{q}^2 + \frac{1}{2} J \dot{\theta}^2 = \frac{1}{2} L_s \dot{q}^2 + \theta \cdot \beta \dot{q}$$

$$\text{losses} = \frac{1}{2} R \dot{q}^2 \quad \text{damping} = c$$

$$V = 0.$$

$$L = T - V = T \quad \text{Generalised coordinates} = q \text{ \& } \theta$$

$$\frac{d}{dt} \left( \frac{\partial L}{\partial \dot{q}} \right) = \frac{d}{dt} \left[ \frac{1}{2} \left( L_s + \frac{2 \Phi_p N}{\dot{q}} \right) \cdot \left( \frac{2 \Phi_p N}{\dot{q}^2} \right) \right]$$

$$N \Phi_p = \theta \propto B = \theta \cdot \beta \quad \beta = \text{const.}$$

$$N \Phi_p = N B \cdot A$$

$$= \frac{d}{dt} \left( \frac{\partial}{\partial \dot{q}} \left[ \frac{1}{2} L_s \dot{q}^2 + \frac{2 \Phi_p N}{2} \dot{q} \right] \right)$$

$$= \frac{d}{dt} \left( \frac{1}{2} L_s (2 \dot{q}) + \theta \beta \dot{q} \right)$$

$$= L_s \ddot{q} + \beta \cdot \dot{\theta} \dot{q}$$

Back  
emf

losses

Voltage applied

$$\frac{\partial L}{\partial q} = 0$$

$$L_s \frac{di}{dt} + \beta \dot{\theta} + R i = V_i$$



$$\frac{d}{dt} \left( \frac{\partial L}{\partial \dot{\theta}} \right) = \frac{d}{dt} \left( \frac{1}{2} J \dot{\theta} \right) = J \ddot{\theta}$$

$$\left( \frac{\partial L}{\partial \theta} \right) = \beta \dot{\theta}$$

$$\therefore J \ddot{\theta} + \underbrace{c \dot{\theta}}_{\text{damping}} - \beta \dot{\theta} = 0.$$

$$J \ddot{\theta} + c \dot{\theta} = \beta \dot{\theta} = \beta i$$

$$\beta = K_t = K_b.$$

equations of motor

$$J \ddot{\theta} + c \dot{\theta} = K_t i$$

No external load  $\Rightarrow$  mechanical eqn


$$L_s \frac{di}{dt} + K_b \dot{\theta} + R i = V_i \rightarrow \text{electrical eqn}$$




Equations of motion for BLDC motor.  $\rightarrow$  Case similar to

PMDC motor now coils are 3 and all fixed

Recall



Reaction torque



Reaction Torque generated, for current  $i_1$  through phase 1

$$T_1 = i_1 \cdot K_t \cdot \sin \theta.$$

Since physically coils are located  $120^\circ$  to each other

$$T_2 = i_2 K_t \cdot \sin(\theta + 120)$$

$$T_3 = i_3 K_t \sin(\theta + 240).$$

$$\text{Total torque} = T_1 + T_2 + T_3.$$

We see that for  $i_1 = i_2 = i_3 = i$

$T_1 + T_2 + T_3 = 0$ . Thus flowing constant current through stator coils will not work.

BLDC motorSo Normally  $i_1 = i \sin \theta$ Commutation in current

$$i_2 = i \sin(\theta + 120)$$

$$i_3 = i \sin(\theta + 240)$$

$$\therefore T_1 = K_t i \sin^2 \theta$$

$$T_2 = K_t i \sin^2(\theta + 120)$$

$$T_3 = K_t i \sin^2(\theta + 240)$$

$$\therefore T = T_1 + T_2 + T_3$$

$$= K_t i (\sin^2 \theta + \sin^2(\theta + 120) + \sin^2(\theta + 240))$$

$$= K_t i \left( \frac{1 - \cos 2\theta}{2} + \frac{1 - \cos 2(\theta + 120)}{2} + \frac{1 - \cos 2(\theta + 240)}{2} \right)$$

$$= \frac{K_t i}{2} (3 - [\cos 2\theta + \cos 2(\theta + 120) + \cos 2(\theta + 240)])$$

$$\boxed{T = \frac{3}{2} K_t i} \rightarrow \text{gives torque proportional to } i$$

Case of misalignmentNormally hall effect sensors are used to sense directions  $\theta, \theta + 120, \theta + 240$ .If consider overall misalignment of  $\alpha$ . (In placement of hall effect sensors based on which

current commutation is done.)

$$T_1 = i_1 K_t \sin \theta$$

$$T_2 = i_2 K_t \sin(\theta + 120)$$

$$T_3 = i_3 K_t \sin(\theta + 240)$$

$$i_1 = i \sin(\theta + \alpha)$$

$$i_2 = i \sin(\theta + \alpha + 120)$$

$$i_3 = i \sin(\theta + \alpha + 240)$$

$$T_1 = i \sin(\theta + \alpha) \sin \theta k_t$$

$$T_2 = i k_t \sin(\theta + \alpha + 120^\circ) \sin(\theta + 120^\circ)$$

$$T_3 = i k_t \sin(\theta + \alpha + 240^\circ) \sin(\theta + 240^\circ)$$

$$T = T_1 + T_2 + T_3$$

$$= i k_t \left[ \sin(\theta + \alpha) \sin \theta + \sin(\theta + \alpha + 120^\circ) \sin(\theta + 120^\circ) + \sin(\theta + \alpha + 240^\circ) \sin(\theta + 240^\circ) \right]$$


$$= \frac{i k_t}{2} \left[ \cos \alpha - \cos(2\theta + \alpha) + \cos \alpha - \cos[2(\theta + 120^\circ) + \alpha] + \cos \alpha - \cos[2(\theta + 240^\circ) + \alpha] \right]$$

$$T = \frac{i k_t}{2} 3 \cos \alpha$$

$\Rightarrow$  Torque is now lesser by factor of  $\cos \alpha$ . Hence alignment

of hall effect sensors w.r.t the direction of magnetic field in respective coils

i) Very important



$\leftarrow$  Misalignment ~~in~~ in mounting

Hall sensors