


TRANSFORMERS:



$$e_p = N_p \frac{d\phi}{dt} \quad \text{FARADAY'S LAW} \quad e_s = N_s \frac{d\phi}{dt}$$

→ The ratio of two voltages:

$$\frac{e_s}{e_p} = \frac{N_s}{N_p}$$


$$\Rightarrow \boxed{e_s = \left(\frac{N_s}{N_p}\right) \cdot e_p} \Rightarrow \text{Potential Variable (effort)}$$

→ Power balance equation is given as


$$e_p i_p = e_s \cdot i_s$$

$$\Rightarrow e_p \cdot i_p = \left(\frac{N_s}{N_p}\right) \cdot e_p \cdot i_s$$

$$\Rightarrow \frac{i_p}{i_s} = \frac{N_s}{N_p} \Rightarrow \boxed{i_p = \frac{N_s}{N_p} \cdot i_s} \rightarrow \text{Kinetic Variable (flow)}$$



Ampere's law:



H = magnetic field intensity

Mathematically

$$\int_0^{l_m} H \cdot dl = \text{mmf} = NI \text{ (Ampere turns)}$$



Flux density: (B)

From Ampere's law

$$\int_0^{l_m} H \cdot dl = NI = \text{mmf}$$


$$H \int_0^{l_m} dl = NI$$


$$\Rightarrow H \cdot [l_m] = NI$$

$$\Rightarrow \boxed{H = \frac{NI}{l_m}} \text{ Amp/m}$$

\Rightarrow The flux density is given by

$$\boxed{B = \frac{\phi}{A_c}} \text{ Tesla [Flux per unit area]} \\ \hookrightarrow \text{weber/m}^2$$





The equations are:


$$1. H = \frac{NI}{L_m} = \frac{\text{mmf}}{L_m}$$

$$2. B = \frac{\Phi}{A_c}$$

$$3. B = \mu H$$

Losses in Practical transformer:

1. Hysteresis loss
2. Eddy current loss.



Hysteresis loss!

The flux density is given by

$$B = \mu H = \mu \cdot \frac{NI}{l_m}$$

$$\Rightarrow I = \frac{B \cdot l_m}{N \cdot \mu} \rightarrow (1) \text{ From Ampere's law}$$

From Faraday's law

$$V = N \cdot \frac{d\phi}{dt}$$

but

$$\phi = B \cdot A_c$$

$$\therefore V = N \cdot A \cdot \frac{d\phi}{dt} \rightarrow (2)$$

The instantaneous energy

$$dE = V \cdot I \cdot dt$$

$$\Rightarrow dE = \left(N A_c \frac{dB}{dt} \right) \cdot \left(\frac{B l_m}{\mu N} \right) \cdot dt \quad \text{joules}$$

$V_c = A_c l_m = \text{Core Volume}$

$$\therefore dE = \mu V_c \cdot B \cdot \frac{dB}{\mu N}$$


$$\Rightarrow dE = \frac{V_c \cdot B}{\mu} \cdot dB \quad \text{joules}$$

The energy per unit volume

$$dE = \left(\frac{B}{\mu} \right) dB \quad \text{joules}$$

$$\Rightarrow dE = H \cdot dB$$

(or)




$$\therefore \int dE = \int \frac{B}{\mu} \cdot dB = \frac{1}{2} \frac{B^2}{\mu} = \frac{1}{2} BH$$

\therefore Hysteresis energy ~~per~~ for complete core

$$E = \frac{1}{2} BH \cdot V_c$$

$$P = \frac{1}{T} E_h = \frac{1}{2} B H V_c \cdot f$$

Eddy Current Loss:



→ By laminations the cross sectional area for circulating is increased.

$$P_e \propto B_m^2 f^2$$

Core loss = Hysteresis loss + Eddy current loss

$$P_{\text{core}} = P_h + P_e$$


$$P_{ey} = i^2 R_{ey}$$

$P_{\text{core}} + P_{ey}$ = total losses in the transformer

VOLT-SEC BALANCE:

From Faraday law of electromagnetism

$$\begin{aligned} e &= N \cdot \frac{d\phi}{dt} \\ &= N A_c \frac{dB}{dt} \end{aligned}$$



$$\Rightarrow B = \frac{1}{NA_c} \int e \, dt$$

$$\Rightarrow \boxed{B \propto \int \frac{e \, dt}{\cancel{V} \, \cancel{sec}}}$$


$$\int V \, dt = V \cdot t$$



$$\int V_m \sin \omega t = \frac{V_m}{\omega} \cos \omega t$$

→ For sinusoidal waveforms

$$e = NA_c \frac{dB}{dt}$$



$$B_m < B_{sat}$$

→ Flux density swings

$-B_m \rightarrow +B_m - B_m$ in one cycle.

$$\underbrace{\int_0^{(T/2)} e \, dt}_{E_{avg}} = \frac{1}{T/2} NA_c \cdot B$$

$(-B_m \rightarrow +B_m)$ in time of 0 to $T/2$

$$\therefore E_{avg} = \frac{2}{T} NA_c B_m$$

$$\Rightarrow \boxed{E_{avg} = 4 \cdot N \cdot A_c \cdot f \cdot B_m}$$

$$\frac{V_m}{\sqrt{2}}$$

$$\frac{\pi \cdot V_m}{2 \cdot \sqrt{2} \cdot V_{rms}}$$

$$\Rightarrow \frac{RMS}{Avg} = 1.11 \Rightarrow RMS = (1.11) Avg$$

$$\boxed{E_{RMS} = 4.44 NA_c f B_m}$$

Where

N = number of turns

f = frequency of Applied voltage

B_m = max. flux density allowed



* B_m for Ferrites: $0.25T$; $B_{sat} = 0.3T$

* B_m for CRGO = $1.7T$; $B_{sat} = 1.7T$
[Cold Rolled Grain Oriented]


$$\frac{E}{f} = 4.44 N A_c B_m$$

\downarrow constant \downarrow constant \downarrow constant


$\therefore E/f = \text{constant} \Rightarrow \text{Volt-sec is constant}$



$N_1 < N_2$
Step up



$N_1 > N_2$
Step down



Galvanic Isolation transformer

Transformer Efficiency:

The efficiency of a transformer at a particular load and power factor is defined as ratio of power output to power input.

$$\therefore \text{Efficiency} = \frac{\text{Output}}{\text{input}}$$

$$= \frac{\text{output}}{\text{output} + \text{losses}}$$

$$= \frac{\text{output}}{\text{output} + \text{Cu loss} + \text{iron loss}}$$

(or)

$$\text{Efficiency} = \frac{\text{input} - \text{losses}}{\text{input}} = 1 - \frac{\text{losses}}{\text{input}}$$

Condition for maximum efficiency:

Iron losses:

P_i = hysteresis loss + eddy current loss

$$= P_h + P_e$$

Copper losses:

$$P_c = I_1^2 R_{01} \text{ (or) } I_2^2 R_{02}$$

Considering primary side:

$$\text{Input} = V_1 I_1 \cos \phi_1$$

$$\therefore \eta = \frac{V_1 I_1 \cos \phi_1 - \text{losses}}{V_1 I_1 \cos \phi_1}$$

$$= \frac{V_1 I_1 \cos \phi_1 - I_1^2 R_{01} - P_i}{V_1 I_1 \cos \phi_1}$$

$$= 1 - \frac{I_1 R_{01}}{V_1 \cos \phi_1} - \frac{P_i}{V_1 I_1 \cos \phi_1}$$

Differentiating both sides w.r.t I_1

$$\frac{d\eta}{dI_1} = 0$$

$$\Rightarrow \frac{R_{01}}{V_1 \cos \phi_1} = \frac{P_i}{V_1 I_1^2 \cos \phi_1}$$

$$\Rightarrow P_i = I_1^2 R_{01} \text{ (or) } I_2^2 R_{02}$$

$$\Rightarrow \boxed{\text{Copper losses} = \text{Iron losses}}$$

∴ Output current corresponding to maximum efficiency is

$$I_2 = \sqrt{\frac{P_i}{R_{02}}}$$

→ Efficiency at any load is given by

$$\eta = \frac{x \times \text{full-load kVA} \times \text{P.F.}}{(x \times \text{full-load kVA} \times \text{P.F.}) + w_i + w_u} \times 100$$

where

x = ratio of actual to full-load kVA

w_i = iron losses in kW;

w_u = C_u loss in kW;

$$C_u \text{ loss @ } x\% \text{ of load} = x^2 \cdot (C_u \text{ loss})$$

Example:

A 600 kVA, 1-phase transformer when working at u.p.f has an efficiency of 92% at full load and also at half load. Determine its efficiency when it operates at unity P.f and 60% of full load.

Sol: At ^{full} ~~half~~ load:

$$\text{output} = 600 \text{ kW}$$

$$\text{Input} = \frac{\text{output}}{\eta} = \frac{600 \times 1000}{0.92}$$

$$= 652.2 \text{ kW}$$

$$\therefore \text{Total loss} = \text{Input} - \text{output} \\ = 52.2 \text{ kW}$$

Let $x = \text{Iron loss} \rightarrow$ it remains constant at all loads

$y = \text{F.L. Cu loss} \rightarrow$ it is $\propto (\text{kVA})^2$

$$\therefore \boxed{x + y = 52.2} \rightarrow (1)$$

At half-load:

$$\text{output} = 300 \text{ kW}$$

$$\text{Input} = \frac{300}{0.92} = 326.08$$

$$\therefore \text{losses} = 26.1 \text{ kW}$$

$$\text{a) half load Cu losses} = \frac{1}{4} (\text{Cu loss @ F.L.})$$

$$\therefore \boxed{\frac{1}{4}x + y = 26.1} \rightarrow (2)$$

∴ By solving (1) & (2)

$$\boxed{x = 17.4 \text{ kW}}; \quad \boxed{y = 34.8 \text{ kW}}$$

At 60% of full load

$$\begin{aligned}\text{Output} &= 0.6 \times 600 \\ &= 360 \text{ kW}\end{aligned}$$

$$\text{Total loss} = W_{cu} + W_i$$

where

$$W_i = \text{iron loss} = 17.4 \text{ kW}$$

$$W_{cu} = x^2 (W_{cu} @ \text{F.L.})$$

$$\begin{aligned}&= (0.6)^2 \times 34.8 \\ &= 12.53 \text{ kW}\end{aligned}$$

$$\therefore \frac{\text{output}}{\text{input}} = \eta \Rightarrow \eta = \frac{360}{360 + 17.4 + 12.53}$$

$$= \frac{360}{389.93} = 0.93$$

$$\Rightarrow \boxed{\eta\% = 93\%}$$

Example 02:

A 600 KVA, 1-phase transformer has an efficiency of 92% both at full & half load at unity power factor. Determine its efficiency at 60% of full-load at 0.8 power factor lag.

$$\therefore \eta = \frac{x \times \text{KVA} \times \cos\phi}{(x \times \text{KVA}) \times \cos\phi + W_i + x^2 W_{cy}} \times 100$$

$x \rightarrow$ % of full load
 ∞

At F.L. u.p.f

here $x=1$

$$\therefore 92 = \frac{1 \times 600 \times 1}{1 \times 600 \times 1 + W_i + 1^2 W_{cy}} \times 100$$

$$\Rightarrow \boxed{W_i + W_{cy} = 52.174 \text{ kW}} \rightarrow (1)$$

At half of F.L., UPF, here $x=1/2$

$$92 = \frac{(1/2) \times 600 \times 1}{(1/2) \times 600 \times 1 + W_i + (1/2)^2 W_{cy}} \times 100 ;$$

$$\therefore \boxed{W_i + 0.75 W_{cy} = 36.087 \text{ kW}} \rightarrow (2)$$

From (1) & (2)

$$W_i = 17.39 \text{ kW};$$

$$W_{cy} = 34.78 \text{ kW};$$

At 60% F.L. 0.8 p.f (lag)

here, $x = 0.6$

$$\eta = \frac{0.6 \times 600 \times 0.8 \times 100}{(0.6 \times 600 \times 0.8) + 17.39 + (0.6)^2 34.78}$$

$$\Rightarrow \boxed{\eta = 85.9\%}$$