

Welding

Joining two pieces of metal, by the application of heat with or without the application of pressure or filler material
permanent joint

Plastic welding

(Pressure welding)

- pieces that are to be joined, heated in molten state,




allowed to solidify


- * with → Pressure
- * without → ~~pressure~~ filler.

eg: Forge welding, Resistance welding

Are welding



Before



After

Fusion welding

(Non-pressure welding)


heated in molten state



- * without pressure
- * with filler.

↓
Arc welding Gas welding

- Joining process



- Difference between the three.
(2 slides)

- Defects in welding.

Principal

- two conductors (charge carrying)



touched momentarily



separated



Electric Arc is formed

- High heat density ($5000-6000^{\circ}\text{C}$) → throughout the length of arc.

- circuit → 2 poles

(electrodes)

① parts to be welded

② electrode held by the operator.

Procedure

- Arc



melts work piece metal
(directly under the arc)



forms small molten pool of metal.

agitated

thoroughly mixing
with filler metal

tip of the electrode
(at the arc)

melts

carried by arc

cools

solid joint

- flux coating over the electrode.



produces inert gas atmosphere



to prevent oxidizing of molten metal.

Safety devices

Welding shields

→ IR/UV rays

2) Gloves → spark, insulate

3) chipping hammer & brush

4) Apron.

5) Earthing clamp.

welding machine

- function \rightarrow low voltage & high current
(10-50V) (50A-200A)

AC arc \rightarrow a step down transformer is used

- polarity changes every cycle.

220/440 V \rightarrow 80 to 100 V.

- neg. high voltage coz it acquire OV twice
high current 100 to 400 A.

DC arc \rightarrow work piece \oplus } \rightarrow straight polarity,
electrode \ominus } high heat is required.

\rightarrow reversed when less heat is required.

Electrodes

\rightarrow used is consumable type and is coated with flux.

\rightarrow coating \rightarrow lime, ferro manganese, cellulose, starch, iron powder.

\rightarrow flux forms slag \rightarrow removed by chipping hammer and wire brush.

\rightarrow purpose of coating \rightarrow protect molten metal from oxidizing
 \rightarrow prevent rapid cooling of metal
 \rightarrow to maintain arc.
 \rightarrow Addition of alloying elements.

Flux

- \rightarrow slag producing elements \rightarrow china clay, mica
- \rightarrow gas shield producing \rightarrow cellulose, wood, starch, CaO3
(electrode end, arc, weld pool)
- \rightarrow Deoxidizing elements \rightarrow ferro manganese.
- \rightarrow Alloying elements \rightarrow ferro alloys of Mo, Mn \rightarrow strength
- \rightarrow Iron powder \rightarrow improves arc behavior,
travel ~~rate~~ speed,
metal deposition rate,
bead appearance.

Gas welding


- fusion method of welding, which a strong gas flame is used to raise the temperature of work piece to melt them.
- \hookrightarrow oxygen & Acetylene
 \hookrightarrow oxygen & Hydrogen.

Procedure


- oxy-acetylene flame — right proportion of O_2 and $HC\equiv CH$ are mixed.
- Temp $\rightarrow 3200^\circ C \rightarrow$ melt all commercial ferrous metals

equipment

- \rightarrow 2 large steel cylinders \rightarrow oxygen \rightarrow black (high P)
 \rightarrow acetylene \rightarrow Maroon (dissolved, at high P)
- \rightarrow rubber tubes, pressure regulators



- $\rightarrow O_2$ & CH_4 are supplied separately to the blow torch
- \hookrightarrow mixed at the nozzle of blow torch.



- excess oxygen. (1.5:1)
- inner white cone is shorter.
- used to weld nickel and non ferrous material
- used for oxyacetylene cutting, and not suitable for welding, since the weld metal will be oxidized.
- equal volumes of oxygen and acetylene
- 1:1 ratio
- inner whitish cone surrounded by a blue flame.
- most of the welding work is done using this flame.
- excess acetylene
- $O_2 : (CH)_2 = 0.95:1$
- It has an inner and outer blue envelope for
- used for welding alloy steels, cast iron and Al to protect from oxidizable elements

Defects in welding (LUPIC)

- lack of fusion. - less heat, just traversing of the welding torch
- porosity. - when gases are trapped in the weld metal
- inclusions - when slag is not removed, before running another weld
- cracking - when there is thermal shrinkage.
- undercut. - excess melting of parent metal reduces strength of the joint.

Soldering

- when 2 or more metal items are joined together by melting and pouring a filler metal (solder) into the joint.
- $M.P. \text{ filler metal} < M.P. \text{ work piece.}$
($1500^{\circ}\text{C} - 3000^{\circ}\text{C}$)
- soldering does not involve melting of work piece.
- $\text{ZnCl}_2 \rightarrow \text{flux} \rightarrow$ to clean the surface
 \rightarrow to prevent oxidation.
- soldering iron \rightarrow apply heat produced from electrical source
- $\text{Pb} + \text{Sn} \rightarrow$ soft solder \rightarrow sheet metal work ($150^{\circ}\text{C} - 300^{\circ}\text{C}$)
 \rightarrow plumbing
 \rightarrow electrical junctions
- $\text{Cu} + \text{Sn} + \text{Ag} \rightarrow$ Hard solder. (600°C to 900°C)

Tools

- | | | |
|-----------------------|---------------|------------------|
| 1. Soldering iron. | 4. Iron stand | 7. Helping hand. |
| 2. Soldering station. | 5. Solder. | |
| 3. Iron tips | 6. sponge | |

Method

- 1) Clean the surface
- 2) Application of flux. \rightarrow resin or borax.

- 3) Tinning of surfaces \rightarrow to remove the tin that forms on the
Cu bit
- 4) Heating .
- 5) Final clean up \rightarrow steel wool \rightarrow remove the rest of
left over flux.

Brazing

- Joining process that relies on melting, flow and solidification of a brazing filler metal to form a leak tight seal, a strong structural bond, between the material.
- produces the coalescence of materials by heating them to the brazing temperature in the presence of a brazing filler metal that has a liquidus temp above 450°C and below the base materials.
- Metallurgical bond \rightarrow is formed by the melting

Make Brazing notes.
It never comes in
exam.
usually

Difference between welding, soldering and Brazing

	welding	soldering	Brazing
strength	Strongest joints strength of joint is more than that of base metal.	weakest usually only to make electrical contact and not bear load.	in between can bear load to some extent
temp.	3800°C	450°C	600°C
Heating of work pieces	work pieces are heated till their MP	it is not required.	heated below the MP.
change in Mech. proper	Mech. prop. of base metal may change at the joint due to heating and cooling	No change in Mech properties.	Negligible change in Mech prop.
Heat treatment	is req. to eliminate undesirable qualities of welding	No heat treatment	No heat treatment
Preheating of work piece	No preheating of work piece is req. as it is carried out at high temp	preheating of workpiece is req. to make good quality joint.	is desirable to make a strong joint

Vision system

Types of vision system.

Image segmentation.