



## Report of Visual Thorough Examination

The undersigned certifies on behalf of this company, that below particulars are correct and that the described lifting equipment is installed correctly & safe to operate.  
The described lifting equipment is thoroughly examined according to LOLER S.I. 1998/2307 or LOLER S.I. 2006/2184 Regulations.  
The inspection is carried out according to the LEEA and/or EKH Code of Practice.

|                          |  |                            |  |                               |  |
|--------------------------|--|----------------------------|--|-------------------------------|--|
| CU Job No: 124-2-0042    |  | Customer PO:               |  | Customer Contact: Mcsorley, m |  |
| Report Number            | : CU/2024/2001659288/V   | Last Thorough Examination  | : 02-Apr-2021  |                               |  |
| Date of Examination      | : <b>08-Mar-2024</b>   | Prev. Examination Type     | : Visual   |                               |  |
| Test Location            | : On Client Site   | Prev. Report Number        | : CU/2021/2001354982/V   |                               |  |
| Re-examination Before    | : 07-Mar-2027  | Inspection Interval Visual | : 36 Months  |                               |  |
| Identification No.       | : <b>RBU-402</b>   | Connected to               | : N/A  |                               |  |
| Serial / Mfg cert. No.   | : N/A  | Related Items              | : N/A  |                               |  |
| Item                     | : Overhead Runway Beam   |                            |  |                               |  |
| Working Load Limit (WLL) | : 20 tonne   |                            |  |                               |  |
| Owner                    | : Shell U.K. Limited<br>1 Altens Farm Road<br>AB12 3FY Aberdeen<br>Great Britain   | Description                | :<br>Overhead Runway Beam<br>Length - 3.066Mtr<br>Location - Level 2 UL2 |                               |  |
| Location                 | : Shearwater platform  |                            |  |                               |  |
| Material                 | : Steel  |                            |  |                               |  |
| Manufacturer             | : Unknown, ,   |                            |  |                               |  |
| Mfg. Standard(s)         | : EN 13155   |                            |  |                               |  |
| Remarks                  | : Requires fabric maintenance , paint breakdown<br>and parent material loss throughout span of<br>beam. Support bolts have slight corrosion. | Noted Defects              | : None   |                               |  |
|                          |  | Required Repairs           | : None   |                               |  |
|                          |  | Limited Validation         | : N/A  |                               |  |
|                          |  | Newly Installed/Assembled  | : N/A  |                               |  |

Date Printed : 15-Mar-2024

Name Inspector : Bain, J.

Qualification : Company Appointed Examiner

Authorised and competent person:

Bain, J.



### Control Union (UK) Limited

Altens Operations Base • AB12 3JZ • Aberdeen • Great Britain

T +441224879768 • cuiuk@controlunion.com • industrialinspections.controlunion.com

Inspections are carried out within the scope of the Principal's explicit, detailed instructions and with due care and skill. All our services are subject to the General Conditions of business of International Federation of Inspection Agencies, a copy of which can be downloaded from <https://industrialinspections.controlunion.com/en/terms-conditions>