

C3M-01 Body Hinge

Parts:

Part	Quantity	Manufacturing Method
Long Arm	2	Waterjet, mill
Short Arm	2	Waterjet, mill
Gas Arm Linkage	4	Waterjet, mill
Mounting Bracket Spacer	10	Waterjet, mill

Procedures:

Arms

1. Using part drawings, write G-code for waterjet to cut arms out of a single piece of 3/16" thick Aluminum bar.
 - a. [insert details about programming here]
 - b. Note that mounting holes are not to final size
2. In SDC, use mill to drill mounting holes to final size (M8)
 - a. First, ensure all sharp edges have been filed before handling parts
 - b. Mount all arms in a vertical stack in the mill clamp, all with end aligned with the end of the clamp
 - c. Using cylindrical edgefinder, zero x off the end of the clamp and y off the exposed long edge of the bars on the other side of the clamp. Remember to use appropriate speed for edgefinder (500RPMs)
 - d. Verify zeros and switch to 8.4mm bit (or Q in American drill bits). Enlarge holes to final size, using appropriate speed for material and drill size. Also remember to use cutting oil!
 - e. Note: if carefully done, the mounting bracket spacer can be cut the same way using the same origin, without the need to re-zero.

Mounting Bracket Spacers

1. Using part drawing, write G-code to cut spacers out of 1/8" Aluminum sheet.
 - a. Holes are final size
 - b. Note that these are cut from the same stock as the gas arm linkage
2. Test fit M6 bolts through the holes of each spacer
 - a. Mark pieces with holes that require reaming
3. In SDC, use mill to drill holes to final size (M6)
 - a. Follow procedure above for zeroing
 - b. Use 6.3mm bit (or E in American drill bits) to enlarge holes to final size

Gas Arm Spacer

1. Using part drawing, write G-code to cut gas arm spacer out of 1/8" Aluminum sheet
 - a. Holes are not to final size
 - b. Some spacers with have countersunk holes; obviously, this is not done using the waterjet
2. In SDC, use drill press to finish holes
 - a. Note: while this is not ideal in terms of accuracy, this part would be difficult to clamp and zero in a drill press due to its shape
 - b. Carefully locate each hole, using sufficient clamping in each case (at least two clamps located on opposite sides of the hole)
 - c. Drill holes to final size using 6.3mm drill bit (or E in American sizes)
 - i. Refer to part drawings to carefully countersink necessary holes
 - d. Test fit gas arm linkages to arms using M6 bolts
 - i. If the holes don't line up on any pieces, use a marker to mark where interference occurs, then repeat step C as necessary