



Customer Repair Report

Model OTHER	Serial Number IQY71982C	Manufacture Date	RMA Number 3002-R1	IRIDEX Service Contact Mark W.	Completion Date
Customer Name BioMedix Optotechnik & Devices (P) Ltd.		Customer Number 10044	Repair Type <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> non-warranty <input type="checkbox"/> Upgrade <input type="checkbox"/> Other		

Customer Description of Problem

E06010

Technician Product Evaluate:

-LOW POWER, THE FIBER DETECTOR PCBA WAS DAMAGED

-The laser module was degrading powers needed to replace OPS diode

Service Performed on Unit:

Waiting for customer approval

ITEMIZED REPAIR CHARGES

Part Number	Price/Unit	Quantity	Description	Total Price
65013		1	GENSIS 577-3000 M PN: 1118554	\$ 10,004.00
65989		1	INSULATION OPSL MFG :ARMACELL # F-05031	\$ 35.64
31720		1	ASSEMBLY CABLE TE COOLER	\$ 303.88
TECHNICIAN HQ		8	Technician Labor	\$ 2,280.00
65451		1	PCBA RESISTANCE FIBER DETECT	\$ 609.00
BILLABLE FREIGHT		1	BILLABLE FREIGHT	\$ -

TOTAL CHARGES **\$ 13,232.52**

Repaired products may contain reconditioned parts, but those are subject to the same specification and quality control standards applied to new materials and are warranted as such. The labor and parts are guaranteed for 90 days after the ship date of the product. Items not covered in the warranty are stated in the IRIDEX Standard Warranty Statement. Your signature below acknowledges the responsibility for payment of the listed charges. Freight and sales tax will be added where applicable.

Print Name:

Signature:

Date: