



Customer Repair Report

| | | | | | |
|---|----------------------------|--------------------------|---|----------------------------------|-----------------|
| Model OTHER | Serial Number GH16335TC | Manufacture Date | RMA Number 02454 | IRIDEX Service Contact Mark W | Completion Date |
| Customer Name Topcon Europe Medical B.V. | | Customer Number 14251 | Repair Type <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> non-warranty <input type="checkbox"/> Upgrade <input type="checkbox"/> Other | | |

Customer Description of Problem

TxCell does not turn on/off with the laser console on/off key. May have relay problem

Technician Product Evaluate:

TXCELL DOES NOT ON/OFF WHITM THE LASER CONSOLE ON/OFF KEY. INTERFACE BOARD IS BAD CAUSING THE PROBLEM, FIBER GOT LOW POWER.

Service Performed on Unit:

Waiting for customer approval

ITEMIZED REPAIR CHARGES

| Part Number | Price/Unit | Quantity | Description | Total Price |
|------------------|------------|----------|--|-------------|
| 70208 | | 1 | ASSY JUMPER RFID SLA 9FT EXTENDED JACKET | \$ 1,013.20 |
| 70014 | | 1 | PCBA SCANNER LASER INTERFACE & INTERLOCK | \$ 1,364.56 |
| TECHNICIAN HQ | | 6 | Technician Labor | \$ 1,710.00 |
| BILLABLE FREIGHT | | 0 | BILLABLE FREIGHT | \$ - |

TOTAL CHARGES **\$ 4,087.76**

Repaired products may contain reconditioned parts, but those are subject to the same specification and quality control standards applied to new materials and are warranted as such. The labor and parts are guaranteed for 90 days after the ship date of the product. Items not covered in the warranty are stated in the IRIDEX Standard Warranty Statement. Your signature below acknowledges the responsibility for payment of the listed charges. Freight and sales tax will be added where applicable.

Print Name:

Signature:

Date: