



Customer Repair Report

Model OTHER	Serial Number IQY71843C	Manufacture Date	RMA Number 03078	IRIDEX Service Contact Mark w	Completion Date
Customer Name BioMedix Optotechnik & Devices (P) Ltd.		Customer Number 10044	Repair Type <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> non-warranty <input type="checkbox"/> Upgrade <input type="checkbox"/> Other		

Customer Description of Problem

E06002

Technician Product Evaluate:

-E06002 power output out of ranges. The laser module has been open up, laser was degrading powers, needed to replace OPS diode, fiber detector PCBA damaged.

Service Performed on Unit:

Waiting for customer approval

ITEMIZED REPAIR CHARGES

Part Number	Price/Unit	Quantity	Description	Total Price
65013		1	GENSIS 577-3000 M PN: 1118554	\$ 10,804.86
31720		1	ASSEMBLY CABLE TE COOLER	\$ 303.88
65989		1	INSULATION OPSL MFG :ARMACELL # F-05031	\$ 35.64
65451		1	PCBA RESISTANCE FIBER DETECT	\$ 609.00
50299		4	CREW 1/4-80 FINE ADJUST BALL END HEX SET THORLABS: F25SS05	\$ 75.04
TECHNICIAN HQ		10	Technician Labor	\$ 2,850.00

TOTAL CHARGES **\$ 14,678.42**

Repaired products may contain reconditioned parts, but those are subject to the same specification and quality control standards applied to new materials and are warranted as such. The labor and parts are guaranteed for 90 days after the ship date of the product. Items not covered in the warranty are stated in the IRIDEX Standard Warranty Statement. Your signature below acknowledges the responsibility for payment of the listed charges. Freight and sales tax will be added where applicable.

Print Name:

Signature:

Date: