



Customer Repair Report

Model OTHER	Serial Number L2797	Manufacture Date	RMA Number 02974	IRIDEX Service Contact Mark W	Completion Date
Customer Name GE Healthcare		Customer Number 12635	Repair Type <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> non-warranty <input type="checkbox"/> Upgrade <input type="checkbox"/> Other		

Customer Description of Problem

Mirror control lever is broken and will not articulate the mirror

Technician Product Evaluate:

Cannot test due to viewing assembly dislocated from T-slot adapter, bent control stem, burnt halogen bulb, fractured T-slot adapter, white light shows dark shadow and will need alignment.

Service Performed on Unit:

Waiting for customer approval

ITEMIZED REPAIR CHARGES

Part Number	Price/Unit	Quantity	Description	Total Price
30800		1	T-SLOT ML LIO IRIDEX: 30800	\$ 31.00
10784		1	LIO Halogen Bulb-10W/6V Heine: X-004.88.068	\$ 135.00
11481		1	DUST CAP W/LANYARD DART: IRIS DWG:	\$ 3.00
12685		1	CONTROL STEM KNOB L & R VIEWING P/N: 11.65 38	\$ 110.00
12687		1	BEAM CONTROL STEMS HEINE SUPPORT KNOBS P/N: 11.65 15	\$ 125.00
TECHNICIAN HQ		4.5	Technician Labor	\$ 1,282.50
BILLABLE FREIGHT		1	BILLABLE FREIGHT	\$ 196.70

TOTAL CHARGES **\$ 1,883.20**

Repaired products may contain reconditioned parts, but those are subject to the same specification and quality control standards applied to new materials and are warranted as such. The labor and parts are guaranteed for 90 days after the ship date of the product. Items not covered in the warranty are stated in the IRIDEX Standard Warranty Statement. Your signature below acknowledges the responsibility for payment of the listed charges. Freight and sales tax will be added where applicable.

Print Name:

Signature:

Date: