



## Customer Repair Report

Model OTHER	Serial Number L2873	Manufacture Date	RMA Number 02574	IRIDEX Service Contact Mark W	Completion Date
Customer Name Oregon Health & Science Univ.		Customer Number 12992	Repair Type <input type="checkbox"/> Warranty <input checked="" type="checkbox"/> non-warranty <input type="checkbox"/> Upgrade <input type="checkbox"/> Other		

### Customer Description of Problem

loose item inside the LIO, Provide an estimate

### Technician Product Evaluate:

Cannot test due to Twisted and burnt assembly fiber optic, broken assembly fiber optic, loose viewing assembly from T-slot adapter, burnt halogen bulb, housing illumination will need adjustment and alignment. Nothing found loosing inside.

### Service Performed on Unit:

Waiting for customer approval

### ITEMIZED REPAIR CHARGES

Part Number	Price/Unit	Quantity	Description	Total Price
88080		1	Jumper Assy Multilam LIO+	\$ 984.00
12685		1	CONTROL STEM KNOB L & R VIEWING P/N: 11.65 38	\$ 110.00
12687		1	BEAM CONTROL STEMS HEINE SUPPORT KNOBS P/N: 11.65 15	\$ 125.00
11481		1	DUST CAP W/LANYARD DART: IRIS DWG:	\$ 3.00
10784		1	LIO Halogen Bulb-10W/6V Heine: X-004.88.068	\$ 135.00
TECHNICIAN HQ		5	Technician Labor	\$ 1,425.00
BILLABLE FREIGHT		1	BILLABLE FREIGHT	\$ 81.69

---

**TOTAL CHARGES** **\$ 2,863.69**

Repaired products may contain reconditioned parts, but those are subject to the same specification and quality control standards applied to new materials and are warranted as such. The labor and parts are guaranteed for 90 days after the ship date of the product. Items not covered in the warranty are stated in the IRIDEX Standard Warranty Statement. Your signature below acknowledges the responsibility for payment of the listed charges. Freight and sales tax will be added where applicable.

Print Name:

Signature:

Date: