



Failure analysis on collapsed towers of overhead electrical lines in the region Münsterland (Germany) 2005

C. Klinger^{*}, M. Mehdiانpour, D. Klingbeil, D. Bettge, R. Häcker, W. Baer

BAM Federal Institute for Materials Research and Testing, Berlin D-12200, Germany

ARTICLE INFO

Article history:

Available online 19 July 2011

Keywords:

Transmission towers
Thomas steel
Embrittlement
Snow loads
Ice loads

ABSTRACT

End of November 2005 strong south-west wind and heavy snowfall were predominant in the region Münsterland, north-western part of Germany. This led to accretion of a considerable quantity of wet snow to overhead electrical lines in form of snow rolls on the conductors. Eighty-two transmission towers failed catastrophically, most of them by buckling, however some by brittle fracture. As a consequence nearly 250,000 people have been cut off from electrical power supply for several days with major media attention.

This paper describes the forensic analysis in order to investigate the failure cause. Therefore extensive materials investigations, mechanical testing of original components and specimens thereof, estimations for the real wind and snow loads and their combinations, structural analyses as well as detailed evaluations on the basis of previous investigations, literature and regulations were conducted. It was revealed that some of the examined components were manufactured from Thomas steel which was partially in embrittled condition. The investigated towers fulfilled the design codes valid at the time of erection. However the present line loads of the wet snow rolls on the conductors exceeded by far the ones given in the design codes valid at that time.

The load case leading to failure was reconstructed by the derived positions of loads mainly caused by unequal and asymmetric distribution of snow rolls on left and right electrical system. The loads and corresponding stresses acting on the structure before failure were estimated. By comparison with the fracture forces from mechanical testing of original members of the collapsed tower the component that primarily failed was localised. The primary fracture occurred on a diagonal member under tension made of Thomas steel which was weakened by embrittlement. The failure cause was a combination of heavy weather conditions (storm, approx. 0 °C and wet snowfall leading to heavy snow rolls on conductors), asymmetric loading conditions and the usage of Thomas steel which was partially embrittled. Finally, recommendations for avoiding future failures are given.

© 2011 Elsevier Ltd. All rights reserved.

1. Introduction, failure background, aims of the investigation

On November 25th/26th, 2005 strong south-west wind with storm force (8 Bft. \approx 18 m/s) and heavy snowfall at a temperature of approx. 0 °C were predominant in the region Münsterland, Germany. Due to these weather conditions wet snow rolls formed around the conductors of several overhead transmission lines. This led to excessive line loads of approx. 5 kg/m, Fig. 1. Some of the covered conductors were sagging to the ground. Eighty-two tension and suspension towers of five different, 110 kV overhead electrical lines collapsed mostly by buckling, e.g. failed catastrophically, Fig. 2. As a consequence nearly

^{*} Corresponding author.

E-mail address: Christian.Klinger@bam.de (C. Klinger).



Fig. 1. Wet snow roll with clear ice cover, diameter approx. 13 cm, line load approx. 5 kg/m. Source RWE.



Fig. 2. Collapsed deviation tension tower M65 and suspension tower M66 (appearing small in background, right). Source RWE.

250.000 people have been cut off from electrical power supply for several days. The BAM Federal Institute for Materials Research and Testing was assigned by the German Federal Network Agency (BNetzA) for the conduction of a forensic failure analysis and an assessment of possible failure causes. The task was to find out if there were other causes besides the weather conditions. Following topics had to be investigated in detail:

- Materials conditions of the specimens taken from the towers.
- Possible ageing of the transmission towers' material.
- Description of failure mechanism(s).
- Code fulfilment at the time of erection or failure.
- Sufficiency of load assumptions, in particular the assigned ice loading zone, given in former or present (time of failure) codes.

Putting it differently the aims of the investigation described in this paper were to identify the loading situation present during the disaster, which of the towers collapsed first, and which substructure in these towers failed first and if embrittlement of the steel used was one of the failure causes. Furthermore, one crucial task was to give recommendations for the prevention of similar disasters. Based on these recommendations the authority BNetzA issued new requirements [1]. Contrary to other publications such as [2] or [3], the aim of this investigation was not to predict the failure under given loads by numerical calculations. The intention was a proof (combined analytical–experimental) of an evident failure by derivation of the corresponding loading (from picture information) and determination of the reduced load carrying capacity of structural parts.

Brittle fractures are not characteristic for this type of mild structural steel. Pohlmann [4] described brittle fractures of diagonal members and corner rods he found analysing in service failures of transmission towers in Europe. Helms et al. [5] investigated the failure of a transmission tower of the german railways and found out, that embrittlement is localised around the stamped holes of steel profiles made of Thomas steel, compare Sections 2.3 and 2.4.

Latest publications regarding failure analyses of transmission towers describe the simulation techniques used for structural failure prediction in order to avoid expensive full scale tests of transmission lattice towers [2,3] or transmission poles [6]. Moon et al. [7] carried out sub-assemblage test of a half-scaled transmission tower to estimate its performance against wind loads and compared the experimental results with those of numerical analysis. Forensic analyses like those on failures of wind turbine towers [8,9] have not been published for transmission tower failures until now.

2. Failure investigation and results

2.1. Failure site inspection

During a visit of the failure site in the western region of Münsterland eleven of the failed electricity towers were inspected on December 20th in 2005, Fig. 3. Signs of surface corrosion were not found. A corrosion induced weakening of the structures could be excluded. Fifteen samples were taken from four of the failed transmission towers: broken diagonal members, corner rod connections and more components. The collapsed transmission tower named M65, Fig. 4, was in focus of the failure investigation based on its function as deviation tension tower, the brittle fracture of a component found there, its condition and accessibility. It was assumed, that the collapse of M65 as deviation tension tower is responsible for the failure of the supporting towers M66...M73. Moreover, an extensive photographic documentation shortly after failure has been available



Fig. 3. Failure site inspection, transmission tower M65 layed down for inspection. Searching for ruptures with brittle fracture surface.




Fig. 4. Failure site inspection, transmission tower M65 in as failed position (left), Source RWE. Corner rods E3 and E4. Diagonal members M65-..., ruptures are marked (right).



Fig. 7. Original fracture surface M65-04 after cleaning. Most of the rust was removed.




Fig. 8. Magnification of fracture surface M65-04, cp. Fig. 7, intergranular fracture with etching pits. SEM, SE mode.




Fig. 9. Fracture surface M65-04, ductile fracture with etching pits at the seams of the fracture surface. SEM, SE mode.

background and mechanisms of ageing as well as its impact on mechanical and technological properties of Thomas steel is given in [10].

In 1878 Sidney G. Thomas and Percy G. Gilchrist introduced a method for steel making which is suitable to use iron ores rich in Phosphorus. The method is based on a basic lining of the Bessemer converter and air blasting from the bottom of the converter. Later on the method was called Thomas process and all steels produced by it Thomas steels. Over the decades, a number of technological modifications of the Thomas process had been successfully invented to improve the properties of Thomas steels. It is important to note that Thomas steels had been used very successfully and gained a remarkable economical importance worldwide. In Germany, where solely until 1943 about 300 million tons of Thomas steels had been molten [11], the production had remained over a period of about 100 years until the late 1970s. At that time the steel making by Thomas process was ceased due to technical and economical aspects.

From a metallurgical point of view, Thomas steels are typically characterized by elevated contents of Phosphorus (due to the iron ore) and Nitrogen (due to air blasting) and they are comparably low in carbon, Table 1. The nitrogen content >0.01 wt.% makes Thomas steels susceptible to ageing.

2.4. Ageing of Thomas steel

Ageing is a time dependent alteration of mechanical and technological steel properties whereas two basic mechanisms are distinguished. Age hardening (quench-ageing, natural ageing) depicts the blockage of dislocations by interstitial atoms and the precipitation of embrittling nitrides and carbides in a supersaturated-iron solid solution. Ageing after a mechanical deformation is denoted strain ageing. Within strain ageing the migration of interstitial atoms to dislocations and their blockage is the predominant mechanism due to the high number of dislocations present. The blockage of dislocations by interstitial atoms as well as the complication of dislocation movement by precipitations reduce ductility and toughness of the material. Basically, both interstitial elements, nitrogen as well as carbon, take part in diffusion processes within ageing. But the major role can be attributed to nitrogen due to its higher solubility in the iron lattice and its higher diffusion rate [12–16].

Embrittlement as result of ageing may become a prime issue with respect to the assessment of the loading behaviour and safety of Thomas steel components. Outstanding examples are cut edges and stamped holes in sheet metal, plates and profiles of screwed or riveted steel structures. These material regions are exposed to significant plastic deformation which acts as prerequisite of strain ageing. In combination with a steel grade susceptible to ageing embrittlement (like Thomas steels) as well as structural stress concentration, higher stress triaxiality due to component thickness and loading features like low temperature and/or higher loading rate brittle fractures can be caused in service. Details of a corresponding failure analysis on overhead transmission line towers of Deutsche Bundesbahn are reported in [5].

2.5. Mechanical testing

In order to find out the type of steel used, standard specimens were prepared from components from tower M65, see Section 2.1, and mainly used for tensile and Charpy tests. Tensile tests were performed in accordance to DIN EN 10002-1 [17]. Tensile strength and elongation of all tested standard specimens ($R_m \sim 400$ MPa, $A \sim 37\%$) were within the tolerances of materials standards for mild steel (present and year of erection). Standard Charpy specimens ISO-V made of a diagonal member of M65 fulfilled the 27 J-criterion at 20 °C with a value of 47 J but failed at 0 °C with a value of 21 J and at –20 °C with a value of 6 J. Thus Charpy testing revealed low temperature embrittlement which still was in agreement with old material standards (DIN 17100:1957). Mechanical testing of standard specimens did not reveal any effect of embrittlement at all. This may be explained by the small volume of strain aged material around stamped holes in components, see Section 2.4, which usually is not part of the material volume of standard specimens.

For estimating the effect of embrittlement on fracture forces, component type specimens containing the original riveted or bolted connection between corner rod and diagonal member were worked out of original parts of deviation tower M65 and tested, Fig. 10. The tests were performed at ambient temperature and at 0 °C and resulted in more or less brittle fractures, Fig. 11. The results were in perfect agreement with previous investigations [4].

The tensile tests of the structural parts, see Fig. 11 and Table 2, revealed fracture forces which partly achieved only 60% of the design capacity, the estimated minimum fracture forces based on the corresponding codes [18]. This means that standard specimens without holes or notches are not suitable for the identification of Thomas steel embrittlement of components, because they did not undergo plastic deformation and ageing. Today steel for use as a construction material for transmission towers has to comply with Sxxx-JR requirements, e.g. a transition temperature ≤ -70 °C.

Table 1

Chemical composition of original members of tower M65 (built 1960). All reported values are in wt.%.

	C	Si	Mn	P	S	N
Corner rod (M65)	0.1690	<0.006	0.3680	0.0338	0.0267	0.0120
Diagonal member (M65)	0.0480	<0.006	0.4680	0.1040	0.0666	0.0160




Fig. 10. Test rig for tensile testing of components (corner rod/diagonal member connection).



Fig. 11. Tensile testing of structural parts (corner rod/diagonal member connection). Brittle fracture of netto cross-section.

Table 2

Results of the tensile tests of structural parts of tower M65.

Tested component	Net cross section (mm ²)	Calc. max. force (kN)	Test temp. (°C)	Max. force during test (kN)	Deviation ¹ %
B3	444	151	23	188	25
B5	444	151	23	177	17
B4	445	151	0	185	22
A5	444	151	0	182	21
C2	464	158	23	137	n.a. ²
C1	464	227	23	155	n.a. ²
M65-07B	464	158	23	131	−17
M65-07A	464	158	23	143	n.a. ²
C3	464	158	0	158	0
C7	464	158	0	164	4
M65-01	464	158	0	170	n.a. ²
M65-08A	464	158	0	125	−21
M65-09A	464	158	0	94	−40

¹ Deviation between calculated maximum force and maximum force during test in %.

² Failure of bolt or rivet.




Fig. 12. Fracture surface M65-09 after mechanical tests in the laboratory. Similar fractographic appearance as the original fracture surface, cp. Figs. 6 and 7.

The fracture surfaces of diagonal members tested in BAM, Fig. 12, appeared almost identical to the original fracture surface concerning areas of brittle and ductile fracture, Fig. 6. Therefore it was concluded, that the fracture forces of the diagonal members during failure of the tower were about the value of those tested in the laboratory (94...125 kN), cp. Table 2. Consequently, these fracture forces were used in further static analyses.

2.6. Influences, failure load case

Weather conditions (snowfall, strong southwest wind) led to preferred deposition of snow on conductors of overhead electrical lines (northwest–southeast) perpendicular to dominant wind direction (southwest). Wet snow rolls with 13 cm and more in diameter formed, Fig. 1, that exceeded the line loads given in former [18] and current [19] design codes. At direction changes of overhead electrical lines specially designed deviation tension towers are used which are able to carry higher horizontal loads. During the severe weather conditions a change in line direction led to a deposition of snow rolls on the conductors, Fig. 1, perpendicular to the wind direction while in the direction parallel to the wind there were nearly no snow rolls. This applies for nearly all aerial lines that were pulled down during that night. Starting from the lines affected, it was investigated why the towers failed. Extensive photographic documentation provided by the operator (references in [20]) showed that snow rolls of the critical size were only existent at one field of deviation towers but not on the other field more parallel to wind direction. Moreover, photographs showed fields of this line BL1503 where conductors on the right side were covered with ice while they were not on the left side. This could be explained by different electrical currents of left and right electric system during snow/ice accretion. This meant for the further investigated deviation tension tower M65 that only the conductors on the right side (viewing direction towards increasing tower numbers) were covered with snow rolls while the conductors on the left side were not. This led to an asymmetric load distribution. The incoming conductors had only little snow coverage. This onesided and field-dependent (unequal) loading with line loads of approx. 5 kg/m was identified as load case before failure of tower M65 and will be referred to as “failure load case”, Fig. 13.

2.7. Load analysis

One deviation tower (M65) and one suspension tower (M66) were modelled for linear structural analysis. According to the current design code for overhead electrical lines (EN 50341-1:2001[19]) and also according to all the earlier codes (e.g. VDE0210:1958 [18]) linear analysis is sufficient. It could be confirmed that the transmission towers M65 and M66 fulfilled the code requirements (VDE0210:1958, [18]) applicable at the time of erection. The calculations clearly showed that for the forensic failure analysis further investigation should be focused on the deviation tower M65 as the suspension tower M66 is much less susceptible to increasing vertical loads respectively asymmetrical loading. From the failure site inspection (see Section 2.1) and fracture surfaces analysis (see Section 2.2) it was obvious, that rupture under tensile loads must be considered.

A “failure load case” could be derived on basis of the available information, Section 2.6, which was used to calculate the forces acting on the components prior to failure, Fig. 13. However, on site rupture was not observed for components of tower M65 showing the highest calculated tensile forces, e.g. highest utilisation factor. By comparison with experimental fracture forces of components (diagonal members) from tower M65, Section 2.5, the component showing primary failure could be identified: primary failure occurred at the joint of a diagonal member under calculated tensile force $F_{S,calc}$ of about




Fig. 13. FE-model of transmission tower M65, main tower dimensions, reconstructed “failure load case” with applied forces in kN and resulting loads on the diagonal member that failed initially.

112 kN, see diagonal member M65-04 in Fig. 4. This diagonal member with a L profile Section 60 mm × 60 mm × 6 mm originally had a design capacity $F_{R,calc} = 158$ kN. Its failure reason is the weakening of this member (made of Thomas steel) by embrittlement down to a fracture force $F_{R,exp}$ of about 100 kN (94–125 kN), see Section 2.5. The brittle fracture of diagonal member M65-04 occurred due to ageing and embrittlement around the stamped holes (highly stretched zone) for the rivets of the joint connecting the member and the main leg, Figs. 6 and 7. As a consequence of the rupture of the diagonal member M65-04, the neighbouring diagonals M65-01 and M65-02 in Fig. 4 ruptured in a similar way due to a subsequent sudden increase of their load. This caused an inevitably large deformation of the tower beneath the cross arms and the tower failed eventually due to lack of bracings and buckling of the main legs.

Other failure mechanisms such as stability failure by buckling of single highly stressed diagonal members, Fig. 4, were under consideration but discarded as primary failure causes since they were contrary to visual observations [20].

3. Failure causes: a combination of several factors

The reason for the low fracture forces of the diagonal members is embrittlement by nitrogen that was introduced during steel production (Thomas-procedure). With high probability the “failure load case” would not have led to the collapse of

deviation tension tower M65 if all diagonal members had been as ductile as mild steel in usual condition and as Thomas steel prior to embrittlement. Due to fracture of a diagonal member under tension at least two more diagonal members failed, Fig. 4. As a consequence the deviation tension tower M65 failed catastrophically, Fig. 2. In the following eight supporting towers were pulled down as a consequence of the cascade effect, right in Fig. 2. The cascade effect also applies to other overhead electrical lines with similar orientation and situation (wind angle, snow rolls). The catastrophic failure of the line BL1503, with tower M65 examined in detail, was caused by a combination of weather conditions, orientation of the line regarding wind direction, onesided formation of snow rolls probably supported by differences in electrical currents between the conductors and usage of members made of Thomas steel and its embrittlement due to ageing.

4. Assessment based on previous investigations, literature survey and regulations

Ageing of Thomas steel as well as the resulting embrittlement is well-known [4] (more references in [20]). This embrittlement causes a remarkable reduction of fracture forces at the connection components [4]. Numerous previous investigations provided by the operator show that component-tested diagonal members possessed in some cases only 60% of the minimum fracture force derived from the corresponding codes. Line loads of approx. 5 kg/m (derived from the size of the wet snow rolls, Fig. 1) and their position (asymmetric distribution etc.) were neither given in the standards relevant at the time of erection [18] nor in the one relevant at the time of the failure [19,21].

5. Recommendations and preventive actions

The results of the thorough investigation [20] raised the awareness of authorities and public that ageing of Thomas steel is a safety and economically relevant challenge for transmission grid operators. In order to prevent similar future failures, recommendations are given in [20,1]. The following recommendations and improvements for regulations/standards/codes and for refurbishment of the existing transmission towers [22] and building of new ones can be derived from the failure analysis conducted. These recommendations have influenced the revision of existing and the issuing of new standards in Germany (given in curly brackets below):

- The standard for construction of power towers should be supplemented by new ice load zones. {implemented nowadays in [23]}
- The line loads due to ice should be checked and re-assessed regarding values {implemented nowadays in [23]} and repetition period.
- The “failure load case” (load positions onesided, unequal in the followings fields) of ice rolls (or similar) discussed in this publication should be added to the load cases in the standard. {implemented nowadays in [23]}
- Existing electricity towers should be refurbished under the following aspects:
 1. Identification and replacement of tension-loaded components made of Thomas steel which are in case of embrittlement due to ageing vulnerable to fracture. {implemented nowadays in [22]}
 2. Consideration of the current transmission tower standards [23] in case of refurbishment.
 3. Priority refurbishment of the deviation tension electricity towers because of potentially greater consequential damages. {implemented nowadays in [22]}

Acknowledgements

The authors would like to thank the German Federal Network Agency (BNetzA) for the permission to publish the results of this failure investigation [20] and R. Wallstabe for his assistance in preparing the english manuscript.

References

- [1] Bundesnetzagentur (BNetzA), Untersuchungsbericht über die Versorgungsstörungen im Netzgebiet des RWE im Münsterland vom 25.11.2005, Bonn, published <<http://www.bundesnetzagentur.de/cae/servlet/contentblob/35932/publicationFile/1588/UntersuchungsberichtId6420pdf.pdf>> (06 2006).
- [2] Albermani F, Kitiipornchai S, Chan R. Failure analysis of transmission towers. Eng Fail Anal 2009;16:1922–8.
- [3] Prasad Rao G, Samuel Knight N, Lakshmanan N, Iyer NR. Investigation of transmission line tower failures. Eng Fail Anal 2010;17:1127–41.
- [4] H. Pohlmann, Schadensanalyse, Resttragfähigkeit und Sanierungskonzepte von Hochspannungs-Freileitungsmasten, Ph.D. Thesis, Universität-Gesamthochschule Essen, 1996.
- [5] Helms R, Kühn H-D, Martin E. Safety against brittle fracture of structural steelwork elements with punched holes. Arch Eisenhüttenwesen 1973;44:917–26.
- [6] Prasad Rao R, Bala Gopal N, Rokade R, Mohan S. Analytical and experimental studies on 400 and 132 kV steel transmission poles. Eng Fail Anal 2011;18:1018–29.
- [7] Byoung-Wook Moon B-W, Park J-H, Lee S-K, Kim J, Kim T, Min K-W. Performance evaluation of a transmission tower by substructure test. J Construct Steel Res 2009;65:1–11.
- [8] R. Lacalle, S. Cicero, J. -lvarez, R. Cicero, V. Madrazo, On the analysis of the causes of cracking in a wind tower, Eng Fail Anal, in press, doi:10.1016/j.engfailanal.2011.02.012 [Corrected Proof 22.02.11].
- [9] Chou J-S, Tu W-T. Failure analysis and risk management of a collapsed large wind turbine tower. Eng Fail Anal 2011;18:295–313.
- [10] Baer W. Zur Alterung von Thomasstählen, vol. 49. MP Materials Testing; 2007. p. 37–47.

- [11] Dick W. Die Thomasstähle. Härterei-Technische Mitteilungen 1943;2:100–9.
- [12] Stolte E, Heller W. Present state of our knowledge on ageing of steels. Part I. Underlying principles. Stahl u. Eisen 1970;90:861–8.
- [13] Heller W, Stolte E. Present state of our knowledge on ageing of steels. Part II. Effects of ageing on steels. Stahl u. Eisen 1970;90:909–16.
- [14] Felix W. Investigation of natural and artificial ageing of general construction steels. Arch Eisenhüttenwesen 1965;36:35–41.
- [15] Verein Deutscher Eisenhüttenleute, editor. Werkstoffkunde Stahl. Band 1: Grundlagen. Springer Verlag; 1984.
- [16] Dahl W, Lenz E. Effect of manganese content on quench ageing and strain ageing of carbon and/or nitrogen. Arch Eisenhüttenwesen 1975;46:119–25.
- [17] DIN EN 10002-1, Metallic materials – tensile testing – part 1: method of test at ambient temperature, German version (12 2001).
- [18] VDE 0210, Vorschriften für den Bau von Starkstrom-Freileitungen (02 1958).
- [19] DIN EN 50341-1, Overhead electrical lines exceeding AC 45 kV – part 1: general requirements – common specifications, German version (03 2002).
- [20] BAM-Gutachten V.3/442, Schadensanalyse an im Münsterland umgebrochenen Strommasten, BAM Bundesanstalt für Materialforschung und-prüfung, Berlin (04 2006).
- [21] DIN EN 50341-3-4, Overhead electrical lines exceeding AC 45 kV – part 3: national normative aspects (NNA), German version (2001).
- [22] VDE-AR-N 4210-3, Test and evaluation methods for determining the load capacity of structural members made of Thomas steel in steel lattice overhead line towers with nominal voltages of 110 kV and above, German version (05 2011).
- [23] DIN EN 50341-1 VDE 0210-1, overhead electrical lines exceeding AC 45 kV – part 1: general requirements – common specifications, German version (04 2010).