

NVD



VULNERABILITIES

SEARCH AND STATISTICS

Q Search Results (Refine Search)

Search Parameters:

- Results Type: Overview
- Keyword (text search): cbr750
- Search Type: Search All
- CPE Name Search: false




There are **30** matching records.
Displaying matches **1** through **20**.

Sort results by:




Publish Date Descending 




Sort




1 2 > >>

Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45635	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:19 PM -0500</p>	<p>V4.0:(not available) V3.1: 8.8 HIGH V2.0: 5.8 MEDIUM</p>




Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45634	Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12. Published: December 25, 2021; 8:15:19 PM -0500	V4.0:(not available) V3.1: 8.8 HIGH V2.0: 5.8 MEDIUM
CVE-2021-45633	Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RBK752 before 3.2.17.12, and RBK852 before 3.2.17.12. Published: December 25, 2021; 8:15:19 PM -0500	V4.0:(not available) V3.1: 8.8 HIGH V2.0: 5.8 MEDIUM
CVE-2021-45632	Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12. Published: December 25, 2021; 8:15:19 PM -0500	V4.0:(not available) V3.1: 8.8 HIGH V2.0: 5.8 MEDIUM
CVE-2021-45631	Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12. Published: December 25, 2021; 8:15:19 PM -0500	V4.0:(not available) V3.1: 8.8 HIGH V2.0: 5.8 MEDIUM




Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45630	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:19 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 7.5 HIGH</p>
CVE-2021-45629	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:19 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 8.8 HIGH</p> <p>V2.0: 5.8 MEDIUM</p>
CVE-2021-45628	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 3.2.18.2, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, RBS850 before 3.2.17.12, RBS40V before 2.6.2.4, and RBW30 before 2.6.2.2.</p> <p>Published: December 25, 2021; 8:15:19 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 8.8 HIGH</p> <p>V2.0: 5.8 MEDIUM</p>
CVE-2021-45627	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 4.6.3.6, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:19 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 7.5 HIGH</p>




Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45622	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, EAX20 before 1.0.0.58, EAX80 before 1.0.1.68, EX7500 before 1.0.0.74, LAX20 before 1.1.6.28, MK62 before 1.0.6.116, MR60 before 1.0.6.116, MS60 before 1.0.6.116, R6400 before 1.0.1.70, R6400v2 before 1.0.4.118, R6700v3 before 1.0.4.118, R6900P before 1.3.3.140, R7000 before 1.0.11.116, R7000P before 1.3.3.140, R7850 before 1.0.5.68, R7900 before 1.0.4.38, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.68, R8000P before 1.4.2.84, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, XR1000 before 1.0.0.58, and XR300 before 1.0.3.68.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>




Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45621	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 3.2.18.2, EAX20 before 1.0.0.58, EAX80 before 1.0.1.68, EX3700 before 1.0.0.94, EX3800 before 1.0.0.94, EX6120 before 1.0.0.64, EX6130 before 1.0.0.44, EX7000 before 1.0.1.104, EX7500 before 1.0.0.74, LAX20 before 1.1.6.28, MR60 before 1.0.6.116, MS60 before 1.0.6.116, R6300v2 before 1.0.4.52, R6400 before 1.0.1.70, R6400v2 before 1.0.4.106, R6700v3 before 1.0.4.106, R6900P before 1.3.3.140, R7000 before 1.0.11.126, R7000P before 1.3.3.140, R7100LG before 1.0.0.72, R7850 before 1.0.5.74, R7900 before 1.0.4.46, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.74, R8000P before 1.4.2.84, R8300 before 1.0.2.154, R8500 before 1.0.2.154, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, XR1000 before 1.0.0.58, and XR300 before 1.0.3.68.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>

Vuln ID 旗	Summary ⓘ	CVSS Severity ⚖️
CVE-2021-45620	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, EAX20 before 1.0.0.58, EAX80 before 1.0.1.68, LAX20 before 1.1.6.28, MR60 before 1.0.6.116, MR80 before 1.1.2.20, MS60 before 1.0.6.116, MS80 before 1.1.2.20, MK62 before 1.0.6.116, MK83 before 1.1.2.20, R6400 before 1.0.1.70, R6400v2 before 1.0.4.106, R6700v3 before 1.0.4.106, R6900P before 1.3.3.140, R7000 before 1.0.11.126, R7000P before 1.3.3.140, R7850 before 1.0.5.74, R7900 before 1.0.4.46, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.74, R8000P before 1.4.2.84, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, XR1000 before 1.0.0.58, and XR300 before 1.0.3.68.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>

Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45616	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR750 before 3.2.18.2, LAX20 before 1.1.6.28, MK62 before 1.0.6.116, MR60 before 1.0.6.116, MS60 before 1.0.6.116, R6900P before 1.3.3.140, R7000 before 1.0.11.126, R7000P before 1.3.3.140, R7850 before 1.0.5.68, R7900 before 1.0.4.46, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.68, R8000P before 1.4.2.84, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, and XR1000 before 1.0.0.58.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>
CVE-2021-45615	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000P before 1.4.2.84, R8300 before 1.0.2.154, R8500 before 1.0.2.154, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 8.8 HIGH</p> <p>V2.0: 5.8 MEDIUM</p>

Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45613	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, D7000v2 before 1.0.0.74, LAX20 before 1.1.6.28, MK62 before 1.0.6.116, MR60 before 1.0.6.116, MS60 before 1.0.6.116, MR80 before 1.1.2.20, MS80 before 1.1.2.20, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX43 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX35v2 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBR750 before 3.2.17.12, RBS750 before 3.2.17.12, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, RBS850 before 3.2.17.12, and XR1000 before 1.0.0.58.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>
CVE-2021-45612	<p>Certain NETGEAR devices are affected by command injection by an unauthenticated attacker. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, EAX20 before 1.0.0.58, EAX80 before 1.0.1.68, EX7500 before 1.0.0.74, LAX20 before 1.1.6.28, MK62 before 1.0.6.116, MR60 before 1.0.6.116, MS60 before 1.0.6.116, R6400v2 before 1.0.4.118, R6700v3 before 1.0.4.118, R6900P before 1.3.3.140, R7000 before 1.0.11.126, R7000P before 1.3.3.140, R7850 before 1.0.5.74, R7900 before 1.0.4.46, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.74, R8000P before 1.4.2.84, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, XR1000 before 1.0.0.58, and XR300 before 1.0.3.68.</p> <p>Published: December 25, 2021; 8:15:18 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 9.8 CRITICAL</p> <p>V2.0: 10.0 HIGH</p>

Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45604	<p>Certain NETGEAR devices are affected by a stack-based buffer overflow by an authenticated user. This affects CBR750 before 3.2.18.2, D6220 before 1.0.0.68, D6400 before 1.0.0.102, D8500 before 1.0.3.60, LAX20 before 1.1.6.28, MK62 before 1.0.6.116, MR60 before 1.0.6.116, MS60 before 1.0.6.116, R6300v2 before 1.0.4.50, R6400 before 1.0.1.68, R6400v2 before 1.0.4.118, R6700v3 before 1.0.4.118, R6900P before 1.3.3.140, R7000 before 1.0.11.116, R7000P before 1.3.3.140, R7850 before 1.0.5.68, R7900 before 1.0.4.38, R7900P before 1.4.2.84, R7960P before 1.4.2.84, R8000 before 1.0.4.68, R8000P before 1.4.2.84, RAX15 before 1.0.3.96, RAX20 before 1.0.3.96, RAX200 before 1.0.4.120, RAX35v2 before 1.0.3.96, RAX40v2 before 1.0.3.96, RAX43 before 1.0.3.96, RAX45 before 1.0.3.96, RAX50 before 1.0.3.96, RAX75 before 1.0.4.120, RAX80 before 1.0.4.120, RBK752 before 3.2.17.12, RBK852 before 3.2.17.12, RBR750 before 3.2.17.12, RBR850 before 3.2.17.12, RBS750 before 3.2.17.12, RBS850 before 3.2.17.12, RS400 before 1.5.1.80, and XR1000 before 1.0.0.58.</p> <p>Published: December 25, 2021; 8:15:17 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 4.5 MEDIUM</p> <p>V2.0: 2.7 LOW</p>
CVE-2021-45601	<p>Certain NETGEAR devices are affected by command injection by an authenticated user. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:17 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 8.8 HIGH</p> <p>V2.0: 6.5 MEDIUM</p>
CVE-2021-45600	<p>Certain NETGEAR devices are affected by command injection by an authenticated user. This affects CBR750 before 4.6.3.6, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.</p> <p>Published: December 25, 2021; 8:15:17 PM -0500</p>	<p>V4.0:(not available)</p> <p>V3.1: 7.2 HIGH</p> <p>V2.0: 6.5 MEDIUM</p>

Vuln ID 	Summary 	CVSS Severity 
CVE-2021-45599	Certain NETGEAR devices are affected by command injection by an authenticated user. This affects CBR40 before 2.5.0.24, CBR750 before 4.6.3.6, RBK852 before 3.2.17.12, RBR850 before 3.2.17.12, and RBS850 before 3.2.17.12.	V4.0:(not available) V3.1: 8.8 HIGH V2.0: 6.5 MEDIUM
	Published: December 25, 2021; 8:15:17 PM -0500	

1	2	>	>>
---	---	---	----



HEADQUARTERS

100 Bureau Drive
Gaithersburg, MD 20899
(301) 975-2000

[Webmaster](#) | [Contact Us](#) | [Our Other Offices](#)

Incident Response Assistance and Non-NVD Related Technical Cyber Security Questions:

US-CERT Security Operations Center
Email: soc@us-cert.gov
Phone: 1-888-282-0870

[Privacy](#) | [Accessibility](#) | [Privacy Program](#) | [Copyrights](#) | [Vulnerability Disclosure](#) | [No Fear Act Policy](#) | [FOIA](#) | [Environmental Policy](#)
[Scientific Integrity](#) | [Information Quality Standards](#) | [Commerce.gov](#) | [Science.gov](#) | [USA.gov](#)