

| Hazardous Component(s) | CAS Number | Percentage* |
|---|------------|-------------|
| Calcium carbonate | 471-34-1 | 10 - 30 |
| Garnet-group minerals | 12178-41-5 | 10 - 30 |
| Butan-2-one O,O',O''-(vinylsilyldiene)trioxime | 2224-33-1 | 5 - 10 |
| Octadecanoic acid | 57-11-4 | 0.1 - 1 |
| Aluminum | 7429-90-5 | 0.1 - 1 |
| Butan-2-one O,O',O'',O'''-silanetetrayltetraoxime | 34206-40-1 | 0.1 - 1 |
| Butanone oxime | 96-29-7 | 1 - 5 |
| White mineral oil (petroleum), highly refined | 8042-47-5 | 0.1 - 1 |

* Exact percentage is a trade secret. Concentration range is provided to assist users in providing appropriate protections.

4. FIRST AID MEASURES

| | |
|----------------------|--|
| Inhalation: | Move to fresh air in case of accidental inhalation of vapours or decomposition products. If symptoms develop and persist, get medical attention. |
| Skin contact: | Wipe off paste with paper towel or cloth. Wash with soap and water. If skin irritation persists, call a physician. |
| Eye contact: | Rinse immediately with plenty of water, also under the eyelids, for at least 15 minutes. Get medical attention. |
| Ingestion: | Do not induce vomiting. In case of adverse health effects seek medical advice. |
| Symptoms: | See Section 11. |

5. FIRE FIGHTING MEASURES

| | |
|---|---|
| Extinguishing media: | Foam, dry chemical or carbon dioxide. |
| Special firefighting procedures: | Wear self contained breathing apparatus. Prevent inhalation of fumes and gases. |
| Unusual fire or explosion hazards: | None |
| Hazardous combustion products: | Oxides of carbon. Oxides of silicon. Formaldehyde. Irritating organic vapours. |

6. ACCIDENTAL RELEASE MEASURES

Use personal protection recommended in Section 8, isolate the hazard area and deny entry to unnecessary and unprotected personnel.

| | |
|-----------------------------------|---|
| Environmental precautions: | Do not allow material to contaminate ground water system. |
| Clean-up methods: | Scrape up as much material as possible. Maintain good ventilation for large spills. Place scrap material in a well ventilated area and allow to cure to rubber. |