

DR 400

Type 5520

No. 168

DR 600

Type 5530

No. 214

DR Retrofit

Type 5400

No. 134

DX-D 100

Type 5410

No. 140

DX-D 300

Type 8207

No. 174

DX-D 400

Type 5420

No. 128

DX-D 500

Type 8206

No. 90

DX-D 600

Type 5430

No. 195

Document ID: 80013595

Service Bulletin

Activate missing Varian logging on VRN 8.0 systems

Task

Timing	Category	Scope
<input checked="" type="radio"/> Next service as agreed with customer	<input type="radio"/> Apply at all sites	<input checked="" type="radio"/> Problem Record: PRB2000819
	<input checked="" type="radio"/> Apply at affected sites as listed below	
	<input type="radio"/> Optional to improve functionality of product	

Task Tracking

After completion of your task the following entry in your Service Report is required:

80013595

*

* Insert the document number into the field "Comment" (SMS form).

Purpose of this document:

- Varian logging is by default not active on systems with VRN 8.0.
- This document instructs to activate VRN 8.0 logging (remote or on site) on the next service intervention.

Affected systems:

All DR systems with software VRN 8.0 are affected.

The solutions described in this Service Bulletin have been reviewed and are NOT reportable because no actions are taken to reduce a "Risk to Health" according to our risk assessment process.

1 Introduction

This Service Bulletin describes the solution for the following Problem Record:

Missing Varian / Varex logging with VRN8.0 [PRB2000819]

Symptom In case of problems with a Varian / Varex* Detector (DX-D 10, DX-D 20, DX-D Fixed) it might be, that the GSN asks for Varian log files for troubleshooting.

The C:/IMAGERS folder has to contain the logging that is needed for the Varian support:

With VRN 8.0, the Varian logging is not active and very limited log files are available there. Very limited log files means: Only the very last / recent one of maybe maximum one day.

*In the past, the company which developed the detectors and delivers the related software was called Varian. Recently it has been renamed to Varex. This is the reason why both names will be used in some documents.

Cause Software issue: With VRN 8.0 no Varian log files are created.

Workaround

- (1) Activate **Development logging** in **MUSICA Acquisition Workstation > Service > Logging**
- (2) Reproduce the fault.
- (3) Copy Varian log files from **C:/IMAGERS\<detector serial number>** folder.



NOTE:

Since solving the problem requires a similar effort as the workaround, it is recommended to implement the solution right away.

Solution On the next service intervention (remote or on site), adapt **HcpConfig.ini** file as follows:

- (1) Open **C:/IMAGERS\<detector serial number>\HcpConfig.ini** with Notepad.
- (2) Add the bold marked line:

```
[VirtCp]
FileRev=2
LogRotation=20
DebugMode=2
```

- (3) Save the ini file.
- (4) Repeat this step for all other Varian Detectors.
- (5) Restart NX.



NOTE:

The *DX-D 10 / DX-D 20 / DX-D Fixed Detector - Service Manual*, Document ID [41222172](#), includes the adaptation of HcpConfig.ini also for new installations of Varian Detectors, for example when replacing a Windows 7 PC by a Windows 10 PC.

2 Verification

**IMPORTANT:**

After the service intervention, make sure that the device is operational as intended, before you hand it over to the customer.

Follow the instructions in this section precisely.

- (1) Verify proper editing by checking presence of Varian log files in **C:/IMAGERS\<detector serial number>** folder.

3 Keywords

Varian, Varex, logging, troubleshooting; VRN8; logfile

4 Version history

Version	Change	Date
1.0	Initial Version	07-2022