

## Service Bulletin

**Revised version: Previously announced DMC Firmware V11R3b8 is replaced by V11R3b9 due to a software issue in b8.**

## Solutions for movements caused by disinfection liquids on the collimator hand-grips

### Task

| Timing  | Category   | Scope  |
|---|--|--|
| <input checked="" type="radio"/> Next service as agreed with customer | <input type="radio"/> Apply at all sites                                 | <input checked="" type="radio"/> Problem Record:<br>PRB2000478, PRB2000628 |
|   | <input checked="" type="radio"/> Apply at affected sites as listed below |  |
|   | <input type="radio"/> Optional to improve functionality of product       |  |

### Task Tracking

After completion of your task the following entry in your Service Report is required:

\*

\* Insert the document number into the field "Comment" (SMS form).

Purpose of this document:

- This document announces two solutions in case the DX-D 100 starts slow circular movements on its own. This is caused by a short-circuit due to excessive use of disinfection liquids on the collimator hand-grips.
- An adhesive protection film for the hand-grip buttons is available as protection against liquid when the user cleans/disinfects the hand-grip buttons.
- With DMC firmware version V11R3b8 (or later), an improvement is introduced to stop the mobile unit after 8 seconds if the movement has been caused by a short-circuit or by a pressed fine positioning button.
- After publication of DMC firmware V11R3b8 a software issue was detected (PRB2000628) and the firmware removed from the Agfa Medimg Library. V11R3b9 is available now and replaces V11R3b8.

Affected sites:

Install the protection film and upgrade the firmware to V11R3b9 at all DX-D 100 / 100 Wireless units where the issue occurs.

The signatures on the approval page indicate the solutions described in this Service Bulletin have been reviewed and are NOT reportable because no actions are taken to reduce a "Risk to Health" according to our risk assessment process.

Use, dissemination, distribution or reproduction of this bulletin by unauthorized personnel is not permitted and may be unlawful. The controlled version of this document is available from the Agfa Medimg Library. Any printed copy of this document is uncontrolled.

Copyright © 2021 Agfa NV | Document ID: 74741907

## 1 Introduction/purpose

### 1.1 Self-propelling unit [PRB2000478]

*Symptom* The mobile unit starts to move independently in small circles.

*Cause* When disinfecting by pouring or spraying liquids on the collimator hand-grips, a short-circuit in the fine positioning controls can occur.

These are the four buttons on the hand-grips, which control the (low speed) motion of each driving wheel forwards or backwards:

RB = Right Back; RF = Right Front

LF = Left Front; LB = Left Back




Figure 1: Fine Positioning Controls

The system is not able to distinguish a button pressed by a user or a short-circuit.

The result is that the unit moves on its own in a very slow motion and normally in circles as if just one button would be pressed. Note that the motion is at very low speed; the motion control does not allow high speeds for these controls.

#### *Solutions* **Solution 1: Protection sticker**

A film (sticker) to cover the four buttons as protection against liquid is available:

- Introduced in production end of January 2021.
- The protection stickers are also available as spare part for field upgrades.

#### **Solution 2: Updated DMC firmware**

With DMC firmware version V11R3b8 (or later), an improvement is introduced to stop the mobile unit after 8 seconds. The unit stops regardless of whether the movement has been caused by a mechanical blocked fine positioning button or by a short-circuit. Install DMC firmware version V11R3b9, which is the replacement of V11R3b8 (see section 1.2).

#### **Prerequisites:**

DMC firmware version V11R3b9 requires DMC hardware revision "H" or later and DMC firmware V11R3b5 or later.

Due to instructions in Mandatory Service Bulletins, these prerequisites should be fulfilled at all sites.



## NOTE:

Nevertheless, check the version\* and in case version is lower, follow the instructions in DX-D 100 Wireless - SB120 - MANDATORY... , Document ID [63468540](#).

\* Refer to *chapter Checking firmware version of the DMC board*, in the latest applicable DX-D 100 or DX-D 100 Wireless - Service Manual.

## 1.2 [PRB2000628] Error in hand grip keys is not detected at starting up with DMC firmware V11R3b8

*Symptom* The system will perform a self-diagnoses during startup, the DMC firmware V11R3b8 introduced an issue in this routine.

It will not detect a potential button (behavior) fault which could result in erroneous movement issues without the user knowing that an error is present.

*Cause* Code problem in the DMC b8 firmware.

*Solution* Installation of DMC firmware V11R3b9.

## 2 Prerequisites



### SOFTWARE:

Download the following software from the Agfa Medimg Library:

- DX-D 100/100 Wireless - Software - DMC Board Firmware V11R3b9, Document ID [74760426](#)



### SPARE PARTS:

Order only in case the cable to load firmware is not available:

- SC+A7130-02 DMC PCB programming Cable

The protection stickers are available as spare part:

- SC+P04271 Protection stickers kit (2 stickers)




Figure 2



### REFERENCED DOCUMENTS:

- DX-D 100 Wireless V11 - Service Manual, Document ID [66210593](#)
- DX-D 100 V11 - Service Manual, Document ID [66209499](#)
- DX-D 100 Wireless - SB120 - MANDATORY - Mandatory check of activities triggered by previous MSBs, Document ID [63468540](#)
- DX-D 100 / DX-D 100 Wireless - Mobile X-Ray Unit - Service Manual, Document ID [41600560](#)



### IMPORTANT:

The installation and service of the product(s) described herein is to be performed by qualified personnel who are employed by Agfa NV or one of its affiliates or who are otherwise authorized by Agfa NV or one of its affiliates to provide such services.



### IMPORTANT:

Strictly observe all safety directions within the "Generic Safety Directions", Document ID [11849633](#).

### 3 Instructions

**REQUIRED TIME:**

10 minutes for Mounting the protection stickers

60 minutes for firmware upgrade and customer information

#### 3.1 Mounting the protection stickers

- (1) Make sure that the surface of Collimator hand-grip buttons and the area around is clean and dry.
- (2) Stick a self-adhesive sticker over the two hand-grip buttons as shown in the figure.
- (3) Make sure that the four buttons are completely covered and the film sticks well.




Figure 3

### 3.2 Firmware upgrade

- (1) Make sure that DMC hardware revision “H” or later and DMC firmware V11R3b5 or later is installed.
- (2) Upgrade the DMC firmware:
  - Only in case the cable to load firmware on the board is *not* present: Order the cable (see section 0).
  - Download firmware V11R3b9 from the Agfa Medimg Library.
  - The firmware upgrade is described in:  
DX-D 100 / DX-D 100 Wireless - Mobile X-Ray Unit - Service Manual, chapter *Troubleshooting*, section 6.8.6 *Updating the Microcontroller*, Document ID [41600560](#).

#### 3.2.1 Customer information

- (1) Inform the customer about the new behavior of the fine positioning controls (the four buttons on the hand-grips):  
Once any of these buttons is pressed, the unit will start moving, but it will stop movement after 8 seconds, and it will be necessary to release and press again the button if the user wants to resume the displacement.

## 4 Verification

Verification of firmware upgrade:

- (1) Follow the instructions in:  
DX-D 100 / DX-D 100 Wireless - Mobile X-Ray Unit - Service Manual, chapter *Troubleshooting*, section 6.8.6 *Updating the Microcontroller*, Document ID [41600560](#).
- (2) Press a fine positioning button to check that the movement stops after 8 seconds. Release and press again the button to check if the movement resumes.
- (3) Also check that all the buttons covered by the protective stickers are working properly.

## 5 Keywords

fw, rev H, Digital Motion Control Board, fine movement keys, handgrip key, handlebar, covering foil

## 6 Version history

| Version | Change  | Date    |
|---------|---|---------|
| 1.0     | Initial Version   | 01-2021 |
| 2.0     | Previously announced DMC Firmware V11R3b8 is replaced by V11R3b9 due to a software issue in b8.<br>Problem Record added for the software issue. | 04-2021 |



### Details as of PDF Creation Date

#### Document Metadata

|                           |  |
|---------------------------|--|
| <b>Title:</b>             | DX-D 100 Wireless - SB162 - Solutions for movements - REMOVED until further notice |
| <b>Livelihood ID:</b>     | 74741907   |
| <b>Version#:</b>          | 11   |
| <b>Version Date:</b>      | 2021-04-01 03:55 PM CET  |
| <b>Status:</b>            | Approved on 2021-04-08 03:50 PM CET  |
| <b>Owner:</b>             | Annette Peters (awtso)   |
| <b>Created By:</b>        | Annette Peters (awtso)   |
| <b>Created Date:</b>      | 2020-10-13 09:52 AM CET  |
| <b>PDF Creation Date:</b> | 2021-04-08 03:50 PM CET  |

**This document was approved by:**

#### Signatures:

1. Josef Wagner (agwj) on 2021-04-01 04:29 PM CET
2. Paul Merckx (amdag) on 2021-04-01 05:18 PM CET
3. Bart Biesemans (amajm) on 2021-04-01 05:03 PM CET
4. Lieven Lauwers (awibr) on 2021-04-08 02:27 PM CET
5. Mark Schuermans (amdxp) on 2021-04-06 09:04 AM CET

#### Detailed Approver History:

- **Approval Workflow started on 2021-04-01 03:57 PM CET**
  - Approval task originally assigned to and completed by Paul Merckx (amdag) on 2021-04-01 05:18 PM CET
  - Approval task originally assigned to and completed by Mark Schuermans (amdxp) on 2021-04-06 09:04 AM CET
  - Approval task originally assigned to and completed by Lieven Lauwers (awibr) on 2021-04-08 02:27 PM CET
  - Approval task originally assigned to and completed by Josef Wagner (agwj) on 2021-04-01 04:29 PM CET
  - Approval task originally assigned to and completed by Bart Biesemans (amajm) on 2021-04-01 05:03 PM CET



**Version & Status History**

| Version# | Date Created            | Status   |
|----------|-------------------------|--|
| 11       | 2021-04-01 03:55 PM CET | Approved - 2021-04-08  |
| 10       | 2021-04-01 03:55 PM CET |  |
| 9        | 2021-03-31 01:27 PM CET | Reviewed - 2021-04-01  |
| 8        | 2021-03-31 01:27 PM CET |  |
| 7        | 2021-03-22 02:40 PM CET | Reviewed - 2021-03-29  |
| 6        | 2021-03-04 05:46 PM CET | Published - 2021-03-05<br>Approved - 2021-03-05  |
| 5        | 2021-01-05 09:01 AM CET | Unpublished - 2021-03-05<br>Published - 2021-02-26<br>Approved - 2021-01-13<br>Reviewed - 2021-01-07 |
| 4        | 2021-01-05 09:00 AM CET |  |
| 3        | 2020-12-14 03:20 PM CET | Reviewed - 2021-01-05  |
| 2        | 2020-10-15 09:11 AM CET | Reviewed - 2020-12-14  |

**Applied Categories and Attributes:**

|                                      |   |
|--------------------------------------|---|
| <b>Agfa Healthcare Library</b>       |   |
| Document Type:                       | Service Bulletin  |
| Category ><br>SubCategory ><br>Item: | Direct Radiography > DX-D 100 Wireless > DX-D 100 Wireless Generic  |
| Content Manager:                     | Josef Wagner (agwj)   |
| Summary:                             | DX-D 100 Wireless - Service Bulletin No. 162 - Version 1.0<br>Has been removed until further notice.<br><br>Reason:<br>The announced DMC Board Firmware V11R3b8 has a software issue and will be replaced by a new one. |
| Language:                            | English   |
| Availability:                        | Extranet  |
| Language Master Document:            |   |
| Fileshare FTP URL:                   |   |