

② Drive a Stepper Motor interface to rotate the motor in clockwise by N steps, introduce suitable delay between successive steps.

Soln:-

```
#include <stdio.h>
#include <reg51.h>
char xdata port at 0xe803;
char xdata porta at 0xe800;
char idata acc at 0x30;

delay() // DELAY BETWEEN THE ROTATION OF
        THE STEPPER MOTOR
{
    int j;
    for (j=0; j<800; j++)
    {
    }
}

void main()
{
    port = 0x80; // CONFIGURE ALL THE PORTS OF
    while (1)    8255 AS OUTPUT PORT
    {
        acc = 0x88;
        porta = acc;
        delay();
        acc = 0x44;
        porta = acc;
        delay();
        acc = 0x22;
        porta = acc;
```

③ ①

```

porta = acc;
delay ();
acc = 0x88;
porta = acc;
delay ();
}
}

```

— X — X — X —