

ELEC 207

Instrumentation and Control

4 – Strain Gauge

Dr Roberto Ferrero

Email: Roberto.Ferrero@liverpool.ac.uk

Telephone: 0151 7946613

Office: Room 506, EEE A block

Stress and strain

Definitions


A strain gauge is a widely used transducer to measure strain:

- Strain is the deformation of a physical body under the action of an applied force (stress):

➤ **Strain** = change in length per unit length: $e = \frac{\Delta l}{l}$

➤ **Stress** = force per unit area: $\sigma = \frac{F}{A}$

➤ **Elastic modulus** = ratio between stress and strain: $E = \frac{\sigma}{e}$




Stress and strain

Poisson's ratio

The longitudinal tensile strain is accompanied by a transverse compressive strain, and vice-versa:

- The ratio between them is called **Poisson's ratio**: $\nu = -\frac{e_T}{e_L}$
 - It is usually between 0.25 and 0.4 for most materials;
 - The negative sign is used because e_T and e_L have opposite signs.




Strain gauge

Operating principle (1)

A **strain gauge** is a metal or semiconductor element that experiences a change in resistance when it is strained:

- It converts a strain into a change in **electrical resistance**, which can be measured.




Strain gauge

Operating principle (2)

The applied strain leads to changes in physical parameters (length l , cross-section area A , resistivity ρ):

- These parameters determine the **resistance** of the material: $R = \rho \frac{l}{A}$



- The **Gauge factor** is defined as: $G = \frac{\Delta R/R}{e} \longrightarrow \frac{\Delta R}{R} = Ge$

Strain gauge

Input-output relationship

The input-output relationship (**transfer function**) of a strain gauge can be written as:

$$\Delta R = R - R_o = R_o G e \quad \longrightarrow \quad R = R_o(1 + G e)$$

- Typical values of gauge factors (G) for **metal** strain gauges are around 2.0;
- Strain values (e) are usually very small, with maximum values around 5%:
 - Strain is often measured in **microstrain** ($\cdot 10^{-6}$);
- Nominal (unstrained) resistance values (R_o) are around 100 Ω .

Strain gauge

Gauge factor (1)

For small changes in the resistance value, the following approximation applies:


$$\Delta R \approx \left(\frac{\partial R}{\partial l} \right) \Delta l + \left(\frac{\partial R}{\partial A} \right) \Delta A + \left(\frac{\partial R}{\partial \rho} \right) \Delta \rho \quad \longrightarrow \quad \frac{\Delta R}{R} \approx \frac{\Delta l}{l} - \frac{\Delta A}{A} + \frac{\Delta \rho}{\rho}$$

- Consider a circular cross section as an example:

$$A = \pi r^2$$

$$\Delta A \approx (2\pi r) \cdot \Delta r$$

$$\frac{\Delta A}{A} \approx \frac{2\pi r \Delta r}{\pi r^2} \approx 2 \frac{\Delta r}{r}$$



Strain gauge

Gauge factor (2)

$$\begin{aligned} e_T = -\nu e_L &\quad \longrightarrow \quad \frac{\Delta r}{r} = -\nu \frac{\Delta l}{l} \quad \longrightarrow \quad \frac{\Delta A}{A} \approx -2\nu \frac{\Delta l}{l} \\ &\quad \longrightarrow \quad \frac{\Delta R}{R} \approx \frac{\Delta l}{l} - \left(-2\nu \frac{\Delta l}{l} \right) + \frac{\Delta \rho}{\rho} = (1 + 2\nu) \frac{\Delta l}{l} + \frac{\Delta \rho}{\rho} \end{aligned}$$

- Therefore the **Gauge factor** can be written as:

$$G \approx \underbrace{1 + 2\nu} + \underbrace{\frac{1}{e} \frac{\Delta \rho}{\rho}}$$

deformation effect

piezoresistive effect


Strain gauge

Metal vs semiconductor materials

- In **metal strain gauges** the deformation effect is dominant:
 - They have a low cost and therefore are very common;
 - They are less sensitive to temperature changes;
 - A typical material is the 'advance' alloy: 54% copper, 44% nickel, 1% manganese.
- In **semiconductor strain gauges** the piezoresistive effect is dominant:
 - They have a higher sensitivity, with Gauge factors higher than 100;
 - They are more sensitive to temperature changes;
 - The most common material is silicon doped with p-type or n-type material.

Strain measurement

Strain gauge in a measurement system



References

Textbook: Principles of Measurement Systems, 4th ed.

For further explanation about the points covered in this lecture, please refer to the following chapters and sections in the **Bentley** textbook:

- Chapter 8, Sec. 8.1.3: **Metal and semiconductor resistive strain gauges.**

NOTE: Topics not covered in the lecture are not required for the exam.

References

Textbook: Measurement and Instrumentation, 2nd ed.

For further explanation about the points covered in this lecture, please refer to the following chapters and sections in the **Morris-Langari** textbook:

- Chapter 13, Sec. 13.7: **Strain Gauges**;
- Chapter 13, Sec. 13.8: **Piezoresistive Sensors**.

NOTE: Topics not covered in the lecture are not required for the exam.