



O9000 (G82 INITIAL SET)  
 #100 = #18 ... POINT R  
 #101 = #26 ... POINT Z  
 #102 = #21 ... U (DWELL)  
 #103 = #9 ... F CUTTING  
 #104 = 0

O9082  
 CANNED CYCLES BY G82



## (2) Pocket Mill

A. The cycle for the pocket machining shown below is created by user macros as follow:



## B. Macro Call Command

G65 P9061 X... Y... Z... R... I... J... K...  
 T... Q... D... F... E... ;

where,

- X, Y: The absolute coordinate values of the start point (the lower left position of the pocket).
- Z: The absolute position of the bottom of the pocket.
- R: The absolute position of rapid traverse tool return.
- I, J: X-axis and Y-axis lengths of the pocket (unsigned).
- K: Finish allowance (left-over allowance. unsigned). Default value is 0.
- T: Cut width rate (designated in %).  
 Cut width = tool radius x T/100
- Q: Z-axis cut depth for each time (unsigned).
- D: Tool offset number.
- F: Feedrate on XY plane.
- E: Feedrate at Z-axis cut.  
 (Tool is fed 4 times as fast as E up to the point 1 mm to the preceding cut bottom.)