

## 2.4.5 FEED PER REVOLUTION<sup>+</sup>

When a spindle pulse generator is installed<sup>+</sup>, the feedrate per revolution function can be used, and a new G code will be used for this function. Before F function for feedrate per revolution is given, G code of F group shown below must be designated. When the power supply is switched on, G94 is in effect.

G code of 05 group	Function
G94	Feed per minute (mm/min) designation
G95	Feed per revolution (mm/rev) designation

Since F code is modal, the code is effective until the next F code is given. However, when G94/G95 are switched over, F code must be designated again.

After the designation of G95, the feedrate-of-tool per spindle-revolution can be given by 4 digits following F. The command range of the F code is as follows.

Table 2.17

		Format	Feedrate (Feed/min) range
Metric output	Metric input	F22	F0.01 - F99.99 mm/rev
	Inch input	F13	F0.001 - F3.936 in./rev
Inch output	Metric input	F22	F0.01 - F99.99 mm/rev
	Inch input	F13	F0.001 - F3.936 in./rev

1/10 of minimum unit of F code programmable range can be programmed by setting the contents of parameter #6020D2,D3 to 1. See Table 2.18.

Table 2.18

		Format	Feedrate (Feed/min) range
Metric output	Metric input	F23	F0.001 - F99.999 mm/rev
	Inch input	F14	F0.0001 - F3.9366 in./rev
Inch output	Metric input	F23	F0.001 - F99.999 mm/rev
	Inch input	F14	F0.0001 - F3.9366 in./rev

However, the programming of feedrate is restricted by the spindle speed (S) as shown below.

F	x	S	≤	Feedrate upper limit value or clamp value
(mm/rev or in./rev)		(rpm)		(mm/min)




Fig. 2.4 Restriction of Feedrate (F) and Spindle Speed (S)

## 2.4.6 AUTOMATIC ACCELERATION AND DECELERATION

Acceleration and deceleration for rapid traverse and cutting feed are automatically performed.

### 2.4.6.1 ACCELERATION AND DECELERATION OF RAPID TRAVERSE AND MANUAL FEED

In the following operation, the pattern of automatic acceleration and deceleration is linear.

- Positioning (G00)
- Manual rapid traverse (RAPID)
- Manual continuous feeding (JOG)
- Manual HANDLE feeding (HANDLE)




Fig. 2.5

Rapid traverse rate and acceleration/deceleration constant of rapid traverse rate can be set by parameter. (#6280 to #6301)

### 2.4.6.2 ACCELERATION/DECELERATION OF FEEDRATE

- Automatic acceleration and deceleration of feed motion (G01 - G03) are in the exponential mode.




Fig. 2.6 Exponential acceleration, deceleration

- Feedrate time constants are set at 4 msec intervals and feedrate bias is set at 2kpps intervals by parameters. (#6092, #6093)

Note:

The automatic acceleration/deceleration parameters are set to the optimum values for the respective machines. Do not change the setting unless this is required for special purposes.