


2.9.15 RETURN FROM REFERENCE ZERO (G29)[†]

This code is used to return the tool to its original position after return to reference zero by automatic return to reference zero, along the same path.

```
G28 Y... Z... ;      Point A → B → C
      ⏟              (Reference zero point)
      Point B

G29 Y... Z... ;      Point C → B → D
      ⏟              Point D
```



Figl 2.29

When G29 is programmed, it is not necessary to consider the distance between point B and C in the program. Particularly when an incremental instruction is used, this is effective for returning tool to the original position, after returning to reference zero.

Movement of C → B and of B → D is made at rapid traverse rates simultaneously along three axes (simultaneously four axes[†]) by G29. However, in an axis for which a coordinate instruction was omitted, the tool will not move.

If G28 is programmed a number of times, the final coordinates of point B which the last G28 creates is effective for the move of G29.

EXAMPLE 1 (In the case of absolute input)

```
N21 G90 ;
N22 G28 Z1000 Y2000 ; → (0, 2000, 1000)
N23 G28 X3000 ; → (3000, 2000, 1000)
```

N24 G29 X-4000 Y-5000 ;

Equal to the two blocks =

```
G00 X3000 Y2000 ;
G00 X-4000 Y-5000 ;
```

EXAMPLE 2

```
N31 G91 ;
N32 G28 Z... ;
N33 G28 X2000 Y4000 ;
N34 M06 ;
N35 G29 X4000 Y-4000 ;
```




Fig. 2.30

NOTES:

- An input error "024" occurs if G29 is programmed in tool radius compensation mode (G41, G42) or during canned cycle mode (G73, G74, G76, G77, G81 to G89).
- An input error "059" occurs if G29 is given without execution of G28 after the control is turned on.
- In principle, cancel tool offset before programming G28 or G29. If they are programmed when offset is also effective, interim positioning point B will also be offset, and the tool passes point B'.




Fig. 2.31