

#6092

Specifies the exponential function acceleration/deceleration time constant for cutting feed (common to all axes).

The setting formula is: "n" =  $\frac{t}{4} - 1$

where, t: time constant(ms), specifiable in units of 4 ms

#6093

Specifies the exponential function acceleration/deceleration speed bias for cutting feed (common to all axes).

Setting: "1" = 2 kpps.

#6094

(X-axis)

#6095

(Y-axis)

#6096

(Z-axis)

#6097

(4th-axis)

#6094 to #6097:

Specify the reference point return method, respectively, for the X-, Y-, Z- and 4th-axes.

"0" of NZ signal enabled		<input type="radio"/>	
NZ signal employed		<input type="radio"/>	<input type="radio"/>
Reference point pulse used	<input type="radio"/>		
Parameter setting	64	48	32

Standard setting: 64

#6106

Specifies the "rapid traverse section" for a "returning semicircle" by the proportionate semicircle radius in circle cutting (G12, G13).

Setting range: 0 - 10 (x 10%)

Examples:

1. A setting of 0 creates a rapid traverse section automatically computed by the program command values.
2. A setting of 10 (= 100%) makes the entire "returning semicircle" into a "rapid traverse section."

#6107

Specifies the number of manual pulse generators.

Setting range: 1 - 3

#6120

G-1

#6121

G-2

#6122

G-3

#6123

G-4

#6124

G-5

#6125

G-6

#6126

G-7

#6127

G-8

#6128

G-9

#6129

G-10

#6120 to #6129:

Specify up to 10 G codes for calling user macros.