

. G00 Z-4000;
 G13 I-5000 J700 D15 F300; D15 = -8.0 mm
 G00 Z4000;




Fig. 2.25

2.9.10 PLANE DESIGNATION (G17, G18, G19)

The plane for making circular interpolation and tool radius compensation is designated by G codes G17/G18/G19.

G17: XY plane
 G18: ZX plane
 G19: YZ plane

When the 4th axis[†] is selected, the following planes are newly added.

G17: XY plane or X α plane
 G18: ZX plane or Z α plane
 G19: YZ plane or Y α plane

α means U, V or W axis.

The move command in each axis can be programmed regardless of the plane designation by G17/G18/G19.

For example, if

G17 Z... ;

is designated, motion is on Z axis.

The plane for making tool radius compensation by command G41 or G42 is univocally determined by G17, G18 or G19: It is not possible to designate compensation plane including the fourth axis.

The XY plane (G17) is selected when the power is turned on.

2.9.11 INCH/METRIC DESIGNATION BY G CODE (G20, G21)[†]

Unit of input data are selectively specified by the following G codes between metric and inch.

G code	Input unit
G20	Inch
G21	Metric


These G codes are programmed at the leading end of a block of its own. If one these G codes are commanded, the units of all the following motions are changed afterwards.

- subsequent programs
- tool offset values
- part of setting parameters
- part of manual movements
- displays

NOTES:

- When G20 or G21 is commanded, the setting of inch/metric selection is changed. Therefore, the state of G20/G21 at the time of power application depends on the setting by parameter #6001 D0.

EXAMPLE



- When G20/G21 selection is commanded in the program, take the following procedure beforehand.

- When work coordinate system (G54 to G59) is used, return it to base coordinate system.
- Cancel all tool compensation command. (G41 to G48)