

REALTEK

RTL8305SC Ver.C & HomePlug CX90010


Notice

Rev: 1.1

Date: 2005.07.28

Author: Davis Lin

1. The EEPROM 24LC02A could be omitted for the HomePlug CX90010 application.
2. The P4FLCTL (Pin-46) should be tied to ground via an 1K resistor.
3. The P4DUPSTA (Pin-48) should be connected to shift-register **74LV164A** Pin-11 as figure 1.
4. The P4SPDSTA(Pin-47) should be floating to force the MII interface operated in 100Mbps mode.
5. The P4MODE[1:0] (Pin-44, Pin-45) should be floating for operated in MII MAC mode.
6. The DISHMPG(Pin-92) should be tied to ground via 1K resistor for HomePlug application.



RTL8305SC Ver.C & CX90010 Workaround solution

Figure.1