

bendlabs

Two Axis Development Kit

Getting Started Guide

TWO AXIS DEVELOPMENT KIT

Getting Started Guide

© Bend Labs
1649 W 1700S • Suite 100
Salt Lake City, UT 84105
www.bendlabs.com

Table of Contents

Precautions	1
Device Setup.....	2
Expected Output	3
Additional References	4

Precautions


Two Axis angular displacement sensor is NOT 5 V tolerant. Requires 1.62 - 3.6 V regulated supply for proper operation.

Don't pull the sensor by the wires

Don't strain the sensor more than 15%

Device Setup

1: Connect Two Axis sensor to the included trinket M0 as shown below:



2: Set up Trinket M0 Arduino IDE


- Follow Adafruit's guide found at <https://learn.adafruit.com/adafruit-trinket-m0-circuitpython-arduino/arduino-ide-setup> to get the Trinket M0 up and running in the Arduino IDE.

3: Integrate Sensor and Trinket

- Download example sketches and `ads_two_axis` Arduino driver at (github link)
- Copy `two_axis_ads_demo` sketch into your Arduino folder
- Copy folder `ads_two_axis_driver` into Arduino/Libraries folder
- Connect the Trinket M0 to a USB port
- Select Trinket M0 from the Arduino board manager and the associated COM port
- Flash `two_axis_ads_demo` sketch onto trinket M0

Expected Output

1: Click on tools and then Serial Plotter in the Arduino IDE or CTRL+SHIFT+L to verify that angular data coming from the Two Axis sensor is correct. (Note that touching the sensor while coupled to AC power can cause 60 Hz line noise).



2: Click on tools and then Serial Monitor in the Arduino IDE or CTRL+SHIFT+M to interface with the Two Axis Sensor through the serial port. A list of serial commands can be found in the `parse_serial_port` function in the `two_axis_demo` sketch.

Additional References

Pin Diagram:

