

Proportional-Integral Motor Speed Control Homework

1.
 - a. Load into Multisim the PI simulation in this Brightspace homework module.
 - b. Verify that $SP=100\%$ and $PV=0\%$ (grounded) and $k_p = 1$, $k_i = 0$, and $CO_{\max} = 100$ (**Upper Voltage Limit**)
 - c. Run the simulation to verify:
 $error = 100\%$, $V_{\text{out power interface}} = 18V$, $\text{rev/sec} = 29 \text{ rev/sec}$, $\text{sensor out} = 59 \text{ kHz}$
 - d. Set V1 to provide an Initial and a Final voltage of 0 V.
 - e. Run the simulation to verify:
 $error \sim 0$, $V_{\text{out power}} \sim 0$, $\text{rev/sec} \sim 0$, $\text{sensor out} \sim 0$
 - f. This verifies that the complete loop is properly calibrated in %. So $m = 1$.
 - g. Reset V1, the SP, with a step that goes from 25 to 75 at 1 sec.
 - h. Remove the output of the B input of the error summer from ground and connect it to -1 V/V calibration triangle.

2.
 - a. To be sure that the controller is never driven to its maximum or to 0 (even for a full-scale step in set point), set $k_p = 1$, $k_i = 0$, and $CO_{\max} = 100$ (**Upper Voltage Limit**). This creates a Proportional controller.
 - b. Change the **Analysis & Simulation** to **Transient**. **TSTOP = 2sec**
Output $V_{\text{set point\%}}$, $V_{\text{controller out\%}}$, and $V_{\text{revpersec \%}}$
 - c. Run the Transient Analysis. Place data marks on the highest and lowest values of $V_{\text{set point}}$, $V_{\text{controller out}}$, and $V_{\text{revpersec \%}}$. Save this plot to submit.
 - d. Write and submit a paragraph describing the performance, rating it as outstanding, ok, or crappy. Explain why the system is performing this way.

3.
 - a. Leave $k_p = 1$. Calculate the value for k_i that will make the system **critically** damped. Include your calculations with the plots. Enter that value for k_i .
 - b. Run the Transient Analysis. Place data marks on the highest and lowest values of $V_{\text{set point}}$, $V_{\text{controller out}}$, and V_{RPM} . Submit this plot.
 - c. Write and submit a paragraph describing the performance, rating it as excellent, getting there, or no improvement. Explain why the system is performing this way.

4.
 - a. Leave $k_p = 1$. Cut k_i to half of its value in step 3.a..
 - b. Run the Transient Analysis. Place data marks on the highest and lowest values of $V_{\text{set point}}$, $V_{\text{controller out}}$, and $V_{\text{RPM \%}}$. Submit this plot.
 - c. Write and submit a paragraph describing the performance. Explain why the system is performing this way.

5.
 - a. Leave $k_p = 1$. Double k_i to twice its value in step 3.a..
 - b. Run the Transient Analysis. Place data marks on the highest and lowest values of $V_{\text{set point}}$, $V_{\text{controller out}}$, and $V_{\text{RPM \%}}$. Submit this plot.
 - c. Write and submit a paragraph describing the performance. Explain why the system is performing this way.

-
6. a. As the motor ages or if it is replaced, its gain and time constant change. Return k_i to the value that caused critical damping. Lower the motor's gain to 1.2 (25% reduction in gain) and increase its time constant to 0.15 (50% slower).
- b. Run the Transient Analysis again. Place all of the markers as described above.
- c. Write and submit a paragraph describing the performance of the system with different motor constants. Is the performance identical, acceptable, or crappy?