

Tutorial Sheet-7

Ravi Yadav (14EE92R09)

Q1

No load speed = 1200 rpm $\approx N_s$ (Synchronous speed)

$N_{FL} = 1140$ rpm (Speed at full load)

frequency = 60 Hz

(a) ~~No of poles~~ Relation between Synchronous speed and frequency and no of poles is

$$N_s \text{ (rpm)} = \frac{120f}{P}$$

$$P = \frac{120 \times f}{N_s}$$

$$P = \frac{120 \times 60}{1200} = 6$$

no of poles are 6

(b)

$$\% \text{ Slip} = \frac{N_s - N_r}{N_s} \times 100$$

$$N_r = (1-s) N_s = 1140 \text{ rpm}$$

$$\therefore \% \text{ Slip} = \frac{1200 - 1140}{1200} \times 100 = 5\%$$


(c)

The frequency of rotor voltage = s.f

$$= 0.05 \times 60 = 3 \text{ Hz}$$

(d)

(i) Speed of rotor field w.r.t rotor



here R.f is the magnetic axis of rotor field

Speed of R.f is N_s

Speed of rotor is N_r

So the relative speed is

$$\begin{aligned} &= N_s - N_r = N_s - (1-S)N_s \\ &= SN_s = 600 \text{ rpm} \end{aligned}$$

(ii) Speed of rotor field w.r.t stator

Since stator is stationary its speed is 0
therefore

Speed of R.f w.r.t stator will be $N_s = 1200 \text{ rpm}$

(iii) Rotor field w.r.t stator field

for interaction between the two fields and to generate torque
both fields rotate at synchronous speed N_s

Thus Speed of R.f w.r.t S.f = 0 rpm

e) $N_r = (1-S) N_s$
 $S = 0.1 \text{ pu}$

thus

$$N_r = (1-0.1) \times 1200 = 1080 \text{ rpm}$$

(f) Rotor frequency = $Sf = 0.1 \times 60 = 6 \text{ Hz}$

(g) Speed of


① rotor field w.r.t to rotor = $0.1 \times 1200 = 120 \text{ rpm}$

② rotor field w.r.t to stator = 1200 rpm

③ rotor field w.r.t stator = 0 rpm

2


Given

Motor \rightarrow 460V, 4 pole, 50hp, 60Hz, 3 ϕ $S_{fL} \rightarrow 0.038$ $r_1 = 0.33 \Omega$, $X_m = 30 \Omega$, $x_1 = 0.42 \Omega$, $x_2' = 0.42$ 

$$V_{th} = \frac{V_1 x_m}{\sqrt{r_1^2 + (x_1 + x_m)^2}} = 261.89, \quad Z_{th} = R_{th} + jX_{th} = \frac{jx_m(r_1 + jx_1)}{r_1 + j(x_1 + x_m)}$$

$$= 0.321 + j0.4176$$

$$Z_{th} = R_{th} + jX_{th}$$

Given $S_{fL} = 0.038$ for the $P_{sh} = 50 \times 746$ W and neglecting rotational losses

$$P_{sh} = P_{mech} \quad (P_{mech} = \text{Mechanical power})$$

$$P_{mech} = 3(1-S) P_g \quad (P_g = \text{air gap power})$$

$$3 \times \frac{(1-S)}{S_{fL}} \frac{i_2^2 r_2}{S_{fL}} = 50 \times 746 \text{ W} = P_{sh}$$

$$\left(\frac{1-S_{fL}}{S_{fL}} \right) \frac{V_{th}^2}{\left(\frac{x_2}{S_{fL}} \right)^2 + (x_2 + x_m)^2} \times r_2 = \frac{50 \times 746}{3}$$

On rearranging the equation

$$692.21 \delta_2^2 - 122.76 \delta_2 + 0.803 = 0$$

Solving the Quadratic equation gives two roots

$$\delta_2 = \frac{122.76 \pm \sqrt{(122.76)^2 - 4 \times 692.21 \times 0.803}}{2 \times 692.21}$$

$$\delta_2 = 0.1705, 0.00682$$

(b)

T_{\max} = Maximum torque can be written as

$$T_{\max} = \frac{3}{2\pi n_s} \frac{V_{th}^2}{\left(R_{th} + \frac{\delta_2}{S_{mt}}\right)^2 + (\delta_2 + R_{th})^2} \frac{\delta_2}{S_{mt}} \quad \text{--- (1)}$$

for maximum torque

$$S_{mt} = \frac{\delta_2}{\sqrt{(R_{th})^2 + (\delta_2 + R_{th})^2}}$$

replacing δ_2/S_{mt} in eq. (1)

$$T_{\max} = \frac{3}{2\pi n_s} \frac{V_{th}^2}{R_{th} + \sqrt{R_{th}^2 + (\delta_2 + R_{th})^2}}$$

$$T_{\max} = 448.10 \text{ Nm}$$

$$S_{\max} = \frac{\delta_2}{\sqrt{R_{th}^2 + (\delta_2 + R_{th})^2}} \times 100 = 0.19$$

$$\text{Speed at maximum torque} = (1 - 0.19) \times \frac{120 \times 60}{4} = 1458 \text{ rpm}$$

Starting torque can be expressed in terms of maximum torque as

$$T_{st} = \frac{2 T_{max}}{\frac{1}{s_{mt}} + s_{mt}}$$

$$T_{st} = \frac{2 \times 448.10}{\frac{1}{0.19} + 0.19} = 198 \text{ N-m}$$

Q3 Given

Motor \rightarrow 460V, 100hp, 4pole, Δ -connected, 60Hz, 3 ϕ

$s_{FL} \rightarrow 0.05$, η efficiency = 0.92 at load P.f = 0.87

$$T_{st} = 1.9 T_{FL}, \quad I_{st} = 8.5 I_{FL}$$

Ans a

$$\eta = \frac{\text{output power}}{\text{input power}}$$

$$\text{i/p power} = \frac{100 \times 746}{0.92}$$

$$\text{Now input power } P_{in} = \sqrt{3} V_L \times I_{rated} \times \cos \theta$$

$$I_{rated} = \frac{P_{in}}{\sqrt{3} \times V_L \times \cos \theta} = \frac{100 \times 746}{0.92 \times \sqrt{3} \times 460 \times 0.87} = 116.98 \text{ amp}$$

$$I_{st} = 8.5 \times I_{rated} = 8.5 \times 116.98 = 994.33 \text{ amp}$$

$$\text{Now } \frac{T_{st}}{T_{FL}} = \left(\frac{I_{st}}{I_{FL}} \right)^2 \times s_{FL}$$

$$\frac{I_{st}}{I_{FL}} = \sqrt{\frac{1.9}{0.05}}$$

$$I_{st} = 161.3 \text{ A}$$

full load power generated

$$\frac{100 \times 746}{0.92} = 3 \times \left(\frac{161.3}{\sqrt{3}} \right)^2 \times r_2 \left(\frac{1 - s_{fl}}{s_{fl}} \right) \quad (\text{Since it is a } \Delta \text{ connected machine})$$

$$\boxed{r_2 = 0.164 \Omega}$$

for rated conditions

$$\frac{100 \times 746}{0.92} = 3 \times \left(\frac{I_{rated}}{\sqrt{3}} \right)^2 \times r_2 \times \left(\frac{1 - s_{rated}}{s_{rated}} \right)$$

$$\boxed{s_{rated} = 0.02693}$$

Now

$$\frac{T_{st}}{T_{rated}} = \left(\frac{I_{st}}{I_{rated}} \right)^2 \times s_{rated}$$

$$\boxed{T_{st} = 1.9456 T_{rated}}$$

Since $T_{st} \propto (V_s)^2$

let n be the reduction in supply voltage

$$T_{st} \propto n^2 (V_s)^2$$

$$T_{st} n^2 = \frac{1}{1.9456}$$

$$n = 0.716$$

$$\text{thus Applied voltage} = 0.716 \times 460 = 329.7 \text{ V}$$

$$\begin{aligned} \text{Starting current} &= n \cdot I_{st} \\ &= 0.7169 \times 994.33 \\ &= 712.8 \text{ A} \end{aligned}$$

$$\eta = 0.9 \text{ at load of } 50 \text{ h.p.}$$

total mechanical loss

$$P_m = \frac{1}{3} P_{NL} \quad (P_{NL} = \text{no load loss})$$

~~$$P_{NL} = P_{NL} + P_m$$~~

~~$$P_{NL} = P_{NL} + P_m$$~~

~~now no load losses contain core loss + mechanical loss~~

~~$$P_m = \frac{1}{3} (P_m + P_{NL})$$~~

$$P_{oh} = 2 P_{iL} \quad (P_{oh} = \text{ohmic losses})$$

∴ now efficiency

$$\eta = \frac{P_{sh}}{P_{sh} + P_f + P_{oh}}$$

here P_f are core + mechanical losses (fix losses)

$$P_f = P_m + P_{iL}$$

$$\text{Since } P_m = \frac{1}{3} P_{iL}$$

$$P_f = \frac{1}{3} P_{iL} + P_{iL}$$

$$P_f = 1.33 P_{iL}$$

$$\text{and } P_{oh} = 2 P_{iL}$$

$$\eta = \frac{P_{sh}}{P_{sh} + 3.33 P_{iL}}$$

$$0.9 = \frac{50 \times 746}{50 \times 746 + 3.33 P_{iL}}$$

$$\boxed{P_{iL} = 1.244 \text{ kW}}$$

~~P_{ee}~~

$$P_m = \frac{1}{3} P_{iL}$$

$$P_m = \frac{1}{3} (1.244) \text{ kW}$$

Now mechanical power

$$P_{\text{mech}} = P_{sh} - P_m$$

$$P_{\text{mech}} \text{ also } P_{\text{mec}} = (1-s) P_g \quad - (1)$$

and ohmic losses

$$P_{oh} = s P_g \quad - (2)$$


on dividing (1) and (2)

$$\frac{(1-s)}{s} = \frac{P_{\text{mec}}}{P_{oh}}$$

$$\boxed{s = 0.032}$$

$$V_1 = \frac{200}{\sqrt{3}} = 115.47 \text{ V}$$

$$x_{20} = 0.1 \Omega, \quad x_{20} = 0.9 \Omega$$



$$\frac{N_{\text{rotor}}}{N_{\text{stator}}} = 0.67$$

$$\textcircled{a} \quad P_{in} = \frac{3 I_2^2 x_{20}}{s} = T \times \omega_s$$

$$T = \frac{3}{2\pi n_s} \cdot \frac{E_{20}^2}{\left(\frac{x_{20}}{s}\right)^2 + x_{20}^2} \cdot \frac{x_{20}}{s}$$

$$T = 40.478 \text{ N-m}$$

$$\textcircled{b} \quad I_2 = \frac{0.67 \times 115.47}{\sqrt{\left(\frac{0.1}{0.54}\right)^2 + (0.9)^2}} = 29.116 \text{ A}$$

Total mech power o/p

$$= 3 \times 29.116^2 \times 0.1 \times \left(\frac{1-0.04}{0.04}\right)$$

$$= 6.1 \text{ kW}$$

$$\textcircled{c} \quad \text{at max torque} \quad s_{mt} = \frac{x_{20}}{x_{20}}$$

$$T_{\text{max}} = \frac{3}{2\pi n_s} \cdot \frac{E_{20}^2}{2 x_{20}^2} x_{20}$$

$$T_{\text{max}} = 63.504 \text{ N-m}$$

$$\textcircled{1} \text{ Speed at max torque} = \frac{120 \times 50}{4} (1 - 0.11) \\ = 1338 \text{ RPM}$$

② At max power condition, current is

$$i_2 = \frac{0.67 \times 115.47}{\sqrt{\left(\frac{0.1}{0.11}\right)^2 + (0.9)^2}} = 60.4774 \text{ Amp}$$

$$\text{max mech power} = 3 i_2^2 r_2 \left(\frac{1 - s_{\max}}{s_{\max}} \right) \\ = 8.952 \text{ kW}$$

Q.6 3ϕ T/m 60V developed between slip rings
per phase rotor voltage = $\frac{60}{\sqrt{3}}$ V

$$r_{20} = 0.6 \Omega, x_{20} = 4 \Omega, r_{\text{ext}} = 5 \Omega, x_{\text{ext}} = 2 \Omega$$

$$\textcircled{a} \text{ Standstill rotor phase current} = \frac{60}{\sqrt{3} \sqrt{(5.6)^2 + (6)^2}} = 4.22 \text{ A}$$

$$\textcircled{b} \text{ With 4\% slip} = \frac{60/\sqrt{3}}{\sqrt{\left(\frac{0.6}{0.04}\right)^2 + (4)^2}} = 2.23 \text{ A}$$

Q.7 per phase rotor resistance $r_{20} = 0.2 \Omega$

$$N_{g1} = 960 \text{ RPM}, N_{g2} = 800 \text{ RPM}$$

$$s_{FL} = \frac{1000 - 960}{1000} = 0.04$$

$$s_{FL}' = \frac{1000 - 800}{1000} = 0.2$$

$$\frac{T_{FL}}{T_{\max}} = \frac{2}{\frac{s_{\max}}{s_{FL}} + \frac{s_{FL}}{s_{\max}}}$$

For $T_{FL1} = T_{FL2}$ the condition is

$$\frac{S_{max1}}{s_{FL}} + \frac{s_{FL}}{S_{max1}} = \frac{S_{max2}}{s_{FL}'} + \frac{s_{FL}'}{S_{max2}}$$

$$S_{max1} = \frac{s_2}{x_{20}} = \frac{0.2}{x_{20}}$$

$$S_{max2} = \frac{R}{x_{20}}$$

$$\frac{0.2}{x_{20} \times 0.04} + \frac{0.04 \times x_{20}}{0.2} = \frac{R}{x_{20} \times 0.2} + \frac{0.2 \times x_{20}}{R}$$

$$(1-R) \left[\frac{5}{x_{20}} - \frac{0.2 \times x_{20}}{R} \right] = 0$$

R should be equal to 1

therefore extra resistance = 0.8 Ω

Or full load slip $s_{FL} = 0.05$

Slip at maximum torque $S_{max} = 0.25$

$$T_{max} = 2.5 T_{FL}$$

$$\frac{T_{st}}{T_{max}} = \frac{2}{\frac{1}{S_{mt}} + S_{mt}}$$

$$= \frac{2}{\frac{1}{0.25} + 0.25}$$

$$T_{st} = 0.4705 \times T_{max}$$

$$T_{st} = 0.4705 \times 2.5 \times T_{FL} = 1.176 T_{FL}$$

$$\frac{T_{FL}}{T_{max}} = \frac{2}{\frac{S_{FL}}{S_{max}} + \frac{S_{max}}{S_{FL}}} = \frac{2}{\frac{0.05}{0.25} + \frac{0.25}{0.05}}$$

$$T_{max} = 2.6 T_{FL}$$

$$T_{st} = 1.223 T_{FL}$$

Q9 500HP, wound rotor i/m rotor resistance is increased by 5 times

(a) The expression of load torque is

$$T = \frac{3}{2\pi s} \frac{V_{th}^2}{\left(\frac{R_{rotor}}{s_{FL}}\right)^2 + X^2} \times \frac{R_{rotor}}{s_{FL}}$$

$$\text{Now if } R_g' = 5 \times R_{rotor}$$

$$\text{slip will change to } = 5 \times s_{FL} = 0.075$$

(b) Rotor ohmic loss at full load torque = 5.69 Kw

Since resistance is increased by 5 times

$$\text{new ohmic loss will be } = 5.69 \times 5 = 28.45 \text{ Kw}$$

(c) Shaft power output if mechanical loss are neglected

$$= 3 \cdot \frac{1}{2} I_2^2 R_{rotor} \left(\frac{1-s_{FL}}{s_{FL}} \right)$$

Now Since both R_{rotor} and s_{FL} change in same proportion with change thus P_{sh} remains unchanged

I_2 will change with rotor resistance

So -

Now during resistance change I_2 and $\frac{R_{rotor}}{s_{fl}}$ remains unchanged

hence

$$\frac{500}{m} - \frac{1-s_{fl}}{s_{fl}} = \frac{1-0.015}{1-0.075}$$

$$m = 469.543$$

(D) at maximum torque

$$s_{man} = \frac{R_{rotor}}{X_{rotor}} = 5 \times \frac{6}{100} = 0.3$$

(e) Rotor current at max torque = $\frac{E_{20}}{\sqrt{3} X_{rotor}}$

$$\text{Current remains same} = 2.82 I_{2fl}$$

(F) Rotor torque at 20% slip = $3.95 T_{st}$

now Torque at 0.2 slip

$$\frac{T_{02}}{T_{man}} = \frac{1}{\frac{0.2}{0.06} + \frac{0.06}{0.2}} = \frac{3.95 T_{st}}{I_{man}}$$

for modified condition

$$T_{st}' = 3.95 T_{st}$$

(g) Relation between T_{man} and T_{fl}

$$T_{man} = 3.95 T_{fl} \left(0.3 + \frac{1}{0.3} \right)$$

$$\frac{T_{st}'}{T_{man}} = \frac{3}{0.3 + \frac{1}{0.3}}$$

$$\text{Since } T_{st}' = 3.95 T_{fl}$$

$$3 I_{2s}^2 \times 5 R_{rotor} = 3.95 \times 3 \times I_{2fl}^2 \times \frac{5 R_{rotor}}{5 \times 0.015}$$

$$I_{2st}' = 7.25 I_{2fl}$$