

Friday, March 18, 2016

## Summary of phasor summation method

1. Express cosine functions as phasors
2. Add the phasors
3. Convert the result, if necessary, back to a cosine function.

Example 1: Determine  $v(t) = v_1(t) + v_2(t)$  and draw a phasor diagram.

where:  $v_1(t) = 5 \sin(\omega t + 45^\circ)$

$$v_2(t) = 10 \cos(\omega t + 90^\circ)$$

"Time-domain"  
representation (cosine  
function)

$$\begin{aligned} v_1(t) &= 5 \sin(\omega t + 45^\circ) \\ &= 5 \cos(\omega t + 45^\circ - 90^\circ) \end{aligned}$$

$$v_2(t) = 10 \cos(\omega t + 90^\circ)$$

Phasor  
notation

$$\bar{V}_1 = 5 \angle -45^\circ$$

$$\bar{V}_2 = 10 \angle 90^\circ$$

$$\text{Thus, } \bar{V} = \bar{V}_1 + \bar{V}_2 = \underbrace{5 \angle -45^\circ} + \underbrace{10 \angle 90^\circ}$$

$$\begin{aligned} 5 \angle -45^\circ &= 5 \cos(-45^\circ) + j5 \sin(-45^\circ) \\ &= 3.54 - j3.54 \end{aligned}$$

$$\begin{aligned} 10 \angle 90^\circ &= 10 \cos(90^\circ) + j10 \sin(90^\circ) \\ &= j10 \end{aligned}$$

$$\begin{aligned} \text{so } \bar{V} &= 3.54 - j3.54 + j10 \\ &= 3.54 + j6.46 \end{aligned}$$

back to polar:


$$\begin{aligned} &\sqrt{3.54^2 + 6.46^2} \angle \tan^{-1}\left(\frac{6.46}{3.54}\right) \\ &= 7.37 \angle 61.28^\circ \end{aligned}$$

Back to the time-domain expression

$$v(t) = 7.37 \cos(\omega t + 61.28^\circ)$$


A common misconception:  $\bar{V} = 3.54 + j6.46$ . The voltage is not a complex number. The voltage is a real-valued cosine with a magnitude of 7.37 and a phase angle of  $61.28^\circ$ .

The phasor diagram:




Phase relationship between sinusoids - important terminology


$$\begin{aligned} \text{Let } v_1(t) &= 10 \cos(\omega t + 45^\circ) & \longleftrightarrow & \bar{V}_1 = 10 \angle 45^\circ \\ v_2(t) &= 8 \cos(\omega t - 45^\circ) & \longleftrightarrow & \bar{V}_2 = 8 \angle -45^\circ \end{aligned}$$



We say that  $v_1(t)$  is  $90^\circ$  higher in phase than  $v_2(t)$ , and therefore  $v_1(t)$  leads  $v_2(t)$  by  $90^\circ$ ; likewise,  $v_2(t)$  lags  $v_1(t)$  by  $90^\circ$ .



Example 2: Consider the phasor diagram below and let  $f = 100 \text{ Hz}$ . Express each phasor voltage in the time domain as  $V_m \cos(\omega t + \theta)$



We have  $\bar{V}_1 = 7 \angle 180^\circ - 45^\circ = 7 \angle 135^\circ$

and  $\bar{V}_2 = 10 \angle 30^\circ$

$\bar{V}_3 = 8 \angle 90^\circ$

↑ always use angular distance from the positive real axis.

We also have  $f = 100 \text{ Hz}$ , so  $\omega = 2\pi f = 200\pi \text{ rad/sec}$ .

Therefore,  $V_1(t) = 7 \cos(200\pi t + 135^\circ)$

$V_2(t) = 10 \cos(200\pi t + 30^\circ)$

$V_3(t) = 8 \cos(200\pi t + 90^\circ)$


- Note that:
- $V_1(t)$  leads  $V_2(t)$  by  $105^\circ$  and leads  $V_3(t)$  by  $45^\circ$
  - $V_3(t)$  leads  $V_2(t)$  by  $60^\circ$  and lags  $V_1(t)$  by  $45^\circ$ .

### Complex impedances

Now we need to revisit the voltage-current relationship for resistors, capacitors, and inductors when voltages and currents are sinusoidal.

## Inductance

Recall for the inductor



$$v_L(t) = L \frac{di_L(t)}{dt}$$

Where we have  $i_L(t) = I_m \cos(\omega t + \theta)$ . The voltage will be

$$v_L(t) = L I_m \frac{d}{dt} [\cos(\omega t + \theta)]$$