

CNC Programming Assignment: “Dot-to-Dot 9-Line Programs”

Learning Goals: Read and write basic Fanuc-style G-code using only the codes on the sheet. Use absolute programming (G90) with G54, G17/G18, G00 rapid, G01 feed, offsets, spindle, and coolant.

Part A — Quick Checks (10 pts)

- 1) What does G54 do?
- 2) Difference between G00 and G01?
- 3) What plane does G17 select? What about G18?
- 4) Why do we turn on G43 H1 (or tool offset) before Z-moves?
- 5) What is the difference between S (RPM) and F (feed)?

Part B — Mill, 9-line “Dot-to-Dot” (45 pts)

Write a 9-line program that starts safely, connects four XY points in order at Z = -0.10 in, feed = 5.0 ipm, then rapids home and ends.

Points (in inches): P1 (0.5, 0.5) → P2 (3.0, 0.5) → P3 (3.0, 2.0) → P4 (0.5, 2.0)

Template:

```
% O1 (MILL DOT-TO-DOT) T1 M06 M03 S7500 G54 G90 G17 G43 H1 Z? M08 G01 F5.0 Z-0.10 G01
X__ Y__ X__ Y__ X__ Y__ X__ Y__ G00 Z__ G00 X0 Y0 M30 %
```

Part C — Lathe, 9-line Straight Turn (35 pts)

Write a 9-line program using Tool 1 (T0101), G54, G18, coolant, spindle S1000 M03, face to Z=0.0, then turn the OD from X1.50 to X1.00 over Z-2.000, feed .006 ipr.

```
% O2 (LATHE STRAIGHT TURN) T0101 G97 S1000 M03 G54 G90 G18 G00 X__ Z__ M08 G01 F.006
Z0.0 G00 X1.60 G00 Z0.1 G01 X1.00 G01 Z-2.000 G00 X__ Z__ M30 %
```

Part D — Stretch Challenges (Extra Credit up to 10 pts)

1) Mill: Add two more XY points to draw a closed shape (≤ 12 lines). 2) Lathe: Add a short chamfer on the front edge (≤ 12 lines). 3) Explain how you would convert your mill code to incremental (G91) and why that might be safer for beginners.

Rubric Summary (100 pts)

Part A	10 pts
Part B	45 pts

Part C	35 pts
Extra Credit	10 pts
Total	100 pts