

Siemens Digital Industries Software

Best Practice for Polar Mode

Summary

This document will provide best practice for outputting polar mode in postprocess.

Table of Contents

1	All motions output as XZC.	1
1.1	Setup in Post Configurator.....	1
1.2	UDE “Set Polar”	2
2	Only rapid motions output in Polar mode	2
2.1	Setup in Post Configurator.....	2
2.2	UDE “Set Polar”	3
3	Documentation History	3

1 All motions output as XZC.

Using OOTB sim07 sinumerik machine as example.

```

N120 T="UGT0202_001" M6
N130 MSG("MILL_FINISH")
N140 TRAF00F
N150 SUPA Z=_Z_HOME D0
N160 SUPA X=_X_HOME Y=_Y_HOME B=_B_HOME C=_C_HOME D1
N170 CYCLE832(_camtolerance,1,1)
N180 COMPOF
N190 G54
N200 G17 G0 X89.997 Y0. B0. C-17.366 S2228 D1 M3
N210 Z50.
N220 Z3.
N230 G94 G1 G90 Z0. F1203.
N240 X89.721 C-17.585
N250 X89.448 C-17.804
N260 X89.179 C-18.021
N270 X88.913 C-18.239
N280 X88.651 C-18.456
N290 X88.392 C-18.673
N300 X88.136 C-18.889
N310 X87.883 C-19.105

```

1.1 Setup in Post Configurator


- Plane Output Supported set to "None", "All Except ZM" or "Non Orthogonal"

- 5th Axis Point set to (0, 0,0), otherwise will get warning message. It also means fixture coordinate system(G54, G55) is located in center of rotary table.

- Polar Mode
Set Polar Mode also for Linear Motions to "On"

1.2 UDE “Set Polar”

Attach to operations which tool axis is (0,0,1)




2 Only rapid motions output in Polar mode

Using OOTB sim07 sinumerik machine as example.


```
N120 T="UGT0202_001" M6
N130 MSG("MILL_FINISH")
N140 TRAFOOF
N150 SUPA Z=_Z_HOME D0
N160 SUPA X=_X_HOME Y=_Y_HOME B=_B_HOME C=_C_HOME D1
N170 CYCLE832(_camtolerance,1,1)
N180 COMPOF
N190 G54
N200 G17 G0 X89.997 Y0. B0. C-17.366 S2228 D1 M3
N210 Z50.
N220 Z3.
N230 G94 G1 G90 Z0. F1203.
N240 X54.572 Y-43.834
N250 X54.31 Y-44.159
N260 X18.885 Y-87.993
N270 Z3.
N280 G0 Z7.
```

2.1 Setup in Post Configurator

- Plane Output Supported set to “None” , “All Except ZM” or “Non Orthogonal”



- 5th Axis Point set to (0, 0,0), otherwise will get warning message. It also means fixture coordinate system(G54, G55) is located in center of rotary table.



- Polar Mode
Set Polar Mode also for Linear Motions to “Off”

▼ Polar Mode

Polar Mode Status at Start of Program: Off

Polar Mode Status for Each End of Path: Reset

Set Polar Mode also for Linear Motions: Off

Set Reference Vector for Polar Mode: X+

Set enabled Moves for Polar Mode: ALL

▼ Interpolation Mode

Set Polar Coordinate Interpolation Mode: Off

Approach Motion Before Interpolation Mode: 5th

2.2 UDE “Set Polar”

Attach to operations which tool axis is (0,0,1)

#Set Polar

Status: Active

Output Mode: ON

OK Cancel

3 Lock Axis UDE

Lock Axis UDE is used to lock specify axis so it doesn't move, other axes move will compensate the locked axis motion. For example, lock Y axis on plane XY will lead to XC-Z motion (tool axis must be (0,0,1)). Lock X axis on plane ZX will lead to ZB -Y motion (tool axis must be (0,1,0)).

In most cases it is used to convert XYZ motions to XZC motions. But it cannot be replaced by Polar UDE. Polar UDE just a subset of it. Lock Axis UDE can lock any axis on any position, such as lock C axis on 90 degree or Lock Y axis on 10mm.

4 Documentation History

When	Who	What
16-Sep-2020	LL	Initial version
