

UNIT-3

Heat Treatment of Steel

↳ Heat treatment is defined as controlled heating & cooling of metals to change their physical & mechanical properties, without changing the product shape.

↳ Various types of heat treatment processes are;

- ① Annealing , ② Normalising , ③ Hardening
- ④ Tempering , ⑤ Spheroidising .

① Annealing :-

↳ It is a type of heat treatment process, where a metal is heated to a suitable temperature, kept at that temperature for sometime and then allowed to cool slowly.

↳ Mostly cooling is done inside the furnace.

↳ Main aim of annealing is to increase the ductility of the metal.

↳ Various types of annealing processes are as follows.

- ① Full Annealing
- ② Process Annealing
- ③ Stress-Relief Annealing
- ④ ~~Iso thermal Annealing~~
- ⑤ Spheroidise Annealing

(A) Full Annealing :-


↳ Full annealing consists of heating the steel to austenitic region, holding it at that temperature for considerable time and then slowly cooling it inside the furnace.

↳ Full annealing process contains the following steps.

(i) Heating of the steel above 725°C . (for ex. 800°C)

(ii) Holding the steel at that temperature for a definite time.

(iii) Allowing the steel to get slowly cooled inside the furnace itself.



↳ Full annealing is done;


- (i) To improve ductility.
- (ii) To Remove internal stresses.
- (iii) To improve mechanical, electrical & magnetic Properties.

(B) Process Annealing :-

↳ It is also called as sub-critical annealing.

↳ Process annealing contains the following steps.

- (i) Heating the steel below critical temperature ($900-600^{\circ}\text{C}$).
- (ii) Holding the steel at that temperature for a definite time.
- (iii) Allowing the steel to get slowly cooled in ~~the~~ the ~~to~~ air.



(C) Stress-Relief Annealing :-

↳ It is used to remove internal stresses present in the material.

↳ Stress Relief annealing contains the following steps.

- (i) Heating the steel below critical temperature ($550^{\circ}\text{C}-650^{\circ}\text{C}$).
- (ii) Holding the steel at that temperature for a definite time. (1-2 hours)
- (iii) Allowing the steel to get slowly cooled in air.

① Spheroidise Annealing :-

↳ It is used to improve machinability of the material.


↳ It contains the following steps.

(i) Heating of the steel just below critical temp. ($650 \sim 720^\circ\text{C}$).

(ii) Holding the steel at that temperature for a suitable time.

~~(iii) Cycling around~~

(iii) Cyclic cooling and heating the steel around critical temperature.



↳ Mostly spheroidise annealing is done for more than 0.8% C steel.


② Normalising :-

↳ Normalising contains the following steps.

(i) Heating the steel $30\sim 50^\circ\text{C}$ above upper critical temperature (UcT).

(ii) Holding the steel at that temperature for a suitable time.

(iii) Allowing the steel to get cooled in still air.



- ↳ Cooling time taken in Normalising process is lesser than Annealing Process. Hence it is commonly used in industry as it is faster, economical & efficient process.
- ↳ The main aim of Normalising is to increase the toughness of the material.

Purpose of Normalising :-

- (i) To improve machinability (ductility)
- (ii) To remove internal stresses.
- (iii) To obtain uniform grain structure.


③ Hardening :-

↳ Hardening contains the following steps.

- (i) Heating the steel 30 to 50°C above "A₃" temperature line in case of hypo-eutectoid steel and 30 to 50°C above A₁ temperature line in case of hyper-eutectoid steel.
- (ii) Holding the steel at that temperature for a suitable time.

(iii) Allowing the steel to get rapidly cool by quenching in water.

↳ Due to rapid cooling, Austenite is directly transformed into Martensite.



Purpose of hardening:-


- ↳ To improve the hardness of steel & wear resistance.
- ↳ To improve strength & toughness.
- ↳ To improve cutting ability of steel.

④ Tempering

↳ Tempering is a heat treatment process of heating the hardened steel to a temperature below A_1 line (Lower critical temperature); in order to make it softer and more ductile.

↳ Tempering contains the following steps.


- (i) Heating the hardened steel below A_1 line [$100-700^{\circ}\text{C}$].
- (ii) Holding the steel at that temperature for a suitable time.
- (iii) Allowing the steel to get cooled to room temperature in air.



↳ Tempering produces tempered martensite with lower hardness than martensite but better toughness & ductility.

↳ Higher tempering temperature and higher the tempering time, ~~more~~ then it leads to lower hardness & better ductility.


⑤ Spheroidising



↳ Spheroidising contains the following steps.

- (i) Heating both hypo-eutectoid & hyper-eutectoid steel just below A_1 -line (Lower critical Temperature).
- (ii) Holding the steel at that temperature for a suitable time.
- (iii) Cyclic cooling & heating the steel around A_1 -line.


Isothermal Transformation Diagram (TTT Diagram)



↳ The relationship between temperature, time and transformation for a specific composition of steel is represented as Isothermal Transformation Diagram "or" TTT diagram.

↳ It helps to determine specific microstructure in materials after having different cooling rates.

↳ TTT diagram is also called as S-curve / C-curve / Bain's Curve.



① Annealing → slow cooling (Furnace) → Coarse Pearlite.


② Normalising → Faster cooling (Air cooling) → Fine Pearlite

③ Austempering → Interrupted → Bainite

④ Quenching (Hardening) → very fast cooling (water) → Martensite

⑤ Tempering → Heating after Quench → Tempered Martensite.

TTT Diagram for Eutectoid Steel (0.8% Carbon steel)



↳ TTT diagram deals with conversion of Austenite into Pearlite, Bainite, Martensite.

↳ In TTT diagram, left side "c"-curve indicates the starting of austenite transformation and right side "c"-curve indicates the ending of austenite transformation.

↳ The time Period between starting and ending of austenite transformation is called as incubation period.


↳ Transformation product between A_1 line (727°C) and nose temperature (550°C) is Pearlite (P).

↳ Transformation product between nose temperature (550°C) and M_s line (220°C) is Bainite (B).


↳ Transformation product below M_f line (120°C) is Martensite.

↳ As the transformation temperature decreases, hardness of the given steel increases. Hence Pearlite is relatively soft, Bainite is medium hard and martensite is very hard.

TTT Diagram for Hypo-eutectoid steel :- [$0.06\text{C} < 0.8$]



TTT Diagram for Hyper-eutectoid steel [% of C > 0.8]



Austenite to Bainite Transformation :-

Bainite :-

→ If the transformation of Austenite takes place below 550°C, then it results in formation of Bainite.



→ Bainite is a combination of ferrite (α) and Cementite (Fe_3C).

→ Bainite is classified into 2 types.

(i) Upper Bainite :- It is formed in the temperature range between 400°C to 550°C.

(ii) Lower Bainite :- It is formed in the temperature range between 250°C to 400°C.

↳ Micro-structure of upper & lower Bainite is drawn below.



Austenite to Martensite Transformation :-

↳ If austenite is cooled at very fast rate, then the resulting micro-structure is called Martensite.

↳ During cooling from austenitic region, austenite starts transforming into martensite at a temperature of about $220^{\circ}C$ & it is represented as " M_s " (Martensite start) in TTT-diagram.

↳ The temperature at which 99% of austenite is transformed into martensite is called " M_f " (Martensite finish) in TTT-diagram which is about $120^{\circ}C$.

↳ The transformation of austenite to martensite isn't fully completed and some amount of austenite will exist at temperature below " M_f ". This is called as Retained Austenite.

↳ Micro-structure of Martensite appears like a rod/needle shape.

