

Roll Number: _____

Thapar University Patiala
Department of Mechanical Engineering
Mid Semester Examination
20th Sept., 2017

BE- 4th Semester



Time: 02 Hours; MM: 60

UTA002: Manufacturing Processes

Name of Faculty: VJ, DG, ATS, NHV, DM, GLK, APS

NOTE: Do all questions in sequence; assume suitable missing data, if any.
Mention your group number on the top of answer sheet.
Support your answers with neat sketches wherever required.
All questions are compulsory and carry equal marks.
Use handout for Q 3 (a).

			Marks
Q1	(a)	From a raw material of 100 mm length and 10 mm diameter, a component having length 100 mm and diameter 8 mm is to be produced in a single pass using a cutting speed of 31.41 m/min and a feed of 0.7 mm/revolution. The workpiece rotates at 1000 rpm. How many times we have to re-sharpen/regrind or replace the cutting tool, if 1000 work-pieces are to be produced. In the Taylor's expression use constants as $n = 1.2$ and $C = 180$.	10
	(b)	Explain in detail, the basic parameters required for specifying the grinding wheel for a given application.	08
	(c)	A cylindrical stainless steel rod with length $L = 150$ mm, diameter $D_0 = 12$ mm is being reduced in diameter to $D_f = 11$ mm by turning on a lathe. The spindle rotates at $N = 400$ rpm, and the tool is travelling at an axial speed of 200 mm/min. Calculate: (a) The cutting speed V (maximum and minimum) (b) The material removal rate MRR (c) The cutting time 't' (d) The power required if the unit power is estimated to 4 W.s/mm ³	05
Q2	(a)	A rolling mill used to roll a strip from $t_0 = 2.0$ mm to $t_f = 1.5$ mm, strip-width of $w = 500$ mm and 10 ft long. The rollers are driven at angular speed of $N = 50$ rpm. Calculate rolling force required when roll diameter is changed from $D_1 = 500$ mm to $D_2 = 300$ mm. Given material flow stress $\sigma = 150 (\epsilon)^{0.25}$ N/mm ² , Where ϵ is the strain rate and can be calculated as $\epsilon = -\ln(t_f/t_0)$.	05
	(b)	Identify the different classifications of metal forming processes. What is no slip point in relation to a rolling operation?	2, 1
	(c)	With the help of neat and clean schematic, distinguish between up and down milling.	4

Q3	<p>(a) Write a CNC part program of the given profile (refer Fig. 1) for its manufacturing on CNC Lathe. Consider the following parameters during machining:</p> <ul style="list-style-type: none"> i. Tool pre-travel allowance is 2 mm. ii. Spindle speed during turning and drilling operation are 1500 and 1000 rpm, respectively. iii. Feed rate during roughing and finish operations in turning cycle are 120 and 60 mm/min, respectively. iv. Feed rate in drilling is 50 mm/min. iii. The workpiece has to face of 5 mm before other operation. iv. In turning operation, the depth of cut during roughing is 0.5 mm and finishing allowance on X and Z is 0.1 mm. v. The depth of cut and tool retract distance in drilling operation are 1 and 2 mm, respectively.  <p style="text-align: center;">Fig. 1</p>	10
(b)	<ol style="list-style-type: none"> 1. Differentiate between absolute and incremental mode of programming in brief. 2. Mention the coordinates (A to G) of the machining path required to manufacture the given component (Fig. 2) in both absolute and incremental coordinate systems.  <p style="text-align: center;">Fig. 2</p>	2, 3
(c)	<p>What types of chips are expected while machining Aluminium alloy. Write all the conditions for obtaining such types of chips? Also, mention a few problems and the various methods to prevent these types of chips?</p>	3, 2
(d)	<p>Define the tool signature of a single point cutting tool? Draw the neat sketch of a single point cutting tool indicating all its faces and cutting edges?</p>	2, 3

Hand Out

G00 X_ Z_ – Rapid transverse

G01 X_ Z_ F_ – Linear motion with feed

G02 X_ Z_ R_ F_ – Tool movement in clockwise direction

G03 X_ Z_ R_ F_ – Tool movement in anti-clockwise direction

G20 – Inches mode

G21 – Metric mode (in mm)

G28 U_ W_ – Go to machine home position in incremental mode

G70 P_ Q_ F_ – Finishing cycle

G98 – Feed in mm/min

U – Incremental mode in X- axis

W – Incremental mode in Z- axis

X – Absolute mode in X- axis

Z – Absolute mode in Z- axis

Multiple turning cycle: G71 U_ R_
 G71 P_ Q_ U_ W_ F_

Drilling cycle: G74 R_
 G74 X_ Z_ Q_ F_

M03 – Spindle rotation in clockwise direction

M04 – Spindle rotation in anti-clockwise direction

M05 – Spindle stop

M06 – Tool change

M30 – Program Stop and Rewind