

Machining Science and Technology Task 1

1

Vikram Ganesh
SC20B062

Raw Materials

2

- Polycarbonate blanks of sizes
 1. $300 \times 300 \times 65 \text{ mm}^3$ - Housing top part base
 2. $300 \times 300 \times 20 \text{ mm}^3$ - Housing top part lid
 3. $300 \times 300 \times 30 \text{ mm}^3$ - Housing bottom part

Overall size of Housing - $300 \times 300 \times 115 \text{ mm}^3$

Mechanical Properties of Polycarbonate

3

Mechanical Property	Value
Young's Modulus	2 - 2.4 GPa
Tensile Strength	55 - 75 MPa
Elongation at fracture	80-150 %
Compressive Strength	>80 MPa
Poisson's Ratio	0.37
Rockwell Hardness	M70
Izod Impact Strength	600 - 850 J/m
Notch Test	20-35 kJ/m ²
Abrasive resistance ASTM D1044	10-15 mg/1000 cycles


Design Considerations

4

- The mentioned sensors had to be exposed outside the housing. Holes/Slots were made accordingly. The antenna of Sensor 4 is exposed out. Holes were made to expose the top parts of Sensor 1 and 3. D-pins are exposed through slots.
- Clearance was required for the electronic board. Bottom housing was made such that the clearance is well met.
- Weight had to be less than 3kg. Thickness has manipulated to accommodate it. Material chosen has good strength properties.
- It was decided to use bolts to join three parts of the housing. (Lid, Base and Bottom).


Weight of Designed Model - 2.437 kg

5




Constraints in assembly met

6




3D Model Images

7





Transparent view of 3D model

8





Housing Top Part - Base

9





Housing Top Part - Lid

10





Housing Top Part

11





Housing Bottom Part

12




Sensor 1

13




Sensor 2 Front view

15




Sensor 3 and 4

16





Sensor 3
Front view



Sensor 4



Sensor 3 and 4

17






Electronics Board

18



D-pins

19




Assembly of Housing

20


Bottom housing assembly

21




Top housing assembly

22



Full assembly

23



Machining Operations

24

Machining of Polycarbonate

25

- Specialized jigs and fixtures required to prevent cracking under high tensile loads.
- PC can be machined using simple lathe or mill.
- For milling and lathe, high rpm (typically 15000) with high feed (typically 3 times that of Al) is used.
- For drilling, to accommodate the poor heat dissipation of the polymer, it is done with low drilling speed and high passes and feed.
- After each machining operation, annealing/stress relieving is required.
- Chatter reduces finish and tool life. The workpiece has to properly be fixed to the work bench.

Lid Machining Sequence

26

Slab
milling




Drilling
(holes)

Lid of Top Housing


27

- Slab Milling
- Depth of cut - 17.3 mm
- Through holes drilled on four corners.



Base Machining Sequence


28



Base of Top Housing


29

- Slab milling of the initial blank in initial pass.
- The supports for the sensors are made using end milling. Mill the inner diameter circles of the supports. Then mill the in-between material of supports
- Drilling of holes (on 4 corners - top and bottom).



Bottom Housing Machining Sequence

30



Bottom Housing

31

- The whole part can be slab milled from initial bottom housing blank.
- The stands for the board (square cross-sectional extrudes with holes) can then be drilled.
- 4 corners can be drilled.
- The opening for D-pins is slab milled.



Machine Tools and Cutting Tools

32

Cutting Tool

33

- Need to have sharp cutting edge. This minimizes deformation.
- Contrary to tool selection in steel where we take slightly blunter tool to increase tool life.
- Blunt tool in PC will push the chip away instead of cutting it off.
- As a result, heat will be high (chip has the highest heat % of the heat balance) and the workpiece will have plastic distortions.
- Small grain size required in cutting edge
- HSS (High speed steel) good for this. Carbide tools without coatings are also good.

Required cutting and machine tools

34

- Milling - Vertical Milling machine
 1. End mill
 2. Slab mill
- Drilling - Drilling machine
 1. Drill bit
- Threading - Tapping
 1. Taps

End and Face mill

35

- More flutes in end mill to accommodate high feed.
- Burr formation is common in milling operations.
- Use secondary material at the edges so that the tool continues into the secondary material.
- High speed steel.

Drill bit and Tap

36

- Drills with twist angles of 12° - 18° and with large flute areas help remove chips and heat from the drilling hole.
- High speed steel
- Remove drill from holes frequently to allow cooling of workpiece and prevent chip accumulation.
- Don't use a used drill bit. It will be dull and can impact the workpiece.
- 3000 rpm is required for 4mm diameter holes.
- Two flute taps with enlarged flutes will help remove chips and keep the taps clear.

Coolant

37

- PC can melt and chips can get welded to surface without coolant.
- Non aromatic, water soluble coolants give good surface finishes and close tolerances. Ex Spray mists.
- High pressure air current is a good choice as they blow away the chips too.
- For deep grooves, soap water can be used.
- Flood coolants - Trim 9106CS, Polycut.


Assumptions

38

Electronic board

39



- Len from M1 to M3 given but length from edge to edge is assumed
- In the D-pin, the circles dimensions are assumed (radius of two larger holes and protrusion along with pins).
- Dimensions of covering of small pins are assumed.




Sensor 1 and 4

40

- Length of antenna is assumed in sensor 4
- Length dimension marked as diameter assumed as length.
- Length of pins assumed.






Manufacturing Drawings

42

Metrology Evaluation
Please see uploaded pdfs


Bottom Housing FV

43



Bottom Housing TV

44




Bottom Housing RSV

45




Top Housing Base FV

46




Top Housing Base TV

47




Top Housing Base Isometric view

48




Top Housing Lid FV

49




Top Housing Lid TV

50



Top Housing Lid Isometric View

51



Measuring methods and Instruments

52

Metrology Evaluation

Parallelism

53

- 2D - height gauge - This electronic device has a probe which when run on the surface measures parallelism wrt datum. The probe senses pressure variations when run along the surface. Internal working is similar to that of dial indicator.
- Dial indicator - The workpiece is divided into grids. The indicator is run over the workpiece. The starting points of each horizontal line is taken as 0(reference). Deflections for each grid point are taken. Then the parallelism is calculated for the whole surface wrt datum.
- Autocollimator - Light rays are captured by the autocollimator from the reflector as it moves along the surface. Based on the angle between the two initial parallel rays after reflection, the autocollimator calculates the parallelism.
- Coordinate measuring machine

Perpendicularity

54

- 2D-Height gauge - when the probe is run along the surface perpendicular to datum, perpendicularity is outputted. The gauge is locked at 90 degree to datum.
- A crude method is to use a square ruler and feeler gauge. The perpendicular part of the ruler is placed touching the surface. Using a feeler gauge the gap between ruler and surface is measured. This is the perpendicularity.
- Coordinate measuring machine - Each point of the workpiece is a unique point in the coordinate system of the machine. Perpendicularity, parallelism, cylindricity are thus measured.

Position Error And Cylindricity

55

- Coordinate measuring machine - Set the reference plane and put the stylus on the measurement point on the target. The measurement result is instantly displayed on the screen.

Measurement of Lengths, Diameters and Threads

56

- 2D Height gauge - Lengths and diameters
- Vernier calliper - Lengths and depths
- Screw gauge - Lengths
- 3-pin micro-meter - Diameters
- Go-No go gauges - for diameter inspection
- Plug gauges - thread inspection

References

57

- https://en.wikipedia.org/wiki/Polycarbonate#Properties_and_processing
- <https://aipprecision.com/machining-polycarbonate-pc-a-plastics-guide/#:~:text=Polycarbonate%20rod%20and%20plate%20are,pressurized%20air%20and%20spray%20mists>.
- <https://www.emcoplastics.com/polycarbonate-machining-and-fabrication/>
- <https://www.fictiv.com/materials/cnc-machining-polycarbonate>
- <https://augustafreepress.com/everything-you-need-to-know-about-polycarbonate-machining/>

- <https://cdn.thomasnet.com/ccp/00399914/221437.pdf>
- <https://www.linkedin.com/pulse/5-tips-polycarbonate-milling-nicole-he>
- <https://fractory.com/milling-cutters-and-tools/>
- https://brlcad.org/design/drafting/Drafting_Manual_Dimensioning_AndTolerancingSymbols_6-1.pdf
- <https://www.keyence.com/ss/products/measure-sys/gd-and-t/orientation-tolerance/perpendicularity.jsp>
- <https://encyclopedia.pub/entry/1314#:~:text=An%20interferometer%20is%20a%20geometric,perpendicularity%2C%20parallelism%2C%20and%20angle.>
- <https://www.keyence.com/ss/products/measure-sys/gd-and-t/location-tolerance/position.jsp>