



Smoothing a curve: Discrete Curve Shortening

- Basic Idea: smooth curve by moving points proportional to curvature, using a rough discrete estimate of curvature and normal
 - No interpolation in the process
- This algorithm will be denoted *curve shortening* or CSM
- Given C , *the estimate at a sample i is:*



Red: final vector on which we move the points




Smoothing a curve: Discrete Curve Shortening






- Algorithm

- Pick the smallest of v_1 and v_2
 - In this case, this is v_1
- We move according to the vector $\vec{k} = \left(v_1 + |v_1| \frac{v_2}{|v_2|} \right) \frac{1}{4}$
 - Divide by 2 since other points are moving too.
- Move point i *and store result in a new curve*;
- Repeat, taking the new curve as input.




Discrete Curve Shortening: Results




Bumps persist













Sharp edges develop
where
samples accumulate






3 steps






3 steps


Original w/ Samples




Original




1 Step




2 Steps




3 Steps




4 Steps




5 Steps




10 Steps




15 Steps






High-curvature features affected
even before removal of slight low-curvature bumps in the shape


Original w/ Samples




Original




1 Step




2 Steps




3 Steps




4 Steps




5 Steps




10 Steps




15 Steps






3 steps




3 steps (alone)

Not as smooth as we want,
and high-curvatures are already affected


Original w/ Samples




Original




1 Step




2 Steps




3 Steps




4 Steps




5 Steps




10 Steps




15 Steps














3 steps




15 steps


High curvatures get affected

Bumps persist (see also previous slide)






3 steps




15 steps

Notice accumulation
of samples at sharp corners
This makes smoothing stop
at these regions.


Original w/ Samples




Original




1 Step




2 Steps




3 Steps




4 Steps




5 Steps




10 Steps













15 Steps







10 steps
Bumps not 100% removed!





10 steps



25 steps

25 steps
Degrades peak
(locally 0 curvature)

